Asset:	_	R THE VISUAL ARTS - BF	RONX. 2040 ANT	TIN PLACE. RR	ONX. NV. 10	0462	X8
Inspection		THE VISUALARIS - DE	1011A, 2040 A11	III I LACE, DI	Time		Last Edited
	4891 ELECTRICAL					-04-22 07:47AN	
sset Data	1071 EEEE HGEHE				2021	0122 07.1711	2021 03 21 03.13111
Question				Answer			
	Systems/Major Ruilding C	omponents been upgraded?		Systems:	Retrofitted LF	ED Lighting (Ex	cept Multipurpose
Trave arry	bystems/Wajor Bunding C	omponents occir apgraded.			Room), Secur		
				Years:	2023		
				Systems:	Fire Alarm Sy	stem Printer	
				Years:	2022		
				Systems:			CCTV System, Fire
				V		n CO Detection	System
				Years:	2018	amanatan Cat	
				Systems: Years:	Emergency G 2006	enerator Set	
						atui aal Crystaura	and Components
				Systems: Years:	2004	cuicai systems	and Components
Type of So	arvica			Below Gro			
	ervice ractive Whiteboard (IWB) l	Exist?		Yes	- wii		
	etration In Electrical Room			No			
		N FIRE RESCUE AREAS					
Question				F	Response		
Are then	re any Life Rescue Assistan	nce Areas, Fire Rescue Areas, an	nd/or Holding Roon	ns in N	No .		
your bu	ilding?						
Priority Co.	ndition						
Exist	Priority	Condition	Component	Location	Person(s)	Person(s)	Photo
Last Year?	Category	Description	Affected	Description	Notified	Title	Image
Yes	Fire Alarm System -	Main Panel is in trouble	Fire Alarm	Main Entrance	Manuel	Fireman	No Photo Taken
	Defective	mode and the bell has	System - Main	Lobby	Taveras		
		been silenced.	Panel				N. D
No	Water Leaks onto Electrical Equipment	N/A	Exit Light, Emergency	2nd Floor Exit 5.	Manuel Taveras	Fireman	No Photo Taken
	Electrical Equipment		Light	3.	Taveras		
No	Exposed Electrical	Raceway is Broken.	Raceway With	Computer Lab	Manuel	Fireman	No Photo Taken
	Wires	Ž	Receptacles	Room 216	Taveras		
Inspection			-				
				Dogwanaa			
Question				Response			
Electrical							
	ETIC FIELD			Does not e			
AUDIT	ORIUM			Does not e	exist		
CAFET	TERIA			Inspected			
	Instance on 1st Floor			Inspected			
Lighti	ing						
	Instance on 1st Floor			Inspected			
Ligh	nting Fixture - Fluorescen	t					
	Instance on 1st Floor			Does not e	exist		
Ligh	nting Fixture - HID						
	Instance on 1st Floor			Does not e	exist		
Ligh	nting Fixture - Incandesce	ent					
	Instance on 1st Floor			Does not e	exist		
	mstance on 1st 11001						
	nting Fixture - LED						
				Inspected			
Ligh	Instance on 1st Floor			Inspected			
Ligh	Instance on 1st Floor			Inspected			

Building Condition Assessment Survey 2023-2024

circui Inspection		100)
Question	Response	
CAFETERIA		
Lighting		
Lighting Fixture - LED		
Pendant Mounted		
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on 1st Floor	Does not exist	
Recessed Mounted		
Instance on 1st Floor	Does not exist	
Local Sound System		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Installation Year	2004	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	-
Projection System		
Instance on 1st Floor	Does not exist	
Theater Lighting System		
Instance on 1st Floor	Does not exist	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected	
Lighting	Inspected	
Does a Chandelier Exist?	No	
Lighting Fixture - Fluorescent	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Inspected	
Pendant Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
COMPUTER LAB	Inspected	
Instance on Room 216	Inspected	
Power Panel?	Yes	
Lighting		
Instance on Room 216	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 216	Does not exist	
Lighting Fixture - HID		
Instance on Room 216	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 216	Does not exist	
Lighting Fixture - LED		
Instance on Room 216	Inspected	
Pendant Mounted		
Instance on Room 216	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room 216	Does not exist	
movement on recom 210		

Building Condition Assessment Survey 2023-2024

rical Inspection Duestion	Response
	кезропѕе
COMPUTER LAB	
Lighting	
Lighting Fixture - LED	
Recessed Mounted	
Instance on Room 216	Does not exist
Raceway With Receptacles	
Instance on Room 216	Inspected
Instance Condition	3- Fair
Deficiency	RECEPTACLES NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
GYMNASIUM	Does not exist
KITCHEN	Inspected
Instance on 1st Floor	Inspected
Lighting_	
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Inspected
Pendant Mounted	тороно — — — — — — — — — — — — — — — — — —
Instance on 1st Floor	Does not exist
Surface Mounted	DOG HOL CAISE
Instance on 1st Floor	Does not exist
	Does not exist
Recessed Mounted	Insuranted
Instance on 1st Floor	Inspected 2- Between Good and Fair
Instance Condition	
Deficiency	No deficiencies recorded
LIBRARY	Inspected
Instance on Room 226	Inspected
Lighting	
Instance on Room 226	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 226	Does not exist
Lighting Fixture - HID	
Instance on Room 226	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 226	Does not exist
Lighting Fixture - LED	
Instance on Room 226	Inspected
Pendant Mounted	
Instance on Room 226	Inspected
Instance Condition	2- Between Good and Fair
nistance Condition	Z- Between Good and I an

No deficiencies recorded

Does not exist

Deficiency

Instance on Room 226

Surface Mounted

Electrical Inspection	A839

cirical inspection		A039
Question	Response	
LIBRARY		
Lighting		
Lighting Fixture - LED		
Recessed Mounted		
Instance on Room 226	Does not exist	
Raceway With Receptacles		
Instance on Room 226	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Projection System		
Instance on Room 226	Does not exist	
LOCKER ROOM	Does not exist	
MULTIPURPOSE ROOM	Inspected	
Instance on Room 120	Inspected	
Lighting		
Instance on Room 120	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 120	Does not exist	
Lighting Fixture - HID		
Instance on Room 120	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 120	Does not exist	
Lighting Fixture - LED		
Instance on Room 120	Inspected	
Pendant Mounted		
Instance on Room 120	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room 120	Does not exist	
Recessed Mounted		
Instance on Room 120	Does not exist	
Local Sound System		
Instance on Room 120	Does not exist	
Projection System		
Instance on Room 120	Does not exist	
Theater Lighting System		
Instance on Room 120	Does not exist	
SCIENCE DEMO ROOM	Does not exist	
SCIENCE LAB	Does not exist	
SCIENCE PREP ROOM	Inspected	
Instance on Room 212 A/B, 213A	Inspected	
Power Panel?	No	
Alternative Use	No	
Lighting	110	
Instance on Room 212 A/B, 213A	Inspected	
Lighting Fixture - Fluorescent	1	
Instance on Room 212 A/B, 213A	Does not exist	
Lighting Fixture - HID		
Instance on Room 212 A/B, 213A	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 212 A/B, 213A	Does not exist	
Lighting Fixture - LED		
9 · <u>8</u>		

Building Condition Assessment Survey 2023-2024

Question	Response	
SCIENCE PREP ROOM		
Lighting		
Lighting Fixture - LED		
Instance on Room 212 A/B, 213A	Inspected	
Pendant Mounted		
Instance on Room 212 A/B, 213A	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room 212 A/B, 213A	Does not exist	
Recessed Mounted		
Instance on Room 212 A/B, 213A	Does not exist	
Emergency Gas Shut-Off Valve		
Instance on Room 212 A/B, 213A	Does not exist	
Emergency Shut-Off Power		
Instance on Room 212 A/B, 213A	Does not exist	
Power Supply		
Instance on Room 212 A/B, 213A	Does not exist	
SWIMMING POOL	Does not exist	
TOILET ROOM - STAFF	Inspected	
	Inspected	
Lighting Lighting Fixture - Fluorescent	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - Incandescent Lighting Fixture - LED	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Does not exist	
Recessed Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
· · · · · · · · · · · · · · · · · · ·		
TOILET ROOM - STUDENT	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Inspected	
Pendant Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
AUXILIARY SIGNAL/BELL SYSTEM	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
EMERGENCY DC STANDBY BATTERY POWER	Does not exist	
EMERGENCY GENERATOR SET	Inspected	
Automatic Transfer Switch (ATS)	Inspected	
Instance	Electrical Room	
Instance Condition	3- Fair	

Electrical Inspection	A839

estion	Response	
EMERGENCY GENERATOR SET		
Automatic Transfer Switch (ATS)		
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	ASCO	
EquipmentId	Fire Alarm Automatic Transfer Switch	
Capacity/Size Quantity	70	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year	2006	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance	Room 204	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	GE Zenith Controls	
EquipmentId	N/A	
Capacity/Size Quantity	800	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year	2006	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance	Water Meter Room	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Firetrol	
EquipmentId	Fire Pump Transfer Switch	
Capacity/Size Quantity	20	
Capacity/Size UOM	HP	
Source of Capacity/Size	Nameplate 2006	
Installation Year Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
	Inspected	
Battery Charger	Roof Generator Enclosure	
Instance Instance Condition	3- Fair	
Instance Quantity	1 EACH	
Instance Quantity Uom		
Manufacturer	La Marche	
EquipmentId	Battery Charger	
Capacity/Size Quantity	10	
Capacity/Size UOM Capacity/Size 2 Quantity	AmpsDC 24	
Capacity/Size 2 UOM	VDC	
Source of Capacity/Size	Nameplate	
Installation Year	2006	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Emergency Distribution Board	Inspected	
Number of Spares	8	
Fused Disconnect Switch Type	Does not exist	
Molded Case Circuit Breaker Type	Inspected	
Instance	Room 204	

Building Condition Assessment Survey 2023-2024

Question		Response
EMERG	ENCY GENERATOR SET	
Emerge	ency Distribution Board	
Molde	ed Case Circuit Breaker Type	
	Instance Condition	2- Between Good and Fair
	Instance Quantity	1
	Instance Quantity Uom	EACH
	Manufacturer	Siemens
	EquipmentId	DPEM
	Capacity/Size Quantity	800
	Capacity/Size UOM	Amps Total
	Capacity/Size 2 Quantity Capacity/Size 2 UOM	1 Section(s)
	Source of Capacity/Size	Nameplate
	Installation Year	2006
	Source of Installation Year	Documented
	Deficiency	No deficiencies recorded
Diesel		Inspected
	Instance	Roof Generator Enclosure
	Instance Condition	3- Fair
	Instance Quantity	1
	Instance Quantity Uom	EACH
	Manufacturer	Rudox Engine & Equipment Co
	EquipmentId	Emergency Generator
	Capacity/Size Quantity	250
	Capacity/Size UOM	kVA
	Capacity/Size 2 Quantity	200
	Capacity/Size 2 UOM	kW
	Capacity/Size 3 Quantity	694
	Capacity/Size 3 UOM Source of Capacity/Size	Amps Nameplate
	Installation Year	2006
	Source of Installation Year	Documented
	Deficiency	DEFECTIVE FUEL SUPPLY/DELIVERY SYSTEM
	Deficiency Quantity	1
	Quantity Uom	EACH
	Potential Action	REPAIR
	Urgency of Action	PRIORITY 5
	Purpose of Action	LEVEL 2
	Violations	No violations recorded
Natural	l Gas	Does not exist
EMERG	ENCY LIGHT/EXIT LIGHT PANEL	Does not exist
EMERGI	ENCY LIGHTING	Inspected
Battery	Pack	Inspected
Condi		3- Fair
	Deficiency	No deficiencies recorded
Non Ba	ttery Pack	Inspected
Condi	•	3- Fair
	Deficiency	No deficiencies recorded
EXIT LIC	GHT	Inspected
Battery		Inspected
Condi		3- Fair
	Deficiency	BATTERY NOT OPERATIONAL
	Deficiency Location/Instance	2nd Floor Exit 5, Near By Room 104, 107.
	Deficiency Quantity	3
	Quantity Uom	EACH
	Potential Action	REPLACE BATTERY

Building Condition Assessment Survey 2023-2024

	n	
estion	Response	
EXIT LIGHT		
Battery Pack		
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Non Battery Pack	Does not exist	
EXIT/EMERGENCY LIGHT	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
TIRE ALARM SYSTEM	Inspected	
Bell/Horn	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Strobe	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Manual Pull Station	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fan Shutdown Control	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Duct Smoke Detector	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Area Smoke Detector	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
CO Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Heat Detector	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Elevator Recall	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Magnetic Door Holder/Contactor	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fused Cutout Panel	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Digital Communicator	Inspected	
Instance	Water Meter Room	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Ademco	
Manufacturer EquipmentId	Fire Alarm communicator	
Installation Year	2004	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Main Panel	Inspected	

Building Condition Assessment Survey 2023-2024

estion	Response	
RE ALARM SYSTEM		
Main Panel		
Bell At Panel	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Electronic)	Inspected	
Instance	Main Entrance Lobby	
Instance Condition	4- Between Fair and Poor	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Edwards System Technology	
Model	EST 3	
EquipmentId	Fire Alarm Control	
Installation Year	2004	
Source of Installation Year	Documented	
Deficiency	PANEL DEFECTIVE	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPAIR	
Urgency of Action	PRIORITY 5 LEVEL 6	
Purpose of Action Violations	12064595Y	
	Does not exist	
Fire Alarm Control Panel (Standard)	Inspected	
Sub-Panel Bell At Panel	Does not exist	
Fire Alarm Control Panel (Electronic)	Inspected	
Instance	Main Entrance Lobby	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
	EACH	
Instance Quantity Uom Manufacturer	Kidde Automated Systems	
Model	FX-5RD	
EquipmentId	CO Detection System Control Panel	
Installation Year	2018	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Standard)	Does not exist	
Remote Annunciator	Inspected	
Display Monitor	Does not exist	
Panel	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Printer	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Punch Register	Does not exist	
Sprinkler Flow/Air Pressure Switch	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Tamper Flow Switch/Chain	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
ROUNDING SYSTEM Condition	Inspected 3- Fair	

Electrical Inspection	X839
-----------------------	------

Question	Response
GROUNDING SYSTEM	**************************************
	No deficiencies recorded
Deficiency	
INTERCOM SYSTEM	Inspected
Elevator	Inspected 2. F. :
Condition	3- Fair
Deficiency	No deficiencies recorded
Holding Area	Does not exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Does not exist
MOTOR CONTROLLER	Inspected
MOTOR CONTROL CENTER	Does not exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Does not exist
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Does not exist
Molded Case Circuit Breaker Type	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
PUBLIC ADDRESS SYSTEM	Inspected
Instance	Room 202
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Dukane 250
Installation Year	2004
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
SECURITY	Inspected
IPDVS/CCTV System	Inspected
Condition	2- Between Good and Fair
Installation Year	2018
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	Custodian's Office Room 114
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 128B
Installation Year	2004
Source of Installation Year	Documented

Electrical Inspection	X839
-----------------------	------

Question	Response
SECURITY	
Intrusion Alarm System	
Central Control Panel	
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3- Fair
	No deficiencies recorded
Deficiency	
Lighting - Security Condition	Inspected 1- Good
	No deficiencies recorded
Deficiency	
SERVICE SWITCH	Inspected
Instance	Electrical Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Precision Switchboard
EquipmentId	Service Switch #1
Capacity/Size Quantity	2500
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2004
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
SWITCHBOARD	Inspected
Number of Spares	1
Fused Disconnect Switch Type	Inspected
Instance	Electrical Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Electrotech
EquipmentId	N/A
Capacity/Size Quantity	2500
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	2
Capacity/Size 2 UOM Source of Capacity/Size	Section(s) Service Switch Size
Installation Year	2004
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not exist
Molded Case Circuit Breaker Type	Does not exist
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Deficiency	No deficiencies recorded

Building Condition Assessment Survey 2023-2024

Question	Response
TELEPHONE SYSTEM	
Standard	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
TRANSFORMER	Does not exist