## **Building Condition Assessment Survey 2023-2024**

X84	456	RONY NV 10	LE AVENUE T	HOOL - BRONX, 916 EAC		Asset:
In Last Edited	Time In	KONA, N1, 10-	LE AVENUE, E	HOOL - BRONA, 710 EAC		Inspection Io
	2023-10-19 08:10AM				00 ELECTRICAL	
2023 11 10 02.3/11/1	2023 10 17 00.107111				00 EEECTIGERE	sset Data
		Answer				Question
	LAN	Systems:		omnonents heen ungraded?	etems/Major Ruilding Co	
	2022	Years:		Have any Systems/Major Building Components been upgraded?		
ng. Telephone System	Interior Lighting, Telephone Sys	Systems:				
ng, retephone bystem	2014	Years:				
5	Motor Starters	Systems:				
	2012	Years:				
is	Security Lights	Systems:				
	2010	Years:				
m System	Intrusion Alarm System	Systems:				
	2002	Years:				
	ound	Below Gro			vice	Type of Serv
		Yes		Exist?	ctive Whiteboard (IWB) E	Does Interac
		No		?	ration In Electrical Room	Water Penetr
				FIRE RESCUE AREAS	ED INTERCOMS IN	DEDICAT
	Response					Question
	10	is in N	d/or Holding Roon	ce Areas, Fire Rescue Areas, an		Are there a your build
						•
	<b>D</b> () <b>D</b> () <b>T</b>			C W.		riority Cond
Person(s) Photo Title Image		Location Description	Component Affected	Condition Description	Priority Category	
Fireman	Lassana Fireman Fofana	Corridor	Exit Light Fixture	Water leaks through the ceiling onto Exit light Fixture	Vater Leaks onto Electrical Equipment	
Fireman No Photo Taken	Lassana Fireman M Fofana	Corridors	Emergency Lighting	Batteries are out of order	Emergency Lighting - Not Operational	N
						nspection
		Response				Question
	• ,					Electrical
		Does not e			IC FIELD	
		Does not e				AUDITO
	exist	Does not e			RIA	CAFETE
		Inspected		MINISTRATIVE SPACE		
		Inspected				Lighting
		No			Chandelier Exist?	
	:	Inspected Does not e			ng Fixture - Fluorescent	
	exist				dant Mounted	
-	n Good and Fair	Inspected 2 Patryan			ace Mounted	
1						
					•	
				nt		
					SIUM	GYMNAS
	exist exist exist exist exist	2- Between		nt	ndition Deficiency essed Mounted ng Fixture - HID ng Fixture - Incandescer ng Fixture - LED FER LAB	Rece Lightin Lightin Lightin COMPUT

#### **Building Condition Assessment Survey 2023-2024**

Question	Response	
LIBRARY	Does not exist	
LOCKER ROOM	Does not exist	
MULTIPURPOSE ROOM	Does not exist	
SCIENCE DEMO ROOM	Does not exist	
SCIENCE LAB	Does not exist	
SCIENCE PREP ROOM	Does not exist	
SWIMMING POOL	Does not exist	
TOILET ROOM - STAFF	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
TOILET ROOM - STUDENT	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
Lighting Fixture - HID	Does not exist	
Tild Tild T	Door not exist	

LEVEL 6

Inspected

Inspected 3- Fair

Does not exist

Does not exist

No violations recorded

Does not exist

No deficiencies recorded

Purpose of Action

Violations

Deficiency

**EXIT/EMERGENCY LIGHT** 

**Non Battery Pack** 

**Non Battery Pack** 

EXIT LIGHT Battery Pack

Condition

## **Building Condition Assessment Survey 2023-2024**

Electrical Inspection X840

ricai inspection	X84
Question	Response
FIRE ALARM SYSTEM	Inspected
Bell/Horn	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Strobe	Does not exist
Manual Pull Station	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	Does not exist
Duct Smoke Detector	Does not exist
Area Smoke Detector	Does not exist
CO Detector	Does not exist
Heat Detector	Does not exist
Elevator Recall	Does not exist
Magnetic Door Holder/Contactor	Does not exist
Fused Cutout Panel	Does not exist
Fire Alarm Digital Communicator	Does not exist
Main Panel	Inspected
Bell At Panel	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Does not exist
Fire Alarm Control Panel (Standard)	Inspected
Instance	Mechanical Room 7A
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Pyrotronics
EquipmentId	Fire Indicating Unit
Installation Year	1972
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Mechanical Room 7A
Deficiency Quantity	9,000
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Sub-Panel	Does not exist
Remote Annunciator	Does not exist
Sprinkler Flow/Air Pressure Switch	Does not exist
Tamper Flow Switch/Chain	Does not exist
GROUNDING SYSTEM	Does not exist
NTERCOM SYSTEM	Does not exist
AN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition Condition	1- Good
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Does not exist
LIGHTNING PROTECTION	Does not exist
MOTOR CONTROLLER	Inspected
MOTOR CONTROL CENTER	Does not exist
MOTOR STARTER/CONTACTOR Condition	Inspected 3- Fair

## **Building Condition Assessment Survey 2023-2024**

Duestion	Response	
MOTOR CONTROLLER	response	
MOTOR STARTER/CONTACTOR		
Deficiency	No deficiencies recorded	
Variable Frequency Drive	Does not exist	
PANEL BOARD	Inspected  Does not exist	
Fused Disconnect Switch Type	Does not exist  Does not exist	
Fused Knife Switch Type	Does not exist  Does not exist	
Fused Toggle Switch Type	Inspected	
Molded Case Circuit Breaker Type  Condition	3- Fair	
Deficiency	PANEL BOARD BEYOND USEFUL LIFE	
Deficiency Location/Instance	Mechanical Room	
Deficiency Quantity	2 EACH	
Quantity Uom	EACH	
Potential Action	REPLACE-UPGRADE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
PUBLIC ADDRESS SYSTEM	Inspected	
Instance	Connected to Main Asset X140	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Model	N/A	
Installation Year	1972	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Connected to Main Asset X140	
Deficiency Quantity	9,000	
Quantity Uom	S.F.	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
SECURITY	Inspected	
IPDVS/CCTV System	Does not exist	
	Y 1	

ECURITY	Inspected
IPDVS/CCTV System	Does not exist
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	Mechanical Room 7A
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 128B
Installation Year	2002
Source of Installation Year	Documented
Deficiency	PANEL NOT CONNECTED TO DOE CENTRAL STATION
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL CONNECTION
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Violations	No violations recorded
Infrared Sensor	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded

## **Building Condition Assessment Survey 2023-2024**

Electrical Inspection X840

item inspection	110
Question	Response
SECURITY	
Intrusion Alarm System	
Panic Switch	Does not exist
Remote Annunciator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting - Security	Inspected
Condition	5- Poor
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Location/Instance	Perimeter of the Building
Deficiency Quantity	7
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 3
Violations	No violations recorded
SERVICE SWITCH	Does not exist
SWITCHBOARD	Does not exist
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
TRANSFORMER	Does not exist