Building Condition Assessment Survey 2023-2024

Electrical In	spection	X842
Asset:	P.S. 95 ANNEX - BRONX, 3990 HILLMAN AVENUE, BRONX, NY, 10463	

Inspection	n Id Inspection Type				Time I	'n	Last Edited
	3534 ELECTRICAL				2024-0	02-27 09:16AN	1 2024-03-22 02:32PM
sset Data							
Question				Answer			
Have any	Systems/Major Building C	Components been upgraded?		Systems:	Most Molded	Case Circuit Br	eaker Panel Board
				Years:	2021, 2015		
				Systems:	LAN		
				Years:	2021		
				Systems:	Partial Exit Lig	ghts (Battery Pa	ick)
				Years:	2017		
				Systems:	Intrusion Alarr	n System	
				Years:	2007		
				Systems:	Fluorescent Li	ghting (Retrofit	ted)
				Years:	2002		
				Systems:	Fire Alarm Sys	stem, Most Sec	urity Lights
				Years:	2001		
Type of S				Below Gro	ound		
	eractive Whiteboard (IWB) netration In Electrical Roor			Yes			
		N FIRE RESCUE AREAS		Yes			
Question		Y FIRE RESCUE AREAS		п	Response		
		nce Areas, Fire Rescue Areas, ar	nd/or Holding Roor		Vo		
your bu	-	,					
Priority Co	ondition						
Exist	Priority	Condition	Component	Location	Person(s)	Person(s)	Photo
Last Year?	Category	Description	Affected	Description	Notified	Title	Image
No	Water Penetration in Electrical Room	N/A	Electrical	Electrical	Miss Lidia	Cleaner	No Photo Taken
Inspection			Equipment	Room			
Question				Response			
Electrica				Response			
	ETIC FIELD			Does not e	exist		
-	FORIUM			Does not e			
CAFE				Does not e			
-		MINISTRATIVE CRACE		Inspected	ZAISt		
		OMINISTRATIVE SPACE		Inspected			
Light Dog	es a Chandelier Exist?			No			
	hting Fixture - Fluorescer			Inspected			
_	endant Mounted			Inspected			
	Condition			3- Fair			
	Deficiency				encies recorded		
S	urface Mounted			Inspected			
	Condition			3- Fair			
	Deficiency			No deficie	encies recorded		
R	ecessed Mounted			Inspected			
	Condition			3- Fair			
	Deficiency				encies recorded		
Lio	hting Fixture - HID			Does not e			
	hting Fixture - Incandesc	ent		Does not e			
Lig	hting Fixture - LED			Does not e			
	mung rixture - 1,r,i)						
Lig				Does not e	exist		
Lig COMP	PUTER LAB			Does not e			
Lig COMP	PUTER LAB NASIUM			Does not e	exist		

Building Condition Assessment Survey 2023-2024

uestion	Response
LIBRARY	Does not exist
LOCKER ROOM	Does not exist
MULTIPURPOSE ROOM	Inspected
Instance on 2nd Floor	Inspected
	nispecieu
Lighting Instance on 2nd Floor	Inspected
Lighting Fixture - Fluorescent	nispected
Instance on 2nd Floor	Inspected
Pendant Mounted	nispected
Instance on 2nd Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
	No deficiencies recorded
Surface Mounted	Turnistad
Instance on 2nd Floor	Inspected 3- Fair
Instance Condition	
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 2nd Floor	Does not exist
Lighting Fixture - HID	
Instance on 2nd Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 2nd Floor	Inspected
Pendant Mounted	
Instance on 2nd Floor	Does not exist
Surface Mounted	
Instance on 2nd Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 2nd Floor	Does not exist
Lighting Fixture - LED	
Instance on 2nd Floor	Does not exist
Local Sound System	
Instance on 2nd Floor	Does not exist
Projection System	
Instance on 2nd Floor	Does not exist
Theater Lighting System	
Instance on 2nd Floor	Inspected
Dimming System	D
Instance on 2nd Floor	Does not exist
Theater Lighting	Termonts 1
Instance on 2nd Floor	Inspected
Instance Condition	3- Fair
Deficiency Deficiency Quantity	LIGHTING FIXTURE BEYOND USEFUL LIFE
	11 EACH
Quantity Uom Potential Action	
Potential Action Urgency of Action	REPLACE-UPGRADE PRIORITY 1
Orgency of Action Purpose of Action	LEVEL 2
Violations	No violations recorded
SCIENCE DEMO ROOM	Does not exist Does not exist

Building Condition Assessment Survey 2023-2024

Trical Inspection	X842
Question	Response
SWIMMING POOL	Does not exist
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Inspected
Condition	3- Fair
Deficiency Deficiency Quantity	LIGHTING FIXTURE BEYOND USEFUL LIFE
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	Does not exist
Lighting Fixture - LED	Does not exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not exist
EMERGENCY GENERATOR SET	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Does not exist
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	3- Fair
Deficiency	BATTERY NOT OPERATIONAL
Deficiency Location/Instance Deficiency Quantity	By Stairs B/2, A/Basement
	2 EACH
Quantity Uom Potential Action	EACH REPLACE BATTERY
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
	Does not exist
Non Battery Pack	
EXIT LIGHT	Inspected
Battery Pack	Inspected

Building Condition Assessment Survey 2023-2024

icui Inspection		24042
uestion	Response	
EXIT LIGHT		
Battery Pack		
Condition	3- Fair	
Deficiency	FIXTURE NOT OPERATIONAL	
Deficiency Location/Instance	Multipurpose Room	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 4	
Violations	E620165	
Non Battery Pack	Does not exist	
EXIT/EMERGENCY LIGHT	Does not exist	
FIRE ALARM SYSTEM	Inspected	
Bell/Horn	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Strobe	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Manual Pull Station	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fan Shutdown Control	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Duct Smoke Detector	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Area Smoke Detector Condition	Inspected 3- Fair	
Deficiency	No deficiencies recorded	
CO Detector	Does not exist	
Heat Detector	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Elevator Recall	Does not exist	
Magnetic Door Holder/Contactor	Does not exist	
Fused Cutout Panel	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Digital Communicator	Inspected	
Instance	Electrical Room	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	AFA Protective Systems	
EquipmentId	Fire Control Panel	
Installation Year	2001	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Main Panel	Inspected	
Bell At Panel	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	

Building Condition Assessment Survey 2023-2024

Question	Response
FIRE ALARM SYSTEM	
Main Panel	
Fire Alarm Control Panel (Electronic)	Inspected
Instance	By Electrical Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Notifier
Model	AIM 200
EquipmentId	Fire Alarm Control Panel
Installation Year	2001
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	Does not exist
Sub-Panel	Does not exist
Remote Annunciator	Inspected
Display Monitor	Does not exist
Panel	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Printer	Does not exist
Punch Register	Does not exist
Sprinkler Flow/Air Pressure Switch	Does not exist
Tamper Flow Switch/Chain	Does not exist
GROUNDING SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	Does not exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Does not exist
Main Equipment Rack (MDF)	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Does not exist
	Does not exist
MOTOR CONTROLLER	
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Does not exist Does not exist
Fused Knife Switch Type Fused Toggle Switch Type	Does not exist
Molded Case Circuit Breaker Type	Inspected
Condition	2- Between Good and Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
PUBLIC ADDRESS SYSTEM	Does not exist
SECURITY	Inspected
IPDVS/CCTV System	Does not exist
Intrusion Alarm System	Inspected
Central Control Panel	Inspected

Building Condition Assessment Survey 2023-2024

Duestion	Response
SECURITY	
Intrusion Alarm System	
Central Control Panel	
Instance	Electrical Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 128B
Installation Year	2007
Installation Year Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Panic Switch	Does not exist
Remote Annunciator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting - Security	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Location/Instance	Building Canopy
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 3
Violations	No violations recorded
Deficiency	LIGHTING FIXTURE PHOTOCELL NOT OPERATIONAL
Deficiency Location/Instance	
Deficiency Quantity	Outside By North Side
Quantity Uom	l EACH
Potential Action	REPLACE PRIORITY 2
Urgency of Action	PRIORITY 3 LEVEL 3
Purpose of Action Violations	
	No violations recorded
SERVICE SWITCH	Inspected
Instance	Electrical Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Delta Metal Product
EquipmentId	Main Switch for Building
Capacity/Size Quantity	400
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1965
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Definionary Lanction/Instance	Electrical Decre

Electrical Room

EACH

Deficiency Location/Instance

Deficiency Quantity Quantity Uom

Building Condition Assessment Survey 2023-2024

uestion	Response		
SERVICE SWITCH			
Potential Action	REPLACE		
Urgency of Action	PRIORITY 1		
Purpose of Action	LEVEL 2		
Violations	No violations recorded		
SWITCHBOARD	Inspected		
Number of Spares	1		
Fused Disconnect Switch Type	Does not exist		
Fused Knife Switch Type	Does not exist		
Molded Case Circuit Breaker Type	Inspected		
Instance	Electrical Room		
Instance Condition	3- Fair		
Instance Quantity	1		
Instance Quantity Uom	EACH		
Manufacturer	Federal Pacific Electric		
EquipmentId	Distribution Box for Each Panel Box		
Capacity/Size Quantity	400		
Capacity/Size UOM	Amps Total		
Capacity/Size 2 Quantity	1		
Capacity/Size 2 UOM	Section(s)		
Source of Capacity/Size	Service Switch Size		
Installation Year	1965		
Source of Installation Year	Documented		
Deficiency	BEYOND USEFUL LIFE		
Deficiency Location/Instance	Electrical Room		
Deficiency Quantity	1		
Quantity Uom	EACH		
Potential Action	REPLACE		
Urgency of Action	PRIORITY 1		
Purpose of Action	LEVEL 2		
Violations	No violations recorded		
TELEPHONE SYSTEM	Inspected		
PBX/Intercom	Inspected		
Condition	3- Fair		
Deficiency	No deficiencies recorded		
Standard	Inspected		
Condition	3- Fair		
Deficiency	No deficiencies recorded		