Building Condition Assessment Survey 2023-2024

P.S. 59 ANNEX - BRONX, 2120 QUARRY ROAD, BRONX, NY, 10457

Mechanical Inspection

Asset:

Asset:		2A - BRUNA, 2120 QUARRY I			T:-	I.	Loot E-lite J
Inspection							Last Edited
	751 MECHANICAI				2023	-12-18 12:13P	M 2024-01-19 04:33P
sset Data							
Question				Answer			
Have any Systems/Major Building Components been upgraded?				Systems: Years:	Electric Dom 2020	estic Water Hea	ater
Are there f	fuel tanks?			No			
Total # of	water main service en	tries to the asset		1			
MERs/Fan	n Rooms Locations			Room D -	- MER		
Are there any spaces with Missing or Defective CO Detectors? Are there any Painted/Obstructed Sprinkler Heads? Are there any Emergency Stop Switches with Missing Hammers?				No			
				No			
Are there a	any Emergency Stop S	Switches with Missing Hammers?		No compo	onents		
Priority Con	ndition						
Exist	Priority	Condition	Component	Location	Person(s)	Person(s)	Photo
Last Year?	Category	Description	Affected	Description	Notified	Title	Image
No conditi	on recorded						
Inspection							
Question				Response	2		
Mechanic	al						
AIR CO	NDITIONING			Inspected			
Chille	d Water System			Does not	exist		
Conde	enser Water Distribut	tion: Piping, Pumps and Auxiliari	es	Does not	exist		
	ng Coil in Ductwork			Does not	exist		
Coolin	ng Tower			Does not			
DX Sp	olit System			Inspected			
Indo	or Unit			Inspected			
Co	ndition			2- Betwee	en Good and Fa	ir	
	Deficiency			No defici	encies recorded		
Outo	door Unit			Inspected			
Co	ndition			2- Betwee	en Good and Fa	ir	
	Deficiency			No defici	encies recorded		
Dry C	ooler			Does not	exist		
	ged / Rooftop Unit			Inspected			
	Instance			Roof			
	Instance Condition			2- Betwee	en Good and Fa	ir	
	Instance Quantity			1			
	Instance Quantity U	Jom		EACH			
	Manufacturer			AAON			
	EquipmentId			N/A			
	Capacity/Size Quar	ntity		20			
	Capacity/Size UON			Tons			
	Source of Capacity			Documen	ted		
	Installation Year			2007			
	Source of Installati	on Year		Custodial	Staff		
	Source of Heating			Electric			
	Refrigerant Type			R-22			
	Deficiency			No defici	encies recorded		
	Instance			Roof			
	Instance Condition			2- Betwee	en Good and Fa	ir	
	Instance Quantity			1			
	Instance Quantity U	Uom		EACH			
	Manufacturer			AAON			
	EquipmentId			N/A			
	Concentra/Cine O						

EquipmentId Capacity/Size Quantity

6

X853

NYC Department of Education

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

	·· r · · · · ·		11000		
Question		Response			
AIR CO	NDITIONING				
Packag	ged / Rooftop Unit				
	Capacity/Size UOM	Tons			
Source of Capacity/Size		Documented			
Installation Year		2007			
Source of Installation Year		Custodial Staff			
	Source of Heating	Electric			
	Refrigerant Type	R-22			
	Deficiency	No deficiencies recorded			
Packag	ged Terminal A/C	Does not exist			
Refrig	erant Leak Detection System	Does not exist			
Refrig	erant Piping	Inspected			
Cond	ition	2- Between Good and Fair			
	Deficiency	No deficiencies recorded			
Return	ı Fan	Does not exist			
CENTR	AL ACID WASTE NEUTRALIZING TANK	Does not exist			
CLIMA	FE CONTROL SYSTEM	Inspected			
BMS		Inspected			
D 110	Instance	Throughout			
	Instance Condition	3- Fair			
	Instance Condition	1			
		EACH			
	Instance Quantity Uom				
	Building Area Covered by Operational System	81-100%			
	Installation Year	2007			
	Source of Installation Year	Custodial Staff			
	Deficiency	BEYOND USEFUL LIFE			
	Deficiency Location/Instance	Throughout			
	Deficiency Quantity	1			
	Quantity Uom	EACH			
	Potential Action	REPLACE			
	Urgency of Action	PRIORITY 1			
	Purpose of Action	LEVEL 2			
	Violations	No violations recorded			
	atic System	Does not exist			
Hybrid System		Does not exist			
Electric System		Does not exist			
COMPA	CTOR	Does not exist			
CONVE	YING	Does not exist			
DOMES	TIC WATER SYSTEM	Inspected			
Domes	tic Cold Water System	Inspected			
	ity System	Does not exist			
	sure Booster System	Does not exist			
-	er Service	Inaccessible			
	tic Hot Water System	Inspected			
Domestic Hot Water System Domestic Hot Water Remote Storage Tank		Does not exist			
Domestic Water Heat Exchanger		Does not exist			
Electric Domestic Water Heater		Inspected			
Condition		1- Good			
Deficiency		No deficiencies recorded			
Gas Fired Domestic Water Heater		Does not exist			
Oil Fired Domestic Water Heater		Does not exist			
Heat Pump Domestic Water Heater		Does not exist			
Domestic Water Distribution Piping		Inspected			
Condition		3- Fair			
	Deficiency	No deficiencies recorded			

X853

NYC Department of Education

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

		A03
Question	Response	
DRAIN/WASTE/VENT AND STORM SYSTEM	Inspected	
Interior Storm Piping	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Sewage/Waste/Vent Piping	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Sewage Ejector Pump	Does not exist	
Sump Pump	Does not exist	
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	Does not exist	
FIXTURES	Inspected	
Staff And Other	Inspected	
Janitor Sink	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lavatory/Sink	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Toilet	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Urinal	Does not exist	
	Inspected	
Student Drinking Fountain	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
-	Inspected	
Lavatory/Sink		
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Locker Room Shower	Does not exist	
Sink And Fountain Combo Unit	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Toilet	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Urinal	Does not exist	
GAS FIRED FURNACE	Does not exist	
GAS SERVICE	Does not exist	
HEATING	Inspected	
Heating Coil In Ductwork	Does not exist	
Hydronic Heating	Does not exist	
Radiator/Convector/Fin Tube	Does not exist	
Steam Heating	Does not exist	
Steam supplied by External Sources	Does not exist	
Unit Heater/Cabinet Heater	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
HEATING PLANT	Does not exist	
Enclosed IDF Room	Does not exist	
KITCHEN	Inspected	
Instance on 1st Floor	Inspected	
CO Detector	millione	

X853

NYC Department of Education

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

estion	Response	
AITCHEN		
CO Detector		
Instance on 1st Floor	Not required	
Gas System		
Instance on 1st Floor	Does not exist	
Grease Trap		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
	No deficiencies recorded	
Deficiency	No deficiencies recorded	
	De comet errict	
Instance on 1st Floor	Does not exist	
Hood Exhaust Ductwork		
Instance on 1st Floor	Does not exist	
Hood Exhaust Fan		
Instance on 1st Floor	Does not exist	
Hood Fire Suppression System		
Instance on 1st Floor	Does not exist	
Hot Water Temperature Booster		
Instance on 1st Floor	Does not exist	
Kitchen Sink		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
1DF Room	Inspected	
Instance on 1st Floor - Office A	Inspected	
Dedicated A/C Equipment	mspected	
Instance on 1st Floor - Office A	Inspected	
Instance Condition	4- Between Fair and Poor	
	DOES NOT EXIST	
Deficiency		
Deficiency Location/Instance Deficiency Quantity	1st Floor - Office A	
Quantity Uom	EACH	
Potential Action	INSTALL	
Urgency of Action Purpose of Action	PRIORITY 3	
*	LEVEL 2	
Violations	No violations recorded	
CIENCE DEMO ROOM	Does not exist	
CIENCE LAB	Does not exist	
CIENCE PREP ROOM	Does not exist	
PRINKLERS, STANDPIPE, FIRE SYSTEM	Does not exist	
WIMMING POOL	Does not exist	
	Inspected	
ENTILATION	*	
Is the building Mechanically ventilated?	Yes Inspected	
Exhaust Fan Condition	3- Fair	
	1-25	
Approximate Total # of Fans	No deficiencies recorded	
Deficiency		
Heating And Ventilating Unit	Does not exist	
Metal Ductwork	Inspected	
Condition	2- Between Good and Fair	
Are there any uninsulated ductwork by design in Mechanical rooms?	No	
Are there chain operated dampers?	No	
Deficiency	No deficiencies recorded	
Supply Fan	Does not exist	