# **Building Condition Assessment Survey 2023-2024**

Asset: P.S. 205B (EC	F) - BRONX, 2375 SOUTHEI	RN BOULEVAR	RD, BRONX, NY	, 10460		
Inspection Id Inspection Type				Time	In	Last Edited
2534 MECHANICAL				2024	-01-19 07:20A	M 2024-03-06 09:30PM
sset Data						
Question			Answer			
Have any Systems/Major Building	Components been upgraded?		Systems:	Electric Dom	estic Water Hea	ater
			Years:	2023		
			Systems:	Drinking Fou	ntains	
			Years:	2022		
Are there fuel tanks?			No			
Total # of water main service entr	ies to the asset		1			
MERs/Fan Rooms Locations			None			
Are there any spaces with Missing	g or Defective CO Detectors?		No			
Are there any Painted/Obstructed			No			
Are there any Emergency Stop Sw	vitches with Missing Hammers?		No compo	onents		
riority Condition						
Exist Priority	Condition	Component	Location	Person(s)	Person(s)	Photo
Last Year? Category	Description	Affected	Description	Notified	Title	Image
No condition recorded						
Inspection						
Question			Response	,		
Mechanical						
AIR CONDITIONING			Inspected			
Chilled Water System			Does not	exist		
Condenser Water Distribution	on: Piping, Pumps and Auxiliario	es	Does not	exist		
Cooling Coil in Ductwork			Does not	exist		
<b>Cooling Tower</b>			Does not	exist		
DX Split System			Inspected			
Indoor Unit			Inspected			
Condition			2- Betwee	en Good and Fa	ir	
Deficiency			No defici	encies recorded		
Outdoor Unit			Inspected			
Condition			2- Betwee	en Good and Fa	ir	
Deficiency			UP TO 5	TONS:DEFEC	ΓΙVE	
Deficiency Location	on/Instance		1st Floor	(near Custodian	office)	
Deficiency Quanti	ty		1			
Quantity Uom			EACH			
Potential Action			REPAIR			
Urgency of Action			PRIORIT			
Purpose of Action			LEVEL 2			
Violations				ions recorded		
Dry Cooler			Does not			
Packaged / Rooftop Unit			Does not			
Packaged Terminal A/C			Inspected			
Condition			3- Fair			
Deficiency	~			IVE MOTOR		
Deficiency Location			Rooms 20	01, 209		
Deficiency Quanti	ıy		2			
Quantity Uom			EACH	NANCE		
Potential Action			MAINTE			
Urgency of Action			PRIORIT	Y 3		
Purpose of Action Violations			LEVEL 2			
Violations			No violati	ions recorded		
Deficiency				IVE CONTROI		

### **Building Condition Assessment Survey 2023-2024**

Mechanical Inspection X864

anicai Inspection	Λου
uestion	Response
AIR CONDITIONING	
Packaged Terminal A/C	
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Refrigerant Leak Detection System	Does not exist
Refrigerant Piping	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Return Fan	Does not exist
	Does not exist
CENTRAL ACID WASTE NEUTRALIZING TANK	
CLIMATE CONTROL SYSTEM	Does not exist
COMPACTOR	Does not exist
CONVEYING	Inspected
Dumbwaiter	Inspected
Condition	3- Fair
Are all the existing dumbwaiters operable?	Yes
Deficiency	No deficiencies recorded
Elevator	Does not exist
Escalator	Does not exist
	Does not exist
Non-auditorium Handicap Lift - Vertical	Does not exist
Non-auditorium Handicap Lift - Stair Ash Hoist	Does not exist
Sidewalk Elevator	Does not exist
	Inspected
DOMESTIC WATER SYSTEM	
Domestic Cold Water System	Inspected
Gravity System	Does not exist
Pressure Booster System	Does not exist
Water Service	Inspected
Instance	Building Exterior - Water Heater Room 116
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Deficiency	WATER MAIN:MISSING BACKFLOW PREVENTION
,	DEVICE
Deficiency Location/Instance	Building Exterior - Water Heater Room 116
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	WATER MAIN:DEFECTIVE VALVE
•	
Deficiency Location/Instance Deficiency Quantity	Building Exterior - Water Heater Room 116
	1 FACU
Quantity Uom	EACH DEDLAGE
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
	Inspected

# **Building Condition Assessment Survey 2023-2024**

X864

**Mechanical Inspection** 

Question	Response
DOMESTIC WATER SYSTEM	
Domestic Hot Water System	
Domestic Water Heat Exchanger	Does not exist
Electric Domestic Water Heater	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Gas Fired Domestic Water Heater	Does not exist
Oil Fired Domestic Water Heater	Does not exist
Heat Pump Domestic Water Heater	Does not exist
Domestic Water Distribution Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
DRAIN/WASTE/VENT AND STORM SYSTEM	Inspected
Interior Storm Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Sewage/Waste/Vent Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Sewage Ejector Pump	Does not exist
Sump Pump	Does not exist
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	Does not exist
FIXTURES	Inspected
Staff And Other	Inspected
Y 11 Ct 1	Inconnected

Does not exist
Inspected
3- Fair
No deficiencies recorded
Inspected
Inspected
3- Fair
No deficiencies recorded
Inspected
3- Fair
No deficiencies recorded
Does not exist
Does not exist
Does not exist
Inspected
Inspected
Inspected
3- Fair
No deficiencies recorded
Inspected
3- Fair
DEFECTIVE AUXILIARY (FAUCET, SHUT OFF
VALVE,ETC.)
Room 220 - Toilet Room
1
EACH
MAINTENANCE
PRIORITY 3
LEVEL 2
No violations recorded
Inspected
3- Fair
CLOGGED/LEAKING
Nurse Room 222
1
EACH
MAINTENANCE
PRIORITY 3
LEVEL 2
No violations recorded
Does not exist
Inspected
Inspected
1- Good
No deficiencies recorded
Inspected

### **Building Condition Assessment Survey 2023-2024**

Mechanical Inspection X864

chanical Inspection	Λ004
Question	Response
FIXTURES	
Student	
Lavatory/Sink	
Deficiency	No deficiencies recorded
Locker Room Shower	Does not exist
Sink And Fountain Combo Unit	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE AUXILIARY (FAUCET, SHUT OFF
Deficiency	VALVE,ETC.)
Deficiency Location/Instance	Room 109, 209,108
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Toilet	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE FLUSHOMETER VALVE
Deficiency Location/Instance	Room 108 - Toilet Room
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Urinal	Does not exist
GAS FIRED FURNACE	Does not exist
GAS SERVICE	Does not exist
	Inspected
HEATING	Does not exist
Heating Coil In Ductwork	Does not exist  Does not exist
Hydronic Heating  Radiator/Convector/Fin Tube	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
	Does not exist
Steam Heating Steam supplied by External Sources	Does not exist  Does not exist
Unit Heater/Cabinet Heater	Inspected
Condition	2- Between Good and Fair
Deficiency	DEFECTIVE
Deficiency Location/Instance	Main Entrance
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
HEATING PLANT	Does not exist
Enclosed IDF Room	Does not exist
KITCHEN	Inspected
Instance on 1st Floor	Inspected
CO Detector	N
Instance on 1st Floor	Not required
Gas System	
Instance on 1st Floor	Does not exist

### **Building Condition Assessment Survey 2023-2024**

Mechanical Inspection	X864

uestion	Response	
KITCHEN		
Grease Trap		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Hood		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Hood Exhaust Ductwork		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Hood Exhaust Fan		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Hood Fire Suppression System		
Instance on 1st Floor	Does not exist	
Hot Water Temperature Booster		
Instance on 1st Floor	Does not exist	
Kitchen Sink		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	Missing Air Gap	
Deficiency Location/Instance	Kitchen	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 4	
Violations	SF103186	
MDF Room	Inspected	
Instance on Room 136	Inspected	
Dedicated A/C Equipment		
Instance on Room 136	Inspected	
Instance Condition	4- Between Fair and Poor	
Deficiency	DOES NOT EXIST	
Deficiency Location/Instance	Room 136	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	INSTALL	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
SCIENCE DEMO ROOM	Does not exist	
SCIENCE LAB	Does not exist	
SCIENCE PREP ROOM	Does not exist	
SPRINKLERS, STANDPIPE, FIRE SYSTEM	Does not exist	
SWIMMING POOL	Does not exist	
	Inspected	
VENTILATION  Is the building Mechanically ventilated?	Yes	
Exhaust Fan	Inspected	
Exhaust Fan Condition	3- Fair	

### **Building Condition Assessment Survey 2023-2024**

#### Mechanical Inspection X864

uestion	Response	
VENTILATION		
Exhaust Fan		
Approximate Total # of Fans	1-25	
Deficiency	No deficiencies recorded	
Heating And Ventilating Unit	Does not exist	
Metal Ductwork	Inspected	
Condition	3- Fair	
Are there any uninsulated ductwork by design in Mechanical rooms?	No	
Are there chain operated dampers?	No	
Deficiency	No deficiencies recorded	
Supply Fan	Does not exist	
Unit Ventilator	Does not exist	