Building Condition Assessment Survey 2023-2024

Architectural Inspection X870

Asset:	P.S. 70 MINISCHOOL - BRONX, 1691 WEEKS AVENUE, BRONX, NY, 10457		
Inspection Id	Inspection Type	Time In	Last Edited
3270	ARCHITECTURAL - SENIOR	2024-02-15 07:49PM	2024-06-16 03:40PM
3309	ARCHITECTURAL - ASSOCIATE	2024-02-15 09:04AM	2024-05-08 12:47PM

Asse

Weather

Facade Photo

set Data		
Question		Answer
Was the Building Fully Accessible	e for Inspection?	Yes
Principal(s) Information		
	Principal Name	Roxanne Ledda
	Principal Organization	P.S. 70 Minischool - Bronx
	Meeting with Principal?	Yes
	Principal Feedback	The Principal had no comments about the condition of the building at this time.
Custodian		Stephen Dejesus
Was the Custodian Present?		No
Fireman		Angel Guerrero
Was the Fireman Present?		Yes
Building Square Footage		9,000
Comments on the Area (for Athlet	tic Field, Playing Surfaces, Leased Spaces)	None
Comments on the Stories (Floors)	plus Basements	1 (No Basement)
Comments on the Year Built		1970
Student Population		N/a
Staff Population		N/a
Comments on the Number of Class	ssrooms	N/a



Eastburn Avenue - Southeast View

Building Condition Assessment Survey 2023-2024

Architectural Inspection

Main Entrance Photo

X870

Facade A - South View



Roof 1 - South View from Main Asset X070

No

No Storm Water Management Type Selected Systems: Exterior concrete painting at Ramps.

Years: 202

Systems: Exterior Metal Wall panel replacement (full); Window

Guard replacement (full), Exterior Door replacement

(partial), Roofing repairs (partial).

Years: 2007

No New Construction

No Tandem

No

Roof Photo

Do Stormwater Management/Green Infrastructure systems exist?

Type

Have any Systems/Major Building Components been upgraded?

Have there been any New Building Additions?

Tandem

Leased Space?

Priority Condition

Exist	Priority	Condition	Component	Location	Person(s)	Person(s)	Photo
Last Year?	Category	Description	Affected	Description	Notified	Title	Image

Structural Engineer Required

Structural	Condition	Component	Location	Person(s)	Person(s)	Photo
Condition Type	Description	Affected	Description	Notified	Title	Image

No condition recorded

No condition recorded

Building Condition Assessment Survey 2023-2024

Architectural Inspection X870

Programmatic Accessibility Status Question			Resp	onse		
Is the Primary or secondary entrance on an accessil	ale route?		Yes	onsc		
Is the building a multi-story building?	oic route:		No			
Do any of the following spaces exist? Classroo			Yes			
Computer, Gymnasiums, Library, Multipurpose		s				
For the spaces that do exist, are they ALL acc Is there at least one Boys and Girls or Unise		the building?	Yes No			
is there at least one boys and onts of Onise	ex tollet accessible ill	the building:	110		Assistive	Fire
Physical Breakdown Structure	Exists	Complies	Required	Deficiency	Listening System	Alar Strol
PROGRAMMATIC ACCESSIBILITY						
Exterior Routes						
Exterior Entrances & Exits		Yes				
Exterior H/C Lifts	No		No			
Exterior Ramps and Railings	Yes	Yes				
Interior Routes						
Corridor and Lobby H/C Lifts	No		No			
Interior Corridor Doors And Hardware	Yes	Yes				
Interior Corridors & Lobbies		Yes				
Interior Elevators	No					
Interior Lobby Doors And Hardware		Yes				
Interior Ramps	No					
Rooms & Spaces						
Art Rooms	No					
Auditorium	No					
Cafeteria	No					
Classrooms	No					
Computer Rooms	No					
Gymnasium	No					
Library	No					
Main Office	No					
Multi-purpose Room	No					
Nurse's Office	No					
Pool	No					
Science Lab	No					
Toilet Rooms (boys)						
1st Floor	Yes	No				
				ACCESSORY ARRANGEMENT INSUFFICIENT LATCH CLEARENCE NO LEVER-TYPE HARDWARE SINK ARRANGEMENT TURNING RADIUS WATER CLOSET ARRANGEMENT		
Toilet Rooms (girls)						
1st Floor	Yes	No		ACCESSORY		


Building Condition Assessment Survey 2023-2024

Architectural Inspection

v	O	7	n
λ	n	• /	u

Physical Breakdown Structure	Exists	Complies	Required	Deficiency	Assistive Listening System	Fire Alarm Strobe
				INSUFFICIENT LATCH		
				CLEARENCE		
				SINK ARRANGEMENT		
				NO LEVER-TYPE		
				HARDWARE		
Toilet Rooms (staff)						
1st Floor	Yes	No				
				ACCESSORY		
				ARRANGEMENT		
				SINK ARRANGEMENT		
				WATER CLOSET		
				ARRANGEMENT		

Building Template



Question	Response	
Architectural		
EXTERIOR	Inspected	
AREAWAY	Does not exist	
AWNINGS AND CANOPIES	Does not exist	
CHIMNEY	Does not exist	
COPING	Does not exist	
CORNICE	Does not exist	
DOORS	Inspected	
DOORS AND FRAMES	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
DOOR HARDWARE	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
LINTELS	Does not exist	
TRANSOM/SIDE LIGHT	Does not exist	
EXTERIOR WALLS	Inspected	
Material Type(s)	Steel	
Replacement Quantity	7,000	
Replacement Uom	S.F.	

Building Condition Assessment Survey 2023-2024

uestion	Response	
EXTERIOR		
EXTERIOR WALLS		
Instance on All Facades	Inspected	
Instance Condition	2- Between Good and Fair	
Instance Quantity	7,000	
Instance Quantity Uom	S.F.	
Deficiency	No deficiencies recorded	
EXTERIOR SOFFITS	Does not exist	
LOADING DOCK	Does not exist	
LOUVER	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
PARAPETS	Does not exist	
PLAZA DECK	Does not exist	
ROOF	Inspected	
ROOFING	Inspected	
ROOF HATCH/SMOKE HATCH	Does not exist	
LEADERS, GUTTERS, DOWNSPOUTS, SCUPPERS	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
ROOF BARRIER/FENCE	Does not exist	
ROOF CAGE	Does not exist	
ROOFING	Inspected	
Replacement Quantity	10,000	
Replacement Uom	S.F.	
Instance on Metal:Roof 1	Inspected	
	Roof 1	
Instance Condition	3- Fair	
Instance Quantity	10,000	
Instance Quantity Uom	S.F.	
Does the roof have major mechanical equipment sitting on Dunnage Steel less than 18" above the Roofing?	No	
Does this Roof Instance have a Sustainable Roof System?	No	-
Do solar panels exist on these roofs?	No	
Is/Are the roof(s) suitable for Solar Panel installation?	Yes	
Installation Year	1970	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
ROOFING DRAINS	Does not exist	
SPECIALTIES	Inspected	
BULKHEAD/PENTHOUSE	Does not exist	
CUPOLA/ SPIRES/ TOWERS	Does not exist	
DORMER	Does not exist	
	Does not exist	
DUNNAGE STEEL		
DUNNAGE STEEL SKYLIGHT/ROOF VENT	Does not exist	
	Does not exist Does not exist	

Building Condition Assessment Survey 2023-2024

Architectural Inspection X870 Question Response **EXTERIOR** STAIRS/RAMPS: EXTERIOR BUILDING CHEEK/FLANK WALLS Condition 2- Between Good and Fair Deficiency No deficiencies recorded RAILINGS Inspected Condition 3- Fair Deficiency RUST - MAJOR Deficiency Location/Instance X870 Deficiency Quantity 10 Quantity Uom L.F. REPLACE Potential Action Urgency of Action PRIORITY 4 LEVEL 2 Purpose of Action Deficiency Photo 1 Main Entrance Deficiency Photo 2 No photo recorded Violations No violations recorded STAIRS/RAMPS Inspected Condition 3- Fair Deficiency CONCRETE: CRACKS/SPALLING - MAJOR Deficiency Location/Instance X870 **Deficiency Quantity** 15 Quantity Uom S.F. Potential Action REPLACE PRIORITY 4 Urgency of Action Purpose of Action LEVEL 2 Deficiency Photo 1

Deficiency Photo 2


Main Entrance

No photo recorded

Building Condition Assessment Survey 2023-2024

Architectural Inspection	X870
--------------------------	------

Question Response **EXTERIOR** STAIRS/RAMPS: EXTERIOR STAIRS/RAMPS Violations No violations recorded Inspected WINDOWS Replacement Quantity 600 Replacement Uom S.F. EXTERIOR GUARDS Inspected Condition 2- Between Good and Fair Deficiency No deficiencies recorded LINTELS Does not exist WINDOWS Inspected Material Type(s) Aluminum Instance on Aluminum - Double Hung: All Facades Inspected 5- Poor Instance Condition Instance Quantity 600 Instance Quantity Uom S.F. Installation Year 1970 Source of Installation Year Custodial Staff Are these windows insulated? No ALUMINUM - DOUBLE HUNG: INOPERABLE BALANCE Deficiency



Elevation

Roof Plan Reference



Elevation Reference Deficiency Quantity Quantity Uom Potential Action Urgency of Action Purpose of Action Deficiency Photo 1

Violations

Facades A and C 36 **EACH** REPLACE BALANCES PRIORITY 3



Room 20 Deficiency Photo 2 No photo recorded No violations recorded

INTERIOR	Inspected	
POOLS	Does not exist	
STRUCTURAL	Inspected	
COLUMNS/BEAMS/BEARING WALLS	Inspected	

Building Condition Assessment Survey 2023-2024

estion	Response	
NTERIOR		
STRUCTURAL		
COLUMNS/BEAMS/BEARING WALLS		
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
FLOOR STRUCTURE	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
FOUNDATION WALLS	Inspected	
Material Type(s)	Concrete	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
ROOF STRUCTURE	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
VAULTS-BUNKERS	Does not exist	
AUDITORIUM	Does not exist	
CAFETERIA	Does not exist	
CLASSROOMS/CORRIDORS/ADMIN SPACES	Inspected	
Ceiling	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Door(s)	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Floor Finish	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Walls	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
	Does not exist	
Specialties GYMNASIUM	Does not exist	
INTERIOR DOOR HARDWARE	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
INTERIOR GUARDS	Does not exist	
KITCHEN	Does not exist	
LIBRARY	Does not exist	
LOCKER ROOM	Does not exist	
MULTI-PURPOSE ROOM	Does not exist	
SCIENCE DEMO ROOM	Does not exist	
SCIENCE LAB	Does not exist	
SCIENCE PREP ROOM	Does not exist	
SHOWER ROOM	Does not exist	
STAIRS/RAMPS: INTERIOR	Does not exist	
TOILET ROOMS - STAFF	Inspected	
Ceiling	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Door(s)	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Floor Finish	Inspected	

Building Condition Assessment Survey 2023-2024

Architectural Inspection	X870
--------------------------	------

uestion	Response	
INTERIOR		
TOILET ROOMS - STAFF		
Floor Finish		
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Stalls	Does not exist	
Walls	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
TOILET ROOMS - STUDENTS	Inspected	
Ceiling	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Door(s)	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Floor Finish	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Stalls	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Walls	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
LIFE SAFETY	Inspected	
F.D. HOLDING AREA	Does not exist	
STEEL STAIRS	Does not exist	
SITE	Not required	

NYC Department of Education Building Condition Assessment Survey 2023-2024

Architectural Inspection X870

Does the SCA expect asset to have artwork?

No