# **Building Condition Assessment Survey 2023-2024**

Asset:	P.S. 121 TEMP.	C.R. BLDG BRONX, 27	50 THROOP AV	ENUE, BRONX	, NY, 10469		
Inspection	n Id Inspection Type				Time	In	Last Edited
	2164 ELECTRICAL				2024-	01-05 08:41Al	M 2024-01-23 02:21P
set Data							
Question				Answer			
Have any	Systems/Major Building C	Components been upgraded?		Systems:	LAN System		
				Years:	2023		
				Systems:	Security Ligh	ting	
				Years:	2022		
				Systems:	Exit/Emergen	cy Lights	
				Years:	2020, 2005		
				Systems:	Telephone Sy	stem	
				Years:	2009	G 4 M	ı: g
				Systems:		m System - Mo	tion Sensors
				Years:	2005	-4	1 C
				Systems:		ctrical Systems	and Components
True - 60	omvio o			Years: Below Gr	1997		
Type of Service Does Interactive Whiteboard (IWB) Exist?				Yes	ounu		
	netration In Electrical Room			No			
		N FIRE RESCUE AREAS		110			
Question		, , , , , , , , , , , , , , , , , , , ,		]	Response		
Are the your bu		nce Areas, Fire Rescue Areas, a	nd/or Holding Room		No		
iority Co	ndition						
xist	Priority	Condition	Component	Location	Person(s)	Person(s)	Photo
ast Year?	Category	Description	Affected	Description	Notified	Title	Image
lo	Missing Key for TCU Enclosure	N/A	Electrical Equipment	Outdoor Electrical Enclosure	Jose DeJesus Jr.	Custodian	No Photo Taken
spection	ı						
Question	l			Response	)		
Electrica	ıl						
ATHLI	ETIC FIELD			Does not	exist		
AUDIT	ORIUM			Does not	exist		
CAFE	ΓERIA			Does not	exist		
CLASS	SROOM/CORRIDOR/AD	MINISTRATIVE SPACE		Inspected			
Light	ting			Inspected			
	es a Chandelier Exist?			No			
Lig	hting Fixture - Fluorescen	nt		Inspected			
Pe	endant Mounted			Does not	exist		
Surface Mounted  Recessed Mounted  Condition  Deficiency			Does not	exist			
			Inspected				
			3- Fair				
					IG FIXTURE B	EYOND USEF	UL LIFE
	Deficiency Quantity			24			
	Quantity Uom			EACH			
					E-UPGRADE		
	Potential Action			PRIORIT			
	Urgency of Action						
	Urgency of Action Purpose of Action			LEVEL 2			
<del></del>	Urgency of Action Purpose of Action Violations			LEVEL 2 No violati	ions recorded		
	Urgency of Action Purpose of Action			LEVEL 2	ions recorded exist		

### **Building Condition Assessment Survey 2023-2024**

Electrical Inspection X	(921	L
-------------------------	------	---

ciricai Inspection	A921
Question	Response
COMPUTER LAB	Does not exist
GYMNASIUM	Does not exist
KITCHEN	Does not exist
LIBRARY	Does not exist
LOCKER ROOM	Does not exist
MULTIPURPOSE ROOM	Does not exist
SCIENCE DEMO ROOM	Does not exist
SCIENCE LAB	Does not exist
SCIENCE LAB SCIENCE PREP ROOM	Does not exist  Does not exist
SWIMMING POOL	Does not exist
TOILET ROOM - STAFF	Does not exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist  Does not exist
Surface Mounted	Inspected
Recessed Mounted Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
AUXILIARY SIGNAL/BELL SYSTEM	Does not exist
EMERGENCY DC STANDBY BATTERY POWER	Does not exist
EMERGENCY GENERATOR SET	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Does not exist
EMERGENCY LIGHTING	Does not exist
EXIT LIGHT	Does not exist
EXIT/EMERGENCY LIGHT	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
FIRE ALARM SYSTEM	Inspected
Bell/Horn	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Strobe	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Manual Pull Station	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	Does not exist
Duct Smoke Detector	Does not exist
Area Smoke Detector	Does not exist
CO Detector	Does not exist
Heat Detector	Does not exist
Elevator Recall	Does not exist

### **Building Condition Assessment Survey 2023-2024**

Electrical Inspection X921

Question	Response
FIRE ALARM SYSTEM	
Magnetic Door Holder/Contactor	Does not exist
Fused Cutout Panel	Inaccessible
Fire Alarm Digital Communicator	Does not exist
Main Panel	Inspected
Bell At Panel	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Room T6
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Edwards System Technology
Model	EST
EquipmentId	Fire Alarm Control Panel
Installation Year	1997
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	Does not exist
Sub-Panel	Does not exist
Remote Annunciator	Does not exist
Sprinkler Flow/Air Pressure Switch	Does not exist
Tamper Flow Switch/Chain	Does not exist
GROUNDING SYSTEM	Inaccessible
INTERCOM SYSTEM	Does not exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Does not exist
LIGHTNING PROTECTION	Does not exist
MOTOR CONTROLLER	Does not exist
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Does not exist
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Does not exist
Molded Case Circuit Breaker Type	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
PUBLIC ADDRESS SYSTEM	Inspected
Instance	Connected to Main Asset X121
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	N/A
Installation Year	1997
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
SECURITY	Inspected
IPDVS/CCTV System	Does not exist
Intrusion Alarm System	Inspected
Central Control Panel	Does not exist
Infrared Sensor	Inspected

# **Building Condition Assessment Survey 2023-2024**

Electrical Inspection X921

Question	Response		
SECURITY			
Intrusion Alarm System			
Infrared Sensor			
Condition	3- Fair		
Deficiency	No deficiencies recorded		
Panic Switch	Does not exist		
Remote Annunciator	Does not exist		
Siren/Strobe	Does not exist		
Lighting - Security	Inspected		
Condition	1- Good		
Deficiency	No deficiencies recorded		
SERVICE SWITCH	Inaccessible		
SWITCHBOARD	Inaccessible		
TELEPHONE SYSTEM	Inspected		
PBX/Intercom	Inspected		
Condition	3- Fair		
Deficiency	No deficiencies recorded		
Standard	Inspected		
Condition	3- Fair		
Deficiency	No deficiencies recorded		
TRANSFORMER	Does not exist		