Building Condition Assessment Survey 2023-2024

Asset:	sset: P.S. 927 - BRONX, 1455 WEBSTER AVENUE, BRONX, NY, 10456						
Inspection	n Id Inspection T	ype			Time	In	Last Edited
4454 MECHANICAL				2024-04-04 10:30AM		M 2024-05-15 09:39AM	
sset Data							
Question				Answer			
Have any	Systems/Major Bui	lding Components been upgraded?		Systems:	Electric Dom	estic Water Hea	ter
				Years:	2023		
Are there fuel tanks?				No			
Total # of water main service entries to the asset				0			
MERs/Fan Rooms Locations				2nd Floor MER			
Are there any spaces with Missing or Defective CO Detectors?				Yes			
Location(s)				2nd Floor	r MER		
Are there	any Painted/Obstru	cted Sprinkler Heads?		No			
Are there any Emergency Stop Switches with Missing Hammers?				No compo	onents		
riority Co	ndition						
Exist	Priority	Condition	Component	Location	Person(s)	Person(s)	Photo
Last Year?	Category	Description	Affected	Description	Notified	Title	Image
No condit	tion recorded						
Inspection	ļ						
Question				Response	e		
Mechanic	cal						

Question	Response		
1 echanical			
AIR CONDITIONING	Inspected		
Chilled Water System	Does not exist		
Condenser Water Distribution: Piping, Pumps and Auxiliaries	Does not exist		
Cooling Coil in Ductwork	Does not exist		
Cooling Tower	Does not exist		
DX Split System	Inspected		
Indoor Unit	Inspected		
Condition	3- Fair		
Deficiency	No deficiencies recorded		
Outdoor Unit	Inspected		
Condition	3- Fair		
Deficiency	No deficiencies recorded		
Dry Cooler	Does not exist		
Packaged / Rooftop Unit	Does not exist		
Packaged Terminal A/C	Does not exist		
Refrigerant Leak Detection System	Does not exist		
Refrigerant Piping	Inspected		
Condition	3- Fair		
Deficiency	No deficiencies recorded		
Return Fan	Does not exist		
CENTRAL ACID WASTE NEUTRALIZING TANK	Does not exist		
CLIMATE CONTROL SYSTEM	Does not exist		
COMPACTOR	Does not exist		
CONVEYING	Inspected		
Dumbwaiter	Does not exist		
Elevator	Inspected		
Condition	3- Fair		
Are all the existing elevators operable?	Yes		
Deficiency	No deficiencies recorded		
Escalator	Does not exist		
Non-auditorium Handicap Lift - Vertical	Does not exist		
Non-auditorium Handicap Lift - Stair	Does not exist		
Ash Hoist	Does not exist		

Building Condition Assessment Survey 2023-2024

Mechanical Inspection X927

Response
Does not exist
Inspected
Does not exist
Inspected
Does not exist
Does not exist
Inspected
1- Good
No deficiencies recorded
Does not exist
Does not exist
Does not exist
Inspected
2- Between Good and Fair
No deficiencies recorded
Inspected
Inspected
2- Between Good and Fair
DEFECTIVE/LEAKS
Room 5, Corridor near Rooms 5, 8
30
L.F.
REPLACE
PRIORITY 3
LEVEL 2
No violations recorded
Inspected
2- Between Good and Fair
No deficiencies recorded
Does not exist
Does not exist
Does not exist
Inspected
Inspected
Inspected
3- Fair
No deficiencies recorded
Inspected
3- Fair
No deficiencies recorded
Inspected
3- Fair
No deficiencies recorded
Does not exist
Inspected
Inspected
3- Fair
No deficiencies recorded
Inspected
3- Fair
No deficiencies recorded
Does not exist

Building Condition Assessment Survey 2023-2024

Mechanical Inspection	X927

Question	Response	
`	Response	
FIXTURES		
Student	Y 1	
Toilet	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Urinal	Does not exist	
GAS FIRED FURNACE	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
GAS SERVICE	Inspected	
Gas Distribution Piping	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Gas Meter Room Exhaust Fan	Does not exist	
Gas Meter Room Vent	Does not exist	
Gas Pressure Booster	Does not exist	
CO/Gas Leak Detection	Does not exist	
HEATING	Does not exist	
HEATING PLANT	Does not exist	
Enclosed IDF Room	Does not exist	
KITCHEN	Does not exist	
MDF Room	Inspected	
Instance on Room 15	Inspected	
Dedicated A/C Equipment		
Instance on Room 15	Inspected	
Instance Condition	4- Between Fair and Poor	
Deficiency	DOES NOT EXIST	
Deficiency Location/Instance Deficiency Quantity	Room 15 1	
Quantity Uom	EACH	
Potential Action	INSTALL	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
SCIENCE DEMO ROOM	Does not exist	
SCIENCE LAB	Does not exist	
SCIENCE PREP ROOM	Does not exist	
SPRINKLERS, STANDPIPE, FIRE SYSTEM	Inspected	
Dry Sprinkler Alarm Valve Assembly	Does not exist	
Wet Sprinkler Alarm Valve Assembly	Does not exist	
Fire Booster Pump Assembly	Does not exist	
Roof Tank	Does not exist	
Siamese Connection	Does not exist	
Sprinkler Head	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Sprinkler Piping	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Standpipe System	Does not exist	
Water Gong	Does not exist	
SWIMMING POOL	Does not exist	
VENTILATION	Inspected	
Is the building Mechanically ventilated?	Yes	
contains international relations.		

Building Condition Assessment Survey 2023-2024

Mechanical Inspection X927

Question	Response		
VENTILATION			
Exhaust Fan	Inspected		
Condition	3- Fair		
Approximate Total # of Fans	1-25		
Deficiency	No deficiencies recorded		
Heating And Ventilating Unit	Does not exist		
Metal Ductwork	Inspected		
Condition	2- Between Good and Fair		
Are there any uninsulated ductwork by design in Mechanical rooms?	Yes		
Are there chain operated dampers?	No		
Deficiency	No deficiencies recorded		
Supply Fan	Does not exist		
Unit Ventilator	Does not exist		