Building Condition Assessment Survey 2023-2024

Electrical Inspection

Inspectio	n Id Inspection Type				Time	In	Last Edited
	3739 ELECTRICAL				2024-	-03-05 09:33AM	1 2024-04-01 12:47PM
Asset Data							
Question				Answer			
Have any	Have any Systems/Major Building Components been upgraded?			Systems:	Recessed LEI	O Lighting	
,	, , ,	1 10		Years:	2020		
				Systems:	Security Ligh	ts	
				Years:	2019		
				Systems:	Telephone Sy	stem	
				Years:	2016		
				Systems:	All Other Sys	tems and Compo	onents
				Years:	1999		
Type of S				Below Gro	ound		
	eractive Whiteboard (IWB)			Yes			
	netration In Electrical Room			No			
		N FIRE RESCUE AREAS)		
Question		nce Areas, Fire Rescue Areas, ar	d/or Holding Poor		Response Tes		
your bu	-	nee Areas, Fire Rescue Areas, ar	iu/or moraling K00	115 111 1	105		
		le in all of these spaces for use of	luring a fire?	Y	Yes		
	all dedicated intercoms op			Y	les		
Priority Co	ondition						
Exist	Priority	Condition	Component	Location	Person(s)	Person(s)	Photo
Last Year?	Category	Description	Affected	Description	Notified	Title	Image
No	Emergency Generator	Emergency Generator not	Emergency	Roof, Oil	Goran	Custodian	No Photo Taken
	Components - Not	Operational, Fusible link	Generator	Tank Room	Mijovic		
	Operational	is Broken		C11			
Yes	Water Leaks onto	Roof Leak	Lighting	3rd Floor	Goran	Custodian	No Photo Taken
	Electrical Equipment		Fixture	Boys Toilet	Mijovic		
				Room, Corridor near			
				Room 325			
Inspection	1						
•				D			
Question				Response			
Electrica							
ATHL	ETIC FIELD			Does not e			
AUDIT	TORIUM			Does not e	exist		
CAFE	ΓERIA			Inspected			
	Instance on 1st Floor			Inspected			
Light	-						
	Instance on 1st Floor			Inspected			
Lig	hting Fixture - Fluorescer	ıt					
_	Instance on 1st Floor			Inspected			
Р	endant Mounted						
_	Instance on 1st Floor			Does not e	exist		
S	urface Mounted						
_	Instance on 1st Floor			Does not e	exist		
R	ecessed Mounted						
	Instance on 1st Floor			Inspected			
	Instance Condition			3- Fair			
				No deficie	encies recorded		
	Deficiency						
Lig	Deficiency hting Fixture - HID						
				Does not e	exist		

Building Condition Assessment Survey 2023-2024

Electrical Inspection

		Λ)
uestion	Response	
CAFETERIA		
Lighting		
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Does not exist	
Local Sound System		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Installation Year	1999	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Cafeteria-1st Floor	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Projection System		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Is the projector on a cart or installed on the ceiling?	Ceiling	
Deficiency	No deficiencies recorded	
Theater Lighting System	D	
Instance on 1st Floor	Does not exist	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected	
Lighting	Inspected	
Does a Chandelier Exist?	No	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Does not exist	
Recessed Mounted	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
COMPUTER LAB	Does not exist	
GYMNASIUM	Does not exist	
KITCHEN	Inspected	
Instance on 1st Floor	Inspected	
	Inspected	
Lighting Instance on 1st Floor	Inspected	
	mspecieu	
Lighting Fivture Flueressent		
Lighting Fixture - Fluorescent Instance on 1st Floor	Inspected	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

trical Inspection	Response	
	Response	
KITCHEN Liebting		
Lighting Lighting Fixture - Fluorescent		
Pendant Mounted		
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Does not exist	
Recessed Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Does not exist	
LIBRARY	Inspected	
Instance on Room 311	Inspected	
Lighting	mipeeed	
Instance on Room 311	Inspected	
Lighting Fixture - Fluorescent	1	
Instance on Room 311	Inspected	
Pendant Mounted	1	
Instance on Room 311	Does not exist	
Surface Mounted		
Instance on Room 311	Does not exist	
Recessed Mounted		
Instance on Room 311	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on Room 311	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 311	Does not exist	
Lighting Fixture - LED		
Instance on Room 311	Does not exist	
Raceway With Receptacles		
Instance on Room 311	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Projection System		
Instance on Room 311	Does not exist	
LOCKER ROOM	Does not exist	
MULTIPURPOSE ROOM	Inspected	
Instance on 1st Floor	Inspected	
Lighting	-	
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Inspected	
Pendant Mounted	-	
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Does not exist	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

Duestion	Response	
MULTIPURPOSE ROOM	Response	
Lighting		
Lighting Fixture - Fluorescent		
Recessed Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
	No deficiencies recorded	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Does not exist	
Local Sound System		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Installation Year	1999	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Multipurpose Room-1st Floor	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Projection System		
Instance on 1st Floor	Does not exist	
Theater Lighting System		
Instance on 1st Floor	Does not exist	
SCIENCE DEMO ROOM	Does not exist	
SCIENCE LAB	Does not exist	
SCIENCE PREP ROOM	Does not exist	
SWIMMING POOL	Does not exist	
	Inspected	
TOILET ROOM - STAFF	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Does not exist	
Pendant Mounted		
Surface Mounted	Does not exist	
Recessed Mounted	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
TOILET ROOM - STUDENT	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Does not exist	
Recessed Mounted	Inspected	
INCOMPANY PROVINCE	-	
	3- Fair	
Condition Deficiency	3- Fair No deficiencies recorded	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

iestion	Response
FOILET ROOM - STUDENT	
Lighting	
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
MERGENCY DC STANDBY BATTERY POWER	Does not exist
MERGENCY GENERATOR SET	Inspected
Automatic Transfer Switch (ATS)	Inspected
Instance	Electrical Room C04 3- Fair
Instance Condition	
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	ASCO
EquipmentId	ATS-1
Capacity/Size Quantity	800
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1999
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room C04
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	ASCO
EquipmentId	Fire Alarm Automatic Transfer Switch
Capacity/Size Quantity	30
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1999
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Battery Charger	Inspected
Instance	Roof - Emergency Generator Enclosure
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Charles Industries
EquipmentId	Battery Charger
Capacity/Size Quantity	10
Capacity/Size UOM	AmpsDC
Capacity/Size 2 Quantity	24
Capacity/Size 2 UOM	VDC
Source of Capacity/Size	Nameplate
Installation Year Source of Installation Year	1999 Documented
	No deficiencies recorded
Deficiency	
Emergency Distribution Board Number of Spares	Inspected 2
	 Inspected
Fused Disconnect Switch Type	Electrical Room C04
Instance Condition	3- Fair
Instance Condition	5- Fair 1

Building Condition Assessment Survey 2023-2024

Electrical Inspection

icui Inspeciion		Δ)
uestion		Response
EMERGENCY GE	NERATOR SET	
Emergency Distri	bution Board	
Fused Disconne	ct Switch Type	
Instance	Quantity Uom	EACH
Manufac	turer	Square D
Equipme	ntId	EMP
Capacity	/Size Quantity	800
Capacity	/Size UOM	Amps Total
	/Size 2 Quantity	2
	/Size 2 UOM	Section(s)
	f Capacity/Size	Nameplate
Installatio		1999
	f Installation Year	Documented
Deficienc		No deficiencies recorded
Molded Case Ci	ircuit Breaker Type	Does not exist
Diesel		Inspected
Instance		Roof - Emergency Generator Enclosure
Instance	Condition	4- Between Fair and Poor
Instance	Quantity	1
Instance	Quantity Uom	EACH
Manufac	turer	Caterpillar
Equipme	ntId	Emergency Generator
Capacity	/Size Quantity	288
Capacity	/Size UOM	kVA
	/Size 2 Quantity	230
	/Size 2 UOM	kW
	/Size 3 Quantity	798
	/Size 3 UOM	Amps
	f Capacity/Size	Nameplate 1999
Installatio		
	f Installation Year	Documented
Deficient	cy ency Quantity	GENERATOR NOT OPERATIONAL
		l EACH
	ty Uom al Action	REPAIR
	ey of Action	PRIORITY 5
•	e of Action	LEVEL 6
Violati		No violations recorded
Natural Gas	0115	Does not exist
	CHT/EVIT I LCHT DANIEL	Does not exist
	GHT/EXIT LIGHT PANEL	
EMERGENCY LIG	GHTING	Inspected
Battery Pack		Does not exist
Non Battery Pack		Inspected 3- Fair
Condition		
Deficienc	cy	No deficiencies recorded
XIT LIGHT		Inspected
Battery Pack		Does not exist
Non Battery Pack	<u> </u>	Inspected
Condition		3- Fair
Deficient	-	FIXTURE LAMP NOT OPERATIONAL
	ency Location/Instance	Main Entrance Lobby, Corridor near Rooms C05, C11
	ency Quantity	3
	ty Uom	EACH
	al Action	MAINTENANCE
-	ey of Action	PRIORITY 5
Purpos	e of Action	LEVEL 2

Building Condition Assessment Survey 2023-2024

Electrical Inspection

Response	
No violations recorded	
Does not exist	
Inspected	
-	
-	
•	
-	
3- Fair	
No deficiencies recorded	
3- Fair	
No deficiencies recorded	
•	
-	
-	
Does not exist	
	Does not existInspected3 - FairNo deficiencies recordedInspected3 - FairNo deficiencies recordedDoes not existInspected3 - FairNo deficiencies recordedInspected3 - FairNo deficiencies recordedInspected <trtr>3 - FairNo deficien</trtr>

NYC Department of Education Building Condition Assessment Survey 2023-2024

Electrical Inspection

rical Inspection	D	X981
uestion	Response	
FIRE ALARM SYSTEM		
Remote Annunciator	Inspected	
Display Monitor	Does not exist	
Panel	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Printer	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Punch Register	Does not exist	
Sprinkler Flow/Air Pressure Switch	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Tamper Flow Switch/Chain	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
GROUNDING SYSTEM	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
INTERCOM SYSTEM	Inspected	
Elevator	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Holding Area	Does not exist	
LAN	Inspected	
Local Distribution Frame (I/LDF)	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Main Equipment Rack (MDF)	Does not exist	
LIGHTNING PROTECTION	Does not exist	
MOTOR CONTROLLER	Inspected	
MOTOR CONTROL CENTER	Does not exist	
MOTOR STARTER/CONTACTOR	Inspected 3- Fair	
Condition		
Deficiency	No deficiencies recorded	
Variable Frequency Drive	Does not exist	
PANEL BOARD	Inspected	
Fused Disconnect Switch Type	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fused Knife Switch Type	Does not exist	
Fused Toggle Switch Type	Does not exist	
Molded Case Circuit Breaker Type	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
PUBLIC ADDRESS SYSTEM	Inspected	
Instance	Room 208	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Model	Rauland MPA 250	
Installation Year	1999	
Source of Installation Year	Documented	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

icui Inspeciion	
uestion	Response
PUBLIC ADDRESS SYSTEM	
Deficiency	No deficiencies recorded
SECURITY	Inspected
IPDVS/CCTV System	Does not exist
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	Custodian's Office - Room 104
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 50P
Installation Year	1999
Source of Installation Year	Documented
Deficiency	PANEL NOT CONNECTED TO DOE CENTRAL STATION
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REWIRE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Violations	No violations recorded
Infrared Sensor	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	3- Fair
	No deficiencies recorded
Deficiency	
Siren/Strobe	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting - Security	Inaccessible
SERVICE SWITCH	Inspected
Instance	Electrical Room C04
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Square D
EquipmentId	Service Disconnect
Capacity/Size Quantity	2000
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1999
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
SWITCHBOARD	Inspected
Number of Spares	1
Fused Disconnect Switch Type	Inspected
Instance	Electrical Room C04
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Square D
munuturer	- 1

Building Condition Assessment Survey 2023-2024

Electrical Inspection

uestion	Response	
SWITCHBOARD		
Fused Disconnect Switch Type		
EquipmentId	N/A	
Capacity/Size Quantity	2000	
Capacity/Size UOM	Amps Total	
Capacity/Size 2 Quantity	2	
Capacity/Size 2 UOM	Section(s)	
Source of Capacity/Size	Nameplate	
Installation Year	1999	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Fused Knife Switch Type	Does not exist	
Molded Case Circuit Breaker Type	Does not exist	
TELEPHONE SYSTEM	Inspected	
PBX/Intercom	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Standard	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
TRANSFORMER	Does not exist	