Building Condition Assessment Survey 2023-2024

		Time 1 2024-	In 04-29 03:11PM	Last Edited 1 2024-04-30 07:54PM
		2024-	04-29 03:11PM	1 2024-04-30 07:54PN
	Answer			
	Systems:	Partial Exit Li	ghts (Battery Pa	ick)
	Years:	2016		
	Systems:	Fire Alarm Sy	stem	
			. 10 .	10
	-		trical Systems a	ind Components
		vund		
	No			
		esponse		
or Holding Room	ms in N	О		
-			` '	Photo
Affecteu	Description	Notified	11tte	Image
	Response			
	Does not e	xist		
	Does not e	xist		
	Does not e	xist		
	Inspected			
	Inspected			
	No			
		xıst		
		iicies recorded		
	•			
		ncies recorded		
	Does not e	xist		
	Does not e	xist		
	Does not e	xist		
	Does not e	xist		
	Does not e	xist		
	Does not a	X1Sf		
	Does not e			
	Does not e Does not e Does not e	xist		
	Component Affected	Years: Systems: Years: Below Gro Yes No Response Component Location Affected Description Response Does not e Does not e Inspected Inspected No Inspected Does not e Inspected Joes not e Inspected Does not e Inspected Joes not e Inspected Joes not e Does not e	Years: 2015 Systems: All Other Elect Years: 1998 Below Ground Yes No Response /or Holding Rooms in No Component Location Person(s) Affected Description Notified Response Does not exist Does not exist Inspected Inspected Inspected No Inspected Does not exist Inspected No Inspected No Inspected Joes not exist Inspected No Inspected No Inspected Joes not exist Inspected	Years: 2015 Systems: All Other Electrical Systems at Years: 1998 Below Ground Yes No Response /or Holding Rooms in No Response /or Holding Rooms in No Response Does not exist Does not exist Inspected Inspected No Inspected Does not exist Inspected Soes not exist Inspected Inspected Joes not exist Inspected Joes not exist Inspected Joes not exist Inspected Joes not exist Inspected Does not exist Inspected Joes not exist Does not exist Inspected Joes not exist Does not exist

Building Condition Assessment Survey 2023-2024

ricui Inspection		A902
Question	Response	
TOILET ROOM - STAFF	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Does not exist	
Recessed Mounted	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
TOILET ROOM - STUDENT	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Does not exist	
Recessed Mounted	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
AUXILIARY SIGNAL/BELL SYSTEM	Does not exist	
EMERGENCY DC STANDBY BATTERY POWER	Does not exist	
EMERGENCY GENERATOR SET	Does not exist	
EMERGENCY LIGHT/EXIT LIGHT PANEL	Does not exist	
EMERGENCY LIGHTING	Inspected	
Battery Pack	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Non Battery Pack	Does not exist	
EXIT LIGHT	Inspected	
Battery Pack	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Non Battery Pack	Does not exist	
EXIT/EMERGENCY LIGHT	Does not exist	
FIRE ALARM SYSTEM	Inspected	
Bell/Horn	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Strobe	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Manual Pull Station	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Fan Shutdown Control	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Duct Smoke Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	

Building Condition Assessment Survey 2023-2024

1		,
Question	Response	
FIRE ALARM SYSTEM		
Area Smoke Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
CO Detector	Does not exist	
Heat Detector	Does not exist	
Elevator Recall	Does not exist	
Magnetic Door Holder/Contactor	Does not exist	
Fused Cutout Panel	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Digital Communicator	Does not exist	
Main Panel	Does not exist	
Sub-Panel	Does not exist	
Remote Annunciator	Does not exist	
Sprinkler Flow/Air Pressure Switch	Does not exist	
Tamper Flow Switch/Chain	Does not exist	
GROUNDING SYSTEM	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
INTERCOM SYSTEM	Does not exist	
LAN	Inspected	
Local Distribution Frame (I/LDF)	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Main Equipment Rack (MDF)	Does not exist	
LIGHTNING PROTECTION	Does not exist	
MOTOR CONTROLLER	Does not exist	
PANEL BOARD	Inspected	
Fused Disconnect Switch Type	Does not exist	
Fused Knife Switch Type	Does not exist	
Fused Toggle Switch Type	Does not exist	
Molded Case Circuit Breaker Type	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
- 		
PUBLIC ADDRESS SYSTEM	Inspected	
Instance	Connected to Main Asset X077	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Model	N/A	
Installation Year	1998	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
SECURITY	Inspected	
IPDVS/CCTV System	Does not exist	
Intrusion Alarm System	Inspected	
Central Control Panel	Inspected	
Instance	Electrical Room	
Instance Condition	3- Fair	
Instance Quantity	1 EACH	
Instance Quantity Uom	EACH	
Model	Vista - 128FBP	
Installation Year	1998	

Building Condition Assessment Survey 2023-2024

incui inspection	A
Question	Response
SECURITY	
Intrusion Alarm System	
Central Control Panel	
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Panic Switch	Does not exist
Remote Annunciator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting - Security	Inspected
Condition	3- Fair
Deficiency	TIME CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 3
Violations	No violations recorded
SERVICE SWITCH	Inspected
Instance	Electrical Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
	Cutler Hammer
Manufacturer	Main
EquipmentId Capacity/Size Quantity	2000
Capacity/Size UOM Source of Capacity/Size	Amps
Installation Year	Nameplate 1998
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
- ·	Inspected
SWITCHBOARD Newsland & Samuel	nispected 16
Number of Spares	Does not exist
Fused Vnife Switch Type	Does not exist Does not exist
Fused Knife Switch Type Molded Case Circuit Breaker Type	Inspected
Instance	Electrical Room
Instance Condition	3- Fair
Instance Quantity	1 EACH
Instance Quantity Uom	
Manufacturer	Cutler Hammer
EquipmentId	N/A
Capacity/Size Quantity	2000
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	2
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate

Building Condition Assessment Survey 2023-2024

Question	Response	
SWITCHBOARD		
Molded Case Circuit Breaker Type		
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
TELEPHONE SYSTEM	Inspected	
PBX/Intercom	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Standard	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
TRANSFORMER	Does not exist	