Building Condition Assessment Survey 2023 - 2024

Inspection Id Inspection Type		Time In	Last Edited
EE: K934 Electrical		2023-11-29 8:28 AM	2024-06-14 3:46 PM
sset Data			
Question	Answer		
Type of Service	Below Gro	ound	
Does Interactive Whiteboard (IWB) Exist?	Yes		
Water Penetration in Electrical Room?	No		
Have any Systems/Major Building Components been upgraded?	Yes		
	Systems:	Public Address System	
	Years:	Under Construction	
	Systems:	Security Lights	
	Years:	2021	
	Systems:	IPDVS/CCTV System	
	Years:	2020	
	Systems:	Intrusion Alarm System (Infrared	d Sensor)
	Years:	2018	
	Systems:	Exit Lights (Battery Pack)	
	Years:	2016	
	Systems:	Interior Lighting, Fire Alarm Sys	stem
	Years:	2004	
	Systems:	Emergency Light/Exit Light Pan	el
	Years:	2001	
	Systems:	Molded Case Circuit Breaker Ty	pe Panel Board
	Years:	1990, 2004	
	Systems:	Switchboard	
	Years:	1990	
DEDICATED INTERCOMS IN FIRE RESCUE AREAS			
Question	Response		
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	No		
riority Condition			
	ation Person(s) cription Notified	Person(s) Title Status	PhotoImage
No condition recorded			
spection			
Question	Respons	se	
Electrical			
AUDITORIUM	Does no	t Exist	
CAFETERIA	Does no	t Exist	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspecte		
Lighting Does a Chandelier exist?	Inspected No		
Lighting Fixture - Fluorescent	Inspected		
Pendant Mounted	Does no	t Exist	
Surface Mounted	Inspecte	d	
Condition	3 - Fair		
Deficiency	No defic	riencies recorded	
Recessed Mounted	Inspecte	d	
Condition	3 - Fair		
Deficiency	No defic	riencies recorded	
VSP (P)	Page 1 of 5		Print Date: 6/25/2024

Building Condition Assessment Survey 2023 - 2024

urcar mspection			
uestion	Response		
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE			
Lighting			
Lighting Fixture - HID	Does not Exist		
Lighting Fixture - Incandescent	Does not Exist		
Lighting Fixture - LED	Does not Exist		
COMPUTER LAB	Does not Exist		
GYMNASIUM	Does not Exist		
KITCHEN	Does not Exist		
LIBRARY	Does not Exist		
LOCKER ROOM	Does not Exist		
MULTIPURPOSE ROOM	Does not Exist		
SCIENCE DEMO ROOM	Does not Exist		
SCIENCE LAB	Does not Exist		
SCIENCE PREP ROOM	Does not Exist		
SWIMMING POOL	Does not Exist		
TOILET ROOM - STAFF	Inspected		
Lighting	Inspected		
Lighting Fixture - Fluorescent	Inspected		
Pendant Mounted	Does not Exist		
Surface Mounted	Inspected		
Condition	3 - Fair		
Deficiency	No deficiencies recorded		
Recessed Mounted	Does not Exist		
Lighting Fixture - HID	Does not Exist		
Lighting Fixture - Incandescent	Does not Exist		
Lighting Fixture - LED	Does not Exist		
TOILET ROOM - STUDENT	Inspected		
Lighting	Inspected		
Lighting Fixture - Fluorescent	Inspected		
Pendant Mounted	Does not Exist		
Surface Mounted	Inspected		
Condition	3 - Fair	-	
Deficiency	No deficiencies recorded		
Recessed Mounted	Does not Exist		
Lighting Fixture - HID	Does not Exist		
Lighting Fixture - Incandescent	Does not Exist		
Lighting Fixture - LED	Does not Exist		
AUXILIARY SIGNAL/BELL SYSTEM	Does not Exist		
EMERGENCY DC STANDBY BATTERY POWER	Does not Exist		
EMERGENCY GENERATOR SET	Does not Exist		
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected		
Condition	3 - Fair		
Deficiency	No deficiencies recorded		
EMERGENCY LIGHTING	Inspected		
Battery Pack	Inspected	Inspected	
Condition	3 - Fair	3 - Fair	
Deficiency	BATTERY NOT OPERATIONAL		

Building Condition Assessment Survey 2023 - 2024

urcar mspection			
uestion	Response		
EMERGENCY LIGHTING			
Battery Pack			
Deficiency Location/Instance	Corridor by Rooms 831, 844, 860		
Deficiency Quantity	3		
Quantity Uom	EACH		
Potential Action	REPLACE BATTERY		
Urgency of Action	PRIORITY 5		
Purpose of Action	LEVEL 2		
Deficiency Photo1	No photo recorded		
Violations	No violations recorded.		
Non Battery Pack	Does not Exist		
EXIT LIGHT	Inspected		
Battery Pack	Inspected		
Condition	2 - Between Good and Fair		
Deficiency	No deficiencies recorded		
Non Battery Pack	Does not Exist		
EXIT/EMERGENCY LIGHT	Does not Exist		
FIRE ALARM SYSTEM	Inspected		
Replacement Quantity	22,000		
Replacement Uom	S.F.		
Bell/Horn	Inspected		
Condition	3 - Fair		
Deficiency	No deficiencies recorded		
Strobe	Inspected		
Condition	3 - Fair		
Deficiency	No deficiencies recorded		
Manual Pull Station	Inspected		
Condition	3 - Fair		
Deficiency	No deficiencies recorded		
Fan Shutdown Control	Does not Exist		
Duct Smoke Detector	Does not Exist		
Area Smoke Detector	Inspected		
Condition	3 - Fair		
Deficiency	No deficiencies recorded		
CO Detector	Does not Exist		
Heat Detector	Does not Exist		
Elevator Recall	Does not Exist		
Magnetic Door Holder/Contactor	Does not Exist		
Fused Cutout Panel	Inspected		
Condition	3 - Fair		
Deficiency	No deficiencies recorded		
Fire Alarm Digital Communicator	Does not Exist		
Main Panel	Inspected		
Bell At Panel	Inspected		
Condition	3 - Fair		
Deficiency	No deficiencies recorded		
Fire Alarm Control Panel (Electronic)	Inspected		
Instance	Electrical Room 834		
Instance Condition	3 - Fair		

Building Condition Assessment Survey 2023 - 2024

estion	Response		
FIRE ALARM SYSTEM			
Main Panel			
Fire Alarm Control Panel (Electronic)			
Instance Quantity	1		
Instance Quantity Uom	EACH		
Instance Manufacturer	Edwards System Technology		
Equipment	Fire Control Panel		
Model	EST 2		
Installation Year	2004		
Source of Installation	Documented		
Deficiency	No deficiencies recorded		
Fire Alarm Control Panel (Standard)	Does not Exist		
Sub-Panel	Does not Exist		
Remote Annunciator	Does not Exist		
Sprinkler Flow/Air Pressure Switch	Does not Exist		
Tamper Flow Switch/Chain	Does not Exist		
GROUNDING SYSTEM	Does not Exist		
NTERCOM SYSTEM	Does not Exist		
LAN	Inspected		
Local Distribution Frame (I/LDF)	Inspected		
Condition	3 - Fair		
Deficiency	No deficiencies recorded		
Main Equipment Rack (MDF)	Does not Exist		
LIGHTNING PROTECTION	Does not Exist		
MOTOR CONTROLLER	Does not Exist		
PANEL BOARD	Inspected		
Fused Disconnect Switch Type	Does not Exist		
Fused Knife Switch Type	Does not Exist		
Fused Toggle Switch Type	Does not Exist		
Molded Case Circuit Breaker Type	Inspected		
Condition	3 - Fair No deficiencies recorded		
Deficiency PUBLIC ADDRESS SYSTEM	Under Construction		
SECURITY	Inspected		
IPDVS/CCTV System	Inspected		
Replacement Quantity	22,000		
Replacement Uom	S.F.		
Installation Year	2020		
Source of Installation		Custodial Staff	
Condition		1 - Good	
Deficiency	No deficiencies recorded		
Intrusion Alarm System	Inspected		
Replacement Quantity		22,000	
Replacement Uom	S.F.		
Central Control Panel	Does not Exist	Does not Exist	
Infrared Sensor	Inspected	Inspected	
Condition	2. Patrygon Cood and Fair	2 - Between Good and Fair	

Building Condition Assessment Survey 2023 - 2024

	_
nestion	Response
SECURITY	
Intrusion Alarm System	Inspected
Panic Switch	Does not Exist
Remote Annunciator	Does not Exist
Siren/Strobe	Does not Exist
Lighting - Security	Inspected
Replacement Uom	EACH
Condition	1 - Good
Deficiency	No deficiencies recorded
SERVICE SWITCH	Does not Exist
SWITCHBOARD	Inspected
Number of Spares	0
Fused Disconnect Switch Type	Inspected
Instance	Electrical Room 834
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	All City Switchboard
Equipment	N/A
Capacity/Size Quantity	800
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	2
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Inspector Estimate
Installation Year	1990
Source of Installation	Documented
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not Exist
Molded Case Circuit Breaker Type	Does not Exist
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
TRANSFORMER	Does not Exist