Building Condition Assessment Survey 2023-2024

Electrical Inspection M052

Asset:	I.S. 52 - MA	ANHATTAN, 650 ACADEMY	Y STREET, MANHA	TTAN, NY, 10	034	
Inspection	Id Inspection T	ype			Time In	Last Edited
2	2951 ELECTRICA	AL .			2024-02-05 07:42AM	2024-06-12 09:46AN
sset Data						
Question				Answer		
Have any	Systems/Major Buil	lding Components been upgraded?	•	Systems:	Molded Case Circuit Breaker Pa	inel Board
				Years:	2023, 2007, 1992	
				Systems:	Fire Alarm Printer	
				Years:	2023	
				Systems:	2nd Floor Gymnasium (Scorebo Frequency Drive	ard), Variable
				Years:	2022	
				Systems:	Recessed Mounted LED Lightin	g (Clinic)
				Years:	2020	
				Systems:	Recessed Mounted Fluorescent	Lighting
				Years:	2017, 2005	
				Systems:	Service Switch, Switchboard, C (322, 411), Interior Fluorescent Library, Students Cafeteria, Cor (126, 410, 525A)), LED Lightin Lighting (Battery Pack), Most E (Non Battery Pack), Exit Lights	Lighting (Except nputer Lab Rooms g, Most Emergency mergency Lighting
				Years:	2017	,
				Systems:	Computer Lab Rooms (126, 410	, 525A), Local Sound
				Years:	System, Intrusion Alarm System 2014	, LAN
				Systems:	Auxiliary Signal/Bell System, P	ublic Address System
			Years:	2013		
				Systems:	Library, Students Cafeteria (Flu Telephone System	orescent Lighting),
				Years:	2012	
				Systems:	Auditorium (Projection System)	, IPDVS/CCTV System
				Years:	2010	
				Systems:	Lighting - Security	
				Years:	2008	
				Systems:	Auditorium (Theater Lighting S	ysiciii)
				Years:	1998	Ct F1
				Systems:	Motor Control Center, Fire Alar Disconnect Switch Type Panel E Light/Exit Light Panel	•
				Years:	1992	
Type of Se	ervice			Below Gr	round	
• •	ractive Whiteboard	(IWB) Exist?		Yes		
Water Pen	etration In Electrica	ıl Room?		No		
DEDICA	TED INTERCO	MS IN FIRE RESCUE AREA	AS			
Question					Response	
Are ther your bui	•	Assistance Areas, Fire Rescue Area	s, and/or Holding Room	is in	No	
iority Con	ndition					
Exist	Priority	Condition Description	Component	Location	Person(s) Person(s) I	Photo

Priori		

Exist	Priority	Condition	Component	Location	Person(s)	Person(s)	Photo
Last Year?	Category	Description	Affected	Description	Notified	Title	Image
No	Public Address System - Speakers Not Operational	All speakers in the Auditorium and Gymnasium are out of order.	Public Address System	Auditorium and Gymnasium	Jean Guerrero	Fireman	No Photo Taken

Inspection

Ouestion	Response
<u></u>	P

Building Condition Assessment Survey 2023-2024

Electrical Inspection	M052

icui Inspection	1710
uestion	Response
ectrical	
ATHLETIC FIELD	Does not exist
AUDITORIUM	Inspected
Instance on 2nd Floor	Inspected
House Lighting	
Instance on 2nd Floor	Inspected
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	
Instance on 2nd Floor	Inspected
Pendant Mounted	•
Instance on 2nd Floor	Does not exist
Surface Mounted	
Instance on 2nd Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	1.00 00.100.100.1000.1000
Instance on 2nd Floor	Does not exist
Lighting Fixture - HID	2000 1000 011100
Instance on 2nd Floor	Does not exist
Lighting Fixture - Incandescent	Does not exist
Instance on 2nd Floor	Does not exist
Lighting Fixture - LED	DOGS HOT CAIST
Instance on 2nd Floor	Inspected
Pendant Mounted	mspected
Instance on 2nd Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
-	No deficiencies recorded
Surface Mounted	T4-1
Instance on 2nd Floor	Inspected 2- Between Good and Fair
Instance Condition	
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 2nd Floor	Does not exist
Local Sound System	
Instance on 2nd Floor	Inspected
Instance Condition	3- Fair
Installation Year	2014
Source of Installation Year Deficiency	Documented No deficiencies recorded
	ivo deficiencies recorded
Projection System Instance on 2nd Floor	Ingnosted
	Inspected
Instance Condition Is the projector on a cart or installed on the ceiling?	3- Fair Ceiling
Deficiency	No deficiencies recorded
	ivo deficiencies recolucu
Theater Lighting System Instance on 2nd Floor	Inspected
	nispecied
Dimming System Instance on 2nd Floor	Inchected
	Inspected 5- Poor
Instance Condition	
Deficiency Deficiency Quantity	DIMMING RACK/LIGHT CONSOLE NOT OPERATIONAL
Quantity Uom	l EACH
Quantity Com	EACH
Potential Action	REPLACE

Building Condition Assessment Survey 2023-2024

Electrical Inspection	M052
0	D

ireai Inspection		111032
Question	Response	
AUDITORIUM		
Theater Lighting System		
Dimming System		
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Theater Lighting		
Instance on 2nd Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
CAFETERIA	Inspected	
Instance on 1st Floor - Students	Inspected	
Instance on 1st Floor - Staff	Inspected	
Lighting	mspected	
Instance on 1st Floor - Students	Inspected	
Instance on 1st Floor - Staff	Inspected	
Lighting Fixture - Fluorescent	peeted	
Instance on 1st Floor - Staff	Inspected	
Instance on 1st Floor - Students	Inspected	
Pendant Mounted	mspected	
Instance on 1st Floor - Staff	Does not exist	
Instance on 1st Floor - Students	Does not exist	
Surface Mounted	Does not exist	
Instance on 1st Floor - Staff	Does not exist	
Instance on 1st Floor - Students	Does not exist	
Recessed Mounted	DOCS HOT CAIST	
Instance on 1st Floor - Staff	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Instance on 1st Floor - Students	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
	No deficiencies recorded	
Lighting Fixture - HID Instance on 1st Floor - Staff	Door wat arrist	
	Does not exist	
Instance on 1st Floor - Students	Does not exist	
Lighting Fixture - Incandescent	Description of the second	
Instance on 1st Floor - Staff Instance on 1st Floor - Students	Does not exist	
	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor - Staff	Does not exist	
Instance on 1st Floor - Students	Does not exist	
Local Sound System	T	
Instance on 1st Floor - Students	Inspected	
Instance Condition	3- Fair	
Installation Year Source of Installation Year	2014 Documented	
Deficiency	No deficiencies recorded	
Instance on 1st Floor - Staff	Does not exist	
	Does not exist	
Projection System Instance on 1st Floor - Students	Does not exist	
Instance on 1st Floor - Staff	Does not exist	
	Does not exist	
Theater Lighting System Instance on 1st Floor - Students	Does not exist	
Instance on 1st Floor - Students	Does not exist Does not exist	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected	

Building Condition Assessment Survey 2023-2024

Question	Response	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE		
Lighting	Inspected	
Does a Chandelier Exist?	No	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
COMPUTER LAB	Inspected	
Instance on Room 322	Inspected	
Power Panel?	No	
Instance on Room 411	Inspected	
Power Panel?	No	
Instance on Room 525A	Inspected	
Power Panel?	No	
Instance on Rooms: 126, 410	Inspected	
Power Panel?	Yes	
Lighting		
Instance on Room 322	Inspected	
Instance on Room 411	Inspected	
Instance on Room 525A	Inspected	
Instance on Rooms: 126, 410	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 322	Inspected	
Instance on Room 411	Inspected	
Instance on Room 525A	Inspected	
Instance on Rooms: 126, 410	Inspected	
Pendant Mounted		
Instance on Room 322	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Instance on Room 411	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Instance on Room 525A	Inspected	
Instance Condition	2- Between Good and Fair	
	No deficiencies recorded	
Deficiency	no deficiencies recorded	

Building Condition Assessment Survey 2023-2024

Electrical Inspection		N1052
Question	Response	

Question	Response
COMPUTER LAB	
Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 322	Does not exist
Instance on Room 411	Does not exist
Instance on Room 525A	Does not exist
Instance on Rooms: 126, 410	Does not exist
Recessed Mounted	
Instance on Room 322	Does not exist
Instance on Room 411	Does not exist
Instance on Room 525A	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Rooms: 126, 410	Does not exist
Lighting Fixture - HID	
Instance on Room 322	Does not exist
Instance on Room 411	Does not exist
Instance on Room 525A	Does not exist
Instance on Rooms: 126, 410	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 322	Does not exist
Instance on Room 411	Does not exist
Instance on Room 525A	Does not exist
Instance on Rooms: 126, 410	Does not exist
Lighting Fixture - LED	
Instance on Room 322	Does not exist
Instance on Room 411	Does not exist
Instance on Room 525A	Does not exist
Instance on Rooms: 126, 410	Does not exist
Raceway With Receptacles	
Instance on Room 322	Inspected 2- Between Good and Fair
Instance Condition	
Deficiency	No deficiencies recorded
Instance on Room 411 Instance Condition	Inspected 2- Between Good and Fair
	No deficiencies recorded
Deficiency Instance on Room 525A	
Instance on Room 525A Instance Condition	Inspected 2- Between Good and Fair
	No deficiencies recorded
Deficiency 126 410	
Instance on Rooms: 126, 410	Inspected 2- Between Good and Fair
Instance Condition	No deficiencies recorded
Deficiency	
GYMNASIUM	Inspected
Instance on 2nd Floor	Inspected
Instance on 5th Floor	Inspected
Lighting Instance on 2nd Floor	Inspected
Instance on 2nd Floor Instance on 5th Floor	Inspected
Lighting Fixture - Fluorescent	шореска
Digitaling Prixture - Proofestent	

Building Condition Assessment Survey 2023-2024

Question	Response
GYMNASIUM	
Lighting	
Lighting Fixture - Fluorescent	
Instance on 2nd Floor	Does not exist
Instance on 5th Floor	Does not exist
Lighting Fixture - HID	
Instance on 2nd Floor	Does not exist
Instance on 5th Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 2nd Floor	Does not exist
Instance on 5th Floor	Does not exist
Lighting Fixture - LED	
Instance on 2nd Floor	Inspected
Instance on 5th Floor	Inspected
Pendant Mounted	
Instance on 2nd Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance on 5th Floor	Does not exist
Surface Mounted	
Instance on 2nd Floor	Does not exist
Instance on 5th Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 2nd Floor	Does not exist
Instance on 5th Floor	Does not exist
Local Sound System	Does not exist
Instance on 2nd Floor	Inspected
Instance Condition	4- Between Fair and Poor
Installation Year	2014
Source of Installation Year	Documented
Deficiency	AMPLIFIER NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance on 5th Floor	Inspected
Instance Condition	4- Between Fair and Poor
Installation Year	2014
Source of Installation Year	Documented
Deficiency	AMPLIFIER NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2

Building Condition Assessment Survey 2023-2024

M052

Question	Response	
GYMNASIUM		
Local Sound System		
Violations	No violations recorded	
Projection System		
Instance on 2nd Floor	Does not exist	
Instance on 5th Floor	Does not exist	
Scoreboard		
Instance on 2nd Floor	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Instance on Ed. Elsen	Does not exist	

JIMINASIUM	
Local Sound System	
Violations	No violations recorded
Projection System	
Instance on 2nd Floor	Does not exist
Instance on 5th Floor	Does not exist
Scoreboard	
Instance on 2nd Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Instance on 5th Floor	Does not exist
Theater Lighting System	
Instance on 2nd Floor	Does not exist
Instance on 5th Floor	Does not exist
KITCHEN	Inspected
Instance on 1st Floor	Inspected
Lighting	•
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	•
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Does not exist
Recessed Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	1.0 40.10.10.10.10.10.10.10.10.10.10.10.10.10
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	DOS NOT CAIST
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	DOES HOT CAIST
Instance on 1st Floor	Does not exist
LIBRARY	Inspected
Instance on Room 309	Inspected
Lighting	Turnes de d
Instance on Room 309	Inspected
Lighting Fixture - Fluorescent	Turnes d
Instance on Room 309	Inspected
Pendant Mounted	
Instance on Room 309	Does not exist
Surface Mounted	
Instance on Room 309	Does not exist
Recessed Mounted	
Instance on Room 309	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Room 309	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 309	Does not exist
Lighting Fixture - LED	
Instance on Room 309	Does not exist

Building Condition Assessment Survey 2023-2024

incui inspection		141032
Question	Response	
LIBRARY		
Raceway With Receptacles		
Instance on Room 309	Does not exist	
Projection System		
Instance on Room 309	Does not exist	
LOCKER ROOM	Inspected	
Instance on Room 509	Inspected	
Alternative Use	Yes	
Lighting		
Instance on Room 509	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 509	Inspected	
Pendant Mounted		
Instance on Room 509	Does not exist	
Surface Mounted		
Instance on Room 509	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on Room 509	Does not exist	
Lighting Fixture - HID		
Instance on Room 509	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 509	Does not exist	
Lighting Fixture - LED		
Instance on Room 509	Does not exist	
MULTIPURPOSE ROOM	Does not exist	
SCIENCE DEMO ROOM	Does not exist	
SCIENCE LAB	Inspected	
Instance on Rooms: 418, 420	Inspected	
Power Panel?	Yes	
Alternative Use	No	
Instance on Room 422	Inspected	
Power Panel?	Yes	
Alternative Use	No	
Lighting		
Instance on Rooms: 418, 420	Inspected	
Instance on Room 422	Inspected	
Lighting Fixture - Fluorescent		
Instance on Rooms: 418, 420	Inspected	
Instance on Room 422	Inspected	
Pendant Mounted		
Instance on Rooms: 418, 420	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Instance on Room 422	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Rooms: 418, 420	Does not exist	
Instance on Room 422	Does not exist	
Recessed Mounted		
Instance on Rooms: 418, 420	Does not exist	

Building Condition Assessment Survey 2023-2024

icai Inspection		MIUS
uestion	Response	
SCIENCE LAB		
Lighting		
Lighting Fixture - Fluorescent		
Recessed Mounted		
Instance on Room 422	Does not exist	
Lighting Fixture - HID		
Instance on Rooms: 418, 420	Does not exist	
Instance on Room 422	Does not exist	
Lighting Fixture - Incandescent		
Instance on Rooms: 418, 420	Does not exist	
Instance on Room 422	Does not exist	
Lighting Fixture - LED		
Instance on Rooms: 418, 420	Does not exist	
Instance on Room 422	Does not exist	
Emergency Gas Shut-Off Valve		
Instance on Rooms: 418, 420	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 422	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Emergency Shut-Off Power		
Instance on Rooms: 418, 420	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 422	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Power Supply		
Instance on Rooms: 418, 420	Does not exist	
Instance on Room 422	Does not exist	
Projection System		
Instance on Rooms: 418, 420	Does not exist	
Instance on Room 422	Does not exist	
SCIENCE PREP ROOM	Does not exist	
SWIMMING POOL	Does not exist	
FOILET ROOM - STAFF	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Inspected	
Condition Condition	2- Between Good and Fair	
	No deficiencies recorded	
Deficiency	No deficiencies recorded Does not exist	
Lighting Fixture - HID		
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
TOILET ROOM - STUDENT	Inspected	

Building Condition Assessment Survey 2023-2024

i icui inspeciion		111032
Question	Response	
TOILET ROOM - STUDENT		
Lighting		
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
AUXILIARY SIGNAL/BELL SYSTEM	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
	Does not exist	
EMERGENCY DC STANDBY BATTERY POWER		
EMERGENCY GENERATOR SET	Does not exist	
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
EMERGENCY LIGHTING	Inspected	
Battery Pack	Inspected	
Condition	2- Between Good and Fair	
Deficiency	BATTERY NOT OPERATIONAL	
Deficiency Location/Instance	Throughout the Building	
Deficiency Quantity	6	
Quantity Uom	EACH	
Potential Action	REPLACE BATTERY	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Deficiency	FIXTURE NOT OPERATIONAL	
Deficiency Location/Instance	Throughout the Building	
Deficiency Quantity	4	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Non Battery Pack	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
EXIT LIGHT	Inspected	
Battery Pack	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Non Battery Pack	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
EXIT/EMERGENCY LIGHT	Does not exist	
FIRE ALARM SYSTEM	Inspected	
Bell/Horn	Inspected	
Condition	3- Fair	

Building Condition Assessment Survey 2023-2024

_		
estion	Response	
TIRE ALARM SYSTEM		
Bell/Horn		
Deficiency	No deficiencies recorded	
Strobe	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Manual Pull Station	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fan Shutdown Control	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Duct Smoke Detector	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Area Smoke Detector	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
CO Detector	Does not exist	
Heat Detector	Does not exist	
Elevator Recall	Does not exist	
Magnetic Door Holder/Contactor	Does not exist	
Fused Cutout Panel	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Digital Communicator	Does not exist	
Main Panel	Inspected	
Bell At Panel	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Electronic)	Inspected	
Instance	Boiler Room	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Simplex	
Model	4100	
EquipmentId	Fire Alarm Control	
Installation Year	1992	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Standard)	Does not exist	
Sub-Panel	Inspected	
Bell At Panel	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Electronic)	Inspected	
Instance	Boiler Room	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Edwards System Technology	
Model	LSS4/36	
EquipmentId	Fire Alarm Strobe Panel	
Installation Year	1992	

Building Condition Assessment Survey 2023-2024

ricui Inspection		MIUSZ
euestion	Response	
FIRE ALARM SYSTEM		
Sub-Panel		
Fire Alarm Control Panel (Electronic)		
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Standard)	Does not exist	
Remote Annunciator	Inspected	
Display Monitor	Does not exist	
Panel	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Printer	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Punch Register	Does not exist	
Sprinkler Flow/Air Pressure Switch	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Tamper Flow Switch/Chain	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
GROUNDING SYSTEM	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
INTERCOM SYSTEM	Does not exist	
LAN	Inspected	
Local Distribution Frame (I/LDF)	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Main Equipment Rack (MDF)	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
LIGHTNING PROTECTION	Does not exist	
MOTOR CONTROLLER	Inspected	
MOTOR CONTROL CENTER	Inspected	
Instance	Boiler Room	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	N/A	
EquipmentId	Fan Roof	
Capacity/Size Quantity	200	
Capacity/Size UOM	Amps	
Capacity/Size 2 Quantity	1	
Capacity/Size 2 UOM	Section(s)	
Source of Capacity/Size	Switchboard Mains Size	
Installation Year	1992	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
MOTOR STARTER/CONTACTOR	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Variable Frequency Drive	Inspected	
Condition	1- Good	

Building Condition Assessment Survey 2023-2024

cui inspection		WIU5.
estion	Response	
MOTOR CONTROLLER		
Variable Frequency Drive		
Deficiency	No deficiencies recorded	
ANEL BOARD	Inspected	
Fused Disconnect Switch Type	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fused Knife Switch Type	Does not exist	
Fused Toggle Switch Type	Does not exist	
Molded Case Circuit Breaker Type	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
PUBLIC ADDRESS SYSTEM	Inspected	
Instance	Room 128	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Model	Dukane 250	
Installation Year	2013	
Source of Installation Year	Documented	
Deficiency	SPEAKER NOT OPERATIONAL	
Deficiency Location/Instance	Gymnasium and Auditorium	
Deficiency Quantity	14	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 6	
Violations	No violations recorded	
ECURITY	Inspected	
IPDVS/CCTV System	Inspected	
Condition	3- Fair	
Installation Year	2010	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Intrusion Alarm System	Inspected	
Central Control Panel	Inspected	
Instance	Custodian's Office - Room 105	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Model	Vista 128BPT	
Installation Year	2014	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
<u>-</u>	Inspected	
Infrared Sensor	•	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Panic Switch	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Remote Annunciator	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Siren/Strobe	Inspected	

Building Condition Assessment Survey 2023-2024

rical Inspection uestion	Response
	лезриняе
SECURITY	
Intrusion Alarm System	
Siren/Strobe	2.0 () 15.
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting - Security	Inspected
Condition	4- Between Fair and Poor
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Location/Instance	Perimeter of the Building
Deficiency Quantity	10
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 3
Violations	No violations recorded
SERVICE SWITCH	Inspected
Instance	Electrical Room 117
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	All City Switchboard
EquipmentId	3000A Service Switch #1
Capacity/Size Quantity	3000
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2017
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room 117
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	All City Switchboard
EquipmentId	Sub-Switchboard in the Boiler Room
Capacity/Size Quantity	800
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2017
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
SWITCHBOARD	Inspected
Number of Spares	3
Fused Disconnect Switch Type	Inspected
Instance	Electrical Room 117
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	All City Switchboard
EquipmentId	DP-ACPP Section #1, 2 1200A Main
Capacity/Size Quantity	1200
Canacity/Siza HOM	Amps Total

Amps Total

Section(s)

Nameplate 2017

Documented

2

Capacity/Size UOM

Capacity/Size 2 Quantity

Capacity/Size 2 UOM

Installation Year

Source of Capacity/Size

Source of Installation Year

Building Condition Assessment Survey 2023-2024

uestion	Response
SWITCHBOARD	
Fused Disconnect Switch Type	
Deficiency	No deficiencies recorded
Instance	Electrical Room 117
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	All City Switchboard
EquipmentId	N/A
Capacity/Size Quantity	3000
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	2
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	2017
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Boiler Room - Old Electrical Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	All City Switchboard
EquipmentId	N/A
Capacity/Size Quantity	800
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	4
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Service Switch Size
Installation Year	1992
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not exist
Molded Case Circuit Breaker Type	Does not exist
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	2- Between Good and Fair
Deficiency	TELEPHONE NOT OPERATIONAL
Deficiency Location/Instance	Room 416, Teachers Cafeteria
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE TELEPHONE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Standard	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
ΓRANSFORMER	Does not exist