Building Condition Assessment Survey 2023-2024

Electrical Inspection

Inspection	n Id Inspection Type				Time	In	Last Edited
	4877 ELECTRICAL				2024-	04-22 09:48AM	1 2024-04-22 12:54PM
sset Data							
Question				Answer			
Have any Systems/Major Building Components been upgraded?				Systems:	Telephone Sy	stem, LAN	
				Years:	2019		
				Systems:	Auditorium (I	Projection Syster	n)
				Years:	2016		
				Systems:	Interior Light Kitchen)	ing (Except Aud	itorium, Cafeteria,
				Years:	2013		
				Systems:	Fluorescent L	ighting (Kitchen	, Cafeteria)
				Years:	2011		
				Systems:	Alarm System Lighting System Breaker Type	n, Auditorium (H em), Switchboar	Sound System, Fire louse Lighting, Theater d, Molded Case Circuit
				Years:	2008		
				Systems:	Intrusion Alar	m System	
				Years:	2002		
				Systems:	• •	ight/Exit Light P	anel
				Years:	1990		
Type of S				Below Gr	ound		
	ractive Whiteboard (IWB)			Yes			
	netration In Electrical Roo	m? N FIRE RESCUE AREAS		No			
Question		IN FIRE RESCUE AREAS		I	Response		
-		ance Areas, Fire Rescue Areas, a	nd/or Holding Roon		No		
your bu	-						
riority Co	ondition						
Exist	Priority	Condition	Component	Location	Person(s)	Person(s)	Photo
Last Year?	Category	Description	Affected	Description	Notified	Title	Image
No	Exposed Electrical Wires	N/A	Raceway With Receptacles	Computer Lab - Room 307	Benny Portille	Fireman	
Inspection	l						
Question	l			Response			
Electrica	1						
ATHL	ETIC FIELD			Does not o	exist		
AUDIT	ORIUM			Inspected			
	Instance on Basement			Inspected			
Hous	e Lighting						
	Instance on Basement			Inspected			
	Does a Chandelier Ex			No			
Lig	hting Fixture - Fluoresce			т, т			
	Instance on Basement			Inspected			
P	endant Mounted			5	• ,		
~	Instance on Basement			Does not o	exist		
S	urface Mounted			T / 1			
	Instance on Basement			Inspected			
	Instance Condition			3- Fair			

```
BCAS Partners Version 2.0 (P)
```

Building Condition Assessment Survey 2023-2024

estion	Response	
UDITORIUM		
House Lighting		
Lighting Fixture - Fluorescent		
Surface Mounted		
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on Basement	Does not exist	
Lighting Fixture - HID		
Instance on Basement	Inspected	
Pendant Mounted		
Instance on Basement	Does not exist	
Surface Mounted		
Instance on Basement	Does not exist	
Recessed Mounted		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - Incandescent		
Instance on Basement	Does not exist	
Lighting Fixture - LED		
Instance on Basement	Does not exist	
Local Sound System		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Installation Year	2008	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System Instance on Basement	Inspected	
	Inspected 2- Between Good and Fair	
Instance Condition Is the projector on a cart or installed on the ceiling?	Ceiling	
Deficiency	No deficiencies recorded	
Theater Lighting System	No deficiencies recorded	
Instance on Basement	Inspected	
Dimming System	inspected	
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Theater Lighting		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
AFETERIA	Inspected	
Instance on 1st Floor		
	Inspected	
Lighting	Inspected	
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent Instance on 1st Floor	Inspected	
	mspecieu	
Pendant Mounted	Does not exist	
Instance on 1st Floor	DOES HOU EXIST	
Surface Mounted Instance on 1st Floor	Inspected	
	Inspected 3- Fair	
Instance Condition Deficiency	3- Fair No deficiencies recorded	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

	NIUð
Response	
Does not exist	
Does not exist	
Does not exist	·
Does not exist	
Inspected	
3- Fair	
2008	
Documented	
No deficiencies recorded	
Does not exist	
Does not exist	
Inspected	
No	
Inspected	
Inspected	
2- Between Good and Fair	
No deficiencies recorded	
Inspected	
2- Between Good and Fair	
LIGHTING FIXTURE BALLAST DEFECTIVE	
2	
EACH	
REPLACE BALLAST	
PRIORITY 3	
LEVEL 2	
No violations recorded	
Inspected	
2- Between Good and Fair	
No deficiencies recorded	
Does not exist	
Does not exist	
Does not exist	
N0	
Inspected	
Inspected	
Inspected	
	-
-	
No deficiencies recorded	
	Does not exist Does n

Building Condition Assessment Survey 2023-2024

iestion	Response	
COMPUTER LAB		
Lighting		
Lighting Fixture - Fluorescent		
Surface Mounted		
Instance on Room 307	Does not exist	
Recessed Mounted		
Instance on Room 307	Does not exist	
Lighting Fixture - HID		
Instance on Room 307	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 307	Does not exist	
Lighting Fixture - LED		
Instance on Room 307	Does not exist	
Raceway With Receptacles		
Instance on Room 307	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
GYMNASIUM	Inspected	
Instance on 2nd Floor	Inspected	
Lighting		
Instance on 2nd Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on 2nd Floor	Does not exist	
Lighting Fixture - HID		
Instance on 2nd Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 2nd Floor	Does not exist	
Lighting Fixture - LED		
Instance on 2nd Floor	Inspected	
Pendant Mounted		
Instance on 2nd Floor	Does not exist	
Surface Mounted		
Instance on 2nd Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 2nd Floor	Does not exist	
Local Sound System		
Instance on 2nd Floor	Inspected	
Instance Condition	3- Fair	
Installation Year	2008	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System		
Instance on 2nd Floor	Does not exist	
Scoreboard		
Instance on 2nd Floor	Does not exist	
Theater Lighting System		
Instance on 2nd Floor	Does not exist	
KITCHEN	Inspected	
Instance on 1st Floor	Inspected	
Lighting		
Instance on 1st Floor	Inspected	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

rical Inspection	MI
Question	Response
KITCHEN	
Lighting	
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on 1st Floor	Does not exist
Recessed Mounted	
Instance on 1st Floor	Does not exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not exist
LIBRARY	Inspected
Instance on Room 214	Inspected
Lighting	
Instance on Room 214	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 214	Inspected
Pendant Mounted	
Instance on Room 214	Does not exist
Surface Mounted	
Instance on Room 214	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Room 214	Does not exist
Lighting Fixture - HID	
Instance on Room 214	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 214	Does not exist
Lighting Fixture - LED	
Instance on Room 214	Inspected
Pendant Mounted	1
Instance on Room 214	Does not exist
Surface Mounted	
Instance on Room 214	Does not exist
Recessed Mounted	
Instance on Room 214	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Raceway With Receptacles	
Instance on Room 214	Does not exist
Projection System	
Instance on Room 214	Does not exist
LOCKER ROOM	Inspected
Instance on 2nd Floor - Boys	Inspected
Alternative Use	
Lighting	Yes

Building Condition Assessment Survey 2023-2024

Electrical Inspection

MU8
Response
Inspected
Inspected
Does not exist
Inspected
2- Between Good and Fair
No deficiencies recorded
Does not exist
Does not exist
Does not exist
Inspected
Inspected
Inspected
Does not exist
Inspected
2- Between Good and Fair
No deficiencies recorded
Does not exist
Inspected
Inspected
Inspected
Does not exist
Inspected
2- Between Good and Fair
No deficiencies recorded
Does not exist
Inspected
3- Fair
DOOR PUSH BUTTON NOT OPERATIONAL
Exterior Wall by Main Entrance
1
EACH
MAINTENANCE

Building Condition Assessment Survey 2023-2024

Electrical Inspection

IVIU
Response
PRIORITY 3
LEVEL 2
No violations recorded
Does not exist
Does not exist
Inspected
3- Fair
No deficiencies recorded
Inspected
Inspected
3- Fair
No deficiencies recorded
Inspected
3- Fair
No deficiencies recorded
Inspected
Inspected
3- Fair
FIXTURE LAMP NOT OPERATIONAL
Boiler Room, by Room 124
2
EACH
MAINTENANCE
PRIORITY 5
LEVEL 2
No violations recorded
Inspected
3- Fair
No deficiencies recorded
Does not exist
Inspected
Inspected
2- Between Good and Fair
No deficiencies recorded
Inspected
2- Between Good and Fair
No deficiencies recorded
Inspected
2- Between Good and Fair
No deficiencies recorded
Inspected
2- Between Good and Fair
No deficiencies recorded
Inspected
2- Between Good and Fair
No deficiencies recorded
Inspected
2- Between Good and Fair
No deficiencies recorded
Under construction

Building Condition Assessment Survey 2023-2024

	~ -
MOS	37

	19108
uestion	Response
FIRE ALARM SYSTEM	
Elevator Recall	Does not exist
Magnetic Door Holder/Contactor	Does not exist
Fused Cutout Panel	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	Does not exist
Main Panel	Inspected
Bell At Panel	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Main Entrance Lobby
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Edwards System Technology
Model	EST 2
EquipmentId	N/A
Installation Year	2008
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	Does not exist
Sub-Panel	Does not exist
Remote Annunciator	Inspected
Display Monitor	Does not exist
Panel	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Printer	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Punch Register	Does not exist
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Tamper Flow Switch/Chain	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	Does not exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Does not exist
MOTOR CONTROLLER	Inspected Decement evict
MOTOR CONTROL CENTER	Does not exist Inspected

Building Condition Assessment Survey 2023-2024

	IVIUO
uestion	Response
MOTOR CONTROLLER	
MOTOR STARTER/CONTACTOR	
Condition	3- Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Does not exist
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Does not exist
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Does not exist
Molded Case Circuit Breaker Type	Inspected
Condition	2- Between Good and Fair
Deficiency	NO SPARE
Deficiency Location/Instance	By Room 206
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL NEW PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	NO SPARE
Deficiency Location/Instance	Kitchen
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
PUBLIC ADDRESS SYSTEM	Inspected
Instance	General Office - Room B14 3- Fair
Instance Instance Condition	General Office - Room B14 3- Fair
Instance Instance Condition Instance Quantity	General Office - Room B14 3- Fair 1
Instance Instance Condition Instance Quantity Instance Quantity Uom	General Office - Room B14 3- Fair 1 EACH
Instance Instance Condition Instance Quantity Instance Quantity Uom Model	General Office - Room B14 3- Fair 1 EACH Biamp MPA250
Instance Instance Condition Instance Quantity Instance Quantity Uom Model Installation Year	General Office - Room B14 3- Fair 1 EACH Biamp MPA250 2008
Instance Instance Condition Instance Quantity Instance Quantity Uom Model Installation Year Source of Installation Year	General Office - Room B14 3- Fair 1 EACH Biamp MPA250 2008 Documented
Instance Instance Condition Instance Quantity Instance Quantity Uom Model Installation Year Source of Installation Year Deficiency	General Office - Room B14 3- Fair 1 EACH Biamp MPA250 2008 Documented CLOCK NOT OPERATIONAL
Instance Instance Condition Instance Quantity Instance Quantity Uom Model Installation Year Source of Installation Year Deficiency Deficiency Location/Instance	General Office - Room B14 3- Fair 1 EACH Biamp MPA250 2008 Documented CLOCK NOT OPERATIONAL Locker Room - Boys
Instance Instance Condition Instance Quantity Instance Quantity Uom Model Installation Year Source of Installation Year Deficiency Deficiency Location/Instance Deficiency Quantity	General Office - Room B14 3- Fair 1 EACH Biamp MPA250 2008 Documented CLOCK NOT OPERATIONAL Locker Room - Boys 1
Instance Instance Condition Instance Quantity Instance Quantity Uom Model Installation Year Source of Installation Year Deficiency Deficiency Deficiency Quantity Quantity Uom	General Office - Room B14 3- Fair 1 EACH Biamp MPA250 2008 Documented CLOCK NOT OPERATIONAL Locker Room - Boys 1 EACH
Instance Instance Condition Instance Quantity Instance Quantity Uom Model Installation Year Source of Installation Year Deficiency Deficiency Location/Instance Deficiency Quantity Quantity Uom Potential Action	General Office - Room B14 3- Fair 1 EACH Biamp MPA250 2008 Documented CLOCK NOT OPERATIONAL Locker Room - Boys 1 EACH REPLACE
Instance Instance Condition Instance Quantity Instance Quantity Uom Model Installation Year Source of Installation Year Deficiency Deficiency Location/Instance Deficiency Quantity Quantity Uom Potential Action Urgency of Action	General Office - Room B14 3- Fair 1 EACH Biamp MPA250 2008 Documented CLOCK NOT OPERATIONAL Locker Room - Boys 1 EACH REPLACE PRIORITY 3
Instance Instance Condition Instance Quantity Instance Quantity Uom Model Installation Year Source of Installation Year Deficiency Deficiency Location/Instance Deficiency Quantity Quantity Uom Potential Action Urgency of Action Purpose of Action	General Office - Room B14 3- Fair 1 EACH Biamp MPA250 2008 Documented CLOCK NOT OPERATIONAL Locker Room - Boys 1 EACH REPLACE PRIORITY 3 LEVEL 2
Instance Instance Condition Instance Quantity Instance Quantity Uom Model Installation Year Source of Installation Year Deficiency Deficiency Location/Instance Deficiency Quantity Quantity Uom Potential Action Urgency of Action Purpose of Action Violations	General Office - Room B14 3- Fair 1 EACH Biamp MPA250 2008 Documented CLOCK NOT OPERATIONAL Locker Room - Boys 1 EACH REPLACE PRIORITY 3 LEVEL 2 No violations recorded
Instance Instance Condition Instance Quantity Instance Quantity Instance Quantity Uom Model Installation Year Source of Installation Year Deficiency Deficiency Deficiency Location/Instance Deficiency Quantity Quantity Uom Potential Action Urgency of Action Purpose of Action Violations SECURITY	General Office - Room B14 3- Fair 1 EACH Biamp MPA250 2008 Documented CLOCK NOT OPERATIONAL Locker Room - Boys 1 EACH REPLACE PRIORITY 3 LEVEL 2 No violations recorded Inspected
Instance Instance Condition Instance Quantity Instance Quantity Instance Quantity Uom Model Installation Year Source of Installation Year Deficiency Deficiency Deficiency Location/Instance Deficiency Quantity Quantity Uom Potential Action Urgency of Action Purpose of Action Violations SECURITY IPDVS/CCTV System	General Office - Room B14 3 - Fair 1 EACH Biamp MPA250 2008 Documented CLOCK NOT OPERATIONAL Locker Room - Boys 1 EACH REPLACE PRIORITY 3 LEVEL 2 No violations recorded Inspected Does not exist
Instance Instance Condition Instance Quantity Instance Quantity Uom Model Installation Year Source of Installation Year Deficiency Deficiency Location/Instance Deficiency Quantity Quantity Uom Potential Action Urgency of Action Purpose of Action Violations	General Office - Room B14 3- Fair 1 EACH Biamp MPA250 2008 Documented CLOCK NOT OPERATIONAL Locker Room - Boys 1 EACH REPLACE PRIORITY 3 LEVEL 2 No violations recorded Inspected Does not exist Inspected
Instance Instance Condition Instance Quantity Instance Quantity Uom Model Installation Year Source of Installation Year Deficiency Deficiency Location/Instance Deficiency Quantity Quantity Uom Potential Action Urgency of Action Purpose of Action Violations	General Office - Room B14 3- Fair 1 EACH Biamp MPA250 2008 Documented CLOCK NOT OPERATIONAL Locker Room - Boys 1 EACH REPLACE PRIORITY 3 LEVEL 2 No violations recorded Inspected Does not exist Inspected Inspected
Instance Instance Condition Instance Quantity Instance Quantity Uom Model Installation Year Source of Installation Year Deficiency Deficiency Location/Instance Deficiency Quantity Quantity Uom Potential Action Urgency of Action Purpose of Action Violations SECURITY IPDVS/CCTV System Intrusion Alarm System Central Control Panel	General Office - Room B14 3- Fair 1 EACH Biamp MPA250 2008 Documented CLOCK NOT OPERATIONAL Locker Room - Boys 1 EACH REPLACE PRIORITY 3 LEVEL 2 No violations recorded Inspected Does not exist Inspected Room B16
Instance Instance Condition Instance Quantity Instance Quantity Uom Model Installation Year Source of Installation Year Deficiency Deficiency Location/Instance Deficiency Quantity Quantity Uom Potential Action Urgency of Action Purpose of Action Violations SECURITY IPDVS/CCTV System Instance Instance Instance Instance	General Office - Room B14 3- Fair 1 EACH Biamp MPA250 2008 Documented CLOCK NOT OPERATIONAL Locker Room - Boys 1 EACH REPLACE PRIORITY 3 LEVEL 2 No violations recorded Inspected Does not exist Inspected Room B16 3- Fair
Instance Instance Condition Instance Quantity Instance Quantity Uom Model Installation Year Source of Installation Year Deficiency Deficiency Location/Instance Deficiency Quantity Quantity Uom Potential Action Urgency of Action Purpose of Action Violations SECURITY IPDVS/CCTV System Intrusion Alarm System Central Control Panel Instance Quantity Instance Quantity	General Office - Room B14 3 - Fair 1 EACH Biamp MPA250 2008 Documented CLOCK NOT OPERATIONAL Locker Room - Boys 1 EACH REPLACE PRIORITY 3 LEVEL 2 No violations recorded Inspected Does not exist Inspected Room B16 3 - Fair 1
Instance Instance Condition Instance Quantity Instance Quantity Uom Model Installation Year Source of Installation Year Deficiency Deficiency Location/Instance Deficiency Quantity Quantity Uom Potential Action Urgency of Action Purpose of Action Violations SECURITY IPDVS/CCTV System Intrusion Alarm System Central Control Panel Instance Instance Condition	General Office - Room B14 3 - Fair 1 EACH Biamp MPA250 2008 Documented CLOCK NOT OPERATIONAL Locker Room - Boys 1 EACH REPLACE PRIORITY 3 LEVEL 2 No violations recorded Inspected Does not exist Inspected Room B16 3 - Fair 1 EACH
Instance Instance Condition Instance Quantity Instance Quantity Uom Model Installation Year Source of Installation Year Deficiency Deficiency Location/Instance Deficiency Quantity Quantity Uom Potential Action Urgency of Action Purpose of Action Violations SECURITY IPDVS/CCTV System Intrusion Alarm System Central Control Panel Instance Quantity Instance Quantity	General Office - Room B14 3 - Fair 1 EACH Biamp MPA250 2008 Documented CLOCK NOT OPERATIONAL Locker Room - Boys 1 EACH REPLACE PRIORITY 3 LEVEL 2 No violations recorded Inspected Does not exist Inspected Room B16 3 - Fair 1 EACH
Instance Instance Condition Instance Quantity Instance Quantity Uom Model Installation Year Source of Installation Year Deficiency Deficiency Location/Instance Deficiency Quantity Quantity Uom Potential Action Urgency of Action Purpose of Action Violations SECURITY IPDVS/CCTV System Instance Instance Instance Instance Quantity Instance Quantity	General Office - Room B14 3 - Fair 1 EACH Biamp MPA250 2008 Documented CLOCK NOT OPERATIONAL Locker Room - Boys 1 EACH REPLACE PRIORITY 3 LEVEL 2 No violations recorded Inspected Does not exist Inspected Room B16 3 - Fair 1 EACH

NYC Department of Education Building Condition Assessment Survey 2023-2024

Electrical Inspection

ical Inspection		MU8
uestion	Response	
SECURITY		
Intrusion Alarm System		
Infrared Sensor	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Panic Switch	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Remote Annunciator	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
	Inspected	
Siren/Strobe Condition		
	3- Fair	
Deficiency	No deficiencies recorded	
Lighting - Security	Under construction	
SERVICE SWITCH	Inspected	
Instance	Electrical Room B29	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Cole Electric	
EquipmentId	Service A	
Capacity/Size Quantity	600	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year	1955	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Electrical Room B29	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Instance	Electrical Room B29	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Federal Pacific Electric	
EquipmentId	Service B	
Capacity/Size Quantity	600	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year	1955	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Electrical Room B29	
Deficiency Quantity	l	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Instance	Electrical Room B29	

NYC Department of Education Building Condition Assessment Survey 2023-2024

Electrical Inspection

Question		Response
SERVIC	E SWITCH	
	Instance Condition	3- Fair
	Instance Quantity	1
	Instance Quantity Uom	EACH
	Manufacturer	Federal Pacific Electric
	EquipmentId	Service A Oil Burner Main
	Capacity/Size Quantity	200
	Capacity/Size UOM	Amps
	Source of Capacity/Size	Nameplate
	Installation Year	1955
	Source of Installation Year	Documented
	Deficiency	BEYOND USEFUL LIFE
	Deficiency Location/Instance	Electrical Room B29
	Deficiency Quantity	1
	Quantity Uom Potential Action	EACH
	Urgency of Action	REPLACE PRIORITY 1
	Purpose of Action	LEVEL 2
	Violations	No violations recorded
	Instance	Electrical Room B29
	Instance Condition	3- Fair
	Instance Condition	
	· · · · · · · · · · · · · · · · · · ·	1 EACH
	Instance Quantity Uom	
	Manufacturer	Federal Pacific Electric
	EquipmentId Capacity/Size Quantity	Service B Oil Burner Main 200
	Capacity/Size UOM	Amps
	Source of Capacity/Size	Nameplate
	Installation Year	1955
	Source of Installation Year	Documented
	Deficiency	BEYOND USEFUL LIFE
	Deficiency Location/Instance	Electrical Room B29
	Deficiency Quantity	1
	Quantity Uom	EACH
	Potential Action	REPLACE
	Urgency of Action	PRIORITY 1
	Purpose of Action	LEVEL 2
	Violations	No violations recorded
SWITCH	IBOARD	Inspected
Numbe	r of Spares	0
Fused l	Disconnect Switch Type	Inspected
	Instance	Electrical Room B29
	Instance Condition	2- Between Good and Fair
	Instance Quantity	1
	Instance Quantity Uom	EACH
	Manufacturer	Metropolitan Electric
	EquipmentId	A
	Capacity/Size Quantity	600
	Capacity/Size UOM	Amps Total
	Capacity/Size 2 Quantity	l Section(s)
	Capacity/Size 2 UOM Source of Capacity/Size	Section(s) Service Switch Size
	Installation Year	2008
	Source of Installation Year	Documented
	Deficiency	No deficiencies recorded
	Instance	Electrical Room B29

Building Condition Assessment Survey 2023-2024

Electrical Inspection

iestion	Response	
SWITCHBOARD		
Fused Disconnect Switch Type		-
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Metropolitan Electric	
EquipmentId	В	
Capacity/Size Quantity	600	
Capacity/Size UOM	Amps Total	
Capacity/Size 2 Quantity	1	
Capacity/Size 2 UOM	Section(s)	
Source of Capacity/Size	Service Switch Size	
Installation Year	2008	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Fused Knife Switch Type	Does not exist	
Molded Case Circuit Breaker Type	Does not exist	
ELEPHONE SYSTEM	Inspected	
PBX/Intercom	Inspected	-
Condition	1- Good	
Deficiency	No deficiencies recorded	
Standard	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
TRANSFORMER	Does not exist	