Asset:	P.S. 102 - MANH	IATTAN, 315 EAST 11	13 STREET, MANHA	TTAN, NY, 100	)29		
Inspection Id	Inspection Type				Time	In	Last Edited
813	ELECTRICAL				2023-	-11-07 09:12AN	M 2024-01-24 04:28
set Data							
Question				Answer			
Have any Syst	ems/Major Building C	omponents been upgraded	d?	Systems:	Public Addres	ss System (Most	t Clocks)
				Years:	2023		
				Systems:	305, 306, 307 (LED Lightin	, 308, Boiler Ro	scept Rooms 303, 304, nom), Multipurpose Room Lighting (Retrofitted Nor urity
				Years:	2022		
				Systems:	Public Addres	ss System (Most	t Speakers)
				Years:	2020		
				Systems:	Intrusion Alar	m System	
				Years:	2018		
				Systems:	Interior Light	ing	
				Years:	2016		
				Systems:	Telephone Sy	stem, LAN	
				Years:	2015	C:': D 1	.D
				Systems:	System, Publi		Panel Board, Fire Alarm em, Local Sound System,
				Years:	2008	,	
				Systems:	Emergency Li	ight/Exit Light l	Panel
				Years:	1995		
Type of Service	e			Below Gr	round		
	we Whiteboard (IWB)			Yes			
	tion In Electrical Room		7	No			
	D INTERCOMS IN	N FIRE RESCUE ARE	EAS		Dogwongo		
Question Are there an	v I ife Rescue Assistar	nce Areas, Fire Rescue Are	eas and/or Holding Roor		Response Yes		
your buildin		ice rifeus, rife reseue rife	cus, und/or froming Roof	113 111	103		
		le in all of these spaces for	r use during a fire?		No		
Which sp	paces do not have dedi	cated intercoms?		]	Rooms 509, 501	, 409, 401, 309,	, 301, 209, 201
iority Condi	tion						
	ority	Condition	Component	Location	Person(s)	Person(s)	Photo
ast Year? Ca	tegory	Description	Affected	Description	Notified	Title	Image
No condition r	ecorded						
spection							
Question				Response	<u> </u>		
Electrical				<b>F</b>			
	PEIELD			Does not	evist		
ATHLETIC							
AUDITORIUM			Inspected				
	nstance on 2nd Floor			Inspected	•		
House Lig	nstance on 2nd Floor			Inspected			
	Does a Chandelier Exis	t?		No	•		
-	g Fixture - Fluorescen			1.5			
_	nstance on 2nd Floor	-		Does not	exist		
	Fixture - HID						
	nstance on 2nd Floor			Does not	exist		
Lighting	g Fixture - Incandesce	ent					
_	nstance on 2nd Floor			Does not	exist		
-	g Fixture - LED						

Electrical Inspection	M102
Question	Response

17
Response
Inspected
Inspected
2- Between Good and Fair
No deficiencies recorded
Inspected
2- Between Good and Fair
No deficiencies recorded
Does not exist
Inspected
3- Fair
2008
Documented
No deficiencies recorded
Does not exist
Does not exist
Inspected
Inspected
Inspected
<u> </u>
Does not exist
Does not exist
Does not exist
Inspected
1
Does not exist
Inspected
2- Between Good and Fair
No deficiencies recorded
1.0 40100101001000
Does not exist
DOG NOT CALST
Inspected
3- Fair
2008
Documented
No deficiencies recorded

## **Building Condition Assessment Survey 2023-2024**

icui Inspection		111102
uestion	Response	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected	
Lighting	Inspected	
Does a Chandelier Exist?	No	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Inspected	
Pendant Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
COMPUTER LAB	Does not exist	
GYMNASIUM	Inspected	
Instance on 1st Floor	Inspected	
Lighting		
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 1st Floor	Does not exist	
Local Sound System		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Installation Year	2008	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System		
Instance on 1st Floor	Does not exist	
Scoreboard		
Instance on 1st Floor	Does not exist	
Theater Lighting System		
Instance on 1st Floor	Does not exist	

Electrical Inspection	M102
Question	Response

iricui Inspection		171102
Question	Response	
KITCHEN	Inspected	
Instance on 1st Floor	Inspected	
Lighting	1	
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent	•	
Instance on 1st Floor	Does not exist	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Inspected	
Pendant Mounted	<u>*</u>	
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	10 delicibiles recorded	
Instance on 1st Floor	Does not exist	
LIBRARY	Inspected	
Instance on Room 402		
	Inspected	
Lighting Instance on Room 402	Lucanostod	
	Inspected	
Lighting Fixture - Fluorescent  Instance on Room 402	Does not exist	
	Does not exist	
Lighting Fixture - HID  Instance on Room 402	Does not exist	
<u> </u>	Does not exist	
Lighting Fixture - Incandescent  Instance on Room 402	Does not exist	
	Does not exist	
Lighting Fixture - LED  Instance on Room 402	Lucanostod	
	Inspected	
Pendant Mounted	Towns and d	
Instance on Room 402	Inspected  2- Between Good and Fair	
Instance Condition		
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room 402	Does not exist	
Recessed Mounted		
Instance on Room 402	Does not exist	
Raceway With Receptacles		
Instance on Room 402	Does not exist	
Projection System		
Instance on Room 402	Does not exist	
LOCKER ROOM	Inspected	
Instance on 1st Floor - Boys	Inspected	
Alternative Use	Yes	
Instance on 2nd Floor - Girls	Inspected	
Alternative Use	Yes	
Lighting		
Instance on 1st Floor - Boys	Inspected	

Electrical Inspection	M102
Question	Response

Question	Response
LOCKER ROOM	
Lighting	
Instance on 2nd Floor - Girls	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor - Boys	Does not exist
Instance on 2nd Floor - Girls	Does not exist
Lighting Fixture - HID	
Instance on 1st Floor - Boys	Does not exist
Instance on 2nd Floor - Girls	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor - Boys	Does not exist
Instance on 2nd Floor - Girls	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor - Boys	Inspected
Instance on 2nd Floor - Girls	Inspected
Pendant Mounted	
Instance on 1st Floor - Boys	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on 2nd Floor - Girls	Does not exist
Surface Mounted	
Instance on 1st Floor - Boys	Does not exist
Instance on 2nd Floor - Girls	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor - Boys	Does not exist
Instance on 2nd Floor - Girls	Does not exist
MULTIPURPOSE ROOM	Inspected
Instance on 1st Floor	Inspected
Lighting	mspecieu
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	2000 1100 4.1100
Instance on 1st Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Recessed Mounted	1.0 401.0101.010
Instance on 1st Floor	Does not exist
Local Sound System	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Installation Year	2008
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
	D' - D - 0/0/0004

## **Building Condition Assessment Survey 2023-2024**

Response  Does not exist
Does not exist
Does not exist
Does not exist
Inspected
Inspected
Does not exist
Does not exist
Does not exist
Inspected
Inspected
2- Between Good and Fair
No deficiencies recorded
Inspected
2- Between Good and Fair
No deficiencies recorded
Does not exist
Inspected
Inspected
Does not exist
Does not exist
Does not exist
Inspected
Inspected
2- Between Good and Fair
No deficiencies recorded
Inspected
2- Between Good and Fair
No deficiencies recorded
Does not exist
Inspected
3- Fair
No deficiencies recorded
Does not exist
Does not exist
Inspected
3- Fair
LESS THAN 20% SPARE CIRCUIT BREAKERS
Electrical Room By Main Entrance
1
EACH
INSTALL NEW PANEL BOARD
PRIORITY 5
LEVEL 2
No violations recorded
Inspected
Inspected 3- Fair

## **Building Condition Assessment Survey 2023-2024**

icui Inspection	1/110
uestion	Response
EMERGENCY LIGHTING	
Battery Pack	
Deficiency	BATTERY NOT OPERATIONAL
Deficiency Location/Instance	Auditorium, Cafeteria
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE BATTERY
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
Non Battery Pack	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Inspected
Condition	3- Fair
Deficiency	FIXTURE LAMP NOT OPERATIONAL
Deficiency Location/Instance Deficiency Quantity	Auditorium
	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
EXIT/EMERGENCY LIGHT	Does not exist
FIRE ALARM SYSTEM	Inspected
Bell/Horn	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Strobe	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Manual Pull Station	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	Inspected
Condition	2- Between Good and Fair
	No deficiencies recorded
Deficiency	
Duct Smoke Detector	Inspected  2- Between Good and Fair
Condition	
Deficiency	No deficiencies recorded
Area Smoke Detector	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
CO Detector	Under construction
Heat Detector	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Elevator Recall	Does not exist
Magnetic Door Holder/Contactor	Does not exist
Fused Cutout Panel	Inspected

## **Building Condition Assessment Survey 2023-2024**

cirical inspection		W1102
Question	Response	
FIRE ALARM SYSTEM		
Fused Cutout Panel		
Deficiency	No deficiencies recorded	
Fire Alarm Digital Communicator	Does not exist	
Main Panel	Inspected	
Bell At Panel	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Electronic)	Inspected	
Instance	Main Entrance Lobby	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	General Electric	
Model	EST 2	
EquipmentId	Fire Alarm Control Panel	
Installation Year	2008	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Standard)	Does not exist	
Sub-Panel	Inspected	
Bell At Panel	Does not exist	
Fire Alarm Control Panel (Electronic)	Under construction	
Fire Alarm Control Panel (Standard)	Does not exist	
Remote Annunciator	Inspected	
Display Monitor	Does not exist	
Panel	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Printer	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Punch Register	Does not exist	
Sprinkler Flow/Air Pressure Switch	Does not exist	
Tamper Flow Switch/Chain	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
GROUNDING SYSTEM	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
INTERCOM SYSTEM	Does not exist	
LAN	Inspected	
Local Distribution Frame (I/LDF)	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Main Equipment Rack (MDF)	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
LIGHTNING PROTECTION	Does not exist	
MOTOR CONTROLLER	Inspected	
MOTOR CONTROLLER  MOTOR CONTROL CENTER	Does not exist	
MOTOR CONTROL CENTER  MOTOR STARTER/CONTACTOR	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
<u> </u>		

## **Building Condition Assessment Survey 2023-2024**

iricui Inspection	11102
Question	Response
MOTOR CONTROLLER	
Variable Frequency Drive	Does not exist
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Does not exist
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Does not exist
Molded Case Circuit Breaker Type	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
PUBLIC ADDRESS SYSTEM	Inspected
Instance	General Office - 1st Floor Mezzanine
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Biamp MPA250
Installation Year	2008
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
SECURITY	Inspected
IPDVS/CCTV System	Does not exist
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	Closet By Old Custodian's Office - Room 271A
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista 128BPT
Installation Year	2018
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting - Security	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
SERVICE SWITCH	Inspected
Instance	Electrical Room at Main Entrance
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Electrotech
Manutacturer EquipmentId	Bolt Switch 800A SS#1
Equipmentid Capacity/Size Quantity	800
Capacity/Size Quantity  Capacity/Size UOM	Amps
y	r

## **Building Condition Assessment Survey 2023-2024**

Question	Response
SERVICE SWITCH	
Source of Capacity/Size	Nameplate
Installation Year	2008
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
SWITCHBOARD	Inspected
Number of Spares	3
Fused Disconnect Switch Type	Inspected
Instance	Boiler Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Electrotech
EquipmentId	Main Switchboard MSA Section 1 and Section 2
Capacity/Size Quantity	800
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	2
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	2008
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not exist
Molded Case Circuit Breaker Type	Does not exist
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
TRANSFORMER	Does not exist