Building Condition Assessment Survey 2023-2024

Asset:	r.s. 145 - MAN	NHATTAN, 150 WEST 105 S	SIKEEI, MANH	IAI IAN, NY, IU	U45	
Inspection Id	Inspection Type				Time In	Last Edited
369	MECHANICAL				2023-10-23 07:46AM	2023-11-28 10:11A
sset Data						
Question				Answer		
Have any Syste	ms/Major Building	g Components been upgraded?		Systems:	DX Split Systems; Terminal U Fixtures - Toilets, Lavatory/Sir (~80%)	_
				Years:	2022	a a
				Systems:	Kitchen - Gas System: Master	Gas Control Valve
				Years: Systems:	Heating Plant; Domestic Hot V Service (except for Kitchen an Steam Condensate Return Pun Heater/Cabinet Heaters in Boi Room - Dedicated A/C Equipr	d Science Rooms); nping System; Unit ler Room (2 of 7); MDF
				Years:	2019	(1))
				Systems:	Unit Heater/Cabinet Heaters for	or Gymnasium (5 of 7)
				Years:	2018	
				Systems:	Climate Control System: Air C Air Dryers, PRV Station, Temp Valves, Damper Actuators	
				Years:	2016	
				Systems:	Wet Sprinkler Alarm Valve As Pumps	sembly; Sewage Ejector
				Years:	2015	
				Systems:	Science Lab; Science Prep Roo Trap (1 of 2)	om; Kitchen - Grease
				Years:	2013	
Are there fuel t	anks?			No		
Total # of water	r main service entr	ries to the asset		2		
MERs/Fan Roo	oms Locations			MERs B2	, B18	
		g or Defective CO Detectors?		No		
•	Painted/Obstructed	Sprinkler Heads?		Yes	0(P (: 1.2)	
Location(s)	lan anaan ay Stan Sy	vitahaa with Missina Hammona?			m Storage Room (painted, 2)	
		vitches with Missing Hammers?		No compo	onenis	
<i>riority Condit</i> Exist Pric	ority	Condition	Component	Location	Person(s) Person(s)	Photo
	egory	Description	Affected	Description	Notified Title	Image
No condition re	corded					
nspection						
Question				Response	,	
Mechanical						
AIR CONDI				Inspected		
Chilled Wa		n		Does not		
-		on: Piping, Pumps and Auxiliar	ries	Does not		
	oil in Ductwork			Does not Does not		
Cooling Tower DX Split System		Inspected				
Indoor U				Inspected		
Conditi				1- Good		
	eficiency				encies recorded	
Outdoor				Inspected		
				1		
Conditi	on			1- Good		

Building Condition Assessment Survey 2023-2024

unicui Inspection	WITTS
uestion	Response
AIR CONDITIONING	
Packaged / Rooftop Unit	Does not exist
Packaged Terminal A/C	Does not exist
Refrigerant Leak Detection System	Does not exist
Refrigerant Piping	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Return Fan	Does not exist
CENTRAL ACID WASTE NEUTRALIZING TANK	Does not exist
CLIMATE CONTROL SYSTEM	Inspected
BMS	Does not exist
Pneumatic System	Inspected
Instance	Throughout
Instance Condition	3- Fair
Instance Quantity	
	EACH
Instance Quantity Uom	
Building Area Covered by Operational System	81-100%
Deficiency	DEFECTIVE TEMPERATURE CONTROL THERMOSTAT
Deficiency Location/Instance	Rooms 102, 122, 135
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Hybrid System	Does not exist
Electric System	Does not exist
COMPACTOR	Does not exist
CONVEYING	Inspected
Dumbwaiter	Does not exist
Elevator	Does not exist
Escalator	Does not exist
Non-auditorium Handicap Lift - Vertical	Does not exist
Non-auditorium Handicap Lift - Stair	Inspected
Condition	3- Fair
Are all the existing non-auditorium handicap stair lifts operable?	Yes
Deficiency	No deficiencies recorded
Ash Hoist	Does not exist
Sidewalk Elevator	Does not exist
DOMESTIC WATER SYSTEM	Inspected
Domestic Cold Water System	Inspected
Gravity System	Does not exist
Pressure Booster System	Does not exist
Water Service	Inspected
Instance	MER B2 - Sprinkler Room, Crawlspace near Room B1
Instance Condition	3- Fair
Instance Quantity	2
	EACH
Instance Quantity Uom	
Deficiency	WATER MAIN:MISSING BACKFLOW PREVENTION DEVICE
Deficiency Location/Instance	MER B2 - Sprinkler Room, Crawlspace near Room B1
Deficiency Quantity	2
	2 EACH
Deficiency Quantity Quantity Uom Potential Action	

Mechanical Inspection	M145
Question	Response

Question	Response
DOMESTIC WATER SYSTEM	
Domestic Cold Water System	
Water Service	
Purpose of Action	LEVEL 2
Violations	No violations recorded
Domestic Hot Water System	Inspected
Domestic Hot Water Remote Storage Tank	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Domestic Water Heat Exchanger	Does not exist
Electric Domestic Water Heater	Does not exist
Gas Fired Domestic Water Heater	Inspected
Instance	Boiler Room
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Lochinyar
EquipmentId	Water Heater
Capacity/Size Quantity	200
Capacity/Size UOM	MBH Input
Capacity/Size 2 Quantity	0
Capacity/Size 2 UOM	Gallons
Source of Capacity/Size	Documented
Installation Year	2019
Source of Installation Year	Custodial Staff
Deficiency	DEFECTIVE FRESH AIR LOUVER/DAMPER
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Oil Fired Domestic Water Heater	Does not exist
Heat Pump Domestic Water Heater	Does not exist
Domestic Water Distribution Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
DRAIN/WASTE/VENT AND STORM SYSTEM	Inspected
Interior Storm Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Sewage/Waste/Vent Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Sewage Ejector Pump	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Sump Pump	Does not exist
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	Does not exist
FIXTURES	Inspected
Staff And Other	Inspected
Janitor Sink	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Deficiency	no deficiencies recorded
	D: 1D 1 0/0/2004

Building Condition Assessment Survey 2023-2024

nestion	Response
FIXTURES	
Staff And Other	
Lavatory/Sink	Inspected
Condition	1- Good
Deficiency	DEFECTIVE AUXILIARY (FAUCET, SHUT OFF VALVE,ETC.)
Deficiency Location/Instance	Womens Toilet Room 304
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Toilet	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Urinal	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Student	Inspected
Drinking Fountain	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lavatory/Sink	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Locker Room Shower	Does not exist
Sink And Fountain Combo Unit	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Toilet	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Urinal	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
AS FIRED FURNACE	Does not exist
	Inspected
AS SERVICE	<u> </u>
Gas Distribution Piping	Inspected 1- Good
Condition	
Deficiency	No deficiencies recorded
Gas Meter Room Exhaust Fan	Does not exist
Gas Meter Room Vent	Does not exist
Gas Pressure Booster	Does not exist Inspected
CO/Gas Leak Detection	
Instance	Boiler Room, Gas Valve Room B8 2- Between Good and Fair
Instance Condition	
Instance Quantity	1
Instance Quantity Uom	EACH
Installation Year	2019
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
Instance	Boiler Room, Basement Corridor, 1st Floor Corridor (CO Detection)

Building Condition Assessment Survey 2023-2024

iicui Inspeciion		171175
estion	Response	
AS SERVICE		
CO/Gas Leak Detection		
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Installation Year	2019	
Source of Installation Year	Custodial Staff	
Deficiency	No deficiencies recorded	
EATING	Inspected	
	Inspected	
Heating Coil In Ductwork Condition	3- Fair	
Deficiency	No deficiencies recorded	
	Does not exist	
Hydronic Heating	Inspected	
Radiator/Convector/Fin Tube Condition	3- Fair	
Deficiency	No deficiencies recorded	
Steam Heating	Inspected	
F&T/Steam Drip Trap	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
MER Steam and Condensate Piping	Inspected	
Condition	3- Fair	
Deficiency	DAMAGED/MISSING INSULATION	
Deficiency Location/Instance	MERs B2, B18	
Deficiency Quantity	100	
Quantity Uom	L.F.	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Deficiency	DEFECTIVE/LEAKS	
Deficiency Location/Instance	MER B18	
Deficiency Quantity	10	
Quantity Uom	L.F.	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Steam Condensate Return Piping	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Steam Condensate Return Pumping System	Inspected	
Condition Condition		
	1- Good	
Deficiency	No deficiencies recorded	
Steam Piping	Inspected	
Condition	3- Fair	
Deficiency	DAMAGED/MISSING INSULATION	
Deficiency Location/Instance	Crawlspace in Rooms B1, B2	
Deficiency Quantity	60	
Quantity Uom	L.F.	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Terminal Unit Thermostatic Trap	Inspected	

Building Condition Assessment Survey 2023-2024

estion	Response	
EATING		
Steam Heating		
Terminal Unit Thermostatic Trap		
Condition	1- Good	
Deficiency	No deficiencies recorded	
Steam supplied by External Sources	Does not exist	
Unit Heater/Cabinet Heater	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
EATING PLANT	Inspected	
Instance on Basement	Inspected	
Is there a water meter on the boiler make-up water piping?	Yes	
Observed Operational?	Yes	
Burner Manufacturer	Webster	
Burner Model	N/A	
Burner Type	Gas	
Heating Plant Oil Number	N/A	
Boiler Auxiliaries		
Instance on Basement	Inspected	
Boiler Auxiliary Piping		
Instance on Basement	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Boiler Emergency Stop Switch		
Instance on Basement	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Boiler Feedwater System		
Instance on Basement	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Boiler Feedwater Treatment(Automatic)		
Instance on Basement	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Boiler Flue Exhaust	1 to deficiencies recorded	
Instance on Basement	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
<u> </u>	No deficiencies recorded	
Boiler Make-up Water Backflow Preventer Instance on Basement	Inspected	
	2- Between Good and Fair	
Instance Condition		
Deficiency	No deficiencies recorded	
Boiler Room Steam And Condensate Piping	*	
Instance on Basement	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Boiler Safety Valve		
Instance on Basement	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Boiler System		
Instance on Basement	Inspected	

Question	Response
HEATING PLANT	
Boiler System	
Coal-fired Boiler	
Instance on Basement	Does not exist
Hot Water Boiler	
Instance on Basement	Does not exist
Modular Boiler	
Instance on Basement	Does not exist
Steam Boiler	
Instance on Basement	Inspected
Instance on Basement	Inspected
Instance	Boiler Room
Instance Condition	1- Good
Instance Quantity	3,694
Instance Quantity Uom	MBH NET
Cast Iron Boiler?	No
Manufacturer	Burnham
EquipmentId	49064-1
Capacity/Size Quantity	4758
Capacity/Size UOM	MBH Gross
Source of Capacity/Size	Documented
Installation Year	2019
Source of Installation Year	Custodial Staff No deficiencies recorded
Deficiency	
Instance	Boiler Room 1- Good
Instance Condition	
Instance Quantity	3,694
Instance Quantity Uom	MBH NET
Cast Iron Boiler?	No Describeration
Manufacturer	Burnham 49064-2
EquipmentId Capacity/Size Quantity	4758
Capacity/Size Quantity Capacity/Size UOM	MBH Gross
Source of Capacity/Size	Documented
Installation Year	2019
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
Fuel System	
Instance on Basement	Inspected
Boiler Fresh Air Louver/Damper	-
Instance on Basement	Inspected
Instance Condition	1- Good
Type	Automatic
Deficiency	No deficiencies recorded
Burner/Burner Control Panel	
Instance on Basement	Inspected
Instance Condition	1- Good
Deficiency	BURNER CONTROL PANEL:DEFECTIVE
Deficiency Location/Instance	Boiler Room @ Boiler #1
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded

Mechanical Inspection	MI	45

ianicai Inspection	IVIII
Question	Response
HEATING PLANT	
Fuel System	
Fuel Oil Storage/Supply System	
Instance on Basement	Does not exist
Gas Trains And Vent At The Boiler	
Instance on Basement	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Enclosed IDF Room	Inspected
Instance on Rooms 119, 219, 319	Inspected
Dedicated A/C Equipment	
Instance on Rooms 119, 219, 319	Inspected
Instance Condition	4- Between Fair and Poor
Deficiency	DOES NOT EXIST
Deficiency Location/Instance	Rooms 119, 219, 319
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	INSTALL
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
KITCHEN	Inspected
Instance on Basement	
	Inspected
CO Detector	Y 1
Instance on Basement	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Gas System	
Instance on Basement	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Grease Trap	
Instance on Basement	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	DEFECTIVE/CLOGGED
Deficiency Location/Instance	Kitchen (1 of 2)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Hood	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Hood Exhaust Ductwork	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Hood Exhaust Fan	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded

Mechanical Inspection	M145
-----------------------	------

numeut Inspection		WIITS
Question	Response	
KITCHEN		
Hood Fire Suppression System		
Instance on Basement	Does not exist	
Hot Water Temperature Booster		
Instance on Basement	Does not exist	
Kitchen Sink		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
MDF Room	Inspected	
Instance on Room 206	Inspected	
Dedicated A/C Equipment		
Instance on Room 206	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
SCIENCE DEMO ROOM	Does not exist	
SCIENCE LAB	Inspected	
Instance on Room 133	Inspected	
Alternative Use	No	
Acid Waste Neutralizing Tank	INO	
Instance on Room 133	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
CO Detector	No deficiencies recorded	
Instance on Room 133	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Emergency Shower	TVO deficiences recorded	
Instance on Room 133	Does not exist	
Eye Wash	Does not exist	
Instance on Room 133	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Hood Exhaust Ductwork	110 4010101010	
Instance on Room 133	Does not exist	
Hood Exhaust Fan		
Instance on Room 133	Does not exist	
Fixed Laboratory Hood		
Instance on Room 133	Does not exist	
Laboratory Sink		
Instance on Room 133	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Make-up Air Unit		
Instance on Room 133	Does not exist	
SCIENCE PREP ROOM	Inspected	
Instance on Room 133A	Inspected	
Alternative Use	No	
Acid Waste Neutralizing Tank		
Instance on Room 133A	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
CO Detector		
Instance on Room 133A	Inspected	
	<u> </u>	

Building Condition Assessment Survey 2023-2024

инісш інгресион	IVII4
uestion	Response
SCIENCE PREP ROOM	
CO Detector	
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Emergency Shower	
Instance on Room 133A	Does not exist
Eye Wash	
Instance on Room 133A	Does not exist
Hood Exhaust Ductwork	
Instance on Room 133A	Does not exist
Hood Exhaust Fan	
Instance on Room 133A	Does not exist
Fixed Laboratory Hood	
Instance on Room 133A	Does not exist
Laboratory Sink	
Instance on Room 133A	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Make-up Air Unit	10 001010101010101001
Instance on Room 133A	Does not exist
	Inspected
SPRINKLERS, STANDPIPE, FIRE SYSTEM	Does not exist
Dry Sprinkler Alarm Valve Assembly	Inspected
Wet Sprinkler Alarm Valve Assembly Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fire Booster Pump Assembly	Does not exist Does not exist
Roof Tank	Does not exist
Siamese Connection Sprinkler Head	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE/DETERIORATED
Deficiency Location/Instance	Auditorium Storage Room (painted, 2)
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Sprinkler Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Standpipe System	Does not exist
Water Gong	Does not exist
SWIMMING POOL	Does not exist
VENTILATION	Inspected
Is the building Mechanically ventilated?	Partial
Exhaust Fan	Inspected 3- Fair
Condition	
Approximate Total # of Fans	1-25
Deficiency	No deficiencies recorded
Heating And Ventilating Unit	Inspected
Condition	4- Between Fair and Poor
Deficiency	DEFECTIVE CONTROLS
Deficiency Location/Instance	Crawlspace in Rooms B1, B2

Building Condition Assessment Survey 2023-2024

-		
estion	Response	
VENTILATION		
Heating And Ventilating Unit		
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Metal Ductwork	Inspected	
Condition	3- Fair	
Are there any uninsulated ductwork by design in Mechanical rooms?	Yes	
Are there chain operated dampers?	Yes	
Deficiency	DAMAGED FLEXIBLE CONNECTION	
Deficiency Location/Instance	MER B2 @ Auditorium Supply Fan	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Deficiency	DEFECTIVE DUCTWORK	
Deficiency Location/Instance	Roof @ Kitchen Hood Exhaust Fan	
Deficiency Quantity	10	
Quantity Uom	L.F.	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Supply Fan	Inspected	
Condition	3- Fair	
Approximate Total # of Fans	1-5	
Deficiency	No deficiencies recorded	
Unit Ventilator	Does not exist	