Building Condition Assessment Survey 2023-2024

ectrical II		HATTAN 701 EAST 1	OC CTDEET MANUE	ATTAN NIN 100	20		M
Asset:		HATTAN, 421 EAST 10	UO SIKEEI, MANHA	A1 1AN, NY, 100		r	I4 F-1241
Inspection					Time I		Last Edited
	2524 ELECTRICAL				2024-0	01-19 09:24AN	1 2024-02-13 08:13A1
set Data							
Question				Answer	E :/E	T 1 1 4	
Have any Systems/Major Building Components been upgraded?			Systems:	Exit/Emergence 2023	cy Lignts		
				Years: Systems:		ourity.	
				Years:	Lightning - Se 2022, 2007	curity	
				Systems:	Public Address	System (Parti	al Sneakers)
				Years:	2018	s system (1 arti	ii opeakers)
				Systems:	Telephone Sys	tem, LAN	
				Years:	2017	,	
				Systems:		n System, Ligh	tning Protection
				Years:	2015	, , ,	Ü
				Systems:	Interior Lightin Emergency Light		rary, Toilet Rooms), Most ttery Pack)
				Years:	2014		•
				Systems:	Public Address	s System (Mast	er Clock)
				Years:	2012		
				Systems:	Toilet Rooms ((Lighting)	
				Years:	2011		
				Systems:	Fire Alarm Sys	stem (Electroni	c Sub-Panel)
				Years:	2007, 2000		
				Systems:	Address System (Elevator Reca Case Circuit B	m (Amplifier/T all, Remote And treaker Panel B	Lighting System), Public uner), Fire Alarm System nunciator Panel), Molded oard, Fused Disconnect ttial Service Switch
				Years:	2007		
				Systems:	Fire Alarm Sys Detector, Fan		tout Panel, Duct Smoke rol)
				Years:	2000		
				Systems:	Emergency Lig	ght/Exit Light l	Panel
				Years:	1985		
Type of Se		Eviat9		Below Gr Yes	ound		
	active Whiteboard (IWB) etration In Electrical Roo			No			
		N FIRE RESCUE ARI	EAS	110			
Question	e any Life Rescue Assista	ance Areas, Fire Rescue Ar			Response No		
iority Coi	ndition						
xist ast Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
es	Electrical Room Used as Storage	N/A	Electrical Equipment	Electrical Room CR2	Jose Marte	Custodian	No Photo Taken
0	Intercom - Not Operational	N/ A	Intercom System - Elevator	Elevator near Stair Case C	Jose Marte	Custodian	No Photo Taken
spection							
Question				Response	<u> </u>		
Electrical							
	TIC FIELD			Does not	exist		
ATHLE	AUDITORIUM						
-	ORIUM			Inspected			

Building Condition Assessment Survey 2023-2024

Electrical InspectionM146QuestionResponse

F		
estion	Response	
AUDITORIUM		
House Lighting		
Instance on 1st Floor	Inspected	
Does a Chandelier Exist?	No	
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 1st Floor	Does not exist	
Lighting Fixture - HID	200 101 5.110	
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent	200 101 51110	
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED	Does not exist	
Instance on 1st Floor	Inspected	
Pendant Mounted	порессе	
Instance on 1st Floor	Does not exist	
	DOCS HOT CAIST	
Surface Mounted Instance on 1st Floor	Does not exist	
Recessed Mounted	Does not exist	
Instance on 1st Floor	Townseld	
	Inspected 2- Between Good and Fair	
Instance Condition		
Deficiency	No deficiencies recorded	
Local Sound System	T 1	
Instance on 1st Floor	Inspected 5- Poor	
Installation Year		
Installation Year Source of Installation Year	1965 Documented	
Deficiency	AMPLIFIER NOT OPERATIONAL	
Deficiency Quantity	AMI EITEK NOT OFEKATIONAL	
Quantity Uom	EACH	
Potential Action	REPLACE SYSTEM	
Urgency of Action	PRIORITY 2	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Projection System	140 violations recorded	
Instance on 1st Floor	Does not exist	
Theater Lighting System	Does not exist	
Instance on 1st Floor	Inspected	
Dimming System	порессеи	
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
	No deficiencies recorded	
Deficiency	ino deficiencies recorded	
Theater Lighting	T	
	Inspected	
Instance on 1st Floor Instance Condition	3- Fair	

Building Condition Assessment Survey 2023-2024

Question	Response
CAFETERIA	Inspected
Instance on 1st Floor - Students	Inspected
Lighting	
Instance on 1st Floor - Students	Inspected
Lighting Fixture - Fluorescent	•
Instance on 1st Floor - Students	Inspected
Pendant Mounted	1
Instance on 1st Floor - Students	Does not exist
Surface Mounted	
Instance on 1st Floor - Students	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor - Students	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 1st Floor - Students	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor - Students	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor - Students	Does not exist
Local Sound System	
Instance on 1st Floor - Students	Inspected
Instance Condition	4- Between Fair and Poor
Installation Year	1965
Source of Installation Year	Documented
Deficiency	SYSTEM DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE SYSTEM
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance Deficiency Quantity	Cafeteria-1st Floor - Students
· ·	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action Violations	LEVEL 2
	No violations recorded
Projection System Instance on 1st Floor - Students	Does not exist
Theater Lighting System	DOGS HOT CAIST
Instance on 1st Floor - Students	Does not exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE Lighting	Inspected Inspected
Lighting Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	2
Quantity Uom	EACH

Building Condition Assessment Survey 2023-2024

MIT
-

Building Condition Assessment Survey 2023-2024

Question	Dagnanga	
Z	Response	
GYMNASIUM		
Local Sound System		
Deficiency	AMPLIFIER NOT OPERATIONAL	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE SYSTEM	
Urgency of Action	PRIORITY 2	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Projection System		
Instance on 1st Floor	Does not exist	
Scoreboard		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Theater Lighting System		
Instance on 1st Floor	Does not exist	
KITCHEN	Inspected	
Instance on 1st Floor	Inspected	
Lighting	•	
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent	1	
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Does not exist	
Surface Mounted	Does not exist	
Instance on 1st Floor	Does not exist	
Recessed Mounted	Does not exist	
	Your sale d	
Instance on 1st Floor	Inspected 2- Between Good and Fair	
Instance Condition		
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Does not exist	
LIBRARY	Inspected	
Instance on Room 209	Inspected	
Lighting		
Instance on Room 209	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 209	Inspected	
Pendant Mounted		
Instance on Room 209	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room 209	Inspected	
Instance Condition	3- Fair	
1		
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on Room 209	Inspected	
Instance Condition	3- Fair	

Building Condition Assessment Survey 2023-2024

cirical inspection		W1140
Question	Response	
LIBRARY		
Lighting		
Lighting Fixture - Fluorescent		
Recessed Mounted		
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on Room 209	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 209	Does not exist	
Lighting Fixture - LED		
Instance on Room 209	Does not exist	
Raceway With Receptacles		
Instance on Room 209	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Projection System		
Instance on Room 209	Does not exist	
LOCKER ROOM	Inspected	
Instance on 1st Floor Behind Gymnasium	Inaccessible	
MULTIPURPOSE ROOM	Does not exist	
SCIENCE DEMO ROOM	Does not exist	
SCIENCE LAB	Does not exist	
SCIENCE PREP ROOM	Does not exist	
SWIMMING POOL	Does not exist	
TOILET ROOM - STAFF	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
TOILET ROOM - STUDENT	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
AUXILIARY SIGNAL/BELL SYSTEM	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
EMERGENCY DC STANDBY BATTERY POWER	Does not exist	
	Does not exist	
EMERGENCY GENERATOR SET		
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected	
Condition	3- Fair	

Building Condition Assessment Survey 2023-2024

Question	Response	
EMERGENCY LIGHT/EXIT LIGHT PANEL		
Deficiency	No deficiencies recorded	
EMERGENCY LIGHTING	Inspected	
Battery Pack	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Non Battery Pack	Inspected	
Condition	2- Between Good and Fair	
Deficiency	FIXTURE NOT OPERATIONAL	
Deficiency Location/Instance	Near Room 129 & 133	
Deficiency Quantity	2	
Quantity Uom	EACH	
Potential Action	REPAIR	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
EXIT LIGHT	Inspected	
Battery Pack	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
	Inspected	
Non Battery Pack Condition	3- Fair	
Deficiency	FIXTURE LAMP NOT OPERATIONAL	
Deficiency Location/Instance Deficiency Quantity	Exit 12	
	1 Decay	
Quantity Uom	EACH MADITED ANGE	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 5 LEVEL 2	
Purpose of Action		
Violations	No violations recorded	
EXIT/EMERGENCY LIGHT	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
FIRE ALARM SYSTEM	Inspected	
Bell/Horn	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Strobe	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Manual Pull Station	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fan Shutdown Control	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
	Inspected	
Duct Smoke Detector	3- Fair	
Condition		
Deficiency	No deficiencies recorded	
Area Smoke Detector	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
CO Detector	Does not exist	
Heat Detector	Does not exist	
Elevator Recall	Inspected	

Building Condition Assessment Survey 2023-2024

1142
Response
2- Between Good and Fair
No deficiencies recorded
Does not exist
Inspected
3- Fair
No deficiencies recorded
Does not exist
Inspected
Inspected
3- Fair
No deficiencies recorded
Does not exist
Inspected
Boiler Room
3- Fair
1
EACH
ACME
Fire Alarm
1965
Documented
BEYOND USEFUL LIFE
Boiler Room
91,000
S.F.
REPLACE
PRIORITY 1
LEVEL 2
No violations recorded
Inspected
Inspected
3- Fair
No deficiencies recorded
Inspected
Boiler Room
2- Between Good and Fair
1
EACH
Edwards System Technology
EST EST
Elevator Smoke Detector Recall Panel
2007
Documented
No deficiencies recorded
Boiler Room
3- Fair
1
EACH
Pyrotronics PS-35
r3-33
Holding Areas 2000

Building Condition Assessment Survey 2023-2024

uestion	Response
FIRE ALARM SYSTEM	
Sub-Panel	
Fire Alarm Control Panel (Electronic)	
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	Inspected
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	ACME
EquipmentId	Sprinkler Alarm System
Installation Year	1965
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	91,000
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	ACME
EquipmentId	Visual Fire Signal Indicator Cabinet
Installation Year	1965
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	91,000
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Remote Annunciator	Inspected
Display Monitor	Does not exist
Panel	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Printer	Does not exist
Punch Register	Does not exist
Sprinkler Flow/Air Pressure Switch	Under construction
Tamper Flow Switch/Chain	Under construction
ROUNDING SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
NTERCOM SYSTEM	Inspected
Elevator	Inspected
Condition	4- Between Fair and Poor
Deficiency	INTERCOM CABINET NOT OPERATIONAL
Deficiency Location/Instance	Inside Elevator near Staircase C
Deficiency Quantity	1

Building Condition Assessment Survey 2023-2024

intent Inspection		111110
Question	Response	
INTERCOM SYSTEM		
Elevator		
Quantity Uom	EACH	
Potential Action	REPAIR	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 6	
Violations	No violations recorded	
Holding Area	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
LAN	Inspected	
Local Distribution Frame (I/LDF)	Inspected	
Condition	2- Between Good and Fair	•
Deficiency	No deficiencies recorded	
Main Equipment Rack (MDF)	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
LIGHTNING PROTECTION	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
MOTOR CONTROLLER	Inspected	
MOTOR CONTROLLER MOTOR CONTROL CENTER	Does not exist	
MOTOR STARTER/CONTACTOR	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Variable Frequency Drive	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
PANEL BOARD	Inspected	
Fused Disconnect Switch Type Condition	Inspected 2- Between Good and Fair	
Deficiency	No deficiencies recorded	
	Does not exist	
Fused Knife Switch Type	Does not exist Does not exist	
Fused Toggle Switch Type Molded Case Circuit Breaker Type	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
PUBLIC ADDRESS SYSTEM	Inspected	
	General Office - Room 125	
Instance	3- Fair	
Instance Condition		
Instance Quantity	1 EACH	
Instance Quantity Uom	EACH	
Model	Dukane 125	
Installation Year	1965	
Source of Installation Year	Documented	
Deficiency Deficiency Location/Instance	BEYOND USEFUL LIFE General Office - Room 125	
Deficiency Location/Instance Deficiency Quantity		
Quantity Uom	91,000 S.F.	
Quantity Com Potential Action	S.F. REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
SECURITY	Inspected	

Building Condition Assessment Survey 2023-2024

icai Inspection	1411
uestion	Response
SECURITY	
IPDVS/CCTV System	Does not exist
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	Custodian's Office - Room 109
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista 128BPT
Installation Year	2015
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	2- Between Good and Fair
Deficiency	SENSOR NOT OPERATIONAL
Deficiency Location/Instance	Room 340
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Violations	No violations recorded
Panic Switch	Inspected
Condition	4- Between Fair and Poor
Deficiency	SWITCH NOT OPERATIONAL
Deficiency Location/Instance	Principal's Office
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Violations	No violations recorded
Remote Annunciator	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting - Security	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
SERVICE SWITCH	Inaccessible
SWITCHBOARD	Inaccessible
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
ΓRANSFORMER	Does not exist