Building Condition Assessment Survey 2023-2024

Mechanical Inspection M218

	Asset:	I.S. 218 - MANHATTAN, 4600 BROADWAY, MANHATTAN, NY, 10040		
	Inspection Id	Inspection Type	Time In	Last Edited
	2386	MECHANICAL	2024-01-11 09:15AM	2024-02-22 11:26AM
Ass	set Data			

2386 MECHANICAL	2024-01-11 09:15AM 2024-02-22 11:26AN
set Data	
Question	Answer
Have any Systems/Major Building Components been upgraded?	Systems: Climate Control System - Pneumatic System: Air Compressors, PRV Station
	Years: 2023
	Systems: Terminal Unit Thermostatic Traps; F&T/Steam Drip Trap (~60%); Steam Condensate Return Pumping System (1 of 2); Boiler Feedwater Treatment(Automatic)
	Years: 2020
	Systems: MDF Room - Dedicated A/C Equipment (DX Split System)
	Years: 2018
	Systems: Boiler Fresh Air Louver/Dampers; Fixtures - Toilets, Urinals
	Years: 2016
	Systems: Gas Meter Room Vent
	Years: 2015
	Systems: Kitchen - Grease Traps
	Years: 2014
Are there fuel tanks?	Yes
Total # of above ground tanks	1
Total capacity of all above ground tanks in gal.	1,000
Total # of below ground tanks	2
Total capacity of all below ground tanks in gal.	30,000
Total # of water main service entries to the asset	3
MERs/Fan Rooms Locations	MER B10, 3rd Floor MER, PH MER
Are there any spaces with Missing or Defective CO Detectors?	Yes
Location(s)	Kitchen, PH MER
Are there any Painted/Obstructed Sprinkler Heads?	Yes
Location(s)	Auditorium (painted, 8; obstructed, 18), Corridor near Room B1 (obstructed, 1)
Are there any Emergency Stop Switches with Missing Hammers?	No components

Priority Condition

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
Yes	Defective Fire/Smoke Damper	(4)	Metal Ductwork	Corridor by Custodian's Office B2; 3rd Floor MER @ RF-5; PH MER @ RF-19	William Clarke	Fireman	9#
No	Other	Defective handle.	Science Lab - Eye Wash	Room 414	William Clarke	Fireman	
No	Defective Boiler Safety Auxiliary	(2)	Boiler Safety Valve	Boiler Room @ Boiler #2	William Clarke	Fireman	

Building Condition Assessment Survey 2023-2024

ection	
Question	Response
lechanical	
AIR CONDITIONING	Inspected
Chilled Water System	Does not exist
Condenser Water Distribution: Piping, Pumps and Auxiliaries	Does not exist
Cooling Coil in Ductwork	Does not exist
Cooling Tower	Does not exist
DX Split System	Inspected
Indoor Unit	Inspected
Condition	3- Fair
Deficiency	UP TO 5 TONS:DEFECTIVE MOISTURE DRAINAGE (BASIN & TUBING)
Deficiency Location/Instance	Telephone Room 101A
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	UP TO 5 TONS:DEFECTIVE
Deficiency Location/Instance	Building Exterior - Camera Room 128
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Outdoor Unit	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Dry Cooler	Does not exist
Packaged / Rooftop Unit	Does not exist
Packaged Terminal A/C	Does not exist
Refrigerant Leak Detection System	Does not exist
Refrigerant Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Return Fan	Does not exist
CENTRAL ACID WASTE NEUTRALIZING TANK	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
CLIMATE CONTROL SYSTEM	Inspected
BMS	Does not exist
Pneumatic System	Inspected
Instance	Throughout
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Building Area Covered by Operational System	81-100%
Deficiency	DEFECTIVE DAMPER ACTUATOR
Deficiency Location/Instance	PH MER @ AH-6, AH-7
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3

Building Condition Assessment Survey 2023-2024

uestion	Response
CLIMATE CONTROL SYSTEM	
Pneumatic System	
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	DEFECTIVE TEMPERATURE CONTROL THERMOSTAT
Deficiency Location/Instance	Gymnasium, Room 429
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Hybrid System	Does not exist
Electric System	Does not exist
COMPACTOR	Does not exist
	Inspected
CONVEYING	Does not exist
Dumbwaiter El. (4)	
Elevator	Inspected 3- Fair
Condition	
Are all the existing elevators operable?	Yes
Deficiency	No deficiencies recorded
Escalator	Does not exist
Non-auditorium Handicap Lift - Vertical	Does not exist
Non-auditorium Handicap Lift - Stair	Does not exist
Ash Hoist	Does not exist
Sidewalk Elevator	Does not exist
DOMESTIC WATER SYSTEM	Inspected
Domestic Cold Water System	Inspected
Gravity System	Does not exist
Pressure Booster System	Does not exist
Water Service	Inspected
Instance	Water Meter Room B13
Instance Condition	3- Fair
Instance Quantity	3
Instance Quantity Uom	EACH
Deficiency	WATER MAIN:MISSING BACKFLOW PREVENTION DEVICE
Deficient Leading Leaders	
Deficiency Location/Instance	Water Meter Room B13
Deficiency Quantity	3 FACH
Quantity Uom	EACH
Potential Action	INSTALL PRICEITY 2
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Domestic Hot Water System	Inspected
Domestic Hot Water Remote Storage Tank	Does not exist
Domestic Water Heat Exchanger	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE AUXILIARIES(RELIEF VALVE, GAUGE, TEMPERATURE REGULATOR, ETC)
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

Building Condition Assessment Survey 2023-2024

uestion	Response
DOMESTIC WATER SYSTEM	•
Domestic Hot Water System	
Domestic Water Heat Exchanger	
Violations	No violations recorded
Deficiency	Flange Leaks
Deficiency Location/Instance Deficiency Quantity	Boiler Room
	1 FACH
Quantity Uom Potential Action	EACH MAINTENIANCE
	MAINTENANCE
Urgency of Action	PRIORITY 3 LEVEL 2
Purpose of Action	
Violations	No violations recorded
Electric Domestic Water Heater	Does not exist
Gas Fired Domestic Water Heater	Does not exist
Oil Fired Domestic Water Heater	Does not exist
Heat Pump Domestic Water Heater	Does not exist
Domestic Water Distribution Piping	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE BACKFLOW PREVENTER
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
DRAIN/WASTE/VENT AND STORM SYSTEM	Inspected
Interior Storm Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Sewage/Waste/Vent Piping	Inspected
Condition	3- Fair
Deficiency	SEWAGE/WASTE PIPING:DEFECTIVE/LEAKS
Deficiency Location/Instance	Room B10
Deficiency Quantity	10
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	INTERIOR FLOOR DRAIN:DEFECTIVE
Deficiency Location/Instance	Fuel Oil Pump Room B11, Toilet Rooms 406, 426
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	MAINTENANCE
	PRIORITY 3
Urgency of Action Purpose of Action	LEVEL 2
Purpose of Action Violations	
	No violations recorded
Sewage Ejector Pump	Inspected 3 Fair

Condition

Sump Pump Condition

Deficiency

Deficiency

DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)

3- Fair

Inspected

Does not exist

3- Fair

No deficiencies recorded

No deficiencies recorded

Building Condition Assessment Survey 2023-2024

писи тигресион	1412
estion	Response
IXTURES	Inspected
Staff And Other	Inspected
Janitor Sink	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lavatory/Sink	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Toilet	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Urinal	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Student Deiglie Ferrytein	Inspected Inspected
Drinking Fountain	-
Condition	3- Fair
Deficiency	CRACKED/PHYSICAL DAMAGE
Deficiency Location/Instance Deficiency Quantity	Gymnasium
	1 FACH
Quantity Uom Potential Action	EACH DEPLACE
	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Lavatory/Sink	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE AUXILIARY (FAUCET, SHUT OFF
	VALVE,ETC.)
Deficiency Location/Instance	Girls Locker Room, Toilet Room 206
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Locker Room Shower	Inspected
Instance on 2nd Floor - Boys	Inspected
Instance Condition	3- Fair
Alternative Use	Yes
Deficiency	No deficiencies recorded
Instance on 2nd Floor - Girls	Inspected
Instance Condition	3- Fair
Alternative Use	Yes
Deficiency	No deficiencies recorded
Sink And Fountain Combo Unit	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
	Inspected
Toilet	
Condition	2- Between Good and Fair
Deficiency	CRACKED/PHYSICAL DAMAGE
Deficiency Location/Instance	1st Floor Girl's Toilet Room
Deficiency Quantity	1
Quantity Uom	EACH

Building Condition Assessment Survey 2023-2024

uestion	Dosponso
uestion	Response
FIXTURES	
Student	
Toilet	
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Urinal	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
GAS FIRED FURNACE	Does not exist
GAS SERVICE	Inspected
Gas Distribution Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Gas Meter Room Exhaust Fan	Does not exist
Gas Meter Room Vent	Inspected 1- Good
Condition	
Deficiency	No deficiencies recorded
Gas Pressure Booster	Inspected
Instance	Basement - Gas Meter Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Spencer
EquipmentId	N/A
Capacity/Size Quantity	5
Capacity/Size UOM	HP
Source of Capacity/Size	Documented
Installation Year	1991
Source of Installation Year	Documented
Deficiency	NOT IN USE
Deficiency Location/Instance	Basement - Gas Meter Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	NO ACTION
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 1
Violations	No violations recorded
CO/Gas Leak Detection	Does not exist
HEATING	Inspected
Heating Coil In Ductwork	Does not exist
Hydronic Heating	Does not exist
Radiator/Convector/Fin Tube	Inspected
Condition	3- Fair
Deficiency	AUXILIARY (VALVE, VENT): DEFECTIVE
Deficiency Location/Instance	Room 434
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	RADIATOR/CONVECTOR:DEFECTIVE/DETERIORATED
Deficiency Location/Instance	Stairs "C/2", "B/5"

Building Condition Assessment Survey 2023-2024

nunicui Inspection	141210
Question	Response
HEATING	
Radiator/Convector/Fin Tube	
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Steam Heating	Inspected
F&T/Steam Drip Trap	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
MER Steam and Condensate Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Steam Condensate Return Piping	Inspected
Condition Condensate Return Figure Condition	3- Fair
Deficiency	No deficiencies recorded
Steam Condensate Return Pumping System	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Steam Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Terminal Unit Thermostatic Trap	Inspected
Condition	1- Good
Deficiency	DEFECTIVE/DETERIORATED
Deficiency Location/Instance	Room 429
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Steam supplied by External Sources	Does not exist
Unit Heater/Cabinet Heater	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
HEATING PLANT	Inspected
Instance on Basement	Inspected
Is there a water meter on the boiler make-up water piping?	No
Burner Manufacturer	Preferred Utilities
Burner Model	BHE 7 3M4
Burner Type	Oil
Heating Plant Oil Number	4
Boiler Auxiliaries	
Instance on Basement	Inspected
Boiler Auxiliary Piping	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	DEFECTIVE BOILER AUTOMATIC FEEDWATER VALVE
Deficiency Location/Instance	Boiler Room @ Boiler #3
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE

estion	Response
EATING PLANT	
Boiler Auxiliaries	
Boiler Auxiliary Piping	
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	DEFECTIVE BLOWDOWN PIPING
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	Boner Room
Quantity Uom	EACH
Potential Action	MAINTENANCE
	PRIORITY 3
Urgency of Action	LEVEL 2
Purpose of Action	
Violations	No violations recorded
Deficiency	DEFECTIVE BOILER FEEDWATER PIPING
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Boiler Emergency Stop Switch	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Boiler Feedwater System	
Instance on Basement	Inspected
Instance Condition	3- Fair
	*
Deficiency	FEEDWATER PUMP:DEFECTIVE
Deficiency Location/Instance Deficiency Quantity	Boiler Room 1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Boiler Feedwater Treatment(Automatic)	
Instance on Basement	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Boiler Flue Exhaust	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	BOILER DAMPER IN BREECHING: DEFECTIVE DAMPER
Deficiency	ACTUATOR
Deficiency Location/Instance Deficiency Quantity	Boiler Room @ Boilers #2, #3
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Boiler Make-up Water Backflow Preventer	
Instance on Basement	Inspected
Instance Condition	3- Fair

Building Condition Assessment Survey 2023-2024

nanical Inspection		
Question	Response	
HEATING PLANT		
Boiler Auxiliaries		
Boiler Make-up Water Backflow Preventer		
Deficiency	No deficiencies recorded	
Boiler Room Steam And Condensate Piping		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Boiler Safety Valve		
Instance on Basement	Inspected	
Instance Condition	4- Between Fair and Poor	
Deficiency	DEFECTIVE	
Deficiency Location/Instance	Boiler Room @ Boiler #2	
Deficiency Quantity	2	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 6	
Violations	No violations recorded	
Boiler System		
Instance on Basement	Inspected	
Coal-fired Boiler		
Instance on Basement	Does not exist	
Hot Water Boiler		
Instance on Basement	Does not exist	
Modular Boiler		
Instance on Basement	Does not exist	
Steam Boiler		
Instance on Basement	Inspected	
Instance on Basement	Inspected	
Instance	Boiler Room	
Instance Condition	3- Fair	
Instance Quantity	4,301	
Instance Quantity Uom	MBH NET	
Cast Iron Boiler?	No	
Manufacturer	Kewanee Boiler Corporation	
EquipmentId	5281-1	
Capacity/Size Quantity	5540	
Capacity/Size UOM	MBH Gross	

Documented 1991

Documented

Boiler Room 3- Fair

4,301 MBH NET

No

5281-2

MBH Gross

Documented

Documented

5540

1991

No deficiencies recorded

Kewanee Boiler Corporation

Source of Capacity/Size

Installation Year Source of Installation Year

 $\frac{Instance\ Condition}{Instance\ Quantity}$

Manufacturer EquipmentId

Instance Quantity Uom
Cast Iron Boiler?

Capacity/Size Quantity

Source of Capacity/Size

Source of Installation Year

Capacity/Size UOM

Installation Year

Deficiency

Instance

inical Inspection		M2
estion		Response
HEATING PLANT		
Boiler System		
Steam Boiler		
Deficiency		No deficiencies recorded
Instance		Boiler Room
Instance Con	dition	3- Fair
Instance Qua	ntity	4,301
Instance Qua	ntity Uom	MBH NET
Cast Iron Bo	· · · · · · · · · · · · · · · · · · ·	No
Manufacture		Kewanee Boiler Corporation
EquipmentId		5281-3
Capacity/Size	e Quantity	5540
Capacity/Size	e UOM	MBH Gross
Source of Ca	pacity/Size	Documented
Installation Y	ear	1991
Source of Ins	tallation Year	Documented
Deficiency		No deficiencies recorded
Fuel System		
Instance on F	Basement	Inspected
Boiler Fresh Air Lo	uver/Damper	
Instance on F	Basement	Inspected
Instance Con	dition	1- Good
Туре		Automatic
Deficiency		No deficiencies recorded
Burner/Burner Cor	trol Panel	
Instance on E		Inspected
Instance Con		3- Fair
Deficiency		OIL BURNER:DEFECTIVE
	Location/Instance	Boiler Room @ Boiler #1
Deficiency		1
Quantity U		EACH
Potential A		MAINTENANCE
Urgency of		PRIORITY 3
Purpose of		LEVEL 2
Violations	Action	No violations recorded
Deficiency		OIL BURNER:DEFECTIVE
	Location/Instance	
Deficiency		Boiler Room @ Boiler #3
		1 EACH
Quantity U Potential A		EACH REPAIR
		PRIORITY 3
Urgency of Purpose of		LEVEL 2
Violations	ACIOII	No violations recorded
		INO VIOIATIONS PECOFICEU
Fuel Oil Storage/Su		Towns and J
Instance on E		Inspected
Instance Con	dition	3- Fair
Deficiency	*	FUEL OIL LEVEL GAUGE:DEFECTIVE
	Location/Instance	Boiler Room
Deficiency		2
Quantity U		EACH
Potential A		MAINTENANCE
Urgency of		PRIORITY 3
Purpose of	Action	LEVEL 2
Violations		No violations recorded
Deficiency		FUEL OIL TRANSFER PUMP:DEFECTIVE
•	Location/Instance	Fuel Oil Transfer Pump Room B11

Mechanicai Inspection	MI218

uestion	Response	
HEATING PLANT		
Fuel System		
Fuel Oil Storage/Supply System		
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Gas Trains And Vent At The Boiler		
Instance on Basement	Does not exist	
Enclosed IDF Room	Inspected	
Instance on Rooms 422, 522	Inspected	
	Inspected	
Dedicated A/C Equipment	Incorporated	
Instance on Rooms 422, 522	Inspected 4- Between Fair and Poor	
Instance Condition		
Deficiency	DOES NOT EXIST	
Deficiency Location/Instance	Rooms 422, 522	
Deficiency Quantity	2	
Quantity Uom	EACH	
Potential Action	INSTALL	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
KITCHEN	Inspected	
Instance on 1st Floor	Inspected	
CO Detector		
Instance on 1st Floor	Inspected	
Instance Condition	4- Between Fair and Poor	
Deficiency	DEFECTIVE/MISSING	
Deficiency Location/Instance	Kitchen	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 6	
Violations	No violations recorded	
Gas System		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Grease Trap		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
	No deficiencies recorded	
Instance on 1st Floor	Ingressted	
	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Hood Exhaust Ductwork		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Hood Exhaust Fan		
Instance on 1st Floor	Inspected	

Mechanical Inspection	M218

Question	Response
KITCHEN	
Hood Exhaust Fan	
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Hood Fire Suppression System	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Hot Water Temperature Booster	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Kitchen Sink	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	Missing Air Gap
Deficiency Location/Instance	Kitchen (1 of 3)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action Urgency of Action	MAINTENANCE PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
MDF Room	Inspected
Instance on Room 140A	Inspected
	inspected
Dedicated A/C Equipment Instance on Room 140A	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
SCIENCE DEMO ROOM	Does not exist
SCIENCE LAB	Inspected
Instance on Rooms 310, 314	Inspected
Alternative Use	No
Instance on Room 312	Inspected
Alternative Use	Yes
Instance on Rooms 410, 412	Inspected
Alternative Use	No
Instance on Room 414	Inspected
Alternative Use	No
Acid Waste Neutralizing Tank	Description of the second of t
Instance on Rooms 310, 314	Does not exist
Instance on Room 312	Does not exist Does not exist
Instance on Rooms 410, 412 Instance on Room 414	
	Does not exist
CO Detector Instance on Rooms 310, 314	Not required
Instance on Rooms 310, 314	Not required
Instance on Rooms 410, 412	Not required
Instance on Rooms 410, 412 Instance on Room 414	Not required
Emergency Shower	not required
Instance on Rooms 310, 314	Does not exist
Instance on Rooms 312	Does not exist
Instance on Rooms 410, 412	Does not exist
Instance on Rooms 414	Does not exist
mountee on Room 717	2000 Mot William

Question	Response	
SCIENCE LAB		
Eye Wash		
Instance on Rooms 310, 314	Does not exist	
Instance on Room 312	Does not exist	
Instance on Rooms 410, 412	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 414	Inspected	
Instance Condition	4- Between Fair and Poor	
Deficiency	DEFECTIVE	
Deficiency Location/Instance	Room 414	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 6	
Violations	No violations recorded	
Hood Exhaust Ductwork	The Mountain 1990 and	
Instance on Rooms 310, 314	Does not exist	
Instance on Room 312	Does not exist	
Instance on Rooms 410, 412	Does not exist	
Instance on Room 414	Does not exist	
	Does not exist	
Hood Exhaust Fan Instance on Rooms 310, 314	Does not exist	
Instance on Room 312	Does not exist	
Instance on Rooms 410, 412	Does not exist	
Instance on Room 414	Does not exist	
Fixed Laboratory Hood		
Instance on Rooms 310, 314	Does not exist	
Instance on Room 312	Does not exist	
Instance on Rooms 410, 412	Does not exist	
Instance on Room 414	Does not exist	
Laboratory Sink		
Instance on Rooms 310, 314	Inspected	
Instance Condition	3- Fair	
Deficiency	DEFECTIVE	
Deficiency Location/Instance	Room 314	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Instance on Room 312	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Rooms 410, 412	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 414	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Make-up Air Unit	1 to deficioness recorded	
Instance on Rooms 310, 314	Does not exist	
	DOG HOL CAISE	

Building Condition Assessment Survey 2023-2024

anicai inspection	141216
uestion	Response
SCIENCE LAB	
Make-up Air Unit	
Instance on Rooms 410, 412	Does not exist
Instance on Room 414	Does not exist
SCIENCE PREP ROOM	Does not exist
SPRINKLERS, STANDPIPE, FIRE SYSTEM	Inspected
Dry Sprinkler Alarm Valve Assembly	Does not exist
Wet Sprinkler Alarm Valve Assembly	Inspected
Condition	3- Fair
Deficiency	NOT IN USE
Deficiency Location/Instance	Water Meter Room B13
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	NO ACTION
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 1
Violations	No violations recorded
Fire Booster Pump Assembly	Does not exist
Roof Tank	Does not exist
Siamese Connection	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Sprinkler Head	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE/DETERIORATED
Deficiency Location/Instance	Auditorium (painted, 8; obstructed, 18), Corridor near Room B1
•	(obstructed, 1)
Deficiency Quantity	27
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Sprinkler Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Standpipe System	Inspected
Hose Valve Assembly	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE FIRE HOSE CABINET
Deficiency Location/Instance	Stairs "E/2", "B/3", "A/5", "B/5", "C/5"
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Water Gong	Does not exist
SWIMMING POOL	Does not exist Does not exist
S VY LIVILING FUUL	DOCS HOT CAIST
	In an and all
VENTILATION Is the building Mechanically ventilated?	Inspected Yes

Building Condition Assessment Survey 2023-2024

estion	Response
ENTILATION	
Exhaust Fan	
Condition	3- Fair
Approximate Total # of Fans	1-25
Deficiency	No deficiencies recorded
Heating And Ventilating Unit	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE CONTROLS
Deficiency Location/Instance	3rd Floor Mechanical Room / AH-5
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Metal Ductwork	Inspected
Condition	3- Fair
Are there any uninsulated ductwork by design in Mechanical rooms?	Yes
Are there chain operated dampers?	No
Deficiency	DEFECTIVE REGISTER/DIFFUSER
Deficiency Location/Instance	Room B12, Gymnasium, Girls Locker Room
Deficiency Quantity	6
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	DEFECTIVE DUCTWORK
Deficiency Location/Instance	Room B9
Deficiency Quantity	10
Quantity Uom	L.F.
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	DEFECTIVE FIRE/SMOKE DAMPER
Deficiency Location/Instance	Corridor by Custodian's Office B2; 3rd Floor MER @ RF-5; PH
·	MER @ RF-19
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Supply Fan	Does not exist