Building Condition Assessment Survey 2023-2024

Asset: PRE-K CENTER @ 2-26 WASHINGTON ST - NY, 10004	- MANHATT	AN, 2-26 WASH	INGTON STE	REET, MANH	IATTAN,
Inspection Id Inspection Type			Time 1	ĺn	Last Edited
1681 MECHANICAL			2023-	12-14 12:15PM	2024-01-15 10:50AM
set Data					
Question		Answer			
Have any Systems/Major Building Components been upgraded?		No Syster	n Upgraded		
Are there fuel tanks?		No	10		
Total # of water main service entries to the asset		0			
MERs/Fan Rooms Locations		MER 224	; Mezzanine ME	ER	
Are there any spaces with Missing or Defective CO Detectors?		No			
Are there any Painted/Obstructed Sprinkler Heads?		Yes			
Location(s)		Room 208	3, 219 (painted, 5	5)	
Are there any Emergency Stop Switches with Missing Hammers?		No compo	nents		
iority Condition					
xist Priority Condition	Component	Location	Person(s)	Person(s)	Photo
·	Affected	Description	Notified	Title	Image
No condition recorded					
spection					
Question		Response			
Mechanical					
AIR CONDITIONING		Inspected			
Chilled Water System		Inspected			
Absorption Chiller		Does not	exist		
Air Cooled Chiller		Does not	exist		
Air Cooled Condenser		Does not	exist		
Chilled Water Distribution: Piping, Pumps and Auxiliaries		Inspected			
Condition		1- Good			
Deficiency		No deficie	encies recorded		
Backflow Preventer		Does not	exist		
Central Station Air Handler		Inspected			
Instance		MER 224			
Instance Condition		1- Good			
Instance Quantity		1			
Instance Quantity Uom		EACH			
Manufacturer		Trane			
EquipmentId		DOAS-1			
Capacity/Size Quantity		3			
Capacity/Size UOM		Fan Moto			
Source of Capacity/Size		Documen	ted		
Installation Year		2015			
Source of Installation Year		Documen			
Deficiency			encies recorded		
Fan Coil Unit		Inspected			
Condition		1- Good			
Deficiency			encies recorded		
Packaged Air Cooled Chiller		Does not			
Water Cooled Chiller		Does not			
Condenser Water Distribution: Piping, Pumps and Auxiliaries		Does not			
Cooling Coil in Ductwork		Does not			
Cooling Tower		Does not	exist		
DX Split System		Inspected			
Indoor Unit		Inspected			
Condition		2- Betwee	n Good and Fair	r	

Building Condition Assessment Survey 2023-2024

Mechanical Inspection	M391
-----------------------	------

Question	Response
AIR CONDITIONING	
DX Split System	
Indoor Unit	
Deficiency	UP TO 5 TONS:DEFECTIVE
Deficiency Location/Instance	Main Lobby
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Outdoor Unit	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Dry Cooler	Does not exist
Packaged / Rooftop Unit	Does not exist
Packaged Terminal A/C	Does not exist
Refrigerant Leak Detection System	Does not exist
Refrigerant Piping	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Return Fan	Does not exist
CENTRAL ACID WASTE NEUTRALIZING TANK	Does not exist
CLIMATE CONTROL SYSTEM	Inspected
BMS	Does not exist
Pneumatic System	Does not exist
Hybrid System	Does not exist
Electric System	Inspected
Instance	Throughout
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Building Area Covered by Operational System	81-100%
Deficiency	DEFECTIVE TEMPERATURE CONTROL THERMOSTAT
Deficiency Location/Instance	Rooms 209, 214
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
COMPACTOR	Does not exist
CONVEYING	Does not exist
DOMESTIC WATER SYSTEM	Inspected
Domestic Cold Water System	Does not exist
Domestic Hot Water System	Inspected
Domestic Hot Water Remote Storage Tank	Does not exist
Domestic Water Heat Exchanger	Does not exist
Electric Domestic Water Heater	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Gas Fired Domestic Water Heater	Does not exist
Oil Fired Domestic Water Heater	Does not exist
Heat Pump Domestic Water Heater	Does not exist
Domestic Water Distribution Piping	Inspected

Building Condition Assessment Survey 2023-2024

Mechanical Inspection M391

aicai Inspeciion	[VI.	
estion	Response	
OMESTIC WATER SYSTEM		
Domestic Water Distribution Piping		
Condition	1- Good	
Deficiency	No deficiencies recorded	
RAIN/WASTE/VENT AND STORM SYSTEM	Inspected	
Interior Storm Piping	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Sewage/Waste/Vent Piping	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Sewage Ejector Pump	Does not exist	
Sump Pump	Does not exist	
UAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	Does not exist	
XTURES	Inspected	
Staff And Other	Inspected	
Janitor Sink	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Lavatory/Sink	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Toilet	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Urinal	Does not exist	
Student	Inspected	
Drinking Fountain	Inspected	
Condition	2- Between Good and Fair	
Deficiency	DEFECTIVE AUXILIARY (FAUCET, SHUT OFF	
	VALVE,ETC.)	
Deficiency Location/Instance	Corridor near Room 218	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Lavatory/Sink	Inspected	
Condition	2- Between Good and Fair	
Deficiency	DEFECTIVE AUXILIARY (FAUCET, SHUT OFF VALVE,ETC.)	
Deficiency Location/Instance	Rooms 203, 214, 218, 219	
Deficiency Quantity	4	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Locker Room Shower	Does not exist	
Sink And Fountain Combo Unit	Does not exist	
Toilet	Inspected	
Condition	2- Between Good and Fair	

Building Condition Assessment Survey 2023-2024

Mec	echanical Inspection	M391

Question	Response	
FIXTURES		
Student		
Urinal	Does not exist	
GAS FIRED FURNACE	Does not exist	
GAS SERVICE	Does not exist	
HEATING	Inspected	
Heating Coil In Ductwork	Does not exist	
Hydronic Heating	Inspected	
Hydronic Hot Water Distribution: Piping, Pumps and Auxiliaries	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Backflow Preventer	Does not exist	
Hot Water Heat Exchanger	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Radiator/Convector/Fin Tube	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Steam Heating	Inspected	
F&T/Steam Drip Trap	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
MER Steam and Condensate Piping	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Steam Condensate Return Piping	Does not exist	
Steam Condensate Return Pumping System	Does not exist	
Steam Piping	Does not exist	
Terminal Unit Thermostatic Trap	Does not exist	
Steam supplied by External Sources	Does not exist	
Unit Heater/Cabinet Heater Condition	Inspected 1- Good	
Deficiency	No deficiencies recorded	
-		
HEATING PLANT	Does not exist	
Enclosed IDF Room	Does not exist	
KITCHEN	Inspected	
Instance on 2nd Floor	Inspected	
CO Detector	NY	
Instance on 2nd Floor	Not required	
Gas System Instance on 2nd Floor	Does not exist	
Grease Trap	Does not exist	
Instance on 2nd Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Hood		
Instance on 2nd Floor	Does not exist	
Hood Exhaust Ductwork		
Instance on 2nd Floor	Does not exist	
Hood Exhaust Fan		
Instance on 2nd Floor	Does not exist	
Hood Fire Suppression System		
Instance on 2nd Floor	Does not exist	
Hot Water Temperature Booster		

Building Condition Assessment Survey 2023-2024

Mechanical Inspection M391

unicui inspection		
uestion	Response	
KITCHEN		
Hot Water Temperature Booster		
Instance on 2nd Floor	Does not exist	
Kitchen Sink		
Instance on 2nd Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
•	Inspected	
MDF Room		
Instance on Room 222A	Inspected	
Dedicated A/C Equipment		
Instance on Room 222A	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
SCIENCE DEMO ROOM	Does not exist	
SCIENCE LAB	Does not exist	
SCIENCE PREP ROOM	Does not exist	
SPRINKLERS, STANDPIPE, FIRE SYSTEM	Inspected	
Dry Sprinkler Alarm Valve Assembly	Does not exist	
Wet Sprinkler Alarm Valve Assembly	Does not exist	
Fire Booster Pump Assembly	Does not exist	
Roof Tank	Does not exist	
Siamese Connection	Does not exist	
Sprinkler Head	Inspected	
Condition	2- Between Good and Fair	
Deficiency	DEFECTIVE/DETERIORATED	
Deficiency Location/Instance	Room 208, 219 (painted, 5)	
Deficiency Quantity	5	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 6	
Violations	No violations recorded	
Sprinkler Piping	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
·	Does not exist	
Standpipe System Water Gong	Does not exist Does not exist	
SWIMMING POOL	Does not exist	
VENTILATION	Inspected	
Is the building Mechanically ventilated?	Yes	
Exhaust Fan	Inspected	
Condition	2- Between Good and Fair	
Approximate Total # of Fans	1-25	
Deficiency	No deficiencies recorded	
Heating And Ventilating Unit	Does not exist	
Metal Ductwork	Inspected	
Condition	1- Good	
Are there any uninsulated ductwork by design in Mechanical rooms?	No	
Are there chain operated dampers?	No	
Deficiency	No deficiencies recorded	
Supply Fan	Does not exist	