# **Building Condition Assessment Survey 2023-2024**

Architectural Inspection M491

Asset:	PRE-K CENTER @ 1683 3RD AVENUE - MANHATTAN, 1683 3RD AVENUE, MANHATTAN, NY, 10128		
Inspection Id	Inspection Type	Time In	Last Edited
2238	ARCHITECTURAL - SENIOR	2024-01-08 07:47AM	2024-02-02 10:36AM
2286	ARCHITECTURAL - ASSOCIATE	2024-01-08 08:35AM	2024-01-08 11:21AM

#### Asse

Comments on the Number of Classrooms

Weather

Facade Photo

set Data		
Question		Answer
Was the Building Fully Accessib	le for Inspection?	No
Inspection Inaccessible Commen	nt	Roof and Basement (no permission)
Principal(s) Information		
	Principal Name	Daliah Singh
	Principal Organization	Pre-K Center Third Avenue - Manhattan
	Meeting with Principal?	No
	Principal Feedback	The Principal's comments are as follows: 1. Air ventilation system in the nurse's office is not working properly and needs to be repaired.
Custodian		Alonzo Carr
Was the Custodian Present?		Yes
Fireman		Maggalie Valez (Handywomen)
Was the Fireman Present?		Yes
Building Square Footage		15,000
Comments on the Area (for Athle	etic Field, Playing Surfaces, Leased Spaces)	None
Comments on the Stories (Floors	s) plus Basements	1 (No Basement)
Comments on the Year Built		2016
Student Population		64
Staff Population		24

Fair



Corner of 3rd Avenue and East 95th Street - South View

#### **Building Condition Assessment Survey 2023-2024**

#### **Architectural Inspection**

Main Entrance Photo

M491



Photo

Image

Assistive

Fire

Facade B - 3rd Avenue

Not taken

No

No Storm Water Management Type Selected

No System Upgraded

No New Construction

No Tandem

Yes 2018

Partial Inspection

Roof Photo

Do Stormwater Management/Green Infrastructure systems exist?

Type

Have any Systems/Major Building Components been upgraded?

Have there been any New Building Additions?

Tandem

Leased Space?

Year Leased

Inspection Type

**Priority Condition** 

Exist	Priority	Condition	Component	Location	Person(s)	Person(s)
Last Year?	Category	Description	Affected	Description	Notified	Title

No condition recorded

#### Structural Engineer Required

Structural	Condition	Component	Location	Person(s)	Person(s)	Photo
Condition Type	Description	Affected	Description	Notified	Title	Image

No condition recorded

#### Programmatic Accessibility

Programmatic Accessibility Status Question	Response	
Is the Primary or secondary entrance on an accessible route?	Yes	
Is the building a multi-story building?	Yes	
Are All floors of the building accessible through compliant means?	Yes	
Accessible classrooms exists on each floor?	Yes	
Boys and Girls or Unisex accessible toilets exist on at least every other floor?	Yes	
If the following spaces exist, are they ALL accessible? Art Room, Auditorium,	Yes	
Cafeteria, Computer, Gymnasiums, Library, Multipurpose Room, Science Labs		


Physical Bre	eakdown Structure	Exists	Complies	Required	Deficiency	Listening	Alarm
						System	Strobe
PROGRAM	MATIC ACCESSIBILITY						
Exterior	Routes						
Ext	terior Entrances & Exits		Yes				
Ext	terior H/C Lifts	No		No			
Ext	terior Ramps and Railings	No		No			
Interior	Routes						
Cor	rridor and Lobby H/C Lifts	No		No			
Inte	erior Corridor Doors And	Yes	Yes				
Hai	rdware						
Inte	erior Corridors & Lobbies		Yes				

## **Building Condition Assessment Survey 2023-2024**

## Architectural Inspection

Physical Breakdown St	ructure	Exists	Complies	Required	Deficiency	Assistive Listening System	Fire Alarm Strobe
Interior Eleva	tors	No				System	Strobe
Interior Lobb	y Doors And Hardware		Yes				
Interior Ramp	os	No					
Rooms & Spaces							
Art Rooms		No					
Auditorium		No					
Cafeteria		No					
Classrooms							
	1st Floor	Yes	Yes				
Computer Roo	oms	No					
Gymnasium		No					
Library		No					
Main Office							
	Room 133	Yes	Yes				
Multi-purpose	Room						
	Room 125	Yes	Yes			No	Yes
Nurse's Office	,						
	Room 1	Yes	Yes				
Pool		No					
Science Lab		No					
Toilet Rooms	(boys)						
	Room 130, also inside Classroom	Yes	Yes				
Toilet Rooms	(girls)						
	Room 130, also inside Classroom	Yes	Yes				
Toilet Rooms	·			<u> </u>			<u> </u>
	Room 131	Yes	Yes				

### **Building Template**



M491


#### Inspection

Question	Response

## **Building Condition Assessment Survey 2023-2024**

Architectural Inspection	M491
Architecturui Inspection	141471

nestion	Response
chitectural	
EXTERIOR	Inspected
AREAWAY	Does not exist
AWNINGS AND CANOPIES	Does not exist
CHIMNEY	Does not exist
COPING	Does not exist
CORNICE	Does not exist
DOORS	Inspected
DOORS AND FRAMES	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
DOOR HARDWARE	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
LINTELS	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
TRANSOM/SIDE LIGHT	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
EXTERIOR WALLS	Inspected
Material Type(s)	Masonry
Replacement Quantity	1,750
Replacement Uom	S.F.
Instance on All Facades	Inspected
Instance Condition	2- Between Good and Fair
Instance Quantity	1,750
Instance Quantity Uom	S.F.
Deficiency	STONE:DETERIORATED JOINTS



Elevation

Roof Plan Reference



Elevation Reference Facade C Deficiency Quantity 20 L.F. Quantity Uom Potential Action REPOINT Urgency of Action PRIORITY 3 Purpose of Action LEVEL 2

#### **Building Condition Assessment Survey 2023-2024**

## Architectural Inspection M491

#### EXTERIOR

Question

#### EXTERIOR WALLS

VAULTS-BUNKERS

Deficiency

CLASSROOMS/CORRIDORS/ADMIN SPACES

Deficiency Location/Instance

Deficiency Quantity

AUDITORIUM

CAFETERIA

Ceiling Condition

Deficiency Photo 1



Response

	Facade C
Deficiency Photo 2	No photo recorded
Violations	No violations recorded
EXTERIOR SOFFITS	Does not exist
LOADING DOCK	Does not exist
LOUVER	Does not exist
PARAPETS	Not required
PLAZA DECK	Does not exist
ROOF	Not required
STAIRS/RAMPS: EXTERIOR	Does not exist
WINDOWS	Inspected
Replacement Quantity	1,500
Replacement Uom	S.F.
EXTERIOR GUARDS	Does not exist
LINTELS	Does not exist
WINDOWS	Inspected
Material Type(s)	Aluminum
Instance on Aluminum - Other:All Facades	Inspected
Instance Condition	1- Good
Instance Quantity	1,500
Instance Quantity Uom	S.F.
Installation Year	2018
Source of Installation Year	Documented
Are these windows insulated?	Yes
Deficiency	No deficiencies recorded
INTERIOR	Inspected
POOLS	Does not exist
STRUCTURAL	Inspected
COLUMNS/BEAMS/BEARING WALLS	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
FLOOR STRUCTURE	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
FOUNDATION WALLS	Inaccessible
ROOF STRUCTURE	Not required

Does not exist

Does not exist

Does not exist Inspected

2- Between Good and Fair

Main Entrance Lobby

GYPSUM BOARD: DAMAGED/DETERIORATED

Inspected

40

## **Building Condition Assessment Survey 2023-2024**

uestion	Response
INTERIOR	•
CLASSROOMS/CORRIDORS/ADMIN SPACES	
Ceiling	
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo 1	EBVEL 2
Deficiency Filoto 1	
	Main Entrance Lobby
Deficiency Photo 2	No photo recorded
Violations	No violations recorded
Door(s)	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Floor Finish	Inspected
Condition	2- Between Good and Fair
Deficiency	VINYL TILES:DETERIORATED SUBSTRATE
Deficiency Location/Instance	Corridor near Room 104
Deficiency Quantity	60
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo 1	Corridor near Room 104
Deficiency Photo 2	No photo recorded
Violations	No violations recorded
Walls	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Specialties	Does not exist
GYMNASIUM	Does not exist
INTERIOR DOOR HARDWARE	Inspected
Condition	2- Between Good and Fair
Condition	No deficiencies recorded
Deficiency	No deficiencies recorded
-	Does not exist
Deficiency	
Deficiency INTERIOR GUARDS	Does not exist

Instance Condition

2- Between Good and Fair

## **Building Condition Assessment Survey 2023-2024**

ectural Inspection estion	Response	
NTERIOR	response	
KITCHEN		
Ceiling		
Deficiency	No deficiencies recorded	
Door(s)	1.0 441101011010110101	
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Floor Finish		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Walls	1.0 441101011010110101	
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
LIBRARY	Does not exist	
LOCKER ROOM	Does not exist	
MULTI-PURPOSE ROOM	Inspected	
Instance on Room 125	Inspected	
Ceiling		
Instance on Room 125	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Door(s)		
Instance on Room 125	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Fixed Equipment		
Instance on Room 125	Does not exist	
Floor Finish		
Instance on Room 125	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Sliding-folding Partition		
Instance on Room 125	Does not exist	
Stage		
Instance on Room 125	Does not exist	
Walls		
Instance on Room 125	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Window Curtains/Shades/Blinds		
Instance on Room 125	Does not exist	
SCIENCE DEMO ROOM	Does not exist	
SCIENCE LAB	Does not exist	
SCIENCE PREP ROOM	Does not exist	
SHOWER ROOM	Does not exist	
STAIRS/RAMPS: INTERIOR	Inspected	
Do Letter Stair Signs Exist?	No	
Ceiling	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Door(s)	Inspected	

#### **Building Condition Assessment Survey 2023-2024**

Duestion	Response	
	Response	
INTERIOR  CTAINS (DAMES INTERIOR		
STAIRS/RAMPS: INTERIOR  Door(s)		
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Partition	Does not exist	
Railings	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Stairs and Landings	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Walls	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
TOILET ROOMS - STAFF	Inspected	
Ceiling	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Door(s)	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Floor Finish	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Stalls	Does not exist	
Walls	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
TOILET ROOMS - STUDENTS	Inspected	
Ceiling	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Door(s)	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Floor Finish	Inspected	
Condition	2- Between Good and Fair	

No deficiencies recorded

2- Between Good and Fair

No deficiencies recorded

Does not exist

Inspected

Inspected

Inspected

Does not exist

Deficiency

Deficiency

F.D. HOLDING AREA

CONTAINERIZATION

DRINKING FOUNTAINS

DRAINAGE SYSTEM FOR ASPHALT DRAINAGE SYSTEM FOR CONCRETE

DRAINAGE SYSTEM FOR SOIL

Stalls

Walls Condition

LIFE SAFETY

**FENCES** 

SITE

STEEL STAIRS

## **Building Condition Assessment Survey 2023-2024**

## Architectural Inspection M491

uestion	Response
SITE	
IRRIGATION SYSTEM	Does not exist
PAVING	Inspected
Student Non-Use	Does not exist
Student Use	Does not exist
Site Sidewalks & Walkways	Does not exist
DOT Sidewalk	Inspected
Asphalt	Does not exist
Concrete	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Pavers	Does not exist
PLAYGROUNDS	Does not exist
PLAYING SURFACE	Does not exist
RETAINING WALLS	Does not exist
SEATING	Does not exist
SITE WALLS (NOT RETAINING WALLS)	Does not exist
STAIRS/RAMPS: EXTERIOR	Does not exist

# NYC Department of Education Building Condition Assessment Survey 2023-2024

Architectural Inspection M491

Does the SCA expect asset to have artwork?

No