### **Building Condition Assessment Survey 2023-2024**

### **Electrical Inspection**

Increation Id Incre-4	tion Type			T:	In	Last Edited
	tion Type			Time		
198 ELECT	RICAL			2023-	10-16 09:56AM	1 2023-10-16 03:13PM
sset Data						
Question		-	Answer	A 11 G	10	
Have any Systems/Majo	or Building Components been upgraded	?	Systems:	-	nd Components	
<b>T</b> 10			Years:	2023		
Type of Service			Below Gro	ound		
Does Interactive Whiteb Water Penetration In Ele	( )		Yes No			
	RCOMS IN FIRE RESCUE ARE	AS	INO			
Question			R	esponse		
	scue Assistance Areas, Fire Rescue Area	as, and/or Holding Room				
your building?	-	, C				
iority Condition						
Txist Priority	Condition	Component	Location	Person(s)	Person(s)	Photo
ast Year? Category	Description	Affected	Description	Notified	Title	Image
No condition recorded						
nspection						
-			D			
Question			Response			
Electrical						
ATHLETIC FIELD			Does not e			
AUDITORIUM			Does not e	xist		
CAFETERIA			Does not e	xist		
CLASSROOM/COR	RIDOR/ADMINISTRATIVE SPACE	C	Inspected			
Lighting			Inspected			
Does a Chandelier			No			
Lighting Fixture			Does not e			
Lighting Fixture			Does not e			
Lighting Fixture			Does not e	xıst		
Lighting Fixture			Inspected			
Pendant Mount	ted		Inspected			
Condition			1- Good			
Deficiency				ncies recorded		
Surface Mounte	ed		Inspected			
Condition			1- Good			
Deficiency				ncies recorded		
Recessed Moun	ted		Inspected			
Condition			1- Good			
Deficiency	, 			ncies recorded		
COMPUTER LAB			Does not e			
GYMNASIUM			Does not e	xist		
KITCHEN			Inspected			
Instance or	n 1st Floor		Inspected			
Lighting						
Instance or			Inspected			
Lighting Fixture						
Instance or			Does not e	xist		
Lighting Fixture						
Instance or			Does not e	xist		
Lighting Fixture						
	1 1st Floor		Does not e			

M508

## **Building Condition Assessment Survey 2023-2024**

### Electrical Inspection

Question	Response
KITCHEN	
Lighting	
Lighting Fixture - LED	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Does not exist
Recessed Mounted	
Instance on 1st Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
LIBRARY	Does not exist
LOCKER ROOM	Does not exist
MULTIPURPOSE ROOM	Inspected
Instance on Room 114	Inspected
Lighting	
Instance on Room 114	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 114	Does not exist
Lighting Fixture - HID	
Instance on Room 114	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 114	Does not exist
Lighting Fixture - LED	
Instance on Room 114	Inspected
Pendant Mounted	
Instance on Room 114	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 114	Does not exist
Recessed Mounted	
Instance on Room 114	Does not exist
Local Sound System	
Instance on Room 114	Does not exist
Projection System	
Instance on Room 114	Does not exist
Theater Lighting System	Descent enit
Instance on Room 114	Does not exist
SCIENCE DEMO ROOM	Does not exist
SCIENCE LAB	Does not exist
SCIENCE PREP ROOM	Does not exist
SWIMMING POOL	Does not exist
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Does not exist
Recessed Mounted	Inspected

M508

## **Building Condition Assessment Survey 2023-2024**

#### **Electrical Inspection**

uestion	Response	
TOILET ROOM - STAFF	Response	
Lighting		
Lighting Fixture - LED		
Recessed Mounted		
Condition	1- Good	
Deficiency	No deficiencies recorded	
TOILET ROOM - STUDENT	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Does not exist	
Recessed Mounted	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
AUXILIARY SIGNAL/BELL SYSTEM	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
EMERGENCY DC STANDBY BATTERY POWER	Does not exist	
EMERGENCY GENERATOR SET	Does not exist	
EMERGENCY LIGHT/EXIT LIGHT PANEL	Does not exist	
EMERGENCY LIGHTING	Inspected	
Battery Pack	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Non Battery Pack	Does not exist	
EXIT LIGHT	Inspected	
Battery Pack	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Non Battery Pack	Does not exist	
EXIT/EMERGENCY LIGHT	Does not exist	
FIRE ALARM SYSTEM	Inspected	
Bell/Horn	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Strobe	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Manual Pull Station	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Fan Shutdown Control	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Duct Smoke Detector	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Area Smoke Detector	Inspected	
Condition Deficiency	1- Good No deficiencies recorded	

# Building Condition Assessment Survey 2023-2024

### Electrical Inspection

ical Inspection		M1209
iestion	Response	
FIRE ALARM SYSTEM		
CO Detector	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Heat Detector	Does not exist	
Elevator Recall	Does not exist	
Magnetic Door Holder/Contactor	Does not exist	
Fused Cutout Panel	Does not exist	-
Fire Alarm Digital Communicator	Does not exist	
Main Panel	Inspected	
Bell At Panel	Does not exist	
Fire Alarm Control Panel (Electronic)	Inspected	
Instance	Main Entrance Lobby	
Instance Condition	1- Good	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Mircom	
Model	FX-2003	
EquipmentId	Fire Alarm Control Panel	
Installation Year	2023	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Standard)	Does not exist	
Sub-Panel	Does not exist	
Remote Annunciator	Inspected	
Display Monitor	Does not exist	
Panel	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Printer	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Punch Register	Does not exist	
Sprinkler Flow/Air Pressure Switch	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Tamper Flow Switch/Chain	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
ROUNDING SYSTEM	Does not exist	
NTERCOM SYSTEM	Does not exist	
	Inspected	
AN Local Distribution Frame (I/LDF)	Does not exist	
Main Equipment Rack (MDF)	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
JGHTNING PROTECTION	Does not exist	
10TOR CONTROLLER	Inspected	
MOTOR CONTROL CENTER	Does not exist	
MOTOR STARTER/CONTACTOR	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Variable Frequency Drive	Does not exist	
PANEL BOARD	Inspected	

## **Building Condition Assessment Survey 2023-2024**

### Electrical Inspection

M5	08

rical Inspection	M50
uestion	Response
PANEL BOARD	
Fused Disconnect Switch Type	Does not exist
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Does not exist
Molded Case Circuit Breaker Type	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
PUBLIC ADDRESS SYSTEM	Inspected
Instance	MDF Room 116
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Bogen Multicom - 2000
Installation Year	2023
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
SECURITY	Inspected
IPDVS/CCTV System	Inspected
Condition	1- Good
Installation Year	2023
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	Custodian's Office - Room 111F
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista 128BPT
Installation Year	2023
Source of Installation Year	Documented
Deficiency	PANEL NOT CONNECTED TO EMERGENCY POWER
Denenery	SOURCE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL CONNECTION
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Violations	No violations recorded
Infrared Sensor	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Siren/Strobe	Does not exist
Lighting - Security	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
SERVICE SWITCH	Inaccessible

## NYC Department of Education Building Condition Assessment Survey 2023-2024

### Electrical Inspection

uestion	Response	
TELEPHONE SYSTEM	Inspected	
PBX/Intercom	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Standard	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
FRANSFORMER	Does not exist	

M508