Building Condition Assessment Survey 2023-2024

	P.S. 98 MINIS	SCHOOL - MANHATTAN, 512	WEST 212 ST	REET, MANHA	ATTAN, NY, 1	.0034	
Inspectio	n Id Inspection Type	2			Time	In	Last Edited
	2419 MECHANICAL				2024-	01-16 11:09AM	2024-02-13 04:33PM
set Data							
Question				Answer			
Have any	Systems/Major Buildir	g Components been upgraded?		Systems:	Fixtures - Toi	lets	
-				Years:	2015		
Are there	e fuel tanks?			No			
Total # of	f water main service ent	ries to the asset		1			
	an Rooms Locations				al Equipment R	oom	
		ng or Defective CO Detectors?		Yes			
Location	()	Sprinklar Haada?		Yes	al Equipment R	oom	
Location	e any Painted/Obstructed	sprinkler neads?			Room 4 (obstru	cted. 17)	
	()	witches with Missing Hammers?		No compo		eted, 17)	
iority Co		0		r			
iorny Co Exist	Priority	Condition	Component	Location	Person(s)	Person(s)	Photo
ast Year?	Category	Description	Affected	Description	Notified	Title	Image
No condi	tion recorded	•		•			
nspection							
Question	1			Response	2		
Mechani	ical						
AIR C	ONDITIONING			Inspected			
	ed Water System			Does not			
		ion: Piping, Pumps and Auxiliaries	6	Does not			
	ing Coil in Ductwork			Does not of Does not of			
	ing Tower Split System			Inspected			
	loor Unit			Inspected			
	Condition			3- Fair			
	Deficiency				encies recorded		
Ou	tdoor Unit			Inspected			
_	Condition				en Fair and Poor		
	Deficiency				TONS:DEFECT		
	Deficiency Locat	ion/Instance			al Equipment R		
	Deficiency Quant	tity		1			
	Quantity Uom			EACH			
	Potential Action			REPAIR			
	Urgency of Action			PRIORIT			
	Purpose of Action	1		LEVEL 2			
	Violations				ions recorded		
	Cooler			Does not			
	aged / Rooftop Unit			Does not of Does not of			
	aged Terminal A/C igerant Leak Detection	System		Does not			
	igerant Leak Detection	system		Inspected			
	ndition			3- Fair			
201	Deficiency				encies recorded		
Retu	rn Fan			Does not			
		EUTRALIZING TANK		Does not			
CENTRAL ACID WASTE NEUTRALIZING TANK CLIMATE CONTROL SYSTEM				Does not			
		1 1/1 1		Does not			
COMP	PACTOR						
~ ~	EYING			Does not	ex1st		

DOMESTIC WATER SYSTEM

Inspected

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

N
N
N
N
N
N
Ň
N
N
N

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

M845	
111040	

	Ma
Question	Response
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	Does not exist
FIXTURES	Inspected
Staff And Other	Inspected
Janitor Sink	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lavatory/Sink	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Toilet	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Urinal	Does not exist
Student	Inspected
Drinking Fountain	Does not exist
Lavatory/Sink	Inspected
Condition	3- Fair
	No deficiencies recorded
Deficiency	Does not exist
Locker Room Shower	
Sink And Fountain Combo Unit	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Toilet	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Urinal	Does not exist
GAS FIRED FURNACE	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
GAS SERVICE	Inspected
Gas Distribution Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Gas Meter Room Exhaust Fan	Does not exist
Gas Meter Room Vent	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Gas Pressure Booster	Does not exist
CO/Gas Leak Detection	Does not exist
HEATING	Inspected
Heating Coil In Ductwork	Does not exist
Hydronic Heating	Does not exist
Radiator/Convector/Fin Tube	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Steam Heating	Does not exist
Steam supplied by External Sources	Does not exist
Unit Heater/Cabinet Heater	Does not exist
HEATING PLANT	Does not exist
Enclosed IDF Room	Inspected
Instance on Closet inside Room 7	Inspected
Dedicated A/C Equipment	
Instance on Closet inside Room 7	Inspected

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

uestion	Response		
Enclosed IDF Room			
Dedicated A/C Equipment			
Instance Condition	4- Between Fair and Poor		
Deficiency	DOES NOT EXIST		
Deficiency Location/Instance	Closet inside Room 7		
Deficiency Quantity	1		
Quantity Uom	EACH		
Potential Action	INSTALL		
Urgency of Action	PRIORITY 3		
Purpose of Action	LEVEL 2		
Violations	No violations recorded		
KITCHEN	Does not exist		
MDF Room	Does not exist		
SCIENCE DEMO ROOM	Does not exist		
SCIENCE LAB	Does not exist		
SCIENCE PREP ROOM	Does not exist		
SPRINKLERS, STANDPIPE, FIRE SYSTEM	Inspected		
Dry Sprinkler Alarm Valve Assembly	Does not exist		
Wet Sprinkler Alarm Valve Assembly	Does not exist		
Fire Booster Pump Assembly	Does not exist		
Roof Tank	Does not exist		
Siamese Connection	Does not exist		
Sprinkler Head	Inspected		
Condition	3- Fair		
Deficiency	DEFECTIVE/DETERIORATED		
Deficiency Location/Instance	Corridor, Room 4 (obstructed, 17)		
Deficiency Quantity	17		
Quantity Uom	EACH		
Potential Action	REPLACE		
Urgency of Action	PRIORITY 5		
Purpose of Action	LEVEL 6		
Violations	No violations recorded		
Sprinkler Piping	Inspected		
Condition	3- Fair		
Deficiency	No deficiencies recorded		
Standpipe System	Does not exist		
Water Gong	Does not exist		
SWIMMING POOL	Does not exist		
VENTILATION	Inspected		
Is the building Mechanically ventilated?	Yes		
Exhaust Fan	Inspected		
Condition	3- Fair		
Approximate Total # of Fans	1-25		
Deficiency	No deficiencies recorded		
Heating And Ventilating Unit	Does not exist		
Metal Ductwork	Inspected		
Condition	3- Fair		
Are there any uninsulated ductwork by design in Mechanical rooms?	No		
Are there chain operated dampers?	No		
Deficiency	DAMAGED/MISSING INSULATION		
Deficiency Location/Instance	Mechanical Equipment Room		
Deficiency Quantity	60		
Quantity Uom	L.F.		
Potential Action	MAINTENANCE		
Urgency of Action			

M845

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

anical Inspection		M845	
uestion	Response		
VENTILATION			
Metal Ductwork			
Purpose of Action	LEVEL 2		
Violations	No violations recorded		
Supply Fan	Does not exist		
Unit Ventilator	Does not exist		