

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

Q332

Asset: BAYSIDE HILLS SCHOOL OF EXCELLENCE - QUEENS, 210-21 48TH AVENUE, 11364

Inspection Id	Inspection Type	Time In	Last Edited
EE : Q332	Electrical	2024-04-03 8:23 AM	2024-04-29 4:28 PM

Asset Data

Question	Answer
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration in Electrical Room?	No
Have any Systems/Major Building Components been upgraded?	Yes
	Systems: LAN
	Years: 2024
	Systems: All Other Electrical Systems and Components
	Years: 2016

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	Yes
Are dedicated intercoms available in all of these spaces for use during a fire?	Yes
Are all dedicated intercoms operational?	Yes

Priority Condition

Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Status	PhotoImage
Yes	Emergency Generator - Automatic Transfer Switch (ATS) Not operational	The Fire Pump Automatic Transfer Switch is consistently sending a false signal to the emergency generator, causing it to randomly activate.	EMERGENCY GENERATOR SET Automatic Transfer Switch (ATS)	Fire Pump Room C11	John Young	Custodian	Sent to DSF	

Inspection

Question	Response
Electrical	
AUDITORIUM	Does not Exist
CAFETERIA	Inspected
Instance on 1st Floor	Inspected
Lighting	Inspected
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Surface Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Recessed Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

Q332

Question	Response
CAFETERIA	
Lighting	
Lighting Fixture - HID	
Instance on 1st Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor	Inspected
Pendant Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Surface Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Recessed Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Local Sound System	Inspected
Instance on 1st Floor	Inspected
Installation Year	2016
Source of Installation	Documented
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Projection System	Does not Exist
Instance on 1st Floor	Does not Exist
Theater Lighting System	Does not Exist
Instance on 1st Floor	Does not Exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected
Lighting	Inspected
Does a Chandelier exist?	No
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Inspected
Pendant Mounted	Does not Exist
Surface Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

Q332

Question	Response
COMPUTER LAB	Does not Exist
GYMNASIUM	Inspected
Instance on Basement	Inspected
Lighting	Inspected
Instance on Basement	Inspected
Lighting Fixture - Fluorescent	
Instance on Basement	Inspected
Pendant Mounted	Does not Exist
Instance on Basement	Does not Exist
Surface Mounted	Inspected
Instance on Basement	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Instance on Basement	Does not Exist
Lighting Fixture - HID	
Instance on Basement	Does not Exist
Lighting Fixture - Incandescent	
Instance on Basement	Does not Exist
Lighting Fixture - LED	
Instance on Basement	Inspected
Pendant Mounted	Inspected
Instance on Basement	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Does not Exist
Instance on Basement	Does not Exist
Recessed Mounted	Does not Exist
Instance on Basement	Does not Exist
Local Sound System	Inspected
Instance on Basement	Inspected
Installation Year	2016
Source of Installation	Documented
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Projection System	Inspected
Is the projector on a cart or installed on the ceiling?	Ceiling
Instance on Basement	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Scoreboard	Does not Exist
Instance on Basement	Does not Exist
Theater Lighting System	Inspected
Instance on Basement	Inspected
Dimming System	
Instance on Basement	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Theater Lighting	
Instance on Basement	Inspected

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

Q332

Question	Response
GYMNASIUM	Inspected
Theater Lighting System	
Theater Lighting	
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
KITCHEN	Inspected
Instance on 1st Floor	Inspected
Lighting	Inspected
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Surface Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Recessed Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 1st Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not Exist
LIBRARY	Inspected
Instance on Room 403	Inspected
Lighting	Inspected
Instance on Room 403	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 403	Inspected
Pendant Mounted	Inspected
Instance on Room 403	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Does not Exist
Instance on Room 403	Does not Exist
Recessed Mounted	Does not Exist
Instance on Room 403	Does not Exist
Lighting Fixture - HID	
Instance on Room 403	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 403	Does not Exist
Lighting Fixture - LED	
Instance on Room 403	Inspected
Pendant Mounted	Does not Exist
Instance on Room 403	Does not Exist
Surface Mounted	Does not Exist
Instance on Room 403	Does not Exist

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

Q332

Question	Response
LIBRARY	
Lighting	Inspected
Lighting Fixture - LED	
Recessed Mounted	Inspected
Instance on Room 403	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Raceway With Receptacles	Inspected
Instance on Room 403	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Projection System	Does not Exist
Instance on Room 403	Does not Exist
LOCKER ROOM	Does not Exist
MULTIPURPOSE ROOM	Does not Exist
SCIENCE DEMO ROOM	Does not Exist
SCIENCE LAB	Inspected
Instance on Room 402	Inspected
Power Panel	No
Alternative use	Yes
Lighting	Inspected
Instance on Room 402	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 402	Inspected
Pendant Mounted	Inspected
Instance on Room 402	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Does not Exist
Instance on Room 402	Does not Exist
Recessed Mounted	Does not Exist
Instance on Room 402	Does not Exist
Lighting Fixture - HID	
Instance on Room 402	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 402	Does not Exist
Lighting Fixture - LED	
Instance on Room 402	Does not Exist
Emergency Gas Shut-Off Valve	Does not Exist
Instance on Room 402	Does not Exist
Emergency Shut-Off Power	Does not Exist
Instance on Room 402	Does not Exist
Power Supply	Does not Exist
Instance on Room 402	Does not Exist
Projection System	Does not Exist
Instance on Room 402	Does not Exist
SCIENCE PREP ROOM	Inspected
Instance on Room 402A	Inspected
Power Panel	No
Alternative use	Yes

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

Q332

Question	Response
SCIENCE PREP ROOM	
Lighting	Inspected
Instance on Room 402A	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 402A	Inspected
Pendant Mounted	Inspected
Instance on Room 402A	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Does not Exist
Instance on Room 402A	Does not Exist
Recessed Mounted	Does not Exist
Instance on Room 402A	Does not Exist
Lighting Fixture - HID	
Instance on Room 402A	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 402A	Does not Exist
Lighting Fixture - LED	
Instance on Room 402A	Does not Exist
Emergency Gas Shut-Off Valve	Does not Exist
Instance on Room 402A	Does not Exist
Emergency Shut-Off Power	Does not Exist
Instance on Room 402A	Does not Exist
Power Supply	Does not Exist
Instance on Room 402A	Does not Exist
SWIMMING POOL	Does not Exist
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not Exist
Surface Mounted	Does not Exist
Recessed Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not Exist
Surface Mounted	Does not Exist
Recessed Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

Q332

Question	Response
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Replacement Quantity	73,000
Replacement Uom	S.F.
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not Exist
EMERGENCY GENERATOR SET	Inspected
Automatic Transfer Switch (ATS)	Inspected
Instance	Fire Pump Room C11
Instance Condition	4 - Between Fair and Poor
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Tornatech
Equipment	Fire Pump Power Transfer Switch
Capacity/Size Quantity	302
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2016
Source of Installation	Documented
Deficiency	ATS NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance	Transfer Switch Room C13
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Kohler Power Systems
Equipment	ATS EMDB
Capacity/Size Quantity	600
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2016
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Transfer Switch Room C13
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Kohler Power Systems
Equipment	ATS ETP
Capacity/Size Quantity	100
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2016

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

Q332

Question	Response
EMERGENCY GENERATOR SET	
Automatic Transfer Switch (ATS)	
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Transfer Switch Room C13
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Kohler Power Systems
Equipment	ATS Fire Alarm System
Capacity/Size Quantity	104
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2016
Source of Installation	Documented
Deficiency	No deficiencies recorded
Battery Charger	Inspected
Instance	Roof - Outdoor Generator Enclosure
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Kohler Power Systems
Equipment	Battery Charger
Capacity/Size Quantity	10
Capacity/Size UOM	AmpsDC
Capacity/Size2 Quantity	24
Capacity/Size2 UOM	VDC
Source of Capacity/Size	Inspector Estimate
Installation Year	2016
Source of Installation	Documented
Deficiency	No deficiencies recorded
Emergency Distribution Board	Inspected
Number of Spares	4
Fused Disconnect Switch Type	Inspected
Instance	Transfer Switch Room C13
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Square D
Equipment	EMDB
Capacity/Size Quantity	600
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	1
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Nameplate
Installation Year	2016
Source of Installation	Documented
Deficiency	No deficiencies recorded
Molded Case Circuit Breaker Type	Does not Exist

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

Q332

Question	Response
EMERGENCY GENERATOR SET	
Diesel	Inspected
Instance	Roof - Outdoor Generator Enclosure
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Kohler Power Systems
Equipment	Emergency Generator
Capacity/Size Quantity	438
Capacity/Size UOM	KVA
Capacity/Size2 Quantity	350
Capacity/Size2 UOM	KW
Capacity/Size3Quantity	1,214
Capacity/Size3 UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2016
Source of Installation	Documented
Deficiency	No deficiencies recorded
Natural Gas	Does not Exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	
	Does not Exist
EMERGENCY LIGHTING	
	Inspected
Battery Pack	Does not Exist
Non Battery Pack	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
EXIT LIGHT	
	Inspected
Battery Pack	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Does not Exist
EXIT/EMERGENCY LIGHT	
	Does not Exist
FIRE ALARM SYSTEM	
	Inspected
Replacement Quantity	73,000
Replacement Uom	S.F.
Bell/Horn	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Strobe	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Manual Pull Station	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Duct Smoke Detector	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

Q332

Question	Response
FIRE ALARM SYSTEM	
Area Smoke Detector	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
CO Detector	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Heat Detector	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Elevator Recall	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Magnetic Door Holder/Contactor	Does not Exist
Fused Cutout Panel	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	Does not Exist
Main Panel	Inspected
Bell At Panel	Does not Exist
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Main Entrance Lobby
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Mircom
Equipment	Fire Alarm Control Panel
Model	FX - 2000
Installation Year	2016
Source of Installation	Documented
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	Does not Exist
Sub-Panel	Does not Exist
Remote Annunciator	Inspected
Display Monitor	Does not Exist
Panel	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Printer	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Punch Register	Does not Exist
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Tamper Flow Switch/Chain	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	
Condition	2 - Between Good and Fair

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

Q332

Question	Response
GROUNDING SYSTEM	Inspected
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	Inspected
Elevator	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Holding Area	Does not Exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
MOTOR CONTROLLER	Inspected
Motor Control Center	Does not Exist
Motor Starter/Contactor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not Exist
Fused Toggle Switch Type	Does not Exist
Molded Case Circuit Breaker Type	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
PUBLIC ADDRESS SYSTEM	Inspected
Replacement Quantity	73,000
Replacement Uom	S.F.
Instance	Room 201
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Bogen Multicom - 2000
Installation Year	2016
Source of Installation	Documented
Deficiency	No deficiencies recorded
SECURITY	Inspected
IPDVS/CCTV System	Inspected
Replacement Quantity	73,000
Replacement Uom	S.F.

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

Q332

Question	Response
SECURITY	
IPDVS/CCTV System	Inspected
Installation Year	2016
Source of Installation	Documented
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Intrusion Alarm System	Inspected
Replacement Quantity	73,000
Replacement Uom	S.F.
Central Control Panel	Inspected
Instance	Custodian's Office
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista-128BPT
Installation Year	2016
Source of Installation	Documented
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	2 - Between Good and Fair
Deficiency	SIREN/STROBE NOT ACTIVE
Deficiency Location/Instance	Exterior Wall facing 48th Avenue
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Lighting - Security	Inspected
Replacement Uom	EACH
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
SERVICE SWITCH	Inspected
Instance	Electrical Room C12
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Square D
Equipment	EMDB
Capacity/Size Quantity	800

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

Q332

Question	Response
SERVICE SWITCH	
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2016
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room C12
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Square D
Equipment	SS 4 Fire Pump
Capacity/Size Quantity	1,600
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2016
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room C12
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Square D
Equipment	MDB
Capacity/Size Quantity	1,600
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2016
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room C12
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Square D
Equipment	N/A
Capacity/Size Quantity	2,500
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2016
Source of Installation	Documented
Deficiency	No deficiencies recorded
SWITCHBOARD	Inspected
Number of Spares	10
Fused Disconnect Switch Type	Inspected
Instance	Penthouse - Electrical Closet (Room 504)
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

Q332

Question	Response
SWITCHBOARD	
Fused Disconnect Switch Type	
Instance Manufacturer	Square D
Equipment	HDB-1, 2
Capacity/Size Quantity	2,500
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	2
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Nameplate
Installation Year	2016
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room C12
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Square D
Equipment	MDB
Capacity/Size Quantity	1,600
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	2
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Nameplate
Installation Year	2016
Source of Installation	Documented
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not Exist
Molded Case Circuit Breaker Type	Does not Exist
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
TRANSFORMER	Does not Exist