Building Condition Assessment Survey 2023 - 2024

Architectural Inspection Q376

Asset:	Asset: 3K CENTER @ 159-25 JAMAICA AVENUE - QUEENS, 159-25 JAMAICA AVENUE, 11432					
Inspection Id	Inspection Type	Time In	Last Edited			
SA : Q376	Architectural - Senior	2024-01-02 12:28 PM	2024-01-16 10:24 AM			
AA : Q376	Architectural - Associate	2024-01-02 12:52 PM	2024-04-05 3:19 PM			

Asset Data

Question		Answer			
Was the building fully ac	ecessible for inspection	Yes			
Building Square Footage		25,000			
Comments on the Area (Leased Spaces)	for Athletic Field, Playing Surfaces,	400,000 S.F. Total Building Area; 25,000 S.F. Leased			
Comments on the Stories	s (Floors) plus Basements	3+B			
Comments on the Number	er of Classrooms	12			
Comments on the Year F	Built	1999			
Student Population		0			
Staff Population		2			
Weather		Fair			
Principal(s) Information					
	Principal Name	N/A			
	Organization	N/A			
	Did you meet with this Principal?	No			
	Did this Principal provide feedback?	No			
Custodian		Joseph Maneri			
Fireman		Rodney Edwards (Cleaner)			
Facade Photo					



Corner of 160th Street and Jamaica Avenue

⁻ Southwest view

Architectural Inspection Q376

Main Entrance Photo



Facade A - Jamaica Avenue

Roof Photo	Nil
Have any Systems/Major Building Components been upgraded?	No
Have there been any Building Additions?	No
Tandem Schools?	No
Leased Space?	Yes
Year Leased	2022
Inspection	Partial Inspection

Priority	Condition
----------	-----------

Priority	Priority	Condition	Component	Location	Person(s)	Person(s) Title	PhotoImage
Condition Exist	Category	Description	Affected	Description	Notified		
Last Year?							

No condition recorded

Structural Engineer Required

Structural Condition Type	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	PhotoImage
No condition recorde	d					

Programmatic Accessibility

Programmatic Accessibility Status Question	Response
Is the primary or secondary entrance on an accessible route?	Yes
Is the building a multi-story building?	Yes
Are all floors of the building accessible through compliant means?	Yes
Accessible classrooms exists on each floor?	Yes
Boys and Girls or Unisex accessible toilets exist on at least every other floor?	Yes
If the following spaces exist, are they ALL accessible? Art Room, Auditorium, Cafeteria, Computer, Gymnasiums, Library, Multipurpose Room, Science Labs	Yes

Physical Breakdown Structure	Exists	Required	Complies	Deficiency	Assistive Fire
					Listening Alarm
					System Strobe
PROGRAMMATIC ACCESSIBILITY					

Exterior Routes						
Exterior Entrances & Exits	Yes					
Exterior H/C Lifts	No No					
Exterior Ramps and Railings	No No					
Exterior Ramps and Railings	No No					


Building Condition Assessment Survey 2023 - 2024

Architectural Inspection Q376

Physical Breakdown Structure		Exists	Required	Complies	Deficiency	Assistive Listening System	
Interior Routes							
Corridor and Lobby H/O	C Lifts	No	No				
Interior Corridor Doors	and Hardware	Yes		Yes			
Interior Corridors and I	Lobbies			Yes			
Interior Elevators		Yes		Yes			
Interior Lobby Doors ar	nd Hardware			Yes			
Interior Ramps		No					
Rooms & Spaces							
Art Rooms		No					
Auditorium		No					
Cafeteria		No					
Classrooms	2nd Floor	Yes		Yes			
Computer Rooms		No					
Gymnasium		No					
Library		No					
Main Office	Room 210	Yes		Yes			
Multi-purpose Room	Rooms 225, 237	Yes		Yes		No	Yes
Nurse's Room	Room 205	Yes		Yes			
Pool		No					
Science Lab		No					
Toilet Rooms (Boys)	2nd Floor	Yes		Yes			
Toilet Rooms (Girls)	2nd Floor	Yes		Yes			
Toilet Rooms (Staff)	2nd Floor	Yes		Yes			

Building Template

Q376



Inspection

Question	Response
Architectural	

Building Condition Assessment Survey 2023 - 2024

chitectural Inspection		Q376
Question	Response	
EXTERIOR	Inspected	
AREAWAY	Does not Exist	
AWNINGS AND CANOPIES	Does not Exist	
CHIMNEY	Does not Exist	
COPING	Not Required	
CORNICE	Does not Exist	
DOORS	Inspected	
DOORS AND FRAMES	Inspected	

Deficiency

Roof Plan reference


Deficiency Photo1

Condition

METAL: DETERIORATED DOOR AND FRAME - MAJOR DETERIORATION

Q376

5 - Poor



Deficiency Quantity 2
Quantity Uom EACH
Potential Action REPLACE
Urgency of Action PRIORITY 4
Purpose of Action LEVEL 2



Violations No violations recorded.

DOOR HARDWARE	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
LINTELS	Does not Exist
TRANSOM/SIDE LIGHT	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
EXTERIOR WALLS	Inspected
Material Type(s)	Masonry
Replacement Quantity	3,500
Replacement Uom	S.F.
Instance on Facades A, B, C	Inspected
Instance Condition	2 - Between Good and Fair

	Q37
Response	
No deficiencies recorded	
*	
Not Required	
Does not Exist	
Not Required	
Does not Exist	
Inspected	
2,500	
S.F.	
Does not Exist	
_	
-	
Does not Exist	
Inspected	
Inspected	
2 - Between Good and Fair	
No deficiencies recorded	
Inspected	
2 - Between Good and Fair	
No deficiencies recorded	
Not Required	
Not Required	
Does not Exist	
Does not Exist	
Does not Exist	
Inspected	
Inspected Inspected	
	Inspected 2 - Between Good and Fair No deficiencies recorded Not Required Inspected 2 - Between Good and Fair No deficiencies recorded Not Required Does not Exist Not Required Does not Exist Inspected 2,500 S.F. Does not Exist Inspected Aluminum Inspected 3 - Fair 2,500 S.F. Yes 1999 Custodial Staff No deficiencies recorded Inspected Inspected Inspected 2 - Between Good and Fair No deficiencies recorded Inspected 2 - Between Good and Fair No deficiencies recorded Not Required Not Required Not Required Not Required Does not Exist Does not Exist

estion	Response
NTERIOR	
CLASSROOMS/CORRIDORS/ADMIN SPACES	
Ceiling	
Deficiency	GYPSUM BOARD: DAMAGED/DETERIORATED
Deficiency Location/Instance	Rooms 239, 241
Deficiency Quantity	30
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
	Room 241
Violations	No violations recorded.
-	
Deficiency Deficiency Location/Instance	ACOUSTIC TILES: DAMAGED/MISSING Rooms 201, 239, 241, Corridor near Room 220.
Deficiency Quantity	50
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	Room 241 No violations recorded.
Door(s) Condition	Inspected 1 - Good
Deficiency	No deficiencies recorded
Floor Finish	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Walls	Inspected
Condition	2 - Between Good and Fair
Deficiency	GYPSUM BOARD: DETERIORATED
Deficiency Deficiency Location/Instance	Room 241
Deficiency Location/instance	K00III 241

itectural Inspection	Q
estion	Response
INTERIOR	
CLASSROOMS/CORRIDORS/ADMIN SPACES	
Walls	
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
	Room 241
Violations	No violations recorded.
Specialties	Does not Exist
GYMNASIUM	Does not Exist
INTERIOR DOOR HARDWARE	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
INTERIOR GUARDS	Does not Exist
KITCHEN	Inspected
Instance on 2nd Floor	Inspected
Ceiling	
Instance on 2nd Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Door(s)	
Instance on 2nd Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Floor Finish	
Instance on 2nd Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Walls Instance on 2nd Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
LIBRARY	Does not Exist
LOCKER ROOM	Does not Exist Does not Exist
MULTI-PURPOSE ROOM Instance on Poom 225	Inspected
Instance on Room 225	Inspected
Instance on Room 237	Inspected
Ceiling	
Instance on Room 237	Inspected
Condition	1 - Good Page 7 of 10 Print Date: 7/01/2

Building Condition Assessment Survey 2023 - 2024

Architectural Inspection **O376** Question Response INTERIOR MULTI-PURPOSE ROOM Ceiling Deficiency No deficiencies recorded Instance on Room 225 Inspected Condition 1 - Good Deficiency No deficiencies recorded Door(s) Instance on Room 225 Inspected Condition 1 - Good Deficiency No deficiencies recorded Instance on Room 237 Inspected Condition 1 - Good Deficiency No deficiencies recorded **Fixed Equipment** Instance on Room 225 Does not Exist Instance on Room 237 Does not Exist Floor Finish Instance on Room 237 Inspected Condition 1 - Good Deficiency No deficiencies recorded Instance on Room 225 Inspected Condition 1 - Good Deficiency No deficiencies recorded **Sliding-folding Partition** Instance on Room 225 Does not Exist Instance on Room 237 Does not Exist Stage Instance on Room 225 Does not Exist Instance on Room 237 Does not Exist Walls Instance on Room 237 Inspected Condition 2 - Between Good and Fair Deficiency GYPSUM BOARD: DETERIORATED Deficiency Location/Instance Near Closets **Deficiency Quantity** 10 S.F. Quantity Uom Potential Action REPLACE Urgency of Action PRIORITY 3 Purpose of Action LEVEL 2 Deficiency Photo1

Near Closets

tectural Inspection		Q37
estion	Response	
NTERIOR		
MULTI-PURPOSE ROOM		
Walls		
Violations	No violations recorded.	
Window Curtains/Shades/Blinds		
Instance on Room 237	Does not Exist	
Instance on Room 225	Does not Exist	
SCIENCE DEMO ROOM	Does not Exist	
SCIENCE LAB	Does not Exist	
SCIENCE PREP ROOM	Does not Exist	
SHOWER ROOM	Does not Exist	
STAIRS/RAMPS: INTERIOR	Inspected	
Do Letter Stair Signs Exist?	Yes	
Ceiling	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Door(s)	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Partition	Does not Exist	
Railings	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Stairs and Landings	Inspected	
Condition	1 - Good	
Deficiency W. H.	No deficiencies recorded	
Walls	Inspected	
Condition	1 - Good No deficiencies recorded	
Deficiency TOILET ROOMS - STAFF		
	Inspected	
Ceiling	Inspected	
Condition	1 - Good	
Door(s)	No deficiencies recorded	
Condition	Inspected 1 - Good	
Deficiency	No deficiencies recorded	
Floor Finish	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Stalls	Does not Exist	
Walls		
Condition	Inspected 1 - Good	
Deficiency	No deficiencies recorded	
TOILET ROOMS - STUDENTS	Inspected	
Cendition	Inspected	
Condition	1 - Good	
Deficiency People	No deficiencies recorded	
Door(s)	Inspected	
Condition	1 - Good	

hitectural Inspection		Q370
uestion	Response	
INTERIOR		
TOILET ROOMS - STUDENTS		
Door(s)	Inspected	
Deficiency	No deficiencies recorded	
Floor Finish	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Stalls	Does not Exist	
Walls	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
LIFE SAFETY	Inspected	
F.D. HOLDING AREA	Does not Exist	
STEEL STAIRS	Does not Exist	
SITE	Does not Exist	
ARTWORK	Does not Exist	