

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Mechanical Inspection

Q608

Asset: **PRE-K CENTER @ 83-30 KEW GARDENS ROAD - QUEENS, 83-30 KEW GARDENS ROAD, New York, 11415**

Inspection Id	Inspection Type	Time In	Last Edited
ME : Q608	Mechanical	2024-02-28 7:15 AM	2024-03-06 9:53 AM

Asset Data

Question	Answer
Are there fuel tanks?	No
Total # of water main service entries to the asset	0
MERs/Fan Rooms Locations	MERs C101, 111, 116
Are there any spaces with Missing or Defective CO Detectors?	No
Are there any Emergency Stop Switches with Missing Hammers?	No
Are there any Painted/Obstructed Sprinkler Heads?	No
Have any Systems/Major Building Components been upgraded?	No

Priority Condition

Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Status	PhotoImage
No condition recorded								

Inspection

Question	Response
<b>Mechanical</b>	
<b>AIR CONDITIONING</b>	Inspected
Chilled Water System	Does not Exist
Condenser Water Distribution: Piping, Pumps and Auxiliaries	Does not Exist
Cooling Coil in Ductwork	Does not Exist
Cooling Tower	Does not Exist
<b>DX Split System</b>	Inspected
Indoor Unit	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Outdoor Unit	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Dry Cooler	Does not Exist
Packaged / Rooftop Unit	Does not Exist
Packaged Terminal A/C	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Refrigerant Leak Detection System	Does not Exist
Refrigerant Piping	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Return Fan	Does not Exist
<b>CENTRAL ACID WASTE NEUTRALIZING TANK</b>	Does not Exist
<b>CLIMATE CONTROL SYSTEM</b>	Inspected
BMS	Does not Exist
Pneumatic System	Does not Exist
Hybrid System	Does not Exist
Electric System	Inspected
Instance	Throughout

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Mechanical Inspection

Q608

<b>Question</b>	<b>Response</b>
<b>CLIMATE CONTROL SYSTEM</b>	
<b>Electric System</b>	
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Building Area Covered by Operational System	81-100%
Deficiency	No deficiencies recorded
<b>COMPACTOR</b>	Does not Exist
<b>CONVEYING</b>	Does not Exist
<b>DOMESTIC WATER SYSTEM</b>	Inspected
<b>Domestic Cold Water System</b>	Does not Exist
<b>Domestic Hot Water System</b>	Inspected
<b>Domestic Hot Water Remote Storage Tank</b>	Does not Exist
<b>Domestic Water Heat Exchanger</b>	Does not Exist
<b>Electric Domestic Water Heater</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Gas Fired Domestic Water Heater</b>	Does not Exist
<b>Heat Pump Domestic Water Heater</b>	Does not Exist
<b>Oil Fired Domestic Water Heater</b>	Does not Exist
<b>Domestic Water Distribution Piping</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>DRAIN/WASTE/VENT AND STORM SYSTEM</b>	Inspected
<b>Interior Storm Piping</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Sewage/Waste/Vent Piping</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Sewage Ejector Pump</b>	Does not Exist
<b>Sump Pump</b>	Does not Exist
<b>DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)</b>	Does not Exist
<b>FIXTURES</b>	Inspected
<b>Staff And Other</b>	Inspected
<b>Janitor Sink</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Lavatory/Sink</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Toilet</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Urinal</b>	Does not Exist
<b>Student</b>	Inspected
<b>Drinking Fountain</b>	Inspected
Condition	2 - Between Good and Fair

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Mechanical Inspection

Q608

Question	Response
<b>FIXTURES</b>	
<b>Student</b>	
<b>Drinking Fountain</b>	
Deficiency	DEFECTIVE AUXILIARY (FAUCET, SHUT OFF VALVE,ETC.)
Deficiency Location/Instance	Corridor adjacent to Room 106
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Lavatory/Sink</b>	
Condition	Inspected
Deficiency	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Locker Room Shower</b>	
	Does not Exist
<b>Sink And Fountain Combo Unit</b>	
	Does not Exist
<b>Toilet</b>	
Condition	Inspected
Deficiency	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Urinal</b>	
	Does not Exist
<b>GAS FIRED FURNACE</b>	
	Does not Exist
<b>GAS SERVICE</b>	
	Does not Exist
<b>HEATING</b>	
	Inspected
<b>Heating Coil In Ductwork</b>	
	Does not Exist
<b>Hydronic Heating</b>	
	Inspected
<b>Hydronic Hot Water Distribution: Piping, Pumps and Auxiliaries</b>	
Condition	Inspected
Condition	1 - Good
Deficiency	PIPING: DAMAGED/MISSING INSULATION
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	10
Quantity Uom	L.F.
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Backflow Preventer</b>	
	Does not Exist
<b>Hot Water Heat Exchanger</b>	
	Does not Exist
<b>Radiator/Convactor/Fin Tube</b>	
Condition	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Steam Heating</b>	
	Does not Exist
<b>Steam supplied by External Sources</b>	
	Does not Exist
<b>Unit Heater/Cabinet Heater</b>	
	Inspected

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Mechanical Inspection

Q608

Question	Response
<b>HEATING</b>	Inspected
<b>Unit Heater/Cabinet Heater</b>	
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>HEATING PLANT</b>	Inspected
Replacement Quantity	214
Replacement Uom	MBH Net
Instance on Basement	Inspected
Burner Type	N/A
Heating Plant Oil Number	N/A
Is there a water meter on the boiler make-up water piping?	No
Burner Exists?	No
<b>Boiler Auxiliaries</b>	Inspected
Instance on Basement	Inspected
<b>Boiler Auxiliary Piping</b>	
Instance on Basement	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Boiler Emergency Stop Switch</b>	
Instance on Basement	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Boiler Feedwater System</b>	
Instance on Basement	Does not Exist
<b>Boiler Feedwater Treatment(Automatic)</b>	
Instance on Basement	Does not Exist
<b>Boiler Flue Exhaust</b>	
Instance on Basement	Does not Exist
<b>Boiler Make-up Water Backflow Preventer</b>	
Instance on Basement	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Boiler Room Steam And Condensate Piping</b>	
Instance on Basement	Does not Exist
<b>Boiler Safety Valve</b>	
Instance on Basement	Does not Exist
<b>Boiler System</b>	Inspected
Instance on Basement	Inspected
<b>Coal-fired Boiler</b>	
Instance on Basement	Does not Exist
<b>Hot Water Boiler</b>	
Instance on Basement	Does not Exist
<b>Modular Boiler</b>	
Instance on Basement	Inspected
Instance	Boiler Room
Instance Condition	2 - Between Good and Fair
Instance Quantity	107
Instance Quantity Uom	MBH Net
Instance Manufacturer	Lochinvar
Equipment	166880-01

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Mechanical Inspection

Q608

Question	Response
<b>HEATING PLANT</b>	Inspected
<b>Boiler System</b>	
<b>Modular Boiler</b>	
Capacity/Size Quantity	154
Capacity/Size UOM	MBH Input
Source of Capacity/Size	Documented
Installation Year	2015
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Boiler Room
Instance Condition	2 - Between Good and Fair
Instance Quantity	107
Instance Quantity Uom	MBH Net
Instance Manufacturer	Lochinvar
Equipment	166880-02
Capacity/Size Quantity	154
Capacity/Size UOM	MBH Input
Source of Capacity/Size	Documented
Installation Year	2015
Source of Installation	Documented
Deficiency	No deficiencies recorded
<b>Steam Boiler</b>	
Instance on Basement	Does not Exist
<b>Fuel System</b>	Does not Exist
Instance on Basement	Does not Exist
<b>Enclosed IDF Room</b>	Does not Exist
<b>KITCHEN</b>	Inspected
Instance on 1st Floor	Inspected
<b>CO Detector</b>	Not Required
Instance on 1st Floor	Not Required
<b>Gas System</b>	Does not Exist
Instance on 1st Floor	Does not Exist
<b>Grease Trap</b>	Inspected
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Hood</b>	Does not Exist
Instance on 1st Floor	Does not Exist
<b>Hood Exhaust Ductwork</b>	Does not Exist
Instance on 1st Floor	Does not Exist
<b>Hood Exhaust Fan</b>	Does not Exist
Instance on 1st Floor	Does not Exist
<b>Hood Fire Suppression System</b>	Does not Exist
Instance on 1st Floor	Does not Exist
<b>Hot Water Temperature Booster</b>	Does not Exist
Instance on 1st Floor	Does not Exist
<b>Kitchen Sink</b>	Inspected
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Mechanical Inspection

Q608

<b>Question</b>	<b>Response</b>
<b>KITCHEN</b>	Inspected
<b>Kitchen Sink</b>	Inspected
Deficiency	No deficiencies recorded
<b>MDF Room</b>	Inspected
Instance on Room C104	Inspected
<b>Dedicated A/C Equipment</b>	Inspected
Instance on Room C104	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>SCIENCE DEMO ROOM</b>	Does not Exist
<b>SCIENCE LAB</b>	Does not Exist
<b>SCIENCE PREP ROOM</b>	Does not Exist
<b>SPRINKLERS, STANDPIPE, FIRE SYSTEM</b>	Inspected
<b>Dry Sprinkler Alarm Valve Assembly</b>	Does not Exist
<b>Wet Sprinkler Alarm Valve Assembly</b>	Does not Exist
<b>Fire Booster Pump Assembly</b>	Does not Exist
<b>Roof Tank</b>	Does not Exist
<b>Siamese Connection</b>	Does not Exist
<b>Sprinkler Head</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Sprinkler Piping</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Standpipe System</b>	Does not Exist
<b>Water Gong</b>	Does not Exist
<b>SWIMMING POOL</b>	Does not Exist
<b>VENTILATION</b>	Inspected
Is the building mechanically ventilated?	Yes
<b>Exhaust Fan</b>	Inspected
Approximate Total # of Fans	1-25
Condition	2 - Between Good and Fair
Deficiency	DEFECTIVE
Deficiency Location/Instance	Corridor above the front desk (Bearings)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Heating And Ventilating Unit</b>	Does not Exist
<b>Metal Ductwork</b>	Inspected
Are there any uninsulated ductwork by design in Mechanical Rooms?	No
Are there chain operated dampers?	No
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Supply Fan</b>	Does not Exist
<b>Unit Ventilator</b>	Does not Exist

NYC Department of Education  
Building Condition Assessment Survey 2023 - 2024

Mechanical Inspection

Q608

---

Question

Response

---

VENTILATION

Unit Ventilator

---