Asset: AVIATION HS ANNEX - QUEENS, 141 JFK AIR	PORT, BUILDING #141, New York, 11434
Inspection Id Inspection Type	Time In Last Edited
ME: Q750 Mechanical	2024-04-22 8:01 AM 2024-05-07 2:58 PM
Asset Data	
Question	Answer
Are there fuel tanks?	No
Total # of water main service entries to the asset	0
MERs/Fan Rooms Locations	None
Are there any spaces with Missing or Defective CO Detectors?	No
Are there any Emergency Stop Switches with Missing Hammers?	No
Are there any Painted/Obstructed Sprinkler Heads?	Yes
Location(s)	Room 2005
Have any Systems/Major Building Components been upgraded?	Yes
	Systems: Drinking Fountain
	Years: 2024
	Systems: Fixtures - Student: Lavatory/Sinks, Toilets, Urinals
	Years: 2018
Priority Condition	
Priority Priority Condition Component Location Condition Exist Category Description Affected Description Last Year?	Person(s) Person(s) Title Status PhotoImage on Notified
No condition recorded	
nspection	
Question	Response
Mechanical	
AIR CONDITIONING	Inspected
Chilled Water System	Does not Exist
Condenser Water Distribution: Piping, Pumps and Auxiliaries	Does not Exist
Cooling Coil in Ductwork	Does not Exist
Cooling Tower	Does not Exist
DX Split System	Inspected
Indoor Unit	Inspected
Condition	5 - Poor
Deficiency	UP TO 5 TONS: DEFECTIVE/DETERIORATED
Deficiency Location/Instance	Main Office Room 2004
Deficiency Quantity	1
Quantity Uom	EACH
Date of LA of	REPLACE
Potential Action	
	PRIORITY 3
Urgency of Action	PRIORITY 3 LEVEL 2
Urgency of Action Purpose of Action	LEVEL 2
Urgency of Action	
Urgency of Action Purpose of Action Deficiency Photo1 Violations	LEVEL 2 No photo recorded No violations recorded.
Urgency of Action Purpose of Action Deficiency Photo1 Violations Outdoor Unit	LEVEL 2 No photo recorded No violations recorded. Inspected
Urgency of Action Purpose of Action Deficiency Photo1 Violations Outdoor Unit Condition	LEVEL 2 No photo recorded No violations recorded. Inspected 5 - Poor
Urgency of Action Purpose of Action Deficiency Photo1 Violations Outdoor Unit Condition Deficiency	LEVEL 2 No photo recorded No violations recorded. Inspected 5 - Poor UP TO 5 TONS: DEFECTIVE/DETERIORATED
Urgency of Action Purpose of Action Deficiency Photo1 Violations Outdoor Unit Condition Deficiency Deficiency Location/Instance	LEVEL 2 No photo recorded No violations recorded. Inspected 5 - Poor UP TO 5 TONS: DEFECTIVE/DETERIORATED Bus Wash Station
Urgency of Action Purpose of Action Deficiency Photo1 Violations Outdoor Unit Condition Deficiency Deficiency Location/Instance Deficiency Quantity	LEVEL 2 No photo recorded No violations recorded. Inspected 5 - Poor UP TO 5 TONS: DEFECTIVE/DETERIORATED Bus Wash Station 1
Urgency of Action Purpose of Action Deficiency Photo1 Violations Outdoor Unit Condition Deficiency Deficiency Deficiency Location/Instance	LEVEL 2 No photo recorded No violations recorded. Inspected 5 - Poor UP TO 5 TONS: DEFECTIVE/DETERIORATED Bus Wash Station

uestion	Response	
AIR CONDITIONING		
DX Split System		
Outdoor Unit		
Purpose of Action	LEVEL 2	
Deficiency Photo1	No photo recorded	
Violations	No violations recorded.	
Dry Cooler	Does not Exist	
Packaged / Rooftop Unit	Inspected	
Instance	Main Entrance	
Instance Condition	3 - Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Source of Heating Refrigerant Type	Gas R-22	
Instance Manufacturer	Trane	
Equipment	N/A	
Capacity/Size Quantity	20	
Capacity/Size UOM	Tons	
Source of Capacity/Size	Inspector Estimate	
Installation Year	2000	
Source of Installation	Documented	
Deficiency	No deficiencies recorded	
Packaged Terminal A/C	Does not Exist	
Refrigerant Leak Detection System	Does not Exist	
Refrigerant Piping	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Return Fan	Does not Exist	
CENTRAL ACID WASTE NEUTRALIZING TANK	Does not Exist	
CLIMATE CONTROL SYSTEM	Does not Exist	
COMPACTOR	Does not Exist	
CONVEYING	Does not Exist	
DOMESTIC WATER SYSTEM	Inspected	
Domestic Cold Water System	Does not Exist	
Domestic Hot Water System	Does not Exist	
Domestic Water Distribution Piping	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
DRAIN/WASTE/VENT AND STORM SYSTEM	Inspected	
Interior Storm Piping	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Sewage/Waste/Vent Piping	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Sewage Ejector Pump	Does not Exist	
Sump Pump	Does not Exist	

Mechanical Inspection		Q750
Question	Response	
FIXTURES	Inspected	
Staff And Other	Inspected	
Janitor Sink	Does not Exist	
Lavatory/Sink	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Toilet	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Urinal	Does not Exist	
Student	Inspected	
Drinking Fountain	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Lavatory/Sink	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Locker Room Shower	Does not Exist	
Sink And Fountain Combo Unit	Does not Exist	
Toilet	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Urinal	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
GAS FIRED FURNACE	Does not Exist	
GAS SERVICE	Inspected	
Gas Distribution Piping	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Gas Meter Room Exhaust Fan	Does not Exist	
Gas Meter Room Vent	Does not Exist	
Gas Pressure Booster	Does not Exist	
CO/Gas Leak Detection	Does not Exist	
HEATING	Inspected	
Heating Coil In Ductwork	Does not Exist	
Hydronic Heating	Does not Exist	
Radiator/Convector/Fin Tube	Does not Exist	
Steam Heating	Inspected	
F&T/Steam Drip Trap	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
MER Steam and Condensate Piping	Does not Exist	
Steam Condensate Return Piping	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Steam Condensate Return Pumping System	Does not Exist	
Steam Piping	Inspected	
Condition	3 - Fair	
Continuon	2 I MII	

chanical Inspection		Q750
Question	Response	
HEATING		
Steam Heating	Inspected	
Steam Piping	Inspected	
Deficiency	No deficiencies recorded	
Terminal Unit Thermostatic Trap	Does not Exist	
Steam supplied by External Sources	Does not Exist	
Unit Heater/Cabinet Heater	Inspected	
Condition	3 - Fair	
Deficiency	DEFECTIVE	
Deficiency Location/Instance	Workshop Room 2006	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Deficiency Photo1	No photo recorded	
Violations	No violations recorded.	
HEATING PLANT	Does not Exist	
Enclosed IDF Room	Does not Exist	
KITCHEN	Does not Exist	
MDF Room		
Instance on Room 2008	Inspected Inspected	
Dedicated A/C Equipment	Inspected	
Instance on Room 2008 Condition	Inspected 4 - Between Fair and Poor	
-		
Deficiency Deficiency Location/Instance	DOES NOT EXIST Room 2008	
Deficiency Quantity	1	
	EACH	
Quantity Uom Potential Action	INSTALL	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Deficiency Photo1	No photo recorded	
Violations	No violations recorded.	
SCIENCE DEMO ROOM	Does not Exist	
SCIENCE LAB	Does not Exist	
SCIENCE PREP ROOM	Does not Exist	
SPRINKLERS, STANDPIPE, FIRE SYSTEM	Inspected	
Dry Sprinkler Alarm Valve Assembly	Does not Exist	
Wet Sprinkler Alarm Valve Assembly	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Fire Booster Pump Assembly	Does not Exist	
Roof Tank	Does not Exist	
Siamese Connection	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Sprinkler Head	Inspected	
Condition	3 - Fair	

estion	Response	
CDDINIZI EDC CTANINDIDE EIDE CVCTEM	K	
SPRINKLERS, STANDPIPE, FIRE SYSTEM		
Sprinkler Head	DEFECTIVE/DETERIOR ATED	
Deficiency	DEFECTIVE/DETERIORATED	
Deficiency Location/Instance	Room 2005	
Deficiency Quantity	1	
Quantity Uom	EACH DEBY A CE	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 6	
Deficiency Photo1	No photo recorded	
Violations	No violations recorded.	
Sprinkler Piping	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Standpipe System	Does not Exist	
Water Gong	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
SWIMMING POOL	Does not Exist	
VENTILATION	Inspected	
Is the building mechanically ventilated?	Partial	
Exhaust Fan	Inspected	
Approximate Total # of Fans	1-25	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Heating And Ventilating Unit	Inspected	
Condition	4 - Between Fair and Poor	
Deficiency	DEFECTIVE	
Deficiency Location/Instance	Workshop Room 2006	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPAIR	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Deficiency Photo1	No photo recorded	
Violations	No violations recorded.	
Metal Ductwork	Inspected	
Are there any uninsulated ductwork by design in Mechanical	specce	
Rooms?	No	
Are there chain operated dampers?	No	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Supply Fan	Does not Exist	