Asset:	CAMBRIA	HEIGHTS AC	CADEMY - QU	EENS, 188-04	91ST AVENUE	c, New York, 11423	
Inspection Id	Inspection	Type				Time In	Last Edited
ME : Q799	9 Mechanical					2024-03-25 7:36 AM	2024-04-03 10:01 A
sset Data							
Question					Answer		
Are there fuel to	anks?				No		
		entries to the asset	:		1		
MERs/Fan Roo			G0 D		Cafeteria N	MER 017	
• •	paces with Miss	sing or Defective	CO Detectors?		Yes	h- 202 205 G-i D D	105 A
Location(s) Are there any F	Emergency Ston	Switches with M	lissing Hammers?		No	bs 303, 305, Science Prep Room 3	OJA
•		ted Sprinkler Head	•		No		
		ding Components			Yes		
, ,	v		10		Systems:	Climate Control System: Electr	ic System (Heat Timer)
					Years:	2023	
					Systems:	Electric Domestic Water Heater	•
					Years:	2020	
					Systems:	Heating Plant; MDF Room - De (DX Split System)	edicated A/C Equipment
					Years:	2016	
					Systems:	DX Split Systems; Electric Pres Water Service; Fixtures - Staff Toilets; Fixtures - Student: Drir Lavatory/Sinks, Toilets, Urinals Condensate Return Pumping Sy Labs; Science Prep Room; Exha	and Other: Lavatory/Sink sking Fountains (50%), s; Gas Service; Steam sstem; Kitchen; Science
					Years:	2015	
					Systems:	Terminal Unit Thermostatic Tra	nps
					Years:	2013	
riority Conditio	n						
Priority I Condition Exist O Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title Status	PhotoImage
No condition recor	·ded						
spection							
Question					Respons	se	
Mechanical							
AIR CONDIT	IONING				Inspected	d	
Chilled Wat	er System				Does not	Exist	
Condenser V	Nater Distribu	tion: Piping, Pur	mps and Auxiliar	ies	Does not	Exist	
Cooling Coil	l in Ductwork				Does not	Exist	
Cooling Tow	ver				Does not	Exist	
	stem				Inspected	d	
DX Split Sys					Inspected	d	
DX Split Sys Indoor Un					1 - Good		
	n				No defic	iencies recorded	
Indoor Un Conditio	ciency				T	d	
Indoor Un Conditio	ciency				Inspected		
Indoor Un Conditio	ciency J nit				1 - Good		
Indoor Un Conditio Defic Outdoor U	ciency J nit				1 - Good		
Indoor Un Conditio Defic Outdoor U	ciency U nit on				1 - Good	iencies recorded	
Indoor Un Conditio Defic Outdoor U Conditio Defic Dry Cooler	ciency U nit on				1 - Good No defic	iencies recorded Exist	

uestion	Response	
AIR CONDITIONING	-	
Refrigerant Leak Detection System	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Refrigerant Piping	Inspected	
Condition	1 - Good	
Deficiency	DAMAGED/MISSING INSULATION	
Deficiency Location/Instance	Cafeteria MER 017	
Deficiency Quantity	10	
Quantity Uom	L.F.	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Deficiency Photo1	No photo recorded	
Violations	No violations recorded.	
Return Fan	Does not Exist	
CENTRAL ACID WASTE NEUTRALIZING TANK	Does not Exist	
CLIMATE CONTROL SYSTEM	Inspected	
BMS	Does not Exist	
Pneumatic System	Does not Exist	
Hybrid System	Does not Exist	
Electric System	Inspected	
Instance	Throughout (Zone Control)	
Instance Condition	3 - Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Building Area Covered by Operational System	81-100%	
Deficiency	No deficiencies recorded	
Instance	Throughout (Heat Timer)	
Instance Condition	1 - Good	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Building Area Covered by Operational System	81-100%	
Deficiency	No deficiencies recorded	
COMPACTOR	Does not Exist	
CONVEYING	Does not Exist	
DOMESTIC WATER SYSTEM	Inspected	
Domestic Cold Water System	Inspected	
Gravity System	Does not Exist	
Pressure Booster System	Inspected	
Electric Pressure Booster System	Inspected	
Instance	Water Meter Room 001	
Instance Condition	2 - Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Instance Manufacturer	Canariis	
Equipment	N/A	
Equipment Capacity/Size Quantity	2	

hanical Inspection		Q79
nestion	Response	
DOMESTIC WATER SYSTEM		
Domestic Cold Water System		
Pressure Booster System		
Electric Pressure Booster System	m . 1 // D	
Capacity/Size UOM	Total # Pumps	
Capacity/Size2 Quantity	10	
Capacity/Size2 UOM	Total Pumps HP	
Source of Capacity/Size	Documented	
Installation Year	2015	
Source of Installation	Documented	
Deficiency	No deficiencies recorded	
Hydraulic/Pneumatic Booster System	Does not Exist	
Water Service	Inspected	
Instance	Water Meter Room 001	
Instance Condition	1 - Good	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Deficiency	No deficiencies recorded	
Domestic Hot Water System	Inspected	
Domestic Hot Water Remote Storage Tank	Does not Exist	
Domestic Water Heat Exchanger	Does not Exist	
Electric Domestic Water Heater	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Gas Fired Domestic Water Heater	Does not Exist	
Heat Pump Domestic Water Heater	Does not Exist	
Oil Fired Domestic Water Heater	Does not Exist	
Domestic Water Distribution Piping	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
DRAIN/WASTE/VENT AND STORM SYSTEM	Inspected	
Interior Storm Piping	Inspected	
Condition	3 - Fair	
Deficiency	DEFECTIVE/LEAKS	
Deficiency Location/Instance	Boiler Room	
Deficiency Quantity	10	
Quantity Uom	L.F.	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Deficiency Photo1	No photo recorded	
Violations	No violations recorded.	
Sewage/Waste/Vent Piping	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Sewage Ejector Pump	Does not Exist	
Sump Pump	Does not Exist	
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT	Does not Exist	

.•	
uestion	Response
FIXTURES	Inspected
Staff And Other	Inspected
Janitor Sink	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Lavatory/Sink	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Toilet	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Urinal	Does not Exist
Student	Inspected
Drinking Fountain	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Lavatory/Sink	Inspected
Condition	2 - Between Good and Fair
Deficiency	DEFECTIVE AUXILIARY (FAUCET, SHUT OFF VALVE,ET
Deficiency Location/Instance	Girls Toilet Room 008, Boys Toilet Room 212
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Locker Room Shower	Does not Exist
Sink And Fountain Combo Unit	Does not Exist
Toilet	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Urinal 	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
GAS FIRED FURNACE	Does not Exist
GAS SERVICE	Inspected
Gas Distribution Piping	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Gas Meter Room Exhaust Fan	Does not Exist
Gas Meter Room Vent	Does not Exist
Gas Pressure Booster	Does not Exist
CO/Gas Leak Detection	Inspected
Instance	Boiler Room
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Installation Year	2015

recorded recorded recorded od and Fair
recorded
od and Fair
ou and fall
recorded
recorded
recorded
UMD
UMP
017 (leak)
76
Œ
lad
led corrlad
corded.
recorded
od and Fair
od and Fair recorded
recorded
recorded od and Fair
recorded
recorded od and Fair
_

tion	Response	
EATING PLANT	-	
Boiler Auxiliaries	Inspected	
Instance on Basement	Inspected	
Boiler Auxiliary Piping		
Instance on Basement	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Boiler Emergency Stop Switch		
Instance on Basement	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Boiler Feedwater System		
Instance on Basement	Does not Exist	
Boiler Feedwater Treatment(Automatic)		
Instance on Basement	Does not Exist	
Boiler Flue Exhaust		
Instance on Basement	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Boiler Make-up Water Backflow Preventer	140 deficiences recorded	
Instance on Basement	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Boiler Room Steam And Condensate Piping	110 40110101010 10001404	
Instance on Basement	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Boiler Safety Valve	110 40110101010 10001404	
Instance on Basement	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Boiler System	Inspected	
Instance on Basement	Inspected	
Coal-fired Boiler	r	
Instance on Basement	Does not Exist	
Hot Water Boiler	Does not Exist	
Instance on Basement	Does not Exist	
	DOES NOT EXIST	
Modular Boiler	D. (Fig.	
Instance on Basement	Does not Exist	
Steam Boiler		
Instance on Basement	Inspected	
Instance	Boiler Room	
Instance Condition	1 - Good	
Instance Quantity	1,766	
Instance Quantity Uom	MBH Net	
Cast Iron Boiler?	No	
Instance Manufacturer	Weil-McLain	
Equipment	72805-01	
Capacity/Size Quantity	1,766	
Capacity/Size UOM	MBH Net	

estion	Response	
EATING PLANT	response	
Boiler System		
Steam Boiler		
Source of Capacity/Size	Documented	
Installation Year	2016	
Source of Installation	Documented	
Deficiency	No deficiencies recorded	
Fuel System	Inspected	
Instance on Basement	Inspected	
Boiler Fresh Air Louver/Damper		
Do Boiler Combustion Air Louvers exist?	Yes	
Type	Fixed Louver	
Instance on Basement	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Burner/Burner Control Panel		
Instance on Basement	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Fuel Oil Storage/Supply System		
Instance on Basement	Does not Exist	
Gas Trains And Vent At The Boiler		
Instance on Basement	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
nclosed IDF Room	Does not Exist	
ITCHEN	Inspected	
Instance on Basement	Inspected	
CO Detector	Not Required	
Instance on Basement	Not Required	
Gas System	Does not Exist	
Instance on Basement	Does not Exist	
Grease Trap	Inspected	
Instance on Basement	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Hood	Does not Exist	
Instance on Basement	Does not Exist	
Hood Exhaust Ductwork	Does not Exist	
Instance on Basement	Does not Exist	
Hood Exhaust Fan	Does not Exist	
Instance on Basement	Does not Exist	
Hood Fire Suppression System	Does not Exist	
Instance on Basement	Does not Exist	
Hot Water Temperature Booster	Inspected	
Instance on Basement	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Kitchen Sink	Inspected	
Instance on Basement	Inspected	

uestion	Response	
KITCHEN	•	
Kitchen Sink		
Condition	2 - Between Good and Fair	
Deficiency	MISSING AIR GAP	
Deficiency Location/Instance	Kitchen	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Deficiency Photo1	No photo recorded	
Violations	No violations recorded.	
MDF Room	Inspected	
Instance on Room 309	Inspected	
Dedicated A/C Equipment	Inspected	
Instance on Room 309	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
SCIENCE DEMO ROOM	Does not Exist	
SCIENCE LAB	Inspected	
Instance on Room 303	Inspected	
Alternative use	No	
Instance on Room 305	Inspected	
Alternative use	No	
Acid Waste Neutralizing Tank	Inspected	
Instance on Room 305	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Instance on Room 303	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
CO Detector	Inspected	
Instance on Room 305	Inspected	
Condition	4 - Between Fair and Poor	
Deficiency	DEFECTIVE/MISSING	
Deficiency Location/Instance	Room 305	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 6	
Deficiency Photo1	No photo recorded	
Violations	No violations recorded.	
Instance on Room 303	Inspected	
Condition	4 - Between Fair and Poor	
Deficiency	DEFECTIVE/MISSING	
Deficiency Location/Instance	Room 303	
Deficiency Quantity	1	
Quantity Uom	EACH	

hanical Inspection		Q799
nestion	Response	
SCIENCE LAB		
CO Detector		
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 6	
Deficiency Photo1	No photo recorded	
Violations	No violations recorded.	
Emergency Shower	Does not Exist	
Instance on Room 305	Does not Exist	
Instance on Room 303	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Eye Wash	Inspected	
Instance on Room 305	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Instance on Room 303	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Hood Exhaust Ductwork	Does not Exist	
Instance on Room 305	Does not Exist	
Instance on Room 303	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Hood Exhaust Fan	Does not Exist	
Instance on Room 305	Does not Exist	
Instance on Room 303	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Fixed Laboratory Hood	Does not Exist	
Instance on Room 305	Does not Exist	
Instance on Room 303	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Laboratory Sink	Inspected	
Instance on Room 305	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Instance on Room 303	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Make-up Air Unit	Does not Exist	
Instance on Room 305	Does not Exist	
Instance on Room 303	Does not Exist	
SCIENCE PREP ROOM	Inspected	
Instance on Room 305A	Inspected	
Alternative use	No	
Acid Waste Neutralizing Tank	Inspected	
Instance on Room 305A	Inspected	
Condition	2 - Between Good and Fair	
- · · · · · · · · · · · · · · · · · · ·		

estion	Response	
CCIENCE PREP ROOM	Response	
CO Detector	Inspected	
Instance on Room 305A	Inspected	
Condition	4 - Between Fair and Poor	
-	DEFECTIVE/MISSING	
Deficiency		
Deficiency Location/Instance Deficiency Quantity	Room 305A	
	I EACH	
Quantity Uom		
Potential Action	MAINTENANCE PRIORITY 5	
Urgency of Action		
Purpose of Action	LEVEL 6	
Deficiency Photo1	No photo recorded	
Violations	No violations recorded.	
Emergency Shower	Inspected	
Instance on Room 305A	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Eye Wash	Inspected	
Instance on Room 305A	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Hood Exhaust Ductwork	Inspected	
Instance on Room 305A	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Hood Exhaust Fan	Inspected	
Instance on Room 305A	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Fixed Laboratory Hood	Inspected	
Instance on Room 305A	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Laboratory Sink	Inspected	
Instance on Room 305A	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Make-up Air Unit	Does not Exist	
Instance on Room 305A	Does not Exist	
SPRINKLERS, STANDPIPE, FIRE SYSTEM	Does not Exist	
WIMMING POOL	Does not Exist	
/ENTILATION Is the building machanically ventilated?	Inspected	
Is the building mechanically ventilated?	Partial	
Exhaust Fan	Inspected	
Approximate Total # of Fans	1-25	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Heating And Ventilating Unit	Does not Exist	

Building Condition Assessment Survey 2023 - 2024

Mechanical Inspection Q799 Question Response VENTILATION Metal Ductwork Inspected Are there any uninsulated ductwork by design in Mechanical No No Rooms? Are there chain operated dampers? 1 - Good Condition Deficiency No deficiencies recorded **Supply Fan** Does not Exist **Unit Ventilator** Does not Exist