# **Building Condition Assessment Survey 2023 - 2024**

Inspection Id Inspection Type		Time In	Last Edited
EE: Q836 Electrical		2024-03-04 7:34 AM	2024-03-21 9:12 AM
sset Data			
Question	Answer		
Type of Service	Below Gro	und	
Does Interactive Whiteboard (IWB) Exist?	Yes		
Water Penetration in Electrical Room?	No		
Have any Systems/Major Building Components been upgraded?	Yes		
	Systems:	Public Address System	
	Years:	2022	
	Systems:	Telephone System	
	Years:	2021	
	Systems: Years:	Intrusion Alarm System (Remot 2017	e Annunciator)
	Systems:	Interior Lighting, Exit Lights (B	attery Pack)
	Years:	2016	attery rack)
	Systems:	IPDVS/CCTV System, Intrusion	Alarm System (Infrare)
	Systems.	Sensor)	, (11114100
	Years:	2011	
	Systems:	Fire Alarm System	
	Years:	2000	
	Systems:	Intrusion Alarm System	
	Years:	1998	
DEDICATED INTERCOMS IN FIRE RESCUE AREAS			
Question  Are there any Life Rescue Assistance Areas, Fire Rescue Areas,	Response No		
and/or Holding Rooms in your building?	110		
riority Condition			
Condition Exist Category Description Affected Desc Last Year?	ation Person(s) cription Notified	Person(s) Title Status	PhotoImage
No condition recorded .			
Ouestion Question	Respons	70	
Electrical	Kespons	90	
AUDITORIUM	Does not	Eviat	
CAFETERIA	Does not		
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE			
Lighting	Inspected		
	Inspected	1	
	•		
Does a Chandelier exist?	No		
Does a Chandelier exist?  Lighting Fixture - Fluorescent	No Inspected		
Does a Chandelier exist?  Lighting Fixture - Fluorescent  Pendant Mounted	No Inspected Inspected	d	
Does a Chandelier exist?  Lighting Fixture - Fluorescent  Pendant Mounted  Condition	No Inspected Inspected 2 - Betw	d een Good and Fair	
Does a Chandelier exist?  Lighting Fixture - Fluorescent  Pendant Mounted  Condition  Deficiency	No Inspected Inspected 2 - Betw No defic	d een Good and Fair iencies recorded	
Does a Chandelier exist?  Lighting Fixture - Fluorescent  Pendant Mounted  Condition  Deficiency  Surface Mounted	No Inspected Inspected 2 - Betw No defic Does not	d een Good and Fair iencies recorded Exist	
Does a Chandelier exist?  Lighting Fixture - Fluorescent  Pendant Mounted  Condition  Deficiency  Surface Mounted  Recessed Mounted	No Inspected Inspected 2 - Betw No defic Does not Inspected	d een Good and Fair iencies recorded Exist	
Does a Chandelier exist?  Lighting Fixture - Fluorescent  Pendant Mounted  Condition  Deficiency  Surface Mounted  Recessed Mounted  Condition	No Inspected Inspected 2 - Betw No defic Does not Inspected 2 - Betw	d een Good and Fair iencies recorded Exist d een Good and Fair	
Does a Chandelier exist?  Lighting Fixture - Fluorescent  Pendant Mounted  Condition  Deficiency  Surface Mounted  Recessed Mounted  Condition  Deficiency	No Inspected Inspected 2 - Betw No defic Does not Inspected 2 - Betw No defic	d een Good and Fair iencies recorded Exist d een Good and Fair iencies recorded	
Does a Chandelier exist?  Lighting Fixture - Fluorescent  Pendant Mounted  Condition  Deficiency  Surface Mounted  Recessed Mounted  Condition  Deficiency  Lighting Fixture - HID	No Inspected Inspected 2 - Betw No defic Does not Inspected 2 - Betw No defic Does not Inspected Does not	deen Good and Fair iencies recorded Exist deen Good and Fair iencies recorded Exist	
Does a Chandelier exist?  Lighting Fixture - Fluorescent  Pendant Mounted  Condition  Deficiency  Surface Mounted  Recessed Mounted  Condition  Deficiency	No Inspected Inspected 2 - Betw No defic Does not Inspected 2 - Betw No defic	d een Good and Fair iencies recorded Exist d een Good and Fair iencies recorded Exist Exist Exist Exist	

## **Building Condition Assessment Survey 2023 - 2024**

urear hispection		Q050
nestion	Response	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE		
Lighting		
Lighting Fixture - LED		
COMPUTER LAB	Does not Exist	
GYMNASIUM	Does not Exist	
KITCHEN	Does not Exist	
LIBRARY	Does not Exist	
LOCKER ROOM	Does not Exist	
MULTIPURPOSE ROOM	Does not Exist	
SCIENCE DEMO ROOM	Does not Exist	
SCIENCE LAB	Does not Exist	
SCIENCE PREP ROOM	Does not Exist	
SWIMMING POOL	Does not Exist	
TOILET ROOM - STAFF	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Does not Exist	
Surface Mounted	Does not Exist	
Recessed Mounted		
Condition	Inspected  2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID	Does not Exist	
Lighting Fixture - Incandescent	Does not Exist	
Lighting Fixture - LED	Does not Exist	
TOILET ROOM - STUDENT	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Does not Exist	
Surface Mounted	Does not Exist	
Recessed Mounted	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID	Does not Exist	
Lighting Fixture - Incandescent	Does not Exist	
Lighting Fixture - LED	Does not Exist	
AUXILIARY SIGNAL/BELL SYSTEM	Does not Exist	
EMERGENCY DC STANDBY BATTERY POWER	Does not Exist	
EMERGENCY GENERATOR SET	Does not Exist	
EMERGENCY LIGHT/EXIT LIGHT PANEL	Does not Exist	
EMERGENCY LIGHTING	Inspected	
Battery Pack	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Non Battery Pack	Does not Exist	
EXIT LIGHT	Inspected	
EXIT LIGHT  Battery Pack	Inspected Inspected	

# **Building Condition Assessment Survey 2023 - 2024**

Question	Response
EXIT LIGHT	Inspected
Battery Pack	Inspected
Deficiency	No deficiencies recorded
Non Battery Pack	Does not Exist
EXIT/EMERGENCY LIGHT	Does not Exist
FIRE ALARM SYSTEM	Inspected
Replacement Quantity	8,000
Replacement Uom	S.F.
Bell/Horn	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Strobe	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Manual Pull Station	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Duct Smoke Detector	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Area Smoke Detector	Does not Exist
CO Detector	Does not Exist
Heat Detector	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Elevator Recall	Does not Exist
Magnetic Door Holder/Contactor	Does not Exist
Fused Cutout Panel	Does not Exist
Fire Alarm Digital Communicator	Does not Exist
Main Panel	Does not Exist
Sub-Panel	Does not Exist
Remote Annunciator	Inspected
Display Monitor	Does not Exist
Panel	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Printer	Does not Exist
Punch Register	Does not Exist
Sprinkler Flow/Air Pressure Switch	Does not Exist
Tamper Flow Switch/Chain	Does not Exist
GROUNDING SYSTEM	
Condition	Inspected 3 - Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	Does not Exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected

## **Building Condition Assessment Survey 2023 - 2024**

uestion	Response
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Does not Exist
LIGHTNING PROTECTION	Does not Exist
MOTOR CONTROLLER	Does not Exist
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Does not Exist
Fused Knife Switch Type	Does not Exist
Fused Toggle Switch Type	Does not Exist
Molded Case Circuit Breaker Type	Inspected
Condition	3 - Fair
Deficiency	PANEL BOARD DOOR LOCK IS MISSING
Deficiency Location/Instance	Mechanical Room
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Mechanical Room
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
PUBLIC ADDRESS SYSTEM	Inspected
Replacement Quantity	8,000
Replacement Uom	S.F.
Instance	Connected to Main Asset Q036
Instance Condition	1 - Good
Instance Quantity	1
Instance Quantity Uom	EACH
Model	N/A
Installation Year	2022
Source of Installation	Custodial Staff
Deficiency	CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Rooms (C.R.1, C.R.4, C.R.6)
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded

# **Building Condition Assessment Survey 2023 - 2024**

stion	Response
CURITY	Inspected
IPDVS/CCTV System	Inspected
Replacement Quantity	8,000
Replacement Uom	S.F.
Installation Year	2011
Source of Installation	Custodial Staff
Condition	3 - Fair
Deficiency	No deficiencies recorded
ntrusion Alarm System	Inspected
Replacement Quantity	8,000
Replacement Uom	S.F.
Central Control Panel	Inspected
Instance	Mechanical Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	N/A
Installation Year	1998
Source of Installation	Inspector Estimate
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	5 - Poor
Deficiency	SWITCH NOT OPERATIONAL
Deficiency Location/Instance	Room M12
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Remote Annunciator	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
ighting - Security	Inspected
Replacement Uom	EACH
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Location/Instance	Exterior Wall (Building Perimeter)
Deficiency Quantity	6
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1

## **Building Condition Assessment Survey 2023 - 2024**

uestion	Response	
SECURITY	Inspected	
Lighting - Security		
Purpose of Action	LEVEL 3	
Deficiency Photo1	No photo recorded	
Violations	No violations recorded.	
SERVICE SWITCH	Inspected	
Instance	Mechanical Room	
Instance Condition	3 - Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Instance Manufacturer	General Switch Co.	
Equipment	Main Switch	
Capacity/Size Quantity	600	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Inspector Estimate	
Installation Year	1972	
Source of Installation	Documented	
Deficiency	No deficiencies recorded	
SWITCHBOARD	Does not Exist	
TELEPHONE SYSTEM	Inspected	
PBX/Intercom	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Standard	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
TRANSFORMER	Does not Exist	