Building Condition Assessment Survey 2023 - 2024

Inspection Id Inspection Type		Time In	Last Edited
EE: Q851 Electrical		2023-11-01 8:12 AM	2024-06-21 10:52 A
et Data			
Question	Answer		
Type of Service	Below Gro	ound	
Does Interactive Whiteboard (IWB) Exist?	Yes		
Water Penetration in Electrical Room?	No		
Have any Systems/Major Building Components been upgraded?	Yes		
	Systems:	Intrusion Alarm System (Infrared	l Sensor, Panic Switch)
	Years:	2022	
	Systems:	Emergency Lighting (Battery Pa	ck), Security Lights
	Years:	2020	
	Systems:	Interior Lighting	
	Years:	2015	
	Systems:	Partial Molded Case Circuit Brea	ker Type Panel Board
	Years:	2010, 2017	
	Systems:	IPDVS/CCTV System	
	Years:	2010	
	Systems:	Intrusion Alarm System (Siren/S	trobe)
	Years:	2002	
DEDICATED INTERCOMS IN FIRE RESCUE AREAS			
Question	Response		
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	No		

Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Status	PhotoImage
Yes	Water Leaks onto Electrical Equipment	N/A	Lighting Fixture	Girls Toilet Room	Charles Saccoccio	Custodian	Sent to DSF	
Yes	Fire Alarm System - Components Not Operational	N/A	FIRE ALARM SYSTEM Sub- Panel Bell At Panel	Fan Room	Charles Saccoccio	Custodian	Sent to DSF	

pection		
Question	Response	
Electrical		
AUDITORIUM	Does not Exist	
CAFETERIA	Does not Exist	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected	
Lighting	Inspected	
Does a Chandelier exist?	No	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Does not Exist	
Surface Mounted	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not Exist	
Lighting Fixture - HID	Does not Exist	
Lighting Fixture - Incandescent	Does not Exist	

Building Condition Assessment Survey 2023 - 2024

	Q051
Response	
Inspected	
Does not Exist	
Inspected	
2 - Between Good and Fair	
No deficiencies recorded	
Does not Exist	
Does not Exist	
Inspected	
Inspected	
Inspected	
Does not Exist	
Inspected	
2 - Between Good and Fair	
No deficiencies recorded	
Does not Exist	
Does not Exist	
Does not Exist Does not Exist	
Does not Exist	
	Inspected Does not Exist Inspected 2 - Between Good and Fair No deficiencies recorded Does not Exist Inspected Inspected Inspected Does not Exist Inspected 2 - Between Good and Fair No deficiencies recorded Does not Exist Does not Exist Inspected Inspected 2 - Between Good and Fair No deficiencies recorded Does not Exist Inspected Inspected Inspected Does not Exist

Building Condition Assessment Survey 2023 - 2024

Response Inspected	
Inspected	
nispected	
Inspected	
No deficiencies recorded	
Does not Exist	
Inspected	
Inspected	
3 - Fair	
No deficiencies recorded	
Does not Exist	
Does not Exist	-
Inspected	
10,000	
Does not Exist	
Inspected	
Inspected	
4 - Between Fair and Poor	
BELL NOT OPERATIONAL	
Fan Room	
1	
EACH	
REPLACE	
PRIORITY 5	
LEVEL 6	
No photo recorded	
	Does not Exist Inspected Inspected 3 - Fair No deficiencies recorded Does not Exist Inspected 10,000 S.F. Inspected 3 - Fair No deficiencies recorded Does not Exist Inspected 3 - Fair No deficiencies recorded Does not Exist Inspected 3 - Fair No deficiencies recorded Does not Exist Inspected 3 - Fair No deficiencies recorded Does not Exist Inspected 4 - Between Fair and Poor BELL NOT OPERATIONAL Fan Room 1 EACH

Building Condition Assessment Survey 2023 - 2024

Question	Response
FIRE ALARM SYSTEM	
Sub-Panel	
Fire Alarm Control Panel (Standard)	Inspected
Instance	Fan Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	ACME
Equipment	Smoke Detection Control Board
Installation Year	1972
Source of Installation	Documented
Deficiency	No deficiencies recorded
Remote Annunciator	Does not Exist
Sprinkler Flow/Air Pressure Switch	Does not Exist
Tamper Flow Switch/Chain	Does not Exist
GROUNDING SYSTEM	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	Does not Exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Does not Exist
LIGHTNING PROTECTION	Does not Exist
MOTOR CONTROLLER	Does not Exist
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Does not Exist
Fused Knife Switch Type	Does not Exist
Fused Toggle Switch Type	Does not Exist
Molded Case Circuit Breaker Type Condition	Inspected 3 - Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Fan Room
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
PUBLIC ADDRESS SYSTEM	Inspected
Replacement Quantity	10,000
Replacement Uom	S.F.
Instance	Connected to Main Asset Q147
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	N/A

Building Condition Assessment Survey 2023 - 2024

PUBLIC ADDRESS SYSTEM Installation Year 2010 Source of Installation Inspector Estimate Deficiency No deficiencies recorded SECURITY Inspected IPDVS/CCTV System Inspected	
Source of Installation Inspector Estimate Deficiency No deficiencies recorded SECURITY Inspected	
Deficiency No deficiencies recorded SECURITY Inspected	
Deficiency No deficiencies recorded SECURITY Inspected	
IDDVS/CCTV System Inspected	
H D Y S/CC I Y S Y SWIII HIS PECIEU	
Replacement Quantity 10,000	
Replacement Uom S.F.	
Installation Year 2010	
Source of Installation Custodial Staff	
Condition 3 - Fair	
Deficiency No deficiencies recorded	
Intrusion Alarm System Inspected	
Replacement Quantity 10,000	
Replacement Uom S.F.	
Central Control Panel Does not Exist	
Infrared Sensor Inspected	
Condition 1 - Good	
Deficiency No deficiencies recorded	
Panic Switch Inspected	
Condition 1 - Good	
Deficiency No deficiencies recorded	
Remote Annunciator Does not Exist	
Siren/Strobe Inspected	
Condition 3 - Fair	
Deficiency No deficiencies recorded	
Lighting - Security Inaccessible	
SERVICE SWITCH Inspected	
Instance Fan Room	
Instance Condition 3 - Fair	
Instance Quantity 1	
Instance Quantity Uom EACH	
Instance Manufacturer I.T.E.	
Equipment Service Sw.	
Capacity/Size Quantity 800	
Capacity/Size UOM Amps	
Source of Capacity/Size Nameplate	
Installation Year 1972	
Source of Installation Documented	
Deficiency No deficiencies recorded	
SWITCHBOARD Does not Exist	
TELEPHONE SYSTEM Inspected	
PBX/Intercom Inspected	_
Condition 3 - Fair	
Deficiency No deficiencies recorded	
Standard Inspected	
StandardInspectedCondition3 - Fair	