### **Building Condition Assessment Survey 2023-2024**

	P.S. 25 ANNEX	(OLD 4) - STATEN ISLANI	D, 4210 ARTHU	R KILL ROAD	, STATEN ISI	LAND, NY, 10	309
Inspection Id	Inspection Type				Time	In	Last Edited
3283	ELECTRICAL				2024-	02-16 07:29AN	1 2024-03-06 01:00PM
sset Data							
Question				Answer			
Have any Syster	ns/Major Building C	Components been upgraded?		Systems:	Public Addres	s System (Ampl	ifier)
				Years:	2020		
				Systems: Years:	Lighting - Sec 2019	urity, LAN, Tel	ephone System
				Systems:	Interior Fluor Exit Lights (E		(Except Gymnasium),
				Years: Systems:	2016 Intrusion Alar	m System (Pani	c Switch)
				Years:	2015	in System (1 am	e Switch)
				Systems:	Gymnasium (	( iahtina)	
				Years:	2010	Lighting)	
				Systems:		oht/Exit Lioht P	anel, Molded Case
				•	Circuit Break	er Panel Board	anci, wiolded Case
				Years:	2000		
				Systems:	Fire Alarm Sy	stem	
				Years:	1999	_	
				Systems:	Intrusion Alar	m System	
				Years:	1998		
				Systems:		h, Switchboard	
				Years:	1995		
Type of Service		F : 49		Below Gr	ound		
	e Whiteboard (IWB) on In Electrical Roor			Yes No			
		N FIRE RESCUE AREAS		110			
Question	INTERCOMS	NTINE RESCUE TITELS			Response		
	Life Rescue Assista	nce Areas, Fire Rescue Areas, an	nd/or Holding Room		No		
your building?	?						
riority Condition							
Exist Prior	rity	Condition	Component	Location	Person(s)	Person(s)	Photo
						Title	Imaga
Last Year? Cate	egory	Description	Affected	Description	Notified	11116	Image
No condition rec		Description	Affected	Description	Notified	Title	mage
No condition rec		Description	Affected	Description	Notified	Title	image
No condition rec		Description	Affected	Response		Title	Image
No condition reconspection  Question  Electrical	corded	Description	Affected	Response	,	Title	Image
No condition reconspection  Question  Electrical  ATHLETIC I	FIELD	Description	Affected	Response  Does not	exist	THE	Image
No condition reconstruction  Question  Electrical  ATHLETIC F	FIELD	Description	Affected	Response  Does not  Does not	exist exist	THE	Image
No condition reconstruction  Question  Electrical  ATHLETIC I  AUDITORIU  CAFETERIA	FIELD	Description	Affected	Does not Does not Inspected	exist exist	THE	Image
No condition reconstruction  Question  Electrical  ATHLETIC I  AUDITORIU  CAFETERIA	FIELD	Description	Affected	Response  Does not  Does not	exist exist	THE	Image
No condition reconstruction  Question  Electrical  ATHLETIC H  AUDITORIU  CAFETERIA  Ins  Lighting	FIELD	Description	Affected	Does not Does not Inspected	exist exist	THE	Image
No condition reconspection  Question  Electrical  ATHLETIC I  AUDITORIU  CAFETERIA  Ins  Lighting  Ins	FIELD UM A stance on Basement		Affected	Does not Does not Inspected Inspected	exist exist	THE	Image
No condition reconspection  Question  Electrical  ATHLETIC I  AUDITORIU  CAFETERIA  Ins  Lighting  Lighting I	FIELD  M A stance on Basement		Affected	Does not Does not Inspected Inspected	exist exist	THE	Image
No condition reconspection  Question  Electrical  ATHLETIC F  AUDITORIU  CAFETERIA  Ins  Lighting  Lighting F  Ins	FIELD  JM  A stance on Basement stance on Basement		Affected	Does not Does not Inspected Inspected	exist exist		Image
No condition reconspection  Question  Electrical  ATHLETIC H  AUDITORIU  CAFETERIA  Ins  Lighting  Lighting Ins  Pendant	FIELD  JM  Stance on Basement  stance on Basement  Fixture - Fluorescer  stance on Basement		Affected	Does not Does not Inspected Inspected	exist exist		Image
No condition reconspection  Question  Electrical  ATHLETIC F  AUDITORIU  CAFETERIA  Ins  Lighting  Ins  Lighting F  Ins  Pendant  Ins	FIELD  M A Stance on Basement  Stance on Basement  Fixture - Fluorescer  Stance on Basement  t Mounted		Affected	Does not Does not Inspected Inspected Inspected	exist exist		Image
No condition reconstruction  Question  Electrical  ATHLETIC F  AUDITORIU  CAFETERIA  Ins  Lighting  Ins  Lighting F  Ins  Pendant  Ins  Surface	FIELD  M A stance on Basement  Fixture - Fluorescer stance on Basement  t Mounted stance on Basement		Affected	Does not Does not Inspected Inspected Inspected	exist exist exist		Image
No condition reconspection  Question  Electrical  ATHLETIC I  AUDITORIU  CAFETERIA  Ins  Lighting  Ins  Lighting I  Ins  Pendant  Ins  Surface  Ins	FIELD  M A stance on Basement stance on Basement Fixture - Fluorescer stance on Basement t Mounted stance on Basement		Affected	Does not Inspected Inspected Inspected Inspected Inspected Inspected	exist exist exist		Illiage
No condition reconspection  Question  Electrical  ATHLETIC I  AUDITORIU  CAFETERIA  Ins  Lighting  Ins  Pendant Ins  Surface  Ins  Ins  Ins  Ins  Ins  Ins  Ins  In	FIELD  JM  A stance on Basement  Fixture - Fluorescer  stance on Basement  t Mounted  stance on Basement		Affected	Does not Does not Inspected Inspected Inspected Inspected 2- Between	exist exist exist		Image
No condition reconstruction    No condition reconstruction	FIELD  JM  A stance on Basement  Stance on Basement  Fixture - Fluorescer  stance on Basement  t Mounted  stance on Basement  Mounted  stance on Basement  stance on Basement		Affected	Does not Does not Inspected Inspected Inspected Inspected 2- Between	exist exist exist en Good and Fai		Image

## **Building Condition Assessment Survey 2023-2024**

Electrical Inspection	R025

Question	Response
CAFETERIA	
Lighting	
Lighting Fixture - HID	
Instance on Basement	Does not exist
Lighting Fixture - Incandescent	
Instance on Basement	Does not exist
Lighting Fixture - LED	
Instance on Basement	Does not exist
Local Sound System	
Instance on Basement	Does not exist
Projection System	
Instance on Basement	Does not exist
Theater Lighting System	
Instance on Basement	Does not exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected
Lighting	Inspected
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
COMPUTER LAB	Inspected
Instance on Room 103	Inspected
Power Panel?	No
Lighting	
Instance on Room 103	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 103	Inspected
Pendant Mounted	•
Instance on Room 103	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 103	Does not exist
Recessed Mounted	
Instance on Room 103	Does not exist
Lighting Fixture - HID	
Instance on Room 103	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 103	Does not exist
Lighting Fixture - LED	
Instance on Room 103	Does not exist
Raceway With Receptacles	
Instance on Room 103	Does not exist
GYMNASIUM	Inspected
Instance on 1st Floor	Inspected
Lighting	

## **Building Condition Assessment Survey 2023-2024**

Question	Response	
GYMNASIUM		
Lighting		
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 1st Floor	Does not exist	
Lighting Fixture - HID		
Instance on 1st Floor	Inspected	
Pendant Mounted	1	
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Does not exist	
Local Sound System		
Instance on 1st Floor	Does not exist	
Projection System		
Instance on 1st Floor	Does not exist	
Scoreboard		
Instance on 1st Floor	Does not exist	
Theater Lighting System		
Instance on 1st Floor	Does not exist	
KITCHEN	Inspected	
Instance on Basement	Inspected	
Lighting		
Instance on Basement	Inspected	
Lighting Fixture - Fluorescent		
Instance on Basement	Inspected	
Pendant Mounted		
Instance on Basement	Does not exist	
<b>Surface Mounted</b>		
Instance on Basement	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on Basement	Does not exist	
Lighting Fixture - HID		
Instance on Basement	Does not exist	
Lighting Fixture - Incandescent		
Instance on Basement	Does not exist	

## **Building Condition Assessment Survey 2023-2024**

incui inspection	1025
Question	Response
KITCHEN	
Lighting	
Lighting Fixture - LED	
Instance on Basement	Does not exist
LIBRARY	Does not exist
LOCKER ROOM	Does not exist
MULTIPURPOSE ROOM	Does not exist
SCIENCE DEMO ROOM	Does not exist
SCIENCE LAB	Does not exist
SCIENCE PREP ROOM	Does not exist
<u></u>	Does not exist
SWIMMING POOL TOURT POOM STAFF	
TOILET ROOM - STAFF	Inspected
Lighting	Inspected Inspected
Lighting Fixture - Fluorescent Pendant Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Does not exist
Recessed Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - Headucscent  Lighting Fixture - LED	Does not exist
TOILET ROOM - STUDENT	Inspected
	Inspected
Lighting Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Condition	5- Poor
Deficiency	BELL TRANSFORMER PANEL NOT OPERATIONAL
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE PANEL
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not exist
EMERGENCY GENERATOR SET	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	3- Fair

## **Building Condition Assessment Survey 2023-2024**

arical Inspection		K025
Question	Response	
EMERGENCY LIGHTING		
Battery Pack		
Deficiency	BATTERY NOT OPERATIONAL	
Deficiency Location/Instance	Boiler Room	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE BATTERY	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Non Battery Pack	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
EXIT LIGHT	Inspected	
Battery Pack	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Non Battery Pack	Does not exist	
EXIT/EMERGENCY LIGHT	Does not exist	
FIRE ALARM SYSTEM	Inspected	
Bell/Horn	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Strobe	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Manual Pull Station	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fan Shutdown Control	Does not exist	
Duct Smoke Detector	Does not exist	
Area Smoke Detector	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
CO Detector	Does not exist	
Heat Detector	Does not exist	
Elevator Recall	Does not exist	
Magnetic Door Holder/Contactor	Does not exist	
Fused Cutout Panel	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Digital Communicator	Does not exist	
Main Panel	Inspected	
Bell At Panel	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Electronic)	Inspected	
Instance	Main Entrance Lobby	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Gamewell	
Model	N/A	
EquipmentId	N/A	
Installation Year	1999	

## **Building Condition Assessment Survey 2023-2024**

iricui Inspection		R025
Question	Response	
FIRE ALARM SYSTEM		
Main Panel		
Fire Alarm Control Panel (Electronic)		
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Standard)	Does not exist	
Sub-Panel	Inspected	
Bell At Panel	Does not exist	
Fire Alarm Control Panel (Electronic)	Inspected	
Instance	Main Entrance Lobby	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Gamewell	
Model	ESP-102	
EquipmentId	Fire Alarm Indicating Circuit	
Installation Year	1999	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Standard)	Does not exist	
Remote Annunciator	Inspected	
Display Monitor	Does not exist	
Panel	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Printer	Does not exist	
Punch Register	Does not exist	
Sprinkler Flow/Air Pressure Switch	Does not exist	
Tamper Flow Switch/Chain	Does not exist	
GROUNDING SYSTEM	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
INTERCOM SYSTEM	Does not exist	
LAN	Inspected	
Local Distribution Frame (I/LDF)	Does not exist	
Main Equipment Rack (MDF)	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
·	Does not exist	
LIGHTNING PROTECTION		
MOTOR CONTROLLER	Inspected	
MOTOR CONTROL CENTER	Does not exist	
MOTOR STARTER/CONTACTOR	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Variable Frequency Drive	Does not exist	
PANEL BOARD	Inspected	
Fused Disconnect Switch Type	Does not exist	
Fused Knife Switch Type	Does not exist	
Fused Toggle Switch Type	Does not exist	
Molded Case Circuit Breaker Type	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
PUBLIC ADDRESS SYSTEM	Inspected	
Instance	Main Office - Room 100	

## **Building Condition Assessment Survey 2023-2024**

uestion	Response
PUBLIC ADDRESS SYSTEM	
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Biamp Advantage 301e
Installation Year	1980
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Main Office - Room 100
Deficiency Quantity	15,500
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
SECURITY	Inspected
IPDVS/CCTV System	Does not exist
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	Electrical Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 50P
Installation Year	1998
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	3- Fair
Deficiency	SENSOR NOT OPERATIONAL
Deficiency Location/Instance	By Room 206A
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Violations	No violations recorded
Panic Switch	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting - Security	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
SERVICE SWITCH	Inspected
Instance	Electrical Room
Instance Instance Condition	3- Fair
Instance Quantity	1 EACH

### **Building Condition Assessment Survey 2023-2024**

Question	Response
SERVICE SWITCH	
Manufacturer	All City Switchboard
EquipmentId	Main
Capacity/Size Quantity	800
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1995
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
SWITCHBOARD	Inspected
Number of Spares	3
Fused Disconnect Switch Type	Inspected
Instance	Electrical Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	All City Switchboard
EquipmentId	N/A
Capacity/Size Quantity	800
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	2
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Service Switch Size
Installation Year	1995
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not exist
Molded Case Circuit Breaker Type	Does not exist
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
TRANSFORMER	Does not exist