Building Condition Assessment Survey 2023-2024

Electrical Inspection R045

Asset:	P.S. 45 - STATEN ISLAND, 58 LAWRENCE AVENUE, STATEN ISLAND, NY, 10310			
Inspection Id	ction Id Inspection Type Time In Last Edited			
3856	ELECTRICAL	2024-03-11 07:15AM	2024-04-04 01:49PM	

Ass

Question	Answer
Have any Systems/Major Building Components been upgraded?	Systems: Lighting - Security
	Years: 2021, 2018
	Systems: Retrofitted Interior LED Lighting
	Years: 2021
	Systems: Partial Molded Case Circuit Breaker Panel Board
	Years: 2018, 2014, 2000, 1990
	Systems: IPDVS/CCTV System, Gymnasium (LED Lighting Variable Frequency Drive
	Years: 2015
	Systems: Library
	Years: 2014
	Systems: Auditorium (Projection System, Local Sound System) Theater Lighting System)
	Years: 2013
	Systems: Fused Disconnect Switch Type Panel Board
	Years: 2010, 2000
	Systems: Emergency Light/Exit Light Panel, Service Switch Switchboard, Telephone System
	Years: 2010
	Systems: Emergency Generator Set (Battery Charger)
	Years: 2007
	Systems: Intrusion Alarm System
	Years: 2006
	Systems: Fire Alarm System, Public Address System, Local Sound System (Cafeteria, Gymnasium)
	Years: 2000
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Water Penetration In Electrical Room?

DEDICATED INTERCOMS IN TIRE RESCUE AREAS	
Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in	No
your building?	

Yes

Priority Condition

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
No	Grounding System - Defective	Grounding Bar completely detached from the Cold water pipe.	Grounding System	Basement - Boiler Room	Harry Cender	Custodian	
No	Water Penetration in Electrical Room	Water penetrates through foundation wall.	Electrical Equipment	Basement - Electrical Room	Harry Cender	Custodian	

Inspection

Inspection	
Question	Response
Electrical	

Building Condition Assessment Survey 2023-2024

ricai Inspection		K045
Question	Response	
ATHLETIC FIELD	Does not exist	
AUDITORIUM	Inspected	
Instance on 1st Floor	Inspected	
House Lighting	*	
Instance on 1st Floor	Inspected	
Does a Chandelier Exist?	No	
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Inspected	
Pendant Mounted	<u> </u>	
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 1st Floor	Does not exist	
Local Sound System		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Installation Year	2013	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Is the projector on a cart or installed on the ceiling?	Ceiling	
Deficiency	No deficiencies recorded	
Theater Lighting System		
Instance on 1st Floor	Inspected	
Dimming System		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Theater Lighting		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
CAFETERIA	Inspected	
Instance on 1st Floor	Inspected	
Lighting	•	
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		

Building Condition Assessment Survey 2023-2024

Electrical Inspection	R045
0 4:	n.

uestion	Response
CAFETERIA	
Lighting	
Lighting Fixture - LED	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor	Does not exist
Local Sound System	
Instance on 1st Floor	Inspected
Instance Condition	5- Poor
Installation Year	2000
Source of Installation Year	Documented
Deficiency	AMPLIFIER NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE SYSTEM
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Projection System	
Instance on 1st Floor	Does not exist
Theater Lighting System	
Instance on 1st Floor	Does not exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected
Lighting	Inspected
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Inspected
Pendant Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Condition	2- Between Good and Fair
·	No deficiencies recorded
Deficiency	
COMPUTER LAB	Does not exist
GYMNASIUM	Inspected
Instance on 3rd Floor	Inspected
Lighting	
Instance on 3rd Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 3rd Floor	Does not exist
Lighting Fixture - HID	
Instance on 3rd Floor	Does not exist
Lighting Fixture - Incandescent	

Building Condition Assessment Survey 2023-2024

Electrical InspectionR045QuestionResponse

1		
Question	Response	
GYMNASIUM		
Lighting		
Lighting Fixture - Incandescent		
Instance on 3rd Floor	Does not exist	
Lighting Fixture - LED		
Instance on 3rd Floor	Inspected	
Pendant Mounted		
Instance on 3rd Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on 3rd Floor	Does not exist	
Recessed Mounted		
Instance on 3rd Floor	Does not exist	
Local Sound System		
Instance on 3rd Floor	Inspected	
Instance Condition	5- Poor	
Installation Year	2000	
Source of Installation Year	Documented	
Deficiency	AMPLIFIER NOT OPERATIONAL	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE SYSTEM	
Urgency of Action	PRIORITY 2	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Projection System		
Instance on 3rd Floor	Does not exist	
Scoreboard		
Instance on 3rd Floor	Does not exist	
Theater Lighting System		
Instance on 3rd Floor	Does not exist	
KITCHEN	Inspected	
Instance on 1st Floor	Inspected	
Lighting		
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 1st Floor	Does not exist	
LIBRARY	Inspected	
Instance on Room 316	Inspected	
	*	

Building Condition Assessment Survey 2023-2024

Electrical Inspection	R045
Liectrical Inspection	K043

neui Inspection		1045
Question	Response	
LIBRARY		
Lighting		
Instance on Room 316	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 316	Does not exist	
Lighting Fixture - HID		
Instance on Room 316	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 316	Does not exist	
Lighting Fixture - LED		
Instance on Room 316	Inspected	
Pendant Mounted		
Instance on Room 316	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room 316	Does not exist	
Recessed Mounted		
Instance on Room 316	Does not exist	
Raceway With Receptacles		
Instance on Room 316	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Projection System		
Instance on Room 316	Does not exist	
LOCKER ROOM	Inspected	
Instance on 3rd Floor	Inspected	
Alternative Use	Yes	
Lighting	103	
Instance on 3rd Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on 3rd Floor	Does not exist	
Lighting Fixture - HID	Does not exist	
Instance on 3rd Floor	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Instance on 3rd Floor	Does not exist	
Lighting Fixture - LED	Does not exist	
Instance on 3rd Floor	Inspected	
Pendant Mounted	nispected	
Instance on 3rd Floor	Does not exist	
Surface Mounted	Does not exist	
Instance on 3rd Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
	140 deficiencies recorded	
Recessed Mounted	Description in the second second	
Instance on 3rd Floor	Does not exist	
MULTIPURPOSE ROOM	Does not exist	
SCIENCE DEMO ROOM	Inspected	
Instance on Room 207	Inspected	
Power Panel?	No	
Alternative Use	No	
Lighting		
Instance on Room 207	Inspected	

Building Condition Assessment Survey 2023-2024

com inspection		110 10
uestion	Response	
SCIENCE DEMO ROOM		
Lighting		
Lighting Fixture - Fluorescent		
Instance on Room 207	Does not exist	
Lighting Fixture - HID		
Instance on Room 207	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 207	Does not exist	
Lighting Fixture - LED		
Instance on Room 207	Inspected	
Pendant Mounted		
Instance on Room 207	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room 207	Does not exist	
Recessed Mounted		
Instance on Room 207	Does not exist	
Emergency Gas Shut-Off Valve		
Instance on Room 207	Does not exist	
Emergency Shut-Off Power		
Instance on Room 207	Does not exist	
Power Supply		
Instance on Room 207	Does not exist	
Projection System		
Instance on Room 207	Does not exist	
SCIENCE LAB	Does not exist	
SCIENCE PREP ROOM	Does not exist	
SWIMMING POOL	Does not exist	
TOILET ROOM - STAFF	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Inspected	
Pendant Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	-
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
TOILET ROOM - STUDENT	Inspected	
	Inspected	
Lighting Lighting Fixture - Fluorescent	Does not exist	
Lighting Fixture - Fluorescent Lighting Fixture - HID	Does not exist	
Lighting Fixture - HID Lighting Fixture - Incandescent	Does not exist Does not exist	
	Inspected	
Lighting Fixture - LED	Inspected	
Dondont Mounted		
Pendant Mounted Condition	2- Between Good and Fair	

Building Condition Assessment Survey 2023-2024

icui Inspection		IXU-13
uestion	Response	
TOILET ROOM - STUDENT		
Lighting		
Lighting Fixture - LED		
Surface Mounted	Does not exist	
Recessed Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
AUXILIARY SIGNAL/BELL SYSTEM	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
EMERGENCY DC STANDBY BATTERY POWER	Does not exist	
EMERGENCY GENERATOR SET	Inspected	
Automatic Transfer Switch (ATS)	Inspected	
Instance	Basement - Fan Room 3- Fair	
Instance Condition	<u> </u>	
Instance Quantity	1 EACH	
Instance Quantity Uom	EACH	
Manufacturer	ASCO	
EquipmentId	N/A	
Capacity/Size Quantity	200	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Inspector Estimate	
Installation Year	1963	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Basement - Fan Room	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Battery Charger	Inspected	
Instance	Basement - Fan Room	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	SENS	
EquipmentId	Battery Charger	
Capacity/Size Quantity	3	
Capacity/Size UOM	AmpsDC	
Capacity/Size 2 Quantity	10	
Capacity/Size 2 UOM	VDC	
Source of Capacity/Size	Nameplate	
Installation Year	2007	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Emergency Distribution Board	Does not exist	
Diesel	Inspected	
Instance	Basement - Generator Enclosure	
Instance Condition	3- Fair	
Instance Quantity	1 EACH	
Instance Quantity Uom	EACH	
Manufacturer	Cummins Onan	
EquipmentId	Emergency Generator	

Building Condition Assessment Survey 2023-2024

uestion	Response	
EMERGENCY GENERATOR SET		
Diesel		
Capacity/Size Quantity	56	
Capacity/Size UOM	kVA	
Capacity/Size 2 Quantity	45	
Capacity/Size 2 UOM	kW	
Capacity/Size 3 Quantity	156	
Capacity/Size 3 UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year	1963	
Source of Installation Year	Documented	
Deficiency	NOT IN USE	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	NO ACTION	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 1	
Violations	No violations recorded	
Natural Gas	Does not exist	
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
EMERGENCY LIGHTING	Inspected	
Battery Pack	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
	Inspected	
Non Battery Pack	3- Fair	
Condition	No deficiencies recorded	
Deficiency		
EXIT LIGHT	Inspected	
Battery Pack	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Non Battery Pack	Inspected	
Condition	3- Fair	
Deficiency	FIXTURE NOT OPERATIONAL	
Deficiency Location/Instance	Auditorium - Stage	
Deficiency Quantity	2	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
EXIT/EMERGENCY LIGHT	Does not exist	
FIRE ALARM SYSTEM	Inspected	
Bell/Horn	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Strobe	Inspected	
	3- Fair	
Condition		
Deficiency	No deficiencies recorded	
Manual Pull Station	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fan Shutdown Control	Inspected	

Building Condition Assessment Survey 2023-2024

		IXUT
nestion	Response	
FIRE ALARM SYSTEM		
Fan Shutdown Control		
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Duct Smoke Detector	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Area Smoke Detector	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
CO Detector	Does not exist	
Heat Detector	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Elevator Recall	Does not exist	
Magnetic Door Holder/Contactor	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fused Cutout Panel	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Digital Communicator	Does not exist	
Main Panel	Inspected	
Bell At Panel	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Electronic)	Inspected	
Instance	Main Entrance Lobby	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Notifier	
Model	AM2020	
EquipmentId	N/A	
Installation Year	2000	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Standard)	Does not exist	
Sub-Panel	Does not exist	
Remote Annunciator	Inspected	
Display Monitor	Does not exist	
Panel	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Printer	Does not exist	
Punch Register	Does not exist	
Sprinkler Flow/Air Pressure Switch	Does not exist	-
Tamper Flow Switch/Chain	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
PROUNDING SYSTEM	Inspected	
Condition	5- Poor	
Deficiency	DETACHED GROUND CONDUCTOR	
Deficiency Location/Instance	Basement - Boiler Room	
Deficiency Quantity	1	

Building Condition Assessment Survey 2023-2024

INTERCOM SYSTEM LAN Inspected Local Distribution Frame (I/LDF) Condition Deficiency Main Equipment Rack (MDF) Condition Condition 3- Fair 3- Fair 3- Fair	Y 5 formions recorded exist I l encies recorded l encies recorded exist I
Quantity UomEACHPotential ActionREPAIRUrgency of ActionPRIORITPurpose of ActionLEVEL 6ViolationsNo violatINTERCOM SYSTEMDoes notLocal Distribution Frame (I/LDF)InspectedCondition3- FairDeficiencyNo deficiMain Equipment Rack (MDF)InspectedCondition3- FairDeficiencyNo defici	cions recorded exist I encies recorded encies recorded exist encies recorded exist
Quantity UomEACHPotential ActionREPAIRUrgency of ActionPRIORITPurpose of ActionLEVEL 6ViolationsNo violatINTERCOM SYSTEMDoes notLANInspectedLocal Distribution Frame (I/LDF)InspectedCondition3- FairDeficiencyNo deficiMain Equipment Rack (MDF)InspectedCondition3- FairDeficiencyNo defici	cions recorded exist I encies recorded encies recorded exist encies recorded exist
Potential Action REPAIR Urgency of Action PRIORIT Purpose of Action LEVEL 6 Violations No violat INTERCOM SYSTEM Does not LAN Inspected Local Distribution Frame (I/LDF) Inspected Condition 3- Fair Deficiency No defici Main Equipment Rack (MDF) Inspected Condition 3- Fair Deficiency No defici	cions recorded exist I encies recorded encies recorded exist encies recorded exist
Urgency of Action Purpose of Action Purpose of Action Violations No violat INTERCOM SYSTEM Does not LAN Inspected Local Distribution Frame (I/LDF) Condition Officiency No defici Main Equipment Rack (MDF) Condition 3- Fair Deficiency No defici	cions recorded exist I encies recorded encies recorded exist encies recorded exist
Purpose of Action Violations No violat INTERCOM SYSTEM Does not LAN Inspected Local Distribution Frame (I/LDF) Condition Oberon Deficiency No defici Main Equipment Rack (MDF) Condition Oberon The Condition Oberon Th	cions recorded exist I encies recorded encies recorded exist encies recorded exist
Violations INTERCOM SYSTEM Does not LAN Inspected Local Distribution Frame (I/LDF) Condition Deficiency Main Equipment Rack (MDF) Condition 3- Fair Deficiency No deficiency No deficiency No deficiency No deficiency No deficiency	exist I encies recorded exist encies recorded exist encies recorded exist
INTERCOM SYSTEM LAN Inspected Condition Deficiency Main Equipment Rack (MDF) Condition Condition Deficiency No deficiency Deficiency No deficiency No deficiency No deficiency No deficiency No deficiency	exist I encies recorded encies recorded exist
LAN Inspected Local Distribution Frame (I/LDF) Inspected Condition 3- Fair Deficiency No defici Main Equipment Rack (MDF) Inspected Condition 3- Fair Deficiency No defici	encies recorded encies recorded encies recorded exist
Local Distribution Frame (I/LDF) Inspected Condition 3- Fair Deficiency No defici Main Equipment Rack (MDF) Inspected Condition 3- Fair Deficiency No defici	encies recorded l encies recorded exist
Condition 3- Fair Deficiency No defici Main Equipment Rack (MDF) Inspected Condition 3- Fair Deficiency No defici	encies recorded encies recorded exist
Deficiency Main Equipment Rack (MDF) Condition Deficiency No deficiency No deficiency	encies recorded exist
Main Equipment Rack (MDF)InspectedCondition3- FairDeficiencyNo defici	encies recorded exist
Condition 3- Fair Deficiency No defici	encies recorded exist
Deficiency No defici	exist I
	exist I
LIGHTNING PROTECTION Does not	I
MOTOR CONTROLLER Inspected	exist
MOTOR CONTROL CENTER Does not	
MOTOR STARTER/CONTACTOR Inspected	<u> </u>
Condition 3- Fair	
Deficiency No defici	encies recorded
Variable Frequency Drive Inspected	
Condition 2- Between	en Good and Fair
Deficiency No defici	encies recorded
PANEL BOARD Inspected	
Fused Disconnect Switch Type Inspected	
Condition 3- Fair	
Deficiency No defici	encies recorded
Fused Knife Switch Type Inspected	
Condition 3- Fair	
Deficiency PANEL F	BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance Corridors	s and Boiler Room
Deficiency Quantity 10	
Quantity Uom EACH	
Potential Action REPLAC	E-UPGRADE
Urgency of Action PRIORIT	Y 1
Purpose of Action LEVEL 2	2
Violations No violat	ions recorded
Fused Toggle Switch Type Does not	exist
Molded Case Circuit Breaker Type Inspected	
Condition 3- Fair	
Deficiency PANEL E	BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance Througho	out the Building
Deficiency Quantity 16	
Quantity Uom EACH	
Potential Action REPLAC	E-UPGRADE
Urgency of Action PRIORIT	
Purpose of Action LEVEL 2	:
Violations No violat	ions recorded
PUBLIC ADDRESS SYSTEM Inspected	<u> </u>
Instance Main Off	ice - Room 253
Instance Condition 3- Fair	
Instance Quantity 1	
Instance Quantity Uom EACH	
Model Telecor II	1

Building Condition Assessment Survey 2023-2024

neui mspection	1407
Question	Response
PUBLIC ADDRESS SYSTEM	
Installation Year	2000
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
SECURITY	Inspected
IPDVS/CCTV System	Inspected
Condition	2- Between Good and Fair
Installation Year	2015
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	Basement - Service Room B
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 128FBP
Installation Year	2006
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	
	3- Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting - Security	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
SERVICE SWITCH	Inspected
Instance	Boiler Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1 EACH
Instance Quantity Uom	EACH
Manufacturer	Electrotech
EquipmentId	Section 1
Capacity/Size Quantity	2500
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate 2010
Installation Year Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Electrotech
EquipmentId	New Building Disconnect

Building Condition Assessment Survey 2023-2024

······································	
uestion	Response
SERVICE SWITCH	
Capacity/Size Quantity	1000
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1963
Source of Installation Year	Inspector Estimate
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
WITCHBOARD	Inspected
Number of Spares	inspecied 5
Fused Disconnect Switch Type	Inspected
	Boiler Room
Instance	2- Between Good and Fair
Instance Condition	
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Electrotech
EquipmentId	Section 1
Capacity/Size Quantity	2500
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Service Switch Size
Installation Year	2010
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Equipment Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Electrotech
EquipmentId	N/A
Equipmenta Capacity/Size Quantity	1200
Capacity/Size Quantity Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	3
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	2010
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
	Does not exist
Fused Knife Switch Type Molded Case Circuit Breaker Type	Does not exist
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Standard	Inspected
	3- Fair
Condition	3- I ali