### **Building Condition Assessment Survey 2023-2024**

Asset:		OND PRE-K CENTER @ 1 T	TELEPORT DRI	IVE - STATEN I	SLAND, 1 TI	ELEPORT DR	RO RIVE,
Inspection Id	Inspection Type				Time	In	Last Edited
	ELECTRICAL				2024	-02-23 07:48AN	M 2024-03-08 02:52PM
set Data	<u> </u>					02 25 07110111	2021.05.00.0212111
Ouestion				Answer			
	ms/Major Building	g Components been upgraded?		Systems:	All Electrical	Systems and Co	omponents
114.0 411, 2,500	mermager Burram	5 components coon appraceu.		Years:	2015	·	1
Type of Service	:			Below Gr	ound		
	e Whiteboard (IWI	B) Exist?		Yes			
	on In Electrical Ro			No			
	INTERCOMS	IN FIRE RESCUE AREAS					
Question	T :f- D A:	A Ein- D A	4/ II-14: D		Response No		
your building	?	stance Areas, Fire Rescue Areas, a	nd/or Holding Roo	ms in	No		
iority Condita	ion						
xist Prio ast Year? Cato	ority egory	Condition  Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
No condition re	<u> </u>			*			
spection							
•							
Question				Response	!		
Electrical							
ATHLETIC	FIELD			Does not			
AUDITORIU	JM			Does not	exist		
CAFETERIA	4			Does not	exist		
CLASSROO	M/CORRIDOR/A	ADMINISTRATIVE SPACE		Inspected			
Lighting	14: 5:0			Inspected			
-	nandelier Exist?			No			
	Fixture - Fluoreso t Mounted	cent		Inspected Inspected			
Condi				<u> </u>	n Good and Fa	ir	
	eficiency				encies recorded		
	Mounted			Inspected	oneres recorded		
Condi					n Good and Fa	ir	
	eficiency				encies recorded		
	ed Mounted			Inspected			
Condi	tion			2- Betwee	n Good and Fa	ir	
De	eficiency			No deficie	encies recorded		
Lighting	Fixture - HID			Does not	exist		
Lighting	Fixture - Incande	scent		Does not	exist		
Lighting	Fixture - LED			Inspected			
Pendant Mounted				Does not			
-	Mounted			Does not	exist		
	ed Mounted			Inspected	G 1 1F		
Condi					n Good and Fa		
-	eficiency				encies recorded		
COMPUTE				Does not			
GYMNASIU	M			Does not	exist		
KITCHEN				Inspected			
	stance on 1st Floor	r		Inspected			
Lighting							
	stance on 1st Floor			Inspected			

## **Building Condition Assessment Survey 2023-2024**

tem inspection		11000
uestion	Response	
KITCHEN		
Lighting		
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Does not exist	
Recessed Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Does not exist	
LIBRARY	Does not exist	
LOCKER ROOM	Does not exist	
MULTIPURPOSE ROOM	Inspected	
Instance on Room 117	Inspected	
Lighting	морения	
Instance on Room 117	Inspected	
Lighting Fixture - Fluorescent	персена	
Instance on Room 117	Inspected	
Pendant Mounted	1	
Instance on Room 117	Does not exist	
Surface Mounted		
Instance on Room 117	Does not exist	
Recessed Mounted		
Instance on Room 117	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on Room 117	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 117	Does not exist	
Lighting Fixture - LED		
Instance on Room 117	Does not exist	
Local Sound System		
Instance on Room 117	Does not exist	
Projection System		
Instance on Room 117	Does not exist	
Theater Lighting System		
Instance on Room 117	Does not exist	
SCIENCE DEMO ROOM	Does not exist	
SCIENCE LAB	Does not exist	
SCIENCE PREP ROOM	Does not exist	
SWIMMING POOL	Does not exist	
TOILET ROOM - STAFF Lighting	Inspected Inspected	

## **Building Condition Assessment Survey 2023-2024**

Does not exist Does not exist Inspected 2- Between Good and Fair
Does not exist Inspected
Inspected
<del>-</del>
2- Between Good and Fair
No deficiencies recorded
Does not exist
Does not exist
Does not exist
Inspected
Inspected
Inspected
Does not exist
Does not exist
Inspected
2- Between Good and Fair
No deficiencies recorded
Does not exist
Does not exist
Does not exist
Inspected
2- Between Good and Fair
No deficiencies recorded
Does not exist
Does not exist
Does not exist
Inspected
Inspected
2- Between Good and Fair
No deficiencies recorded
Does not exist
Inspected
Inspected
2- Between Good and Fair
No deficiencies recorded
Does not exist
Does not exist
Inspected
Inspected
2- Between Good and Fair
No deficiencies recorded
Inspected
2- Between Good and Fair
No deficiencies recorded
Inspected
2- Between Good and Fair
No deficiencies recorded
Inspected
2- Between Good and Fair
No deficiencies recorded
Inspected

## **Building Condition Assessment Survey 2023-2024**

ricui inspection		Kuud
Question	Response	
FIRE ALARM SYSTEM		
Duct Smoke Detector		
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Area Smoke Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
CO Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Heat Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Elevator Recall	Does not exist	
Magnetic Door Holder/Contactor	Does not exist	
Fused Cutout Panel	Does not exist	
Fire Alarm Digital Communicator	Does not exist	
Main Panel	Does not exist	
Sub-Panel	Inspected	
Bell At Panel	Does not exist	
Fire Alarm Control Panel (Electronic)	Inspected	
Instance	Main Entrance Lobby	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Vigilant	
Model	VS Series	
EquipmentId	Fire Alarm Control Panel	
Installation Year	2015	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Standard)	Does not exist	
Remote Annunciator	Inspected	
Display Monitor	Does not exist	
Panel	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Printer	Does not exist	
Punch Register	Does not exist	
Sprinkler Flow/Air Pressure Switch	Does not exist	
Tamper Flow Switch/Chain	Does not exist	
GROUNDING SYSTEM	Does not exist	
INTERCOM SYSTEM	Does not exist	
LAN	Inspected	
Local Distribution Frame (I/LDF)	Does not exist	
Main Equipment Rack (MDF)	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
LIGHTNING PROTECTION	Does not exist	
MOTOR CONTROLLER	Inspected	
MOTOR CONTROLLER  MOTOR CONTROL CENTER	Does not exist	
MOTOR CONTROL CENTER  MOTOR STARTER/CONTACTOR	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	

## **Building Condition Assessment Survey 2023-2024**

ciricai Inspection	KUU0
Question	Response
MOTOR CONTROLLER	
Variable Frequency Drive	Does not exist
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Does not exist
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Does not exist
Molded Case Circuit Breaker Type	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
PUBLIC ADDRESS SYSTEM	Inspected
Instance	MDF Room 123
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Telecor II
Installation Year	2015
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
SECURITY	Inspected
IPDVS/CCTV System	Inspected
Condition	2- Between Good and Fair
Installation Year	2015
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	Custodian's Office
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity  Instance Quantity Uom	EACH
Model	Vista 128BPT
Installation Year	2015
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	•
	2- Between Good and Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting - Security	Does not exist
SERVICE SWITCH	Inspected
Instance	Building Owner Electrical Room Outside Exit 4 by Elevator Area
Instance Condition	2- Between Good and Fair
Instance Quantity	1
	EACH
Instance Quantity Uom	
Manufacturer	Siemens Pro V 68V 400 A 277/480V
EquipmentId	Pre K 68K 400A 277/480V

## **Building Condition Assessment Survey 2023-2024**

ricui Inspection	Kuu
Question	Response
SERVICE SWITCH	
Capacity/Size Quantity	400
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2015
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
SWITCHBOARD	Inspected
Number of Spares	9
Fused Disconnect Switch Type	Does not exist
Fused Knife Switch Type	Does not exist
Molded Case Circuit Breaker Type	Inspected
Instance	Electrical Room 124
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Electrotech
EquipmentId	PP1 PNL 400A 277/480V
Capacity/Size Quantity	400
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	2015
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
TRANSFORMER	Inspected
Instance	Electrical Room 124
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Rex Power Magnetics
EquipmentId	XFRM
Capacity/Size Quantity	75
Capacity/Size UOM	kVA
Source of Capacity/Size	Nameplate
Installation Year	2015
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
•	