Mechanical Inspection

Building Condition Assessment Survey 2023-2024

R080

Asset:	REGION 7/ ROC F - STATEN	ISLAND, 715 OCEAN TEF	RRACE, STATE	N ISLAND, NY	r, 10301	
Inspection	Id Inspection Type			Time l	ĺ n	Last Edited
-	4455 MECHANICAL			2024-0	04-01 08:57AN	1 2024-04-11 08:57AN
Isset Data						
Question			Answer			
Have any	Systems/Major Building Components been	upgraded?	Systems:	Drinking Foun	tains (4 of 6)	
			Years:	2024		
			Systems:			Compressor, Pneumatic
					Refrigerated Air	Dryers
			Years:	2019		
			Systems:			Equipment (1 of 2,
			Years:	Packaged / Ro 2015	onop Omi)	
Are there	fuel tanks?		No	2013		
	water main service entries to the asset		3			
	n Rooms Locations			t - MER A3		
	any spaces with Missing or Defective CO D	etectors?	No	i WILKINS		
	any Painted/Obstructed Sprinkler Heads?		Yes			
Location(Basemen	t Storage Area (p	ainted, 2)	
Are there	any Emergency Stop Switches with Missing	Hammers?	No comp	onents		
Priority Co.	ndition					
Exist	Priority Condition	Component	Location	Person(s)	Person(s)	Photo
Last Year?	Category Description	Affected	Description	Notified	Title	Image
	ion recorded			- 100		
Inspection						
Question			Response	e		
Mechanic	cal					
AIR CO	ONDITIONING		Inspected	l		
Chille	d Water System		Inspected	l		
Abs	orption Chiller		Does not	exist		
Air	Cooled Chiller		Does not	exist		
Air	Cooled Condenser		Does not	exist		
Chil	lled Water Distribution: Piping, Pumps ar	d Auxiliaries	Inspected	l		
Co	ondition		3- Fair			
	Deficiency		PUMP:D	EFECTIVE		
	Deficiency Location/Instance		Roof			
	Deficiency Quantity		2			
	Quantity Uom		EACH			
	Potential Action			ENANCE		
	Urgency of Action		PRIORIT			
	Purpose of Action		LEVEL 2			
	Violations			tions recorded		
	kflow Preventer		Does not			
	tral Station Air Handler		Does not			
	Coil Unit		Inspected	1		
Co	ondition		3- Fair			
	Deficiency		DEFECT			
	Deficiency Location/Instance		Room A1	141B		
	Deficiency Quantity		1			
	Quantity Uom Potential Action		EACH			
	Potential Action Urgency of Action		REPAIR PRIORIT	rv 3		
	Purpose of Action		LEVEL 2			
	Violations			tions recorded		
Pac	kaged Air Cooled Chiller		Inspected	1		

Building Condition Assessment Survey 2023-2024

anical Inspection	
uestion	Response
AIR CONDITIONING	
Chilled Water System	
Packaged Air Cooled Chiller	
Instance	Roof
Instance Condition	5- Poor
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Bohn
EquipmentId	#1
Capacity/Size Quantity	30
Capacity/Size UOM	Tons
Source of Capacity/Size	Inspector Estimate
Installation Year	1966
Source of Installation Year	Documented
Refrigerant Type	R-22
Deficiency	UP TO 100 TONS:DEFECTIVE UNIT
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Roof
Instance Condition	5- Poor
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Bohn
EquipmentId	#2
Capacity/Size Quantity	30
Capacity/Size UOM	Tons
Source of Capacity/Size	Inspector Estimate
Installation Year	1966
Source of Installation Year	Documented
Refrigerant Type	R-22
Deficiency	UP TO 100 TONS:DEFECTIVE UNIT
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Water Cooled Chiller	Does not exist
Condenser Water Distribution: Piping, Pumps and Auxiliaries	Does not exist
Cooling Coil in Ductwork	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Cooling Tower	Does not exist
DX Split System	Inspected
Indoor Unit	Inspected
Condition	4- Between Fair and Poor
Deficiency	UP TO 5 TONS:DEFECTIVE
Deficiency Location/Instance	Storage Room A5, Rooms A107, A118, A118A, A200
Deficiency Quantity	5
Quantity Uom	EACH
Detential Action	DEDAID

REPAIR

PRIORITY 3

Potential Action

Urgency of Action

estion	Dosnonso
	Response
IR CONDITIONING	
DX Split System	
Indoor Unit	
Purpose of Action	LEVEL 2
Violations	No violations recorded
Outdoor Unit	Inspected
Condition	4- Between Fair and Poor
Deficiency	UP TO 5 TONS:DEFECTIVE
Deficiency Location/Instance	Building Exterior, Roof
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Dry Cooler	Does not exist
Packaged / Rooftop Unit	Does not exist
Packaged Terminal A/C	Inspected
Condition	4- Between Fair and Poor
Deficiency	DEFECTIVE
Deficiency Location/Instance	Rooms A115, A116, A135 and other locations
Deficiency Quantity	10
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	DEFECTIVE FRESH AIR INTAKE
Deficiency Location/Instance	Rooms A135, A231, A235 and other locations
Deficiency Quantity	25
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Refrigerant Leak Detection System	Does not exist
Refrigerant Piping	Inspected 3- Fair
Condition	
Deficiency	DAMAGED/MISSING INSULATION
Deficiency Location/Instance	Building Exterior, Roof
Deficiency Quantity	60
Quantity Uom	L.F.
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	DEFECTIVE/DETERIORATED
Deficiency Location/Instance	Building Exterior
Deficiency Quantity	20
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
	Inspected
Return Fan	nispected

Mechanical Inspection		KUðU
	_	

anical Inspection	R08
nestion	Response
AIR CONDITIONING	
Return Fan	
Deficiency	No deficiencies recorded
CENTRAL ACID WASTE NEUTRALIZING TANK	Does not exist
CLIMATE CONTROL SYSTEM	Inspected
BMS	Does not exist
Pneumatic System	Inspected
Instance	Throughout
Instance Condition	4- Between Fair and Poor
Instance Quantity	1
Instance Quantity Uom	EACH
Building Area Covered by Operational System	0-20%
Deficiency	PNEUMATIC TUBING: DEFECTIVE/LEAKS AIR
Deficiency Location/Instance	Room A304 and other locations
Deficiency Quantity	50
Quantity Uom	L.F.
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	DEFECTIVE DAMPER ACTUATOR
Deficiency Location/Instance	MER A3; Storage Room A5
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	DEFECTIVE LOCAL CONTROL PANEL
Deficiency Location/Instance	MER A3 @ S-1
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	DEFECTIVE TEMPERATURE CONTROL THERMOSTAT
Deficiency Location/Instance	Various Locations
Deficiency Quantity	10
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Hybrid System	Does not exist
Electric System	Does not exist
COMPACTOR	Inspected
Condition	2- Between Good and Fair
	No deficiencies recorded
Deficiency	
CONVEYING	Inspected
Dumbwaiter	Does not exist
Elevator	Inspected
Condition	2- Between Good and Fair
Are all the existing elevators operable?	Yes

80
3

2	Noo
uestion	Response
CONVEYING	
Escalator	Does not exist
Non-auditorium Handicap Lift - Vertical	Does not exist
Non-auditorium Handicap Lift - Stair	Does not exist
Ash Hoist	Does not exist
Sidewalk Elevator	Does not exist
DOMESTIC WATER SYSTEM	Inspected
Domestic Cold Water System	Inspected
Gravity System	Does not exist
Pressure Booster System	Does not exist
Water Service	Inspected
Instance	Basement - MER A3
Instance Condition	3- Fair
Instance Quantity	3
Instance Quantity Uom	EACH
Deficiency	WATER MAIN:MISSING BACKFLOW PREVENTION DEVICE
Deficiency Location/Instance	Basement - MER A3
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	INSTALL
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	WATER MAIN: DEFECTIVE VALVE
Deficiency Location/Instance	Basement - MER A3 / Domestic (pressure regulator)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Domestic Hot Water System	Inspected
Domestic Hot Water Remote Storage Tank	Does not exist
Domestic Water Heat Exchanger	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Electric Domestic Water Heater	Does not exist
Gas Fired Domestic Water Heater	Does not exist
Oil Fired Domestic Water Heater	Does not exist
Heat Pump Domestic Water Heater	Does not exist
Domestic Water Distribution Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
DRAIN/WASTE/VENT AND STORM SYSTEM	Inspected
Interior Storm Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Sewage/Waste/Vent Piping	Inspected
Condition	3- Fair
Deficiency	SEWAGE/WASTE PIPING:DEFECTIVE/LEAKS
Deficiency Location/Instance	Storage Room A5
Deficiency Quantity	10
Quantity Uom	L.F.
Potential Action	REPLACE

Building Condition Assessment Survey 2023-2024

Mechanical Inspection R080

Question	Response
DRAIN/WASTE/VENT AND STORM SYSTEM	
Sewage/Waste/Vent Piping	
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	INTERIOR FLOOR DRAIN: DEFECTIVE
Deficiency Location/Instance	MER A3
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action Violations	LEVEL 2
	No violations recorded
Sewage Ejector Pump	Does not exist
Sump Pump Condition	Inspected 3- Fair
	No deficiencies recorded
Deficiency	
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	Does not exist
FIXTURES	Inspected
Staff And Other	Inspected
Janitor Sink	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lavatory/Sink	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Toilet	Inspected
Condition	3- Fair
Deficiency	CRACKED/PHYSICAL DAMAGE
Deficiency Location/Instance	2nd Floor Women's Toilet Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
U <u>rinal</u>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Student	Inspected
Drinking Fountain	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lavatory/Sink	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Locker Room Shower	Does not exist
Sink And Fountain Combo Unit	Does not exist
Toilet	Inspected
Condition	3- Fair
Deficiency	CRACKED/PHYSICAL DAMAGE
Deficiency Location/Instance	1st Floor Girl's Toilet Room
Deficiency Quantity	2
Quantity Uom	EACH

Mechanical Inspection	R080
-----------------------	------

Question	Response
FIXTURES	
Student	
Toilet	
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Urinal	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
GAS FIRED FURNACE	Does not exist
GAS SERVICE	Does not exist
HEATING	Inspected
Heating Coil In Ductwork	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Hydronic Heating	Inspected
Hydronic Hot Water Distribution: Piping, Pumps and Auxiliaries	Inspected
Condition	3- Fair
Deficiency	PIPING:DEFECTIVE/LEAKS
Deficiency Location/Instance	MER A3
Deficiency Quantity	20
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PIPING:DEFECTIVE VALVE
Deficiency Location/Instance	MER A3
Deficiency Quantity	4 EACH
Quantity Uom Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Backflow Preventer	Does not exist
Hot Water Heat Exchanger	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Radiator/Convector/Fin Tube	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Steam Heating	Does not exist
Steam supplied by External Sources	Does not exist
Unit Heater/Cabinet Heater	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
HEATING PLANT	Does not exist
Enclosed IDF Room	Does not exist
KITCHEN	Does not exist
MDF Room	Inspected
Instance on Room A103	Inaccessible
	Does not exist
SCIENCE DEMO ROOM	
SCIENCE LAB	Does not exist

Mechanical Inspection	R080

	n
uestion	Response
SCIENCE PREP ROOM	Does not exist
SPRINKLERS, STANDPIPE, FIRE SYSTEM	Inspected
Dry Sprinkler Alarm Valve Assembly	Does not exist
Wet Sprinkler Alarm Valve Assembly	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fire Booster Pump Assembly	Does not exist
Roof Tank	Does not exist
Siamese Connection	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Sprinkler Head	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE/DETERIORATED
Deficiency Location/Instance	Basement Storage Area (painted, 2)
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Sprinkler Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Standpipe System	Inspected
Hose Valve Assembly	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Water Gong	Does not exist
WIMMING POOL	Does not exist
ENTILATION	Inspected
	Yes
Is the building Mechanically ventilated? Exhaust Fan	Inspected
Condition	3- Fair
Approximate Total # of Fans	1-25
Deficiency	DEFECTIVE MOTOR
Deficiency Location/Instance	Roof / E6
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	DEFECTIVE
Deficiency Location/Instance	Roof / E7 (bearing)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded

Building Condition Assessment Survey 2023-2024

Mechanical Inspection R080

*	
uestion	Response
VENTILATION	
Exhaust Fan	
Deficiency Location/Instance	Roof
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Heating And Ventilating Unit	Does not exist
Metal Ductwork	Inspected
Condition	3- Fair
Are there any uninsulated ductwork by design in Mechanical rooms?	Yes
Are there chain operated dampers?	Yes
Deficiency	DEFECTIVE REGISTER/DIFFUSER
Deficiency Location/Instance	Storage Room A5
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	DAMAGED/MISSING INSULATION
Deficiency Location/Instance	MER A3
Deficiency Quantity	20
Quantity Uom	L.F.
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Supply Fan	Inspected
Condition	3- Fair
Approximate Total # of Fans	1-5
Deficiency	No deficiencies recorded
Unit Ventilator	Inspected
Condition	4- Between Fair and Poor
Deficiency	DEFECTIVE FRESH AIR INTAKE
Deficiency Location/Instance	Room A305 and other location
Deficiency Quantity	25
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded