Building Condition Assessment Survey 2023-2024

Asset:		I.S. 82 - STA	ΓEN ISLAND, 104 GORDON S	IKEEI, SIAI	EN ISLAND, NI	1, 10304		
Inspection	ı Id	Inspection Typ	oe e			Time	In	Last Edited
	3708	MECHANICA	L			2024-	03-04 09:10AM	2024-03-05 02:13PI
sset Data								
Question					Answer			
Have any	Syster	ms/Major Buildi	ing Components been upgraded?		Systems:	Sump Pumps		
•	•	· ·			Years:	2023		
					Systems:	MDF Room -	Dedicated A/C E	Equipment (DX Split
						System)		
					Years:	2021		
Are there					Yes			
		oove ground tan			0			
			round tanks in gal.		0			
		elow ground tan			1			
	-		ground tanks in gal. atries to the asset		5,000			
		main service er ms Locations	inies to the asset		l None			
			ing or Defective CO Detectors?		No			
			ed Sprinkler Heads?		No			
			Switches with Missing Hammers?		No compo	nents		
			Switches with Missing Hammers.		No compo	лень		
riority Co								
Exist Last Year?	Prio Cate	-	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
No condit						- 101222		
<i>nspection</i> Question					Response			
Mechanic					P			
		TIONING			Inspected			
		ter System			Does not o			
			tion: Piping, Pumps and Auxiliarie	ie.	Does not o			
		il in Ductwork	tion. 1 iping, 1 umps and Auxmarie		Does not o			
Cooli					Does not o			
DX S					Inspected			
	oor Ui				Inspected			
-	onditio				1- Good			
	_	eficiency				encies recorded		
Out	door				Inspected			
-	onditio				1- Good			
	_	eficiency				encies recorded		
Dry (Does not o			
		Rooftop Unit			Does not o			
		Terminal A/C			Does not o			
		t Leak Detection	n System		Does not o			
		t Piping	ii Systeiii		Inspected			
	dition	1 0			1- Good			
Con	_	eficiency				encies recorded		
	יי	Jiio io iio y			1 VO GCITCIO			
Retur	E				Does not o	eviet		

CENTRAL ACID WASTE NEUTRALIZING TANK

CLIMATE CONTROL SYSTEM

Pneumatic System

Instance

Instance Condition

Hybrid System

Electric System

BMS

Does not exist

Does not exist

Does not exist

Throughout (Heat Timer System)

2- Between Good and Fair

Inspected

Does not exist

Inspected

Building Condition Assessment Survey 2023-2024

uestion	Response
CLIMATE CONTROL SYSTEM	
Electric System	
Instance Quantity	1
Instance Quantity Uom	EACH
Building Area Covered by Operational System	81-100%
Deficiency	No deficiencies recorded
Instance	Rooms 113, 115, M02, M16, M20, M21, 210,212, 214, 215, 305, 307 and other locations
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Building Area Covered by Operational System	81-100%
Deficiency	No deficiencies recorded
COMPACTOR	Does not exist
CONVEYING	Does not exist
DOMESTIC WATER SYSTEM	Inspected
Domestic Cold Water System	Inspected
Gravity System	Does not exist
Pressure Booster System	Does not exist
Water Service	Inspected
Instance	Boiler Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1 EACH
Instance Quantity Uom	
Deficiency	No deficiencies recorded
Domestic Hot Water System	Inspected
Domestic Hot Water Remote Storage Tank	Does not exist
Domestic Water Heat Exchanger	Does not exist
Electric Domestic Water Heater	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Gas Fired Domestic Water Heater	Does not exist
Oil Fired Domestic Water Heater	Does not exist
Heat Pump Domestic Water Heater	Does not exist
Domestic Water Distribution Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
DRAIN/WASTE/VENT AND STORM SYSTEM	Inspected
Interior Storm Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Sewage/Waste/Vent Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Sewage Ejector Pump	Does not exist
Sump Pump	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	Does not exist
FIXTURES	Inspected
Staff And Other	Inspected
Janitor Sink	Inspected
Condition	3- Fair

Building Condition Assessment Survey 2023-2024

Question	Response	
FIXTURES		
Staff And Other		
Janitor Sink		
Deficiency	No deficiencies recorded	
Lavatory/Sink	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Toilet	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Urinal	Does not exist	
Student	Inspected	
Drinking Fountain	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Lavatory/Sink	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Locker Room Shower	Does not exist	
Sink And Fountain Combo Unit	Does not exist	
Toilet	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Urinal	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
GAS FIRED FURNACE	Does not exist	
GAS SERVICE	Does not exist	
HEATING	Inspected	
Heating Coil In Ductwork	Does not exist	
Hydronic Heating	Does not exist	
Radiator/Convector/Fin Tube	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Steam Heating	Inspected	
F&T/Steam Drip Trap	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
MER Steam and Condensate Piping	Does not exist	
Steam Condensate Return Piping	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Steam Condensate Return Pumping System	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Steam Piping	Inspected	
Condition	3- Fair	
Deficiency	DEFECTIVE/LEAKS	
Deficiency Location/Instance	Gymnasium, Cafeteria	
Deficiency Quantity	40	
Quantity Uom	L.F.	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 3	

Building Condition Assessment Survey 2023-2024

uestion	Response
HEATING	
Steam Heating	
Steam Piping	
Purpose of Action	LEVEL 2
Violations	No violations recorded
Terminal Unit Thermostatic Trap	Inspected
Condition	2- Between Good and Fair
Deficiency	DEFECTIVE/DETERIORATED
Deficiency Location/Instance	Rooms 204, 207, 217 and other locations
Deficiency Quantity	10
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Steam supplied by External Sources	Does not exist
Unit Heater/Cabinet Heater	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
HEATING PLANT	Inspected
Instance on Basement	Inspected
Is there a water meter on the boiler make-up water piping?	Yes
Observed Operational?	Yes
Burner Manufacturer	Webster
Burner Model	JB2C-15-RM7800L-M.25VGD-MP-UL-BAR
Burner Type	Oil
Heating Plant Oil Number	2
Boiler Auxiliaries	
Instance on Basement	Inspected
Boiler Auxiliary Piping	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Boiler Emergency Stop Switch	
Instance on Basement	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Boiler Feedwater System	
Instance on Basement	Does not exist
Boiler Feedwater Treatment(Automatic)	
Instance on Basement	Does not exist
Boiler Flue Exhaust	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
	No deficiencies recorded
Boiler Make-up Water Backflow Preventer	T 1
Instance on Basement	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Boiler Room Steam And Condensate Piping	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	DEFECTIVE ISOLATION VALVE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1

Building Condition Assessment Survey 2023-2024

uestion	Response	
HEATING PLANT		
Boiler Auxiliaries		
Boiler Room Steam And Condensate Piping		
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Deficiency	DEFECTIVE/LEAKS	
Deficiency Location/Instance	Boiler Room	
Deficiency Quantity	10	
Quantity Uom	L.F.	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Boiler Safety Valve		
Instance on Basement	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Boiler System		
Instance on Basement	Inspected	
Coal-fired Boiler		
Instance on Basement	Does not exist	
Hot Water Boiler	Does not exist	
Instance on Basement	Does not exist	
Modular Boiler	DOCS NOT CAIST	
Instance on Basement	Does not exist	
Steam Boiler	Does not exist	
Instance on Basement	Inconstad	
	Inspected	
Instance on Basement	Inspected	
Instance	Boiler Room	
Instance Condition	3- Fair	
Instance Quantity	2,087	
Instance Quantity Uom	MBH NET	
Cast Iron Boiler?	No	
Manufacturer	Rockmills Boiler	
EquipmentId	N/A	
Capacity/Size Quantity	24	
Capacity/Size UOM	Burner GPH	
Source of Capacity/Size	Documented 1074	
Installation Year	1974	
Source of Installation Year	Documented	

Page 5 of 8

Inspected

Inspected
1- Good

Automatic

No deficiencies recorded

Print Date: 8/8/2024

Fuel System

BCAS Partners Version 2.0 (P)

Instance on Basement

Boiler Fresh Air Louver/Damper
Instance on Basement

Instance Condition

Burner/Burner Control Panel

Type

Deficiency

Building Condition Assessment Survey 2023-2024

uestion	Response	
HEATING PLANT	тезропяс	
Fuel Oil Storogo/Supply System		
Fuel Oil Storage/Supply System	Turnantad	
Instance on Basement	Inspected 3- Fair	
Instance Condition		
Deficiency	No deficiencies recorded	
Gas Trains And Vent At The Boiler		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	NOT IN USE	
Deficiency Location/Instance	Boiler Room	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	NO ACTION	
Urgency of Action	PRIORITY 1 LEVEL 1	
Purpose of Action Violations		
	No violations recorded	
Enclosed IDF Room	Does not exist	
KITCHEN	Inspected	
Instance on 1st Floor	Inspected	
CO Detector		
Instance on 1st Floor	Not required	
Gas System		
Instance on 1st Floor	Does not exist	
Grease Trap		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Hood		
Instance on 1st Floor	Does not exist	
Hood Exhaust Ductwork		
Instance on 1st Floor	Does not exist	
Hood Exhaust Fan		
Instance on 1st Floor	Does not exist	
Hood Fire Suppression System		
Instance on 1st Floor	Does not exist	
Hot Water Temperature Booster		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Kitchen Sink		
Instance on 1st Floor	Inspected	
Instance Condition	1- Good	
-		

No deficiencies recorded

No deficiencies recorded

Inspected

Inspected

Inspected

1- Good

Inspected Inspected

Does not exist

Deficiency

Dedicated A/C Equipment

Deficiency
SCIENCE DEMO ROOM

Instance on Room M04

Instance on Room M04

Instance on Room 305
Alternative Use

Instance Condition

MDF Room

SCIENCE LAB

Building Condition Assessment Survey 2023-2024

Mechanical Inspection	R082

estion	Response	
CIENCE LAB		
Acid Waste Neutralizing Tank		
Instance on Room 305	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
CO Detector		
Instance on Room 305	Not required	
Emergency Shower		
Instance on Room 305	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Eye Wash		
Instance on Room 305	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Hood Exhaust Ductwork		
Instance on Room 305	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Hood Exhaust Fan		
Instance on Room 305	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Fixed Laboratory Hood		
Instance on Room 305	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Laboratory Sink		
Instance on Room 305	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Make-up Air Unit		
Instance on Room 305	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
CIENCE PREP ROOM	Inspected	
Instance on Room 306	Inspected	
Alternative Use	No	
Acid Waste Neutralizing Tank	140	
Instance on Room 306	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
CO Detector	100 deficiencies recorded	
Instance on Room 306	Not required	
Emergency Shower	Not required	
Instance on Room 306	Does not exist	
Eye Wash	DOCS HOT CAIST	
Instance on Room 306	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
	No deficiencies recorded	
Hood Exhaust Ductwork Instance on Room 306	Does not exist	
	Does not exist	
Hood Exhaust Fan		

Building Condition Assessment Survey 2023-2024

uestion	Response	
SCIENCE PREP ROOM		
Fixed Laboratory Hood		
Instance on Room 306	Does not exist	
Laboratory Sink		
Instance on Room 306	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Make-up Air Unit		
Instance on Room 306	Does not exist	
SPRINKLERS, STANDPIPE, FIRE SYSTEM	Does not exist	
SWIMMING POOL	Does not exist	
VENTILATION	Inspected	
Is the building Mechanically ventilated?	Partial	
Exhaust Fan	Inspected	
Condition	1- Good	
Approximate Total # of Fans	1-25	
Deficiency	No deficiencies recorded	
Heating And Ventilating Unit	Does not exist	
Metal Ductwork	Inspected	
Condition	1- Good	
Are there any uninsulated ductwork by design in Mechanical rooms?	No	
Are there chain operated dampers?	No	
Deficiency	No deficiencies recorded	
Supply Fan	Does not exist	
Unit Ventilator	Does not exist	