Building Condition Assessment Survey 2023-2024

Asset: THE RICHMOND PRE-K CENTER @ 104 HOUSMA AVENUE, STATEN ISLAND, NY, 10303	AN AVENUE - STATEN ISLAND, 104 HOUSMAN
Inspection Id Inspection Type	Time In Last Edited
5047 MECHANICAL	2024-04-30 11:03AM 2024-04-30 09:15I
set Data	
Question	Answer
Have any Systems/Major Building Components been upgraded?	No System Upgraded
Are there fuel tanks?	No
Total # of water main service entries to the asset	1
MERs/Fan Rooms Locations	None
Are there any spaces with Missing or Defective CO Detectors?	No
Are there any Painted/Obstructed Sprinkler Heads?	No
Are there any Emergency Stop Switches with Missing Hammers?	No components
iority Condition	
xist Priority Condition Compon	· · · · · · · · · · · · · · · · · · ·
ast Year? Category Description Affected	l Description Notified Title Image
No condition recorded	
spection	
Question	Response
Mechanical	
AIR CONDITIONING	Inspected
Chilled Water System	Does not exist
Condenser Water Distribution: Piping, Pumps and Auxiliaries	Does not exist
Cooling Coil in Ductwork	Does not exist
Cooling Tower	Does not exist
DX Split System	Inspected
Indoor Unit	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
O <u>utdoor Unit</u>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Dry Cooler	Does not exist
Packaged / Rooftop Unit	Inspected
Instance	Roof 1- Good
Instance Condition	
Instance Quantity	1 EACH
Instance Quantity Uom	
Manufacturer	Daikin RTU #1
EquipmentId Capacity/Size Quantity	30
Capacity/Size Quantity Capacity/Size UOM	Tons
Source of Capacity/Size	Inspector Estimate
Installation Year	2019
Source of Installation Year	Documented
Source of Heating	Electric
Refrigerant Type	R-410A
Deficiency	No deficiencies recorded
Packaged Terminal A/C	Does not exist
Refrigerant Leak Detection System	Does not exist
Refrigerant Piping	Inspected
Condition	1- Good
Condition	
Deficiency	No deficiencies recorded

Building Condition Assessment Survey 2023-2024

Mechanical Inspection R094

uestion	Response	
CLIMATE CONTROL SYSTEM	Inspected	
BMS	Inspected	
Instance	Throughout	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Building Area Covered by Operational System	81-100%	
Installation Year	2019	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Pneumatic System	Does not exist	
Hybrid System	Does not exist	
Electric System	Does not exist	
COMPACTOR	Does not exist	
CONVEYING	Inspected	
Dumbwaiter	Does not exist	
Elevator	Inspected	
Condition	2- Between Good and Fair	
Are all the existing elevators operable?	Yes	
Deficiency	No deficiencies recorded	
Escalator Escalator	Does not exist	
Non-auditorium Handicap Lift - Vertical	Does not exist	
Non-auditorium Handicap Lift - Stair	Does not exist	
Ash Hoist	Does not exist	
Sidewalk Elevator	Does not exist	
DOMESTIC WATER SYSTEM	Inspected	
Domestic Cold Water System	Inspected	
Gravity System	Does not exist	
Pressure Booster System	Does not exist	
Water Service	Inspected	
Instance	Room C10	
Instance Condition	1- Good	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Deficiency	No deficiencies recorded	
Domestic Hot Water System	Inspected	
Domestic Hot Water System Domestic Hot Water Remote Storage Tank	Does not exist	
Domestic Water Heat Exchanger	Does not exist	
Electric Domestic Water Heater	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Gas Fired Domestic Water Heater	Does not exist	
	Does not exist Does not exist	
Oil Fired Domestic Water Heater	Does not exist Does not exist	
Heat Pump Domestic Water Heater		
Domestic Water Distribution Piping Condition	Inspected 1- Good	
Deficiency	No deficiencies recorded	
DRAIN/WASTE/VENT AND STORM SYSTEM	Inspected	
Interior Storm Piping	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Sewage/Waste/Vent Piping	Inspected	
Condition	1- Good	

Building Condition Assessment Survey 2023-2024

Mechanical Inspection R094

uestion	Response	
DRAIN/WASTE/VENT AND STORM SYSTEM		
Sewage Ejector Pump	Does not exist	
Sump Pump	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	Does not exist	
FIXTURES	Inspected	
	Inspected	
Staff And Other Janitor Sink	Inspected	
Condition	1- Good	
	No deficiencies recorded	
Deficiency		
Lavatory/Sink	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Toilet	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Urinal	Does not exist	
Student	Inspected	
Drinking Fountain	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Lavatory/Sink	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Locker Room Shower	Does not exist	
Sink And Fountain Combo Unit	Does not exist	
Toilet	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Urinal	Does not exist	
GAS FIRED FURNACE	Does not exist	
	Does not exist	
GAS SERVICE		
HEATING	Inspected	
Heating Coil In Ductwork	Does not exist	
Hydronic Heating	Does not exist	
Radiator/Convector/Fin Tube	Inspected 1- Good	
Condition		
Deficiency	No deficiencies recorded	
Steam Heating	Does not exist	
Steam supplied by External Sources	Does not exist Inspected	
Unit Heater/Cabinet Heater Condition	1- Good	
	DEFECTIVE	
Deficiency		
Deficiency Location/Instance Deficiency Quantity	Room C10, Electrical Closet 209	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
	LEVEL 2	
Purpose of Action	No violations recorded	
Violations		
HEATING PLANT	Does not exist	

Building Condition Assessment Survey 2023-2024

Mechanical Inspection	R094
Question	Response

Question	Response	
KITCHEN	Inspected	
Instance on 2nd Floor	Inspected	
CO Detector	тырсесса	
Instance on 2nd Floor	Not required	
Gas System	Tiot required	
Instance on 2nd Floor	Does not exist	
Grease Trap		
Instance on 2nd Floor	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Hood		
Instance on 2nd Floor	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Hood Exhaust Ductwork		
Instance on 2nd Floor	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Hood Exhaust Fan		
Instance on 2nd Floor	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Hood Fire Suppression System	110 00110101010101010101	
Instance on 2nd Floor	Does not exist	
Hot Water Temperature Booster		
Instance on 2nd Floor	Does not exist	
Kitchen Sink		
Instance on 2nd Floor	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
MDF Room	Inspected	
Instance on Room 109	Inspected	
Dedicated A/C Equipment	This process is a second of the second of th	
Instance on Room 109	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
SCIENCE DEMO ROOM	Does not exist	
SCIENCE LAB	Does not exist	
SCIENCE PREP ROOM	Does not exist	
SPRINKLERS, STANDPIPE, FIRE SYSTEM	Does not exist	
SWIMMING POOL	Does not exist	
VENTILATION	Inspected	
Is the building Mechanically ventilated?	Yes	
Exhaust Fan	Inspected	
Condition	1- Good	
Approximate Total # of Fans	1-25	
Deficiency	No deficiencies recorded	
Heating And Ventilating Unit	Does not exist	
Metal Ductwork	Inspected	
Condition	1- Good	
Are there any uninsulated ductwork by design in Mechanical rooms?	No	
Are there chain operated dampers?	No	
Deficiency	No deficiencies recorded	
Supply Fan	Does not exist	

Building Condition Assessment Survey 2023-2024

Mechanical Inspection		R094
Question	Dosnonso	

VENTILATION
Unit Ventilator Does not exist