Building Condition Assessment Survey 2023-2024

Architectural Inspection R436

Asset:	NEW DORP HS AF (NEW)-STATEN ISLAND, 465 NEW	DORP LANE, STATEN ISLAND, NY, 10306	
Inspection Id	Inspection Type	Time In	Last Edited
4657	ARCHITECTURAL - ASSOCIATE	2024-04-11 09:12AM	2024-04-12 02:05PM
4726	ARCHITECTURAL - SENIOR	2024-04-10 09:29AM	2024-05-13 05:34PM
set Data			
Question		Answer	
Was the Buildin	ng Fully Accessible for Inspection?	Yes	
Principal(s) Inf	Formation		
	Principal Name	Seth Shoenfeld	
	Principal Organization	New Drop H.S Staten Island	
	Meeting with Principal?	Yes	
	Principal Feedback	The Principal had no comments about the co	ondition of the athletic
		field at this time.	
Custodian		Edward Perez	
Was the Custoo	lian Present?	Yes	
Fireman		Demetrio Martino	
Was the Firema	an Present?	Yes	
Building Squar	re Footage	0	
Comments on t	the Area (for Athletic Field, Playing Surfaces, Leased Spaces)	Total Site Area: 811914 SF; Play Surface Ar	rea: 450000 SF

None

1983

3121

5

Comments on the Stories (Floors) plus Basements
Comments on the Year Built
Student Population
Staff Population
Comments on the Number of Classrooms
Weather

Facade Photo



Main Field from Press Box

Building Condition Assessment Survey 2023-2024

Architectural Inspection

Main Entrance Photo

R436

Roof Photo Not taken

Do Stormwater Management/Green Infrastructure systems exist?

Have any Systems/Major Building Components been upgraded?

Type

Main Entrance Gate

No

No Storm Water Management Type Selected

Systems: Handball Court repairs

Years: 2023

Systems: Running Track Surface replacement; Football/Soccer

Field Artificial Turf replacement; New Aluminum

Bleachers

Years: 2019

Systems: Running Track repairs

Years: 2008

Systems: "Take the Field" upgrades: Football Field - Synthetic

Turf installation, Baseball Field - Natural Turf installation, Running Track, Softball Field - upgrade

Years: 2002

No New Construction

No Tandem

No

Priority Condition

Tandem

Exist	Priority	Condition	Component	Location	Person(s)	Person(s)	Photo
Last Year?	Category	Description	Affected	Description	Notified	Title	Image
No	Tripping Hazard	Major cracks are more than 1-inch wide and are a potential tripping hazard	Tennis Court Surface	Tennis Courts	Demetrio Martino	Fireman	

Structural Engineer Required

Have there been any New Building Additions?

Structural	Condition	Component	Location	Person(s)	Person(s)	Photo
Condition Type	Description	Affected	Description	Notified	Title	Image


No condition recorded

Programmatic Accessibility

Programmatic Accessibility Status Question			Resp	onse		
Physical Breakdown Structure	Exists	Complies	Required	Deficiency	Assistive Listening	Fire Alarm
					System	Strobe

an entire entire and an appearance

Building Template



Inspection Question Response Architectural **EXTERIOR** Does not exist Inspected INTERIOR AUDITORIUM Does not exist Does not exist **CAFETERIA** CLASSROOMS/CORRIDORS/ADMIN SPACES Inspected Inspected Ceiling Condition 1- Good No deficiencies recorded Deficiency Does not exist Door(s) Floor Finish Inspected Condition 1- Good Deficiency No deficiencies recorded Walls Inspected Condition 1- Good Deficiency No deficiencies recorded Does not exist **Specialties** Does not exist **GYMNASIUM** Under construction INTERIOR DOOR HARDWARE INTERIOR GUARDS Under construction Does not exist KITCHEN Does not exist LIBRARY LOCKER ROOM Does not exist Does not exist MULTI-PURPOSE ROOM SCIENCE DEMO ROOM Does not exist Does not exist SCIENCE LAB Does not exist SCIENCE PREP ROOM Does not exist SHOWER ROOM Under construction STAIRS/RAMPS: INTERIOR Under construction TOILET ROOMS - STAFF Under construction **TOILET ROOMS - STUDENTS** ATHLETIC FIELDS Inspected Inspected PLAYING SURFACE 450,000 Replacement Quantity

Building Condition Assessment Survey 2023-2024

uestion	Response
ATHLETIC FIELDS	Teo,ponde
PLAYING SURFACE	
Replacement Uom	S.F.
Synthetic Turf Field exists?	Yes
Synthetic Turf Installation Year	2019
Instance on Baseball Field	Inspected
Instance Condition	3- Fair
Instance Quantity	100,000
Instance Quantity Uom	S.F.
Deficiency	NATURAL TURF:DAMAGED/WORN OUT
Deficiency Location/Instance Deficiency Location/Instance	RASS Newton finds Transmit Tourism Tou
Deficiency Quantity	100
Quantity Uom	S.F.
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo 1	
	Center Outfield
Deficiency Photo 2	No photo recorded
Violations	No violations recorded
Instance on Football / Soccer Field	Inspected
Instance Condition	2- Between Good and Fair
Instance Quantity	160,000
Instance Quantity Uom	S.F.
Deficiency	No deficiencies recorded
Instance on Handball Courts	Inspected
Instance Condition	2- Between Good and Fair
Instance Quantity	20,000
Instance Quantity Uom	S.F.
Deficiency	ASPHALT:DAMAGED/DETERIORATED
Deficiency Location/Instance	Handball Courts
Deficiency Location/Instance	R435 ***********************************
	F
Deficiency Quantity	25
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3

Building Condition Assessment Survey 2023-2024

Architectural Inspection R436 Question Response ATHLETIC FIELDS PLAYING SURFACE Purpose of Action LEVEL 2 Deficiency Photo 1 Handball Courts Deficiency Photo 2 No photo recorded Violations No violations recorded Instance on Running Track Inspected 2- Between Good and Fair Instance Condition Instance Quantity 30,000 Instance Quantity Uom S.F. ATHLETIC WEARING Deficiency SURFACE:DAMAGED/DETERIORATED Deficiency Location/Instance Running Track Deficiency Location/Instance Deficiency Quantity 5 Quantity Uom S.F. Potential Action MAINTENANCE PRIORITY 3 Urgency of Action Purpose of Action LEVEL 2 Deficiency Photo 1 Running Track No photo recorded Deficiency Photo 2 Violations No violations recorded Instance on Softball Field Inspected 3- Fair Instance Condition 80,000 Instance Quantity Instance Quantity Uom NATURAL TURF: DAMAGED/WORN OUT Deficiency

Deficiency Location/Instance

Softball Field

Building Condition Assessment Survey 2023-2024

Architectural Inspection R436 Question Response ATHLETIC FIELDS PLAYING SURFACE Deficiency Location/Instance Deficiency Quantity 3,500 Quantity Uom S.F. Potential Action REPLACE Urgency of Action PRIORITY 3 Purpose of Action LEVEL 2 Deficiency Photo 1 Softball Field Deficiency Photo 2 No photo recorded Violations No violations recorded Instance on Tennis Courts Inspected 5- Poor Instance Condition 60,000 Instance Quantity Instance Quantity Uom S.F. ASPHALT:DAMAGED/DETERIORATED Deficiency Tennis Courts Deficiency Location/Instance Deficiency Location/Instance **Deficiency Quantity** 10,000 Quantity Uom S.F. Potential Action REPLACE Urgency of Action PRIORITY 5 Purpose of Action LEVEL 6 Deficiency Photo 1 Tennis Courts Deficiency Photo 2 No photo recorded Violations No violations recorded

Inspected Does not exist

FIXED EQUIPMENT

Basketball Backboard

Building Condition Assessment Survey 2023-2024

hitectural Inspection		R43
Question	Response	
ATHLETIC FIELDS		
FIXED EQUIPMENT		
Basketball Hoops	Does not exist	
Basketball Posts	Does not exist	
Football Goal Posts	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Tennis Net Posts	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
SEATING	Inspected	
Benches	Inspected	
Concrete	Does not exist	
Metal/Wood/Plastic	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Bleachers	Inspected	
Concrete	Does not exist	
Metal/Wood/Plastic	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
SITE	Inspected	
CONTAINERIZATION	Does not exist	
DRAINAGE SYSTEM FOR ASPHALT	Inspected	
Catch Basins/Manhole - Surrounded by Asphalt	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Culverts - Asphalt Covering	Does not exist	

Inspected

Inspected

Inspected Inspected

Does not exist

Does not exist

Does not exist

2- Between Good and Fair No deficiencies recorded

2- Between Good and Fair

No deficiencies recorded

Inspected 3- Fair Condition Deficiency CHAIN LINK:DAMAGED/DETERIORATED Deficiency Location/Instance Handball court, tennis courts, football field **Deficiency Quantity** Quantity Uom S.F. Potential Action REPLACE Urgency of Action PRIORITY 3 LEVEL 2 Purpose of Action

DRAINAGE SYSTEM FOR CONCRETE

Condition

Condition

FENCES

Deficiency

Deficiency

Culverts - Soil Covering

DRINKING FOUNTAINS

Culverts - Concrete Covering DRAINAGE SYSTEM FOR SOIL

Catch Basins/Manhole - Surrounded by Concrete

Catch Basins/Manhole - Surrounded by Soil

Building Condition Assessment Survey 2023-2024

estion	Response
SITE	
FENCES	
Deficiency Photo 1	
	Handball court
Deficiency Photo 2	No photo recorded
Violations	No violations recorded
IRRIGATION SYSTEM	Inspected
Condition	5- Poor
Deficiency	INOPERABLE
Deficiency Location/Instance	Baseball field
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo 2	No photo recorded
Violations	No violations recorded
PAVING	Inspected
Student Non-Use	Inspected
Gravel Exists?	No
Asphalt	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Concrete	Inspected
Condition	3- Fair
Deficiency	CRACKS - MAJOR
Deficiency Location/Instance	Handball court
Deficiency Quantity	75
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo 1	
	Handball court
Deficiency Photo 2	No photo recorded
Violations	No violations recorded
Pavers	Does not exist
Student Use	Inspected
Gravel Exists?	No
Asphalt	Inspected
Condition	3- Fair

Deficiency

CRACKS - MAJOR

Building Condition Assessment Survey 2023-2024

nestion	Response	
SITE		
PAVING		
Student Use		
Asphalt		
Deficiency Location/Instance	Near tennis courts, around football field	
Deficiency Quantity	300	
Quantity Uom	S.F.	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Deficiency Photo 1		
	-	
	The second secon	
	The second second	
	Near tennis courts	
Deficiency Photo 2	No photo recorded	
Violations	No violations recorded	
Concrete	Does not exist	
Pavers	Does not exist	-
Site Sidewalks & Walkways	Inspected	
Asphalt	Inspected	
Condition	3- Fair	
Deficiency	CRACKS - MAJOR	
Deficiency Location/Instance	Near football field, Handball court	
Deficiency Quantity	250	
Quantity Uom	S.F.	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Deficiency Photo 1		
	Near football field	
Deficiency Photo 2	No photo recorded	
Violations	No violations recorded	
Concrete	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Pavers	Does not exist	
DOT Sidewalk	Does not exist	
	Does not exist Does not exist	
PLAYGROUNDS DLAVING SURFACE	Does not exist Does not exist	
PLAYING SURFACE DETAINING WALLS	Inspected	
RETAINING WALLS Condition	2- Between Good and Fair	
Condition	2- Detween Good and Fair	

Building Condition Assessment Survey 2023-2024

Question	Response	
SITE		
SEATING	Does not exist	
SITE WALLS (NOT RETAINING WALLS)	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
STAIRS/RAMPS: EXTERIOR	Does not exist	

NYC Department of Education Building Condition Assessment Survey 2023-2024

Architectural Inspection	R436
--------------------------	------

Does the SCA expect asset to have artwork?

No