#### **Building Condition Assessment Survey 2023-2024**

Electrical Inspection R973

Asset:	P.S. 373 TEMP. C.R. BLDG S.I., 91 HENDERSON AVENUE, STATEN ISLAND, NY, 10301		
Inspection Id	Inspection Type	Time In	Last Edited
3460	ELECTRICAL	2024-02-26 10:41AM	2024-03-19 09:54AM

2024-02-26 10:41AM 2024-03-19 09:54AM
Answer
Systems: Exit Lights (Battery Pack)
Years: 2021
Systems: Lighting - Security
Years: 2017, 1998
Systems: IPDVS/CCTV System
Years: 2015
Systems: Toilet Rooms (Fluorescent Lighting)
Years: 2014
Systems: Intrusion Alarm System
Years: 2000
Systems: All Other Electrical Systems and Components
Years: 1998
Below Ground
Yes

#### DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Water Penetration In Electrical Room?

Question	Response	
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in	No	
your building?		

#### **Priority Condition**

Exist	Priority	Condition	Component	Location	Person(s)	Person(s)	Photo
Last Year?	Category	Description	Affected	Description	Notified	Title	Image
Yes	Water Leaks onto Electrical Equipment	Water leaks from the roof onto light fixture.	Lighting Fixture	Room 100	Robert Miller	Fireman	

ctrical Equipment	onto light fixture.	Fixture	Miller	

No

pection	
Question	Response
Electrical	
ATHLETIC FIELD	Does not exist
AUDITORIUM	Does not exist
CAFETERIA	Does not exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected
Lighting	Inspected
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Surface Mounted	Inspected
Condition	3- Fair

### **Building Condition Assessment Survey 2023-2024**

uestion	Response	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE		
Lighting		
Lighting Fixture - Fluorescent		
Surface Mounted		
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE BALLAST	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Recessed Mounted	Inspected	
Condition	3- Fair	
Deficiency  Deficiency Quantity	LIGHTING FIXTURE BALLAST DEFECTIVE	
Deficiency Quantity	4 FACH	
Quantity Uom Potential Action	EACH REPLACE BALLAST	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - Healiucsecht  Lighting Fixture - LED	Does not exist	
	Does not exist	
COMPUTER LAB		
GYMNASIUM	Does not exist	
KITCHEN	Does not exist	
LIBRARY	Does not exist	
LOCKER ROOM	Does not exist	
MULTIPURPOSE ROOM	Inspected	
Instance on 1st Floor	Inspected	
Lighting		
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Does not exist	
Recessed Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Does not exist	
Local Sound System	2000 100 01100	
Instance on 1st Floor	Does not exist	
Projection System	2000 100 2010	
Instance on 1st Floor	Does not exist	
Theater Lighting System		
Instance on 1st Floor	Does not exist	

### **Building Condition Assessment Survey 2023-2024**

iteu inspection		10/13
Question	Response	
SCIENCE DEMO ROOM	Does not exist	
SCIENCE LAB	Does not exist	
SCIENCE PREP ROOM	Does not exist	
	Does not exist	
SWIMMING POOL		
TOILET ROOM - STAFF	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Does not exist	
Recessed Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
TOILET ROOM - STUDENT	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Does not exist	
Recessed Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
AUXILIARY SIGNAL/BELL SYSTEM	Does not exist	
EMERGENCY DC STANDBY BATTERY POWER	Does not exist	-
EMERGENCY GENERATOR SET	Does not exist	
EMERGENCY LIGHT/EXIT LIGHT PANEL	Does not exist	
EMERGENCY LIGHTING	Inspected	
Battery Pack	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Non Battery Pack	Does not exist	
EXIT LIGHT	Inspected	
Battery Pack	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
	Does not exist	
Non Battery Pack	Does not exist	
EXIT/EMERGENCY LIGHT		
FIRE ALARM SYSTEM	Inspected	
Bell/Horn	Inspected 3- Fair	
Condition		
Deficiency	No deficiencies recorded	
Strobe	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Manual Pull Station	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fan Shutdown Control	Inspected	

### **Building Condition Assessment Survey 2023-2024**

nicui inspection		K9/3
Question	Response	
FIRE ALARM SYSTEM		
Fan Shutdown Control		
Deficiency	No deficiencies recorded	
Duct Smoke Detector	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Area Smoke Detector	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
CO Detector	Does not exist	
Heat Detector	Does not exist	
Elevator Recall	Does not exist	
Magnetic Door Holder/Contactor	Does not exist	
Fused Cutout Panel	Inaccessible	
Fire Alarm Digital Communicator	Does not exist	
Main Panel	Inspected	
Bell At Panel	Does not exist	
Fire Alarm Control Panel (Electronic)	Inspected	
Instance	Main Entrance	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Edwards System Technology	
Model	EST 2	
EquipmentId	Fire Alarm Control Panel	
Installation Year	1998	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Standard)	Does not exist	
Sub-Panel	Does not exist	
Remote Annunciator	Does not exist	
Sprinkler Flow/Air Pressure Switch	Does not exist	
Tamper Flow Switch/Chain	Does not exist	
GROUNDING SYSTEM	Inaccessible	
INTERCOM SYSTEM	Does not exist	
LAN	Inspected	
Local Distribution Frame (I/LDF)	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Main Equipment Rack (MDF)	Does not exist	
LIGHTNING PROTECTION	Does not exist	
MOTOR CONTROLLER	Does not exist	
PANEL BOARD	Inspected	
Fused Disconnect Switch Type	Does not exist	
Fused Knife Switch Type	Does not exist	
Fused Toggle Switch Type	Does not exist	
Molded Case Circuit Breaker Type	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
PUBLIC ADDRESS SYSTEM	Inspected	
Instance	Connected to Main Asset R040	
Instance Condition	3- Fair	
Instance Quantity	1	

### **Building Condition Assessment Survey 2023-2024**

Question	Response
PUBLIC ADDRESS SYSTEM	
Model	N/A
Installation Year	1998
Source of Installation Year	Documented
Deficiency	CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Corridor
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
SECURITY	Inspected
IPDVS/CCTV System	Inspected
Condition	2- Between Good and Fair
Installation Year	2015
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Intrusion Alarm System	Inspected
Central Control Panel	Does not exist
Infrared Sensor	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Panic Switch	Does not exist
Remote Annunciator	Does not exist
Siren/Strobe	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting - Security	Inspected
Condition	4- Between Fair and Poor
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Location/Instance	Building Perimeter
Deficiency Quantity	7
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 3
Violations	No violations recorded
SERVICE SWITCH	Inaccessible
SWITCHBOARD	Inspected
Number of Spares	1
Fused Disconnect Switch Type	Does not exist
• •	Does not exist
Fused Knife Switch Type  Molded Case Circuit Breaker Type	Inspected
Instance	Electrical Room
Instance Condition	3- Fair
	<u>·</u>
Instance Quantity	1 EACH
Instance Quantity Uom	EACH
Manufacturer	Square D
EquipmentId	DP-1
Capacity/Size Quantity	1200
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	1998

# **Building Condition Assessment Survey 2023-2024**

uestion	Response	
SWITCHBOARD		
Molded Case Circuit Breaker Type		
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
FELEPHONE SYSTEM	Inspected	
PBX/Intercom	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Standard	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
TRANSFORMER	Does not exist	