Building Condition Assessment Survey 2023-2024

Asset:	P.S. 35 - BRONX,	261 EAST 163 STREET, I	BRONX, NY, 10	0451			
Inspection	1 Id Inspection Type				Time 1	In	Last Edited
2	2444 ELECTRICAL				2024-	01-17 08:32AM	1 2024-02-13 08:26A
set Data							
Question				Answer			
Have any	Systems/Major Building Co	omponents been upgraded?		Systems:	LED Lighting	(Staircase)	
				Years:	2023		
				Systems:	LAN		
				Years:	2022		
				Systems:		ghting, Exit Lig	hts
				Years:	2019		
				Systems:	Interior Lighti	ng	
				Years:	2015		
				Systems:	Telephone Sys	stem	
				Years:	2012		7
				Systems: Years:	2nd Floor Mul Security Light 2009		(Projection System),
				Systems:	Fire Alarm Sy	stem	
				Years:	2008	Stelli	
				Systems:	Switchboards		
				Years:	2007, 1998		
				Systems:		Circuit Breaker	Panel Board
				Years:	2007, 1997		
				Systems:	Service Switch	h	
				Years:	1998		
				Systems:		ght/Exit Light P	anel, Intrusion Alarm
				Ž	System		,
				Years:	1992		
				Systems:	Public Addres	s System	
				Years:	1990		
Type of Se				Below Gro	ound		
	ractive Whiteboard (IWB) E			Yes			
	etration In Electrical Room			No			
	ATED INTERCOMS IN	FIRE RESCUE AREAS		т)		
Question	re any Life Rescue Assistant	ce Areas, Fire Rescue Areas, an	d/or Holding Room		Response No		
your bui		te ricus, i ne reseue ricus, un	d/of Holding Roof	1			
iority Co							
xist ast Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
	ion recorded						
spection							
Question				Response			
Electrical					• .		
	ETIC FIELD			Does not e			
AUDITORIUM			Does not e	exist			
CAFET				Inspected			
	Instance on Basement			Inspected			
Lighti				Y 4			
	Instance on Basement			Inspected			
Ligh	Instance on Basement	;		Inamasta 1			
n.	Instance on Basement			Inspected			
re	Instance on Basement			Does not e	exist		
	motance on Dascincill			Does not 6	-1110t		

Building Condition Assessment Survey 2023-2024

Question	Response	
CAFETERIA		
Lighting		
Lighting Fixture - Fluorescent		
Surface Mounted		
Instance on Basement	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on Basement	Does not exist	
Lighting Fixture - HID		
Instance on Basement	Does not exist	
Lighting Fixture - Incandescent		
Instance on Basement	Does not exist	
Lighting Fixture - LED	2000 100 01100	
Instance on Basement	Does not exist	
Local Sound System	DOES NOT CAUSE	
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Installation Year	1960	
Source of Installation Year	Inspector Estimate	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Cafeteria-Basement	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Projection System		
Instance on Basement	Does not exist	
Theater Lighting System		
Instance on Basement	Does not exist	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected	
Lighting	Inspected	
Does a Chandelier Exist?	Yes	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
	Does not exist	
Recessed Mounted	Does not exist Does not exist	
Lighting Fixture - HID		
Lighting Fixture - Incandescent	Inspected	
Pendant Mounted	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Does not exist	
Recessed Mounted	Does not exist	
Lighting Fixture - LED	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	

Building Condition Assessment Survey 2023-2024

incui Inspection		A033
Question	Response	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE		
Lighting		
Lighting Fixture - LED		
Recessed Mounted	Does not exist	
COMPUTER LAB	Does not exist	
GYMNASIUM	Does not exist	
KITCHEN	Inspected	
Instance on Basement	Inspected	
Lighting	Turn acts d	
Instance on Basement	Inspected	
Lighting Fixture - Fluorescent	Y 1	
Instance on Basement	Inspected	
Pendant Mounted		
Instance on Basement	Does not exist	
Surface Mounted		
Instance on Basement	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on Basement	Does not exist	
Lighting Fixture - HID		
Instance on Basement	Does not exist	
Lighting Fixture - Incandescent		
Instance on Basement	Does not exist	
Lighting Fixture - LED		
Instance on Basement	Does not exist	
LIBRARY	Inspected	
Instance on 1st Floor	Inspected	
Lighting		
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on 1st Floor	Does not exist	
Recessed Mounted		
Instance on 1st Floor	Does not exist	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Does not exist	
Raceway With Receptacles		
Instance on 1st Floor	Does not exist	
Projection System		
Instance on 1st Floor	Does not exist	
LOCKER ROOM	Does not exist	
MULTIPURPOSE ROOM	Inspected	
Instance on 2nd Floor	Inspected	

Building Condition Assessment Survey 2023-2024

Electrical Inspection X035

Question Response

T		
uestion	Response	
MULTIPURPOSE ROOM		
Instance on Basement	Inspected	
Lighting	•	
Instance on 2nd Floor	Inspected	
Instance on Basement	Inspected	
Lighting Fixture - Fluorescent		
Instance on 2nd Floor	Inspected	
Instance on Basement	Inspected	
Pendant Mounted	•	
Instance on 2nd Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Instance on Basement	Does not exist	
Surface Mounted	200 100 01100	
Instance on 2nd Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Instance on Basement	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
-	No deficiencies recorded	
Recessed Mounted Instance on 2nd Floor	Does not exist	
Instance on Basement	Does not exist	
Lighting Fixture - HID		
Instance on 2nd Floor	Does not exist	
Instance on Basement	Does not exist	
Lighting Fixture - Incandescent		
Instance on 2nd Floor	Does not exist	
Instance on Basement	Does not exist	
Lighting Fixture - LED		
Instance on 2nd Floor	Inspected	
Instance on Basement	Does not exist	
Pendant Mounted		
Instance on 2nd Floor	Does not exist	
Surface Mounted		
Instance on 2nd Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 2nd Floor	Does not exist	
Local Sound System		
Instance on 2nd Floor	Inspected	
Instance Condition	5- Poor	
Installation Year	1960	
Source of Installation Year	Documented	
Deficiency	AMPLIFIER NOT OPERATIONAL	
Deficiency Quantity	1	
Quantity Uom	EACH DEN ACE SYSTEM	
Potential Action	REPLACE SYSTEM	
Urgency of Action	PRIORITY 2	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Instance on Basement	Inspected	

Building Condition Assessment Survey 2023-2024

incui inspection		21055
Question	Response	
MULTIPURPOSE ROOM		
Local Sound System		
Installation Year	1960	
Source of Installation Year	Inspector Estimate	
Deficiency	AMPLIFIER NOT OPERATIONAL	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE SYSTEM	
Urgency of Action	PRIORITY 2	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Projection System		
Instance on 2nd Floor	Inspected	
Instance Condition	3- Fair	
Is the projector on a cart or installed on the ceiling?	Ceiling	
Deficiency	No deficiencies recorded	
Instance on Basement	Does not exist	
Theater Lighting System		
Instance on 2nd Floor	Does not exist	
Instance on Basement	Does not exist	
SCIENCE DEMO ROOM	Does not exist	
SCIENCE LAB	Does not exist	
SCIENCE PREP ROOM	Does not exist	
SWIMMING POOL	Does not exist	
TOILET ROOM - STAFF	Inspected	
	Inspected	
Lighting Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
	Inspected	
Surface Mounted	2- Between Good and Fair	
Condition		
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
TOILET ROOM - STUDENT	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
AUXILIARY SIGNAL/BELL SYSTEM	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
EMERGENCY DC STANDBY BATTERY POWER	Does not exist	
EMERGENCY GENERATOR SET	Does not exist	

Building Condition Assessment Survey 2023-2024

ricai inspection	AUSS
Question	Response
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Non Battery Pack	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
	Inspected
Battery Pack Condition	1- Good
Deficiency	No deficiencies recorded
Non Battery Pack	Does not exist
EXIT/EMERGENCY LIGHT	Does not exist
FIRE ALARM SYSTEM	Inspected
Bell/Horn	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Strobe	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Manual Pull Station	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	Does not exist
Duct Smoke Detector	Does not exist
Area Smoke Detector	Does not exist
CO Detector	Does not exist
Heat Detector	Does not exist
Elevator Recall	Does not exist
Magnetic Door Holder/Contactor	Does not exist
Fused Cutout Panel	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	Does not exist
Main Panel	Inspected
Bell At Panel	Does not exist
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Electrical Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Mircom
Model	FX - 2000
EquipmentId	Fire Alarm Control
Installation Year	2008
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	Does not exist
Sub-Panel	Does not exist
Remote Annunciator	Does not exist
Sprinkler Flow/Air Pressure Switch	Inspected
* · · · · · · · · · · · · · · · · · · ·	

Building Condition Assessment Survey 2023-2024

neui mspection		14055
Question	Response	
FIRE ALARM SYSTEM		
Sprinkler Flow/Air Pressure Switch		
Deficiency	No deficiencies recorded	
Tamper Flow Switch/Chain	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
GROUNDING SYSTEM	Inspected	
	3- Fair	
Condition		
Deficiency	No deficiencies recorded	
INTERCOM SYSTEM	Does not exist	
LAN	Inspected	
Local Distribution Frame (I/LDF)	Does not exist	
Main Equipment Rack (MDF)	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
LIGHTNING PROTECTION	Does not exist	
MOTOR CONTROLLER	Inspected	
MOTOR CONTROL CENTER	Does not exist	
MOTOR STARTER/CONTACTOR	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Variable Frequency Drive	Does not exist	
PANEL BOARD	Inspected	
	Does not exist	
Fused Disconnect Switch Type	Does not exist Does not exist	
Fused Knife Switch Type Fused Toggle Switch Type	Does not exist	
Molded Case Circuit Breaker Type	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
PUBLIC ADDRESS SYSTEM	Inspected	
Instance	General Office	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Model	Rauland TC2100	
Installation Year	1990	
Source of Installation Year	Inspector Estimate	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	General Office	
Deficiency Quantity	45,000	
Quantity Uom	S.F.	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
SECURITY	Inspected	
IPDVS/CCTV System	Does not exist	
Intrusion Alarm System	Inspected	
Central Control Panel	Inspected	
Instance	Custodian's Office	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
• · · · · · · · · · · · · · · · · · · ·		

Building Condition Assessment Survey 2023-2024

uestion	Response	
SECURITY		
Intrusion Alarm System		
Central Control Panel		
Installation Year	1992	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Custodian's Office	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 3	
Violations	No violations recorded	
Infrared Sensor	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Panic Switch	Inspected	
Condition	3- Fair	
	-	
Deficiency	No deficiencies recorded	
Remote Annunciator	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Siren/Strobe	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lighting - Security	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
SERVICE SWITCH	Inspected	
Instance	Electrical Room	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Electrotech	
EquipmentId	Main Dist	
Capacity/Size Quantity	1200	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year	1998	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
SWITCHBOARD	Inspected	
Number of Spares	3	
Fused Disconnect Switch Type	Inspected	
Instance	Electrical Room	
Instance Condition	2- Between Good and Fair	
Instance Quantity		
	1 EACH	
Instance Quantity Uom		
Manufacturer	Cutler Hammer	
EquipmentId	DIST Panel	
Capacity/Size Quantity	600	
Capacity/Size UOM	Amps Total	
Capacity/Size 2 Quantity	1	
Capacity/Size 2 UOM	Section(s)	
Source of Capacity/Size	Nameplate	

Building Condition Assessment Survey 2023-2024

uestion	Response	
SWITCHBOARD		
Fused Disconnect Switch Type		
Installation Year	2007	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance	Electrical Room	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Electrotech	
EquipmentId	N/A	
Capacity/Size Quantity	1200	
Capacity/Size UOM	Amps Total	
Capacity/Size 2 Quantity	1	
Capacity/Size 2 UOM	Section(s)	
Source of Capacity/Size	Nameplate	
Installation Year	1998	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Fused Knife Switch Type	Does not exist	
Molded Case Circuit Breaker Type	Does not exist	
FELEPHONE SYSTEM	Inspected	
PBX/Intercom	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Standard	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
TRANSFORMER	Does not exist	