Building Condition Assessment Survey 2023-2024

Electrical Inspection X052

Asset:	I.S. 302 - BRONX, 681 KELLY STREET, BRONX, NY, 10455			
Inspection Id	Inspection Type		Time In	Last Edited
3000	ELECTRICAL		2024-02-06 09:18AM	2024-05-10 02:55PN
et Data				
Question		Answer		
Have any Systems/Major Building Components been upgraded?		Systems:	Auditorium (Retrofitted Surface LAN (MDF and IDF), Public Ac Sound System, Security Lights	
		Years:	2023	
		Systems:	IPDVS/CCTV System, Gymnas	ium (LED Lighting)
		Years:	2022	
		Systems:	Partial Molded Case Circuit Bre	aker Panel Board
		Years:	2020, 2011, 2000, 1996	
		Systems:	Exit Light (Battery Pack)	
		Years:	2020	
		Systems:	Emergency Lighting (Battery Pa	ck)
		Years:	2018	
		Systems:	Telephone System	
		Years:	2016	
		Systems:	Kitchen (Fluorescent Lighting), Fire Alarm System	Partial Motor Starter,
		Years:	2015	
		Systems:	Partial Emergency Lighting (No: Interior Fluorescent Lighting Ex	•
		Years:	2012	
		Systems:	Intrusion Alarm System	
		Years:	1998	
		Systems:	Fused Disconnect Type Panel Bo Light/Exit Light Panel	oard, Emergency
		Years:	1995	
Type of Service		Below Gr	round	
Does Interactiv	e Whiteboard (IWB) Exist?	Yes		
	,			

Water Penetration In Electrical Room?

	DEDICATED INTERCOMS IN FIRE RESCUE AREAS	
(Question	Response
	Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in	No
	your building?	

Electrical

Priority Condition							
Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
Yes	Fire Alarm System - Components Not Operational	N/A	Fire Alarm System - Magnetic Door Holder/Contac tor	Near Room 331	Freddy Lee	Fireman	No Photo Taken
No	Water Leaks onto Electrical Equipment	N/A	Lighting Fixture	Basement Room B13	Fredy Lee	Fireman	Down 812
No	Water Penetration in Electrical Room	N/A	Electrical Equipment	Electrical Meter Room	Fredy Lee	Fireman	No Photo Taken
Inspection	1						
Question	1			Response	2		

Building Condition Assessment Survey 2023-2024

Electrical Inspection	A032

Response	
Does not exist	
Inspected	
Inspected	_
No	
Inspected	
·	
Inspected	
2- Between Good and Fair	
	-
Does not exist	
2000 1000 011100	-
Does not exist	
DOGS HOT CALLET	
Does not exist	
DOGS HOT CAIST	
Does not exist	
Dues not exist	
Inspected	
inspected	
Does not exist	
DOCS HOL CAISE	
Inconceted	
<u> </u>	
ino deficiencies recorded	
Door not oriot	
Does not exist	
Inconceted	
ivo deficieles recorded	
Inspected	
140 deficiences recorded	
Inspected	
mspecce	
Does not exist	
DOCS HOL CAISE	
Inconceted	
	Does not exist Inspected Inspected Inspected Inspected Inspected Inspected

Building Condition Assessment Survey 2023-2024

Electrical Inspection	X052
Question	Response

inea inspection		11032
Question	Response	
AUDITORIUM		
Theater Lighting System		
Theater Lighting		
Violations	No violations recorded	
CAFETERIA	Inspected	
Instance on Basement - Staff	Inspected	
Instance on Basement - Students	Inspected	
Lighting	Inspected	
Instance on Basement - Staff	Inspected	
Instance on Basement - Students	Inspected	
Lighting Fixture - Fluorescent		
Instance on Basement - Staff	Inspected	
Instance on Basement - Students	Inspected	
Pendant Mounted		
Instance on Basement - Staff	Does not exist	
Instance on Basement - Students	Does not exist	
Surface Mounted	Book not exist	
Instance on Basement - Staff	Does not exist	
Instance on Basement - Students	Does not exist	
Recessed Mounted	DOCS HOT CAIST	
Instance on Basement - Staff	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Instance on Basement - Students		
	Inspected 2- Between Good and Fair	
Instance Condition		
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on Basement - Staff	Does not exist	
Instance on Basement - Students	Does not exist	
Lighting Fixture - Incandescent		
Instance on Basement - Staff	Does not exist	
Instance on Basement - Students	Does not exist	
Lighting Fixture - LED		
Instance on Basement - Staff	Does not exist	
Instance on Basement - Students	Does not exist	
Local Sound System		
Instance on Basement - Staff	Does not exist	
Instance on Basement - Students	Inspected	
Instance Condition	1- Good	
Installation Year	2023	
Source of Installation Year	Documented No deficiencies recorded	
Deficiency	No deficiencies recorded	
Projection System Instance on Basement - Staff	Does not exist	
Instance on Basement - Students	Does not exist	
Theater Lighting System Instance on Basement - Staff	Does not exist	
Instance on Basement - Students	Does not exist	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected	
Lighting Dogs a Chandelian Exist?	Inspected	
Does a Chandelier Exist?	No Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected 2- Between Good and Fair	
Condition	2- Detween Good and Fair	

Building Condition Assessment Survey 2023-2024

icai inspection		AUS
nestion	Response	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE		
Lighting		
Lighting Fixture - Fluorescent		
Pendant Mounted		
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
COMPUTER LAB	Does not exist	
GYMNASIUM	Inspected	
Instance on 1st Floor	Inspected	
Lighting	inspected	
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Instance on 1st Floor	Does not exist	
Lighting Fixture - HID	DOES NOT CAUST	
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent	DOES NOT CAIST	
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED	Does not exist	
Instance on 1st Floor	Inspected	
Pendant Mounted	nispected	
Instance on 1st Floor	Does not exist	
	Does not exist	
Surface Mounted Instance on 1st Floor	Inspected	
	1- Good	
Instance Condition		
Deficiency Deficiency Quantity	LIGHTING FIXTURE BALLAST DEFECTIVE 6	
Quantity Uom	EACH	
Potential Action	REPLACE BALLAST	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Recessed Mounted		
Instance on 1st Floor	Does not exist	
Local Sound System		
Instance on 1st Floor	Inspected	
Instance Condition	1- Good	
Installation Year	2023	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System		
Instance on 1st Floor	Does not exist	
Scoreboard		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	

Building Condition Assessment Survey 2023-2024

Electrical InspectionX052QuestionResponse

neui mspection		11032
Question	Response	
GYMNASIUM		
Theater Lighting System		
Instance on 1st Floor	Does not exist	
KITCHEN	Inspected	
Instance on Basement	Inspected	
Lighting		
Instance on Basement	Inspected	
Lighting Fixture - Fluorescent		
Instance on Basement	Inspected	
Pendant Mounted		
Instance on Basement	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Basement	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on Basement	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID	Tvo deficiences recorded	
Instance on Basement	Does not exist	
Lighting Fixture - Incandescent	DOES NOT CAIST	
Instance on Basement	Does not exist	
Lighting Fixture - LED	DOGS HOT CAIST	
Instance on Basement	Does not exist	
	Inspected	
LIBRARY		
Instance on Room 300	Inspected	
Lighting	Inspected	
	Inspected	
Lighting Fixture - Fluorescent Instance on Room 300		
	Inspected	
Pendant Mounted		
Instance on Room 300	Inspected 2- Between Good and Fair	
Instance Condition		
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room 300	Does not exist	
Recessed Mounted		
Instance on Room 300	Does not exist	
Lighting Fixture - HID		
Instance on Room 300	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 300	Does not exist	
Lighting Fixture - LED		
Instance on Room 300	Does not exist	
Raceway With Receptacles		
Instance on Room 300	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Projection System		
Instance on Room 300	Does not exist	

Building Condition Assessment Survey 2023-2024

Question	Response
LOCKER ROOM	Inspected
Instance on 2nd Floor - Girls	Inspected
Alternative Use	Yes
Instance on 1st Floor - Boys	Inaccessible
Lighting	I AND SOLOTO
Instance on 2nd Floor - Girls	Inspected
Lighting Fixture - Fluorescent	
Instance on 2nd Floor - Girls	Does not exist
Lighting Fixture - HID	Does not exist
Instance on 2nd Floor - Girls	Does not exist
Lighting Fixture - Incandescent	2000 100 01100
Instance on 2nd Floor - Girls	Inspected
Pendant Mounted	Inspected
Instance on 2nd Floor - Girls	Does not exist
Surface Mounted	DOGS HOT CAIST
Instance on 2nd Floor - Girls	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	18
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	
Instance on 2nd Floor - Girls	Does not exist
Lighting Fixture - LED	
Instance on 2nd Floor - Girls	Does not exist
MULTIPURPOSE ROOM	Does not exist
SCIENCE DEMO ROOM	Inspected
Instance on Room 311	Inspected
Power Panel?	Yes
Alternative Use	
	Yes
Instance on Room 307	Inspected
Power Panel?	No
Alternative Use	Yes
Lighting	
Instance on Room 311	Inspected
Instance on Room 307	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 311	Inspected
Instance on Room 307	Inspected
Pendant Mounted	
Instance on Room 311	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 307	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 311	Does not exist
Instance on Room 307	Does not exist
Recessed Mounted	

Building Condition Assessment Survey 2023-2024

icui Inspection		7103
iestion	Response	
SCIENCE DEMO ROOM		
Lighting		
Lighting Fixture - Fluorescent		
Recessed Mounted		
Instance on Room 307	Does not exist	
Lighting Fixture - HID		
Instance on Room 311	Does not exist	
Instance on Room 307	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 311	Does not exist	
Instance on Room 307	Does not exist	
Lighting Fixture - LED		
Instance on Room 311	Does not exist	
Instance on Room 307	Does not exist	
Emergency Gas Shut-Off Valve		
Instance on Room 311	Does not exist	
Instance on Room 307	Does not exist	
Emergency Shut-Off Power		
Instance on Room 311	Does not exist	
Instance on Room 307	Does not exist	
Power Supply		
Instance on Room 311	Does not exist	
Instance on Room 307	Does not exist	
Projection System		
Instance on Room 311	Does not exist	
Instance on Room 307	Does not exist	
CIENCE LAB	Inspected	
Instance on Room 310	Inspected	
Power Panel?	Yes	
Alternative Use	Yes	
Lighting_		
Instance on Room 310	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 310	Inspected	
Pendant Mounted		
Instance on Room 310	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room 310	Does not exist	
Recessed Mounted		
Instance on Room 310	Does not exist	
Lighting Fixture - HID		
Instance on Room 310	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 310	Does not exist	
Lighting Fixture - LED		
Instance on Room 310	Does not exist	
Emergency Gas Shut-Off Valve		
Instance on Room 310	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Emergency Shut-Off Power		
Instance on Room 310	Does not exist	

Building Condition Assessment Survey 2023-2024

неш твресион	Aus
Question	Response
SCIENCE LAB	
Power Supply	
Instance on Room 310	Does not exist
Projection System	
Instance on Room 310	Does not exist
SCIENCE PREP ROOM	Does not exist
SWIMMING POOL	Does not exist
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	8
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	Does not exist
Lighting Fixture - LED	Does not exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	12
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action Purpose of Action	PRIORITY 1 LEVEL 2
Violations	No violations recorded
Recessed Mounted	Does not exist
Lighting Fixture - LED	Does not exist Does not exist
AUXILIARY SIGNAL/BELL SYSTEM Condition	Inspected 3- Fair
Deficiency	No deficiencies recorded

Building Condition Assessment Survey 2023-2024

Question	Response	
EMERGENCY DC STANDBY BATTERY POWER	Does not exist	
EMERGENCY GENERATOR SET	Does not exist	
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected 3- Fair	
Condition		
Deficiency	No deficiencies recorded	
EMERGENCY LIGHTING	Inspected	
Battery Pack	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Non Battery Pack	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
EXIT LIGHT	Inspected	
Battery Pack	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Non Battery Pack	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
EXIT/EMERGENCY LIGHT	Does not exist	
FIRE ALARM SYSTEM	Inspected	
Bell/Horn	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Strobe	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Manual Pull Station	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Fan Shutdown Control	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Duct Smoke Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Area Smoke Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
CO Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Heat Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Elevator Recall	Does not exist	
Magnetic Door Holder/Contactor	Inspected	
Condition	2- Between Good and Fair	
Deficiency	CONTACTOR NOT OPERATIONAL	
Deficiency Location/Instance	Near Room 331	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 5	

Building Condition Assessment Survey 2023-2024

нсш інгресион	Λυ
uestion	Response
FIRE ALARM SYSTEM	
Magnetic Door Holder/Contactor	
Purpose of Action	LEVEL 6
Violations	12117572Н
Fused Cutout Panel	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	Does not exist
Main Panel	Inspected
Bell At Panel	Does not exist
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Main Entrance Lobby
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Gamewell
Model	E3 Series
EquipmentId	Fire Alarm Control Panel
Installation Year	2015
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	Does not exist
Sub-Panel	Does not exist
Remote Annunciator	Inspected
Display Monitor	Does not exist
Panel	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Printer	Inspected
Condition	5- Poor
Deficiency	PRINTER NOT OPERATIONAL
Deficiency Location/Instance	Custodian's Office
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
Punch Register	Does not exist
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Tamper Flow Switch/Chain	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
NTERCOM SYSTEM	Does not exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected

Building Condition Assessment Survey 2023-2024

Question	Response
LAN	
Main Equipment Rack (MDF)	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Does not exist
MOTOR CONTROLLER	Inspected
MOTOR CONTROL CENTER	Does not exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Does not exist
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room (Original Building)
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Molded Case Circuit Breaker Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Throughout the Building
Deficiency Quantity	22
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PANEL BOARD COVER IS MISSING
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PANEL BOARD DOOR LOCK IS MISSING
Deficiency Location/Instance	Boiler Room, Electrical Meter Room
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
PUBLIC ADDRESS SYSTEM	Inspected
Instance	Main Office - Room 106
Instance Condition	1- Good

Building Condition Assessment Survey 2023-2024

Question	Response
PUBLIC ADDRESS SYSTEM	
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Telecor II
Installation Year	2023
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
SECURITY	Inspected
IPDVS/CCTV System	Inspected
Condition	1- Good
Installation Year	2022
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	Custodian's Office
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 50P
Installation Year	1998
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	3- Fair
Deficiency	SENSOR NOT OPERATIONAL
Deficiency Location/Instance	Kitchen
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Violations	No violations recorded
Panic Switch	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting - Security	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
SERVICE SWITCH	Inspected
Instance	Electrical Meter Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Empire Switchboard
Manuracturer EquipmentId	N/A
Equipmentid Capacity/Size Quantity	N/A 800
Capacity/Size UOM	Amps
1 ,	

Building Condition Assessment Survey 2023-2024

n	Response
ICE SWITCH	
Source of Capacity/Size	Fuse Size
Installation Year	1962
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Meter Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Electrical Meter Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Empire Switchboard
EquipmentId	N/A
Capacity/Size Quantity	800
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1962
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Meter Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Electrical Meter Room
Instance Condition	3- Fair
Instance Quantity	1
	EACH
Instance Quantity Uom	
Manufacturer	Empire Switchboard
EquipmentId	N/A
Capacity/Size Quantity	600
Capacity/Size UOM	Amps
Source of Capacity/Size	Fuse Size 1962
Installation Year Source of Installation Year	
	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Meter Room
Deficiency Quantity	1 EACH
Quantity Uom	EACH DEPLACE
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Electrical Meter Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Empire Switchboard
EquipmentId	SERVICE B NEW BUILDING

Building Condition Assessment Survey 2023-2024

ricui inspection	Αυδ
Question	Response
SERVICE SWITCH	
Capacity/Size Quantity	600
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1962
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Meter Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
_	
Violations	No violations recorded
SWITCHBOARD	Inspected
Number of Spares	1
Fused Disconnect Switch Type	Does not exist
Fused Knife Switch Type	Does not exist
Molded Case Circuit Breaker Type	Inspected
Instance	Electrical Room (Addition Building)
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Empire Switchboard
EquipmentId	MAIN DIST. SECTION A
Capacity/Size Quantity	600
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	1962
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room (Addition Building)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Electrical Room (Addition Building)
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Empire Switchboard
EquipmentId	N/A
Capacity/Size Quantity	600
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	1962
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room (Addition Building)
Deficiency Quantity	1
Quantity Uom	EACH

Building Condition Assessment Survey 2023-2024

rical Inspection	Response
uestion	Kesponse
SWITCHBOARD	
Molded Case Circuit Breaker Type	
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Electrical Room (Original Building)
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Empire Switchboard
EquipmentId	N/A
Capacity/Size Quantity	800
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	1962
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room (Original Building)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Electrical Room (Original Building) 3- Fair
Instance Condition	
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Empire Switchboard
EquipmentId	MAIN DIST. SECTION B
Capacity/Size Quantity	800
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	1962
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room (Original Building)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Standard	Inspected 2- Between Good and Fair
Condition	2- Between Good and Fair

No deficiencies recorded

Does not exist

Deficiency

TRANSFORMER