

**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

**Mechanical Inspection**

**X053**


**Asset:** P.S. 53 - BRONX, 360 EAST 168 STREET, BRONX, NY, 10456

Inspection Id	Inspection Type	Time In	Last Edited
2095	MECHANICAL	2024-01-03 07:12AM	2024-04-19 09:53AM

**Asset Data**

Question	Answer
Have any Systems/Major Building Components been upgraded?	Systems: Boiler #1 re-tubed Years: 2023 Systems: Kitchen - Gas System; Gas Distribution Piping (~50%) Years: 2021 Systems: Gas Fired Domestic Water Heater; Domestic Hot Water Remote Storage Tank Years: 2020 Systems: Fixtures - Toilets, Urinals; Terminal Unit Thermostatic Traps (~90%); F&T/Steam Drip Traps Years: 2018 Systems: MDF Room - Dedicated A/C Equipment (DX Split System) Years: 2015
Are there fuel tanks?	Yes
Total # of above ground tanks	2
Total capacity of all above ground tanks in gal.	15,000
Total # of below ground tanks	0
Total capacity of all below ground tanks in gal.	0
Total # of water main service entries to the asset	2
MERs/Fan Rooms Locations	Boiler Room Mechanical Area
Are there any spaces with Missing or Defective CO Detectors?	Yes
Location(s)	Kitchen
Are there any Painted/Obstructed Sprinkler Heads?	Yes
Location(s)	Rooms 252, 254, Closet next to Rooms 312, 412 (painted, 5)
Are there any Emergency Stop Switches with Missing Hammers?	No components

**Priority Condition**

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
Yes	Defective Boiler Safety Auxiliary	(4)	Boiler Safety Valve	Boiler Room @ Boilers #1, #2	Vladimir Pali	Fireman	

**Inspection**

Question	Response
<b>Mechanical</b>	
<b>AIR CONDITIONING</b>	Inspected
Chilled Water System	Does not exist
Condenser Water Distribution: Piping, Pumps and Auxiliaries	Does not exist
Cooling Coil in Ductwork	Does not exist
Cooling Tower	Does not exist
<b>DX Split System</b>	Inspected
Indoor Unit	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Outdoor Unit	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Dry Cooler</b>	Does not exist
<b>Packaged / Rooftop Unit</b>	Does not exist

**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

***Mechanical Inspection***

**X053**

<b>Question</b>	<b>Response</b>
<b>AIR CONDITIONING</b>	
<b>Packaged Terminal A/C</b>	Does not exist
<b>Refrigerant Leak Detection System</b>	Does not exist
<b>Refrigerant Piping</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Return Fan</b>	Does not exist
<b>CENTRAL ACID WASTE NEUTRALIZING TANK</b>	
	Does not exist
<b>CLIMATE CONTROL SYSTEM</b>	
	Inspected
<b>BMS</b>	Does not exist
<b>Pneumatic System</b>	Inspected
Instance	Throughout except Auditorium
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Building Area Covered by Operational System	81-100%
Deficiency	No deficiencies recorded
<b>Hybrid System</b>	Does not exist
<b>Electric System</b>	Does not exist
<b>COMPACTOR</b>	
	Does not exist
<b>CONVEYING</b>	
	Does not exist
<b>DOMESTIC WATER SYSTEM</b>	
	Inspected
<b>Domestic Cold Water System</b>	Inspected
<b>Gravity System</b>	Does not exist
<b>Pressure Booster System</b>	Inspected
<b>Electric Pressure Booster System</b>	Does not exist
<b>Hydraulic/Pneumatic Booster System</b>	Inspected
<b>Water Pressure Booster - Compressor</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Pressure Booster Pump</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Domestic Cold Water Tank</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Water Service</b>	Inspected
Instance	Boiler Room Mechanical Area by Findlay Ave, Basement by Teller Ave
Instance Condition	3- Fair
Instance Quantity	2
Instance Quantity Uom	EACH
Deficiency	WATER MAIN:MISSING BACKFLOW PREVENTION DEVICE
Deficiency Location/Instance	Boiler Room Mechanical Area by Findlay Ave, Basement by Teller Ave
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	INSTALL
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Domestic Hot Water System</b>	Inspected
<b>Domestic Hot Water Remote Storage Tank</b>	Inspected

**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

***Mechanical Inspection***

**X053**

<b>Question</b>	<b>Response</b>
<b>DOMESTIC WATER SYSTEM</b>	
<b>Domestic Hot Water System</b>	
<b>Domestic Hot Water Remote Storage Tank</b>	
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Domestic Water Heat Exchanger</b>	Does not exist
<b>Electric Domestic Water Heater</b>	Does not exist
<b>Gas Fired Domestic Water Heater</b>	Inspected
Instance	Boiler Room Mechanical Area
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Lochinvar
EquipmentId	N/A
Capacity/Size Quantity	500
Capacity/Size UOM	MBH Input
Capacity/Size 2 Quantity	0
Capacity/Size 2 UOM	Gallons
Source of Capacity/Size	Documented
Installation Year	2020
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
<b>Oil Fired Domestic Water Heater</b>	Does not exist
<b>Heat Pump Domestic Water Heater</b>	Does not exist
<b>Domestic Water Distribution Piping</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>DRAIN/WASTE/VENT AND STORM SYSTEM</b>	
	Inspected
<b>Interior Storm Piping</b>	
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Sewage/Waste/Vent Piping</b>	
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Sewage Ejector Pump</b>	Does not exist
<b>Sump Pump</b>	
Condition	4- Between Fair and Poor
Deficiency	DEFECTIVE
Deficiency Location/Instance	Boiler Room Mechanical Area, Boiler Room
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	DEFECTIVE/DETERIORATED
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)</b>	Does not exist
<b>FIXTURES</b>	Inspected

**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

**Mechanical Inspection**

**X053**

Question	Response
<b>FIXTURES</b>	
<b>Staff And Other</b>	Inspected
<b>Janitor Sink</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Lavatory/Sink</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Toilet</b>	Inspected
Condition	1- Good
Deficiency	CRACKED/PHYSICAL DAMAGE
Deficiency Location/Instance	Basement -Toilet Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Urinal</b>	Does not exist
<b>Student</b>	Inspected
<b>Drinking Fountain</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Lavatory/Sink</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Locker Room Shower</b>	Does not exist
<b>Sink And Fountain Combo Unit</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Toilet</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Urinal</b>	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
<b>GAS FIRED FURNACE</b>	Does not exist
<b>GAS SERVICE</b>	Inspected
<b>Gas Distribution Piping</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Gas Meter Room Exhaust Fan</b>	Does not exist
<b>Gas Meter Room Vent</b>	Does not exist
<b>Gas Pressure Booster</b>	Does not exist
<b>CO/Gas Leak Detection</b>	Inspected
Instance	Boiler Room, Boiler Room Mechanical Area
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Installation Year	1999
Source of Installation Year	Inspector Estimate
Deficiency	No deficiencies recorded
<b>HEATING</b>	Inspected
<b>Heating Coil In Ductwork</b>	Does not exist

**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

**Mechanical Inspection**

**X053**

<b>Question</b>	<b>Response</b>
<b>HEATING</b>	
<b>Hydronic Heating</b>	Does not exist
<b>Radiator/Convactor/Fin Tube</b>	Inspected
Condition	3- Fair
Deficiency	RADIATOR/CONVECTOR:DEFECTIVE
Deficiency Location/Instance	1st Floor - Exit "C", Kitchen
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Steam Heating</b>	Inspected
<b>F&amp;T/Steam Drip Trap</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>MER Steam and Condensate Piping</b>	Does not exist
<b>Steam Condensate Return Piping</b>	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE/LEAKS
Deficiency Location/Instance	Kitchen
Deficiency Quantity	10
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Steam Condensate Return Pumping System</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Steam Piping</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Terminal Unit Thermostatic Trap</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Steam supplied by External Sources</b>	Does not exist
<b>Unit Heater/Cabinet Heater</b>	Inspected
Condition	4- Between Fair and Poor
Deficiency	DEFECTIVE/DETERIORATED
Deficiency Location/Instance	Auditorium (1 of 3)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>HEATING PLANT</b>	
Instance on Basement	Inspected
Is there a water meter on the boiler make-up water piping?	Yes
Observed Operational?	Yes
Burner Manufacturer	Industrial Combustion
Burner Model	6VD213TTDV7007AA L
Burner Type	Oil
Heating Plant Oil Number	2

**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

**Mechanical Inspection**

**X053**

Question	Response
<b>HEATING PLANT</b>	
<b>Boiler Auxiliaries</b>	
Instance on Basement	Inspected
<b>Boiler Auxiliary Piping</b>	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	DAMAGED/MISSING INSULATION
Deficiency Location/Instance	Boiler Room (behind Boiler #1, #2)
Deficiency Quantity	20
Quantity Uom	L.F.
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Boiler Emergency Stop Switch</b>	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Boiler Feedwater System</b>	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Boiler Feedwater Treatment(Automatic)</b>	
Instance on Basement	Inspected
Instance Condition	4- Between Fair and Poor
Deficiency	DEFECTIVE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Boiler Flue Exhaust</b>	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Boiler Make-up Water Backflow Preventer</b>	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Boiler Room Steam And Condensate Piping</b>	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	DEFECTIVE ISOLATION VALVE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Boiler Safety Valve</b>	
Instance on Basement	Inspected
Instance Condition	5- Poor

**NYC Department of Education**  
**Building Condition Assessment Survey 2023-2024**

**Mechanical Inspection**

**X053**

Question	Response
<b>HEATING PLANT</b>	
<b>Boiler Auxiliaries</b>	
<b>Boiler Safety Valve</b>	
Deficiency	DEFECTIVE
Deficiency Location/Instance	Boiler Room @ Boilers #1, #2
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
<b>Boiler System</b>	
Instance on Basement	Inspected
<b>Coal-fired Boiler</b>	
Instance on Basement	Does not exist
<b>Hot Water Boiler</b>	
Instance on Basement	Does not exist
<b>Modular Boiler</b>	
Instance on Basement	Does not exist
<b>Steam Boiler</b>	
Instance on Basement	Inspected
Instance on Basement	Inspected
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	6,014
Instance Quantity Uom	MBH NET
Cast Iron Boiler?	No
Manufacturer	A. L. Eastmond & Sons Inc.
EquipmentId	6255-01
Capacity/Size Quantity	6014
Capacity/Size UOM	MBH Net
Source of Capacity/Size	Documented
Installation Year	1999
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	6,014
Instance Quantity Uom	MBH NET
Cast Iron Boiler?	No
Manufacturer	A. L. Eastmond & Sons Inc.
EquipmentId	6255-02
Capacity/Size Quantity	6014
Capacity/Size UOM	MBH Net
Source of Capacity/Size	Documented
Installation Year	1999
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>Fuel System</b>	
Instance on Basement	Inspected
<b>Boiler Fresh Air Louver/Damper</b>	
Instance on Basement	Inspected
Instance Condition	3- Fair
Type	Automatic
Deficiency	No deficiencies recorded

**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

**Mechanical Inspection**

**X053**

Question	Response
<b>HEATING PLANT</b>	
<b>Fuel System</b>	
<b>Burner/Burner Control Panel</b>	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	BURNER CONTROL PANEL:DEFECTIVE OPACITY SENSOR
Deficiency Location/Instance	Boiler Room - Boiler #1 (smoke capacity sensor)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 4
Violations	39026299M
<b>Fuel Oil Storage/Supply System</b>	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Gas Trains And Vent At The Boiler</b>	
Instance on Basement	Does not exist
<b>Enclosed IDF Room</b>	
Instance on Room 426	Inspected
<b>Dedicated A/C Equipment</b>	
Instance on Room 426	Inspected
Instance Condition	4- Between Fair and Poor
Deficiency	DOES NOT EXIST
Deficiency Location/Instance	Room 426
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>KITCHEN</b>	
Instance on 1st Floor	Inspected
<b>CO Detector</b>	
Instance on 1st Floor	Inspected
Instance Condition	4- Between Fair and Poor
Deficiency	DEFECTIVE/MISSING
Deficiency Location/Instance	Kitchen
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
<b>Gas System</b>	
Instance on 1st Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
<b>Grease Trap</b>	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Hood</b>	
Instance on 1st Floor	Inspected



**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

**Mechanical Inspection**

**X053**

Question	Response
<b>KITCHEN</b>	
<b>Hood</b>	
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Hood Exhaust Ductwork</b>	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Hood Exhaust Fan</b>	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Hood Fire Suppression System</b>	
Instance on 1st Floor	Does not exist
<b>Hot Water Temperature Booster</b>	
Instance on 1st Floor	Does not exist
<b>Kitchen Sink</b>	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	DEFECTIVE
Deficiency Location/Instance	Kitchen
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 4
Violations	SF91127
<b>MDF Room</b>	
Instance on Room B1A	Inspected
<b>Dedicated A/C Equipment</b>	
Instance on Room B1A	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>SCIENCE DEMO ROOM</b>	
	Does not exist
<b>SCIENCE LAB</b>	
	Does not exist
<b>SCIENCE PREP ROOM</b>	
	Does not exist
<b>SPRINKLERS, STANDPIPE, FIRE SYSTEM</b>	
	Inspected
<b>Dry Sprinkler Alarm Valve Assembly</b>	
	Does not exist
<b>Wet Sprinkler Alarm Valve Assembly</b>	
	Does not exist
<b>Fire Booster Pump Assembly</b>	
	Does not exist
<b>Roof Tank</b>	
	Does not exist
<b>Siamese Connection</b>	
	Does not exist
<b>Sprinkler Head</b>	
Condition	Inspected
Condition	4- Between Fair and Poor
Deficiency	DEFECTIVE/DETERIORATED
Deficiency Location/Instance	Rooms 252, 254, Closet next to Rooms 312, 412 (painted, 5)
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
<b>Sprinkler Piping</b>	
Condition	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded

**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

**Mechanical Inspection**

**X053**

<b>Question</b>	<b>Response</b>
<b>SPRINKLERS, STANDPIPE, FIRE SYSTEM</b>	
Standpipe System	Does not exist
Water Gong	Does not exist
<b>SWIMMING POOL</b>	
	Does not exist
<b>VENTILATION</b>	
Is the building Mechanically ventilated?	Inspected Partial
<b>Exhaust Fan</b>	
Condition	Inspected
Approximate Total # of Fans	2- Between Good and Fair
Deficiency	1-25
	No deficiencies recorded
<b>Heating And Ventilating Unit</b>	
	Does not exist
<b>Metal Ductwork</b>	
	Inspected
Condition	3- Fair
Are there any uninsulated ductwork by design in Mechanical rooms?	Yes
Are there chain operated dampers?	Yes
Deficiency	No deficiencies recorded
<b>Supply Fan</b>	
	Inspected
Condition	5- Poor
Approximate Total # of Fans	1-5
Deficiency	DEFECTIVE/DETERIORATED
Deficiency Location/Instance	Boiler Room Mechanical Area / Auditorium Blower
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Unit Ventilator</b>	
	Inspected
Condition	4- Between Fair and Poor
Deficiency	DEFECTIVE MOTOR
Deficiency Location/Instance	Multipurpose Room, Cafeteria
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded