## **Building Condition Assessment Survey 2023-2024**

Asset:							
	P.S. 58 - BRONX	, 459 EAST 176 STREET,	BRONX, NY, 104	457			
Inspection Id	Inspection Type				Time		Last Edited
	) ELECTRICAL				2024-	02-29 11:50AM	1 2024-02-29 02:18P
sset Data							
Question				Answer			
Have any Syste	ems/Major Building C	omponents been upgraded?		Systems:		Case Circuit Bro	eaker Panel Boards
				Years:	2021, 1999	Called Back I Called	- (D-# D1-)
				Systems: Years:	Emergency Li Exit/Emergen 2019		s (Battery Pack),
				Systems:		stem Intrusion A	Alarm (Central Control
				Years:	Panel) 2017	stem, mirasion i	nam (centar contor
				Systems:	Partial Motor	Starters	
				Years:	2016		
				Systems:	LED Lighting		
				Years:	2015		
				Systems:	Fire Alarm Sy	stem	
				Years:	2014		
				Systems:	Intrusion Alar	m System	
				Years:	2002		
				Systems:	Emergency Li	ight/Exit Lights	Panel
				Years:	1999, 1992		
				Systems:	Systems, Inter		ddress, Local Sound Lighting, Service Switch, et Panel Boards
				Years:	1999	r used Disconne	et I anei Boards
Type of Servic	e			Below Gro	ound		
	ve Whiteboard (IWB)	Exist?		Yes			
	tion In Electrical Roon			No			
	D INTERCOMS IN	N FIRE RESCUE AREAS					
		nce Areas, Fire Rescue Areas, an	nd/or Holding Room		Response No		
your building							
riority Condi		C Pr	<u> </u>	T	<b>D</b> ()	<b>n</b> ()	DI 4
	iority tegory	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
	e Alarm System -	N/A	Fire Alarm System - Main	Main Entrance Lobby	Stephen Guerrero	Fireman	No Photo Taken
	fective		Panel	Loody			
Def	fective		•	Loody			
Def	fective		•	Response			
Def Inspection	fective		•	-			
Inspection Question			•	Response  Does not e	exist		
Inspection Question Electrical	C FIELD		•	Response  Does not e	exist		
nspection Question Electrical ATHLETIC AUDITORI	C FIELD IUM IA		•	Does not e  Does not e  Inspected	exist		
nspection Question Electrical ATHLETIC AUDITORI CAFETERI	C FIELD IUM		•	Response  Does not e	exist		
nspection Question Electrical ATHLETIC AUDITORI CAFETERI It Lighting	C FIELD IUM IA Instance on Basement		•	Does not of Does not of Inspected Inspected	exist		
Definition  Question  Question  Electrical  ATHLETIC  AUDITORI  CAFETERI  Lighting  In	C FIELD  IUM  IA  Instance on Basement	ıf	•	Does not e  Does not e  Inspected	exist		
Defining Lighting	C FIELD  IUM  IA  Instance on Basement  Instance on Basement  Instance on Basement	ıt	•	Does not e  Does not e  Inspected  Inspected	exist		
Defining Lighting	C FIELD  IUM  IA  Instance on Basement  Instance on Basement  Fixture - Fluorescen  Instance on Basement	ıt	•	Does not of Does not of Inspected Inspected	exist		
Topic description    Conspection   Question   Electrical   ATHLETIC   AUDITORI   CAFETERI   In Lighting   In Light	C FIELD  IUM  IA  Instance on Basement  Instance on Basement  Instance on Basement	nt .	•	Does not e  Does not e  Inspected  Inspected	exist		

Does not exist

Instance on Basement

## **Building Condition Assessment Survey 2023-2024**

Electrical Inspection		X058
Question	Response	

Question	Response
CAFETERIA	
Lighting	
Lighting Fixture - LED	
Instance on Basement	Inspected
Pendant Mounted	
Instance on Basement	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Basement	Does not exist
Recessed Mounted	
Instance on Basement	Does not exist
Local Sound System	
Instance on Basement	Inspected
Instance Condition	3- Fair
Installation Year	1999
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Cafeteria-Basement
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Projection System	
Instance on Basement	Does not exist
Theater Lighting System	
Instance on Basement	Does not exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected
Lighting	Inspected
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	12
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
COMPUTER LAB	Inspected
Instance on Room 211	Inspected
Power Panel?	No
	INU
Lighting Instance on Room 211	Inspected
Lighting Fixture - Fluorescent	mspecied
Eighting Fixture - Fluorescent	
P	D 0 011

### **Building Condition Assessment Survey 2023-2024**

rical Inspection	n	X0
Question	Response	
COMPUTER LAB		
Lighting		
Lighting Fixture - Fluorescent	T 1	
Instance on Room 211	Inspected	
Pendant Mounted		
Instance on Room 211	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room 211	Does not exist	
Recessed Mounted		
Instance on Room 211	Does not exist	
Lighting Fixture - HID		
Instance on Room 211	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 211	Does not exist	
Lighting Fixture - LED		
Instance on Room 211	Does not exist	
Raceway With Receptacles		
Instance on Room 211	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
GYMNASIUM	Inspected	
Instance on Basement	Inspected	
Lighting		
Instance on Basement	Inspected	
Lighting Fixture - Fluorescent		
Instance on Basement	Inspected	
Pendant Mounted		
Instance on Basement	Does not exist	
Surface Mounted		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on Basement	Does not exist	
Lighting Fixture - HID		
Instance on Basement	Does not exist	
Lighting Fixture - Incandescent		
Instance on Basement	Does not exist	
Lighting Fixture - LED		
Instance on Basement	Inspected	
Pendant Mounted		
Instance on Basement	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Basement	Does not exist	
Recessed Mounted		
Instance on Basement	Does not exist	

Inspected

3- Fair

1999

Local Sound System

Instance on Basement

Instance Condition

Installation Year

## **Building Condition Assessment Survey 2023-2024**

circui inspection		74030
Question	Response	
GYMNASIUM		
Local Sound System		
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Gymnasium-Basement	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Projection System		
Instance on Basement	Does not exist	
Scoreboard		
Instance on Basement	Does not exist	
Theater Lighting System		
Instance on Basement	Does not exist	
KITCHEN	Inspected	
Instance on Basement	Inspected	
Lighting	nispected .	
Instance on Basement	Inspected	
	nispected	
Lighting Fixture - Fluorescent  Instance on Basement	Lucusotod	
	Inspected	
Pendant Mounted		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Basement	Does not exist	
Recessed Mounted		
Instance on Basement	Does not exist	
Lighting Fixture - HID		
Instance on Basement	Does not exist	
Lighting Fixture - Incandescent		
Instance on Basement	Does not exist	
Lighting Fixture - LED		
Instance on Basement	Inspected	
Pendant Mounted	inspected .	
Instance on Basement	Inspected	
	2- Between Good and Fair	
Instance Condition	No deficiencies recorded	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Basement	Does not exist	
Recessed Mounted		
Instance on Basement	Does not exist	
LIBRARY	Inspected	
Instance on Room 101/102	Inspected	
Lighting		
Instance on Room 101/102	Inspected	
Lighting Fixture - Fluorescent	-	
Instance on Room 101/102	Inspected	
Pendant Mounted		
Instance on Room 101/102	Inspected	
Instance Condition	3- Fair	
HISTAINCE CONDITION	J- 1 an	

## **Building Condition Assessment Survey 2023-2024**

Electrical InspectionX058QuestionResponse

incui inspection		A030
Question	Response	
LIBRARY		
Lighting		
Lighting Fixture - Fluorescent		
Pendant Mounted		
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room 101/102	Does not exist	
Recessed Mounted		
Instance on Room 101/102	Does not exist	
Lighting Fixture - HID		
Instance on Room 101/102	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Instance on Room 101/102	Does not exist	
Lighting Fixture - LED	Does not exist	
Instance on Room 101/102	Does not exist	
Raceway With Receptacles	Does not exist	
Instance on Room 101/102	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Projection System	TVO deficiences recorded	
Instance on Room 101/102	Does not exist	
	Does not exist	
LOCKER ROOM		
MULTIPURPOSE ROOM	Inspected	
Instance on 1st Floor	Inspected	
Lighting		
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on 1st Floor	Does not exist	
Recessed Mounted		
Instance on 1st Floor	Does not exist	
Local Sound System		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Installation Year	1999	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Multipurpose Room-1st Floor	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	DEDLACE	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	

## **Building Condition Assessment Survey 2023-2024**

Question	Response
MULTIPURPOSE ROOM	response
Local Sound System	
Violations	No violations recorded
Projection System	TO TOMOB TOOTAGE
Instance on 1st Floor	Does not exist
Theater Lighting System	
Instance on 1st Floor	Inspected
Dimming System	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Theater Lighting	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
SCIENCE DEMO ROOM	Does not exist
SCIENCE LAB	Does not exist
SCIENCE PREP ROOM	Does not exist
SWIMMING POOL	Does not exist
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist  Does not exist
Lighting Fixture - HID	Does not exist  Does not exist
Lighting Fixture - Incandescent	Does not exist  Does not exist
Lighting Fixture - LED	
AUXILIARY SIGNAL/BELL SYSTEM	Inspected 3- Fair
Condition	No deficiencies recorded
· · · · · · · · · · · · · · · · · · ·	
EMERGENCY DC STANDBY BATTERY POWER	Does not exist
EMERGENCY GENERATOR SET	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Condition Deficiency	3- Fair
	LESS THAN 20% SPARE CIRCUIT BREAKERS

## **Building Condition Assessment Survey 2023-2024**

teut Inspection	710
uestion	Response
EMERGENCY LIGHT/EXIT LIGHT PANEL	
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL NEW PANEL BOARD
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PANEL BOARD DOOR LOCK IS MISSING
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Non Battery Pack	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	1- Good
	No deficiencies recorded
Deficiency	
Non Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EXIT/EMERGENCY LIGHT	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
FIRE ALARM SYSTEM	Inspected
Bell/Horn	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
	Inspected
Strobe Condition	2- Between Good and Fair
	No deficiencies recorded
Deficiency	
Manual Pull Station	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Duct Smoke Detector	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Area Smoke Detector	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
CO Detector	Inspected

## **Building Condition Assessment Survey 2023-2024**

uestion	Response	
FIRE ALARM SYSTEM		
CO Detector		
Deficiency	No deficiencies recorded	
Heat Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Elevator Recall	Does not exist	
Magnetic Door Holder/Contactor	Does not exist	
Fused Cutout Panel	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Digital Communicator	Does not exist	
Main Panel	Inspected	
Bell At Panel	Does not exist	
Fire Alarm Control Panel (Electronic)	Inspected	
Instance	Main Entrance Lobby	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Siemens	
Model	FC92X	
EquipmentId	Fire Alarm Control Panel	
Installation Year	2014	
Source of Installation Year	Documented	
Deficiency	PANEL DEFECTIVE	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPAIR	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 6	
Violations	12136077Y	
Fire Alarm Control Panel (Standard)	Does not exist	
Sub-Panel	Does not exist	
Remote Annunciator	Inspected	
Display Monitor	Does not exist	
Panel	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Printer	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Punch Register	Does not exist	
Sprinkler Flow/Air Pressure Switch	Does not exist	
Tamper Flow Switch/Chain	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
GROUNDING SYSTEM	Inspected	
	3- Fair	
Condition		
Deficiency	No deficiencies recorded	
NTERCOM SYSTEM	Inspected	
Elevator	Under construction	
Holding Area	Does not exist	
LAN	Inspected	
Local Distribution Frame (I/LDF)	Inspected	
Condition	3- Fair	

## **Building Condition Assessment Survey 2023-2024**

Electrical Inspection	X058

Question	Response	
LAN		
Local Distribution Frame (I/LDF)		
Deficiency	No deficiencies recorded	
Main Equipment Rack (MDF)	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
LIGHTNING PROTECTION	Does not exist	
MOTOR CONTROLLER	Inspected	
MOTOR CONTROLLER  MOTOR CONTROL CENTER	Does not exist	
MOTOR STARTER/CONTACTOR	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Variable Frequency Drive	Does not exist	
PANEL BOARD	Inspected	
Fused Disconnect Switch Type	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fused Knife Switch Type	Does not exist	
Fused Toggle Switch Type	Does not exist	
Molded Case Circuit Breaker Type	Inspected	
Condition	3- Fair	
Deficiency	NO SPARE	
Deficiency Location/Instance	Kitchen	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE PANEL BOARD	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
PUBLIC ADDRESS SYSTEM	Inspected	
Instance	General Office - Room 210	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Model	Rauland TC2100	
Installation Year	1999	
Source of Installation Year	Documented	
Deficiency	CLOCK NOT OPERATIONAL	
Deficiency Location/Instance	Classrooms and Corridors	
Deficiency Quantity	10	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
SECURITY	Inspected	
IPDVS/CCTV System	Does not exist	
Intrusion Alarm System	Inspected	
Central Control Panel	Inspected	
Instance	Custodian's Office	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Model	Vista 128BPT	
Installation Year	2017	
Installation 10al		

### **Building Condition Assessment Survey 2023-2024**

rical Inspection	D.	<u> </u>
uestion	Response	
SECURITY		
Intrusion Alarm System		
Central Control Panel	D	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Infrared Sensor	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Panic Switch	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Remote Annunciator	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Siren/Strobe	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lighting - Security	Under construction	
SERVICE SWITCH	Inspected	
Instance	Electrical Room	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Siemens	
EquipmentId	Service Disconnect	
Capacity/Size Quantity	2000	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year	1999	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
SWITCHBOARD	Inspected	
Number of Spares	4	
Fused Disconnect Switch Type	Inspected	
Instance	Electrical Room	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Siemens	
EquipmentId	MDB	
Capacity/Size Quantity	2000	
Capacity/Size UOM	Amps Total	
Capacity/Size 2 Quantity	2	
Capacity/Size 2 UOM	Section(s)	
Source of Capacity/Size	Service Switch Size	
Installation Year	1999	
Source of Installation Year	Documented No. 1.5 circuit accorded	
Deficiency	No deficiencies recorded	
Fused Knife Switch Type	Does not exist	
Molded Case Circuit Breaker Type	Does not exist	

Inspected Inspected

Inspected

2- Between Good and Fair
No deficiencies recorded

TELEPHONE SYSTEM

Deficiency

PBX/Intercom Condition

Standard

### **Building Condition Assessment Survey 2023-2024**

trical Inspection		X058
Question	Response	
TELEPHONE SYSTEM		
Standard		
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
TRANSFORMER	Does not exist	