

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X067

Asset: P.S. 67 - BRONX, 2024 MOHEGAN AVENUE, BRONX, NY, 10460

Inspection Id	Inspection Type	Time In	Last Edited
3300	ELECTRICAL	2024-02-16 09:26AM	2024-06-17 09:17AM

Asset Data

Question	Answer
Have any Systems/Major Building Components been upgraded?	Systems: Battery Pack Emergency Lights Years: 2024 Systems: Partial LAN (IDF and MDF), Science Lab - Room 510 (Projection System). Years: 2023 Systems: Variable Frequency Drive, Fire Alarm System Main Panel (Within Old Enclosure) Years: 2022 Systems: Partial Molded Case Circuit Breaker Panel Boards Years: 2021, 2019, 2014, 1998 Systems: Exit Lighting (Battery Pack), Motor Starters, Medical Office LED Lighting Years: 2021 Systems: Auditorium (Local Sound System, Projection System), Fire Alarm System (Partial Fan Shutdown Controls, Partial Duct Detectors) Years: 2019 Systems: Interior Lighting Except (Science Lab - Room 508, 510, Science Prep Room 509, Recessed Fluorescent Lighting), Telephone System Years: 2014 Systems: Science Lab: Rooms - 508, 510, Science Prep Room 509, Recessed Fluorescent Lighting (Classrooms and Corridors), IPDVS/CCTV System Years: 2012 Systems: Fire Alarm System (Except Main Panel), Public Address System, Switchboard, Security Lighting, Emergency Light/Exit Panel, Local Sound System (Cafeteria, 1st Floor Gymnasium), Fused Disconnect Switch Type Panel Board Years: 1998
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration In Electrical Room?	Yes

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	No

Priority Condition

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
No	Fire Alarm System - Defective	The Panel is in Trouble mode, due to Battery and Charger not Operational.	Fire Alarm System	Main Entrance Lobby	Francisco Acevedo	Fireman	No Photo Taken
Yes	Water Penetration in Electrical Room	N/A	Electrical Equipment	Electrical Room	Francisco Acevedo	Fireman	No Photo Taken

Inspection

Question	Response
Electrical	
ATHLETIC FIELD	Does not exist
AUDITORIUM	Inspected
Instance on 2nd Floor	Inspected
House Lighting	

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X067

Question	Response
AUDITORIUM	
House Lighting	
Instance on 2nd Floor	Inspected
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	
Instance on 2nd Floor	Inspected
Pendant Mounted	
Instance on 2nd Floor	Does not exist
Surface Mounted	
Instance on 2nd Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 2nd Floor	Does not exist
Lighting Fixture - HID	
Instance on 2nd Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 2nd Floor	Does not exist
Lighting Fixture - LED	
Instance on 2nd Floor	Does not exist
Local Sound System	
Instance on 2nd Floor	Inspected
Instance Condition	2- Between Good and Fair
Installation Year	2019
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Projection System	
Instance on 2nd Floor	Inspected
Instance Condition	1- Good
Is the projector on a cart or installed on the ceiling?	Ceiling
Deficiency	No deficiencies recorded
Theater Lighting System	
Instance on 2nd Floor	Inspected
Dimming System	
Instance on 2nd Floor	Does not exist
Theater Lighting	
Instance on 2nd Floor	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	49
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
CAFETERIA	
Instance on 1st Floor	Inspected
Lighting	
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X067

Question	Response
CAFETERIA	
Lighting	
Lighting Fixture - Fluorescent	
Surface Mounted	
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor	Does not exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not exist
Local Sound System	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Installation Year	1998
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Cafeteria-1st Floor
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Projection System	
Instance on 1st Floor	Does not exist
Theater Lighting System	
Instance on 1st Floor	Does not exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	
Pendant Mounted	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Pendant Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Condition	1- Good
Deficiency	No deficiencies recorded
Recessed Mounted	
Condition	1- Good
Deficiency	No deficiencies recorded

NYC Department of Education
Building Condition Assessment Survey 2023-2024

Electrical Inspection

X067

Question	Response
COMPUTER LAB	Inspected
Instance on Room 314	Inspected
Power Panel?	No
Lighting	
Instance on Room 314	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 314	Inspected
Pendant Mounted	
Instance on Room 314	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 314	Does not exist
Recessed Mounted	
Instance on Room 314	Does not exist
Lighting Fixture - HID	
Instance on Room 314	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 314	Does not exist
Lighting Fixture - LED	
Instance on Room 314	Does not exist
Raceway With Receptacles	
Instance on Room 314	Does not exist
GYMNASIUM	Inspected
Instance on 1st Floor	Inspected
Instance on 5th Floor	Inspected
Lighting	
Instance on 1st Floor	Inspected
Instance on 5th Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Does not exist
Instance on 5th Floor	Does not exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Instance on 5th Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Instance on 5th Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Inspected
Instance on 5th Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Instance on 5th Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Does not exist
Instance on 5th Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X067

Question	Response
GYMNASIUM	
Lighting	
Lighting Fixture - LED	
Recessed Mounted	
Instance on 5th Floor	Does not exist
Local Sound System	
Instance on 1st Floor	Inspected
Instance Condition	5- Poor
Installation Year	1998
Source of Installation Year	Documented
Deficiency	AMPLIFIER NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE SYSTEM
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance on 5th Floor	Does not exist
Projection System	
Instance on 1st Floor	Does not exist
Instance on 5th Floor	Does not exist
Scoreboard	
Instance on 1st Floor	Does not exist
Instance on 5th Floor	Does not exist
Theater Lighting System	
Instance on 1st Floor	Does not exist
Instance on 5th Floor	Does not exist
KITCHEN	
Instance on 1st Floor	Inspected
Lighting	
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Does not exist
Recessed Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not exist
LIBRARY	
Instance on Room 411	Inspected
Lighting	
Instance on Room 411	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 411	Inspected
Pendant Mounted	

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X067

Question	Response
LIBRARY	
Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	
Instance on Room 411	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 411	Does not exist
Recessed Mounted	
Instance on Room 411	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Room 411	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 411	Does not exist
Lighting Fixture - LED	
Instance on Room 411	Does not exist
Raceway With Receptacles	
Instance on Room 411	Does not exist
Projection System	
Instance on Room 411	Does not exist
LOCKER ROOM	Does not exist
MULTIPURPOSE ROOM	Inspected
Instance on 1st Floor - North, 1st Floor - South	Inspected
Lighting	
Instance on 1st Floor - North, 1st Floor - South	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor - North, 1st Floor - South	Inspected
Pendant Mounted	
Instance on 1st Floor - North, 1st Floor - South	Does not exist
Surface Mounted	
Instance on 1st Floor - North, 1st Floor - South	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor - North, 1st Floor - South	Does not exist
Lighting Fixture - HID	
Instance on 1st Floor - North, 1st Floor - South	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor - North, 1st Floor - South	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor - North, 1st Floor - South	Does not exist
Local Sound System	
Instance on 1st Floor - North, 1st Floor - South	Inspected
Instance Condition	5- Poor
Installation Year	1998
Source of Installation Year	Documented
Deficiency	AMPLIFIER NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE SYSTEM
Urgency of Action	PRIORITY 2

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X067

Question	Response
MULTIPURPOSE ROOM	
Local Sound System	
Purpose of Action	LEVEL 2
Violations	No violations recorded
Projection System	
Instance on 1st Floor - North, 1st Floor - South	Does not exist
Theater Lighting System	
Instance on 1st Floor - North, 1st Floor - South	Does not exist
SCIENCE DEMO ROOM	
	Does not exist
SCIENCE LAB	
	Inspected
Instance on Room 508	Inspected
Power Panel?	Yes
Alternative Use	Yes
Instance on Room 510	Inspected
Power Panel?	No
Alternative Use	Yes
Lighting	
Instance on Room 508	Inspected
Instance on Room 510	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 508	Inspected
Instance on Room 510	Inspected
Pendant Mounted	
Instance on Room 508	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 510	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 508	Does not exist
Instance on Room 510	Does not exist
Recessed Mounted	
Instance on Room 508	Does not exist
Instance on Room 510	Does not exist
Lighting Fixture - HID	
Instance on Room 508	Inspected
Instance on Room 510	Inspected
Pendant Mounted	
Instance on Room 508	Does not exist
Instance on Room 510	Does not exist
Surface Mounted	
Instance on Room 508	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 510	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Room 508	Does not exist
Instance on Room 510	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 508	Does not exist

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X067

Question	Response
SCIENCE LAB	
Lighting	
Lighting Fixture - Incandescent	
Instance on Room 510	Does not exist
Lighting Fixture - LED	
Instance on Room 508	Does not exist
Instance on Room 510	Does not exist
Emergency Gas Shut-Off Valve	
Instance on Room 508	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 510	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	
Instance on Room 508	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 510	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Power Supply	
Instance on Room 508	Inspected
Instance on Room 510	Inspected
Instructor Unit	
Instance on Room 508	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 510	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Meter Demonstration Unit	
Instance on Room 508	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 510	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Student Unit	
Instance on Room 508	Does not exist
Instance on Room 510	Does not exist
Projection System	
Instance on Room 508	Does not exist
Instance on Room 510	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
SCIENCE PREP ROOM	
Instance on Room 509	Inspected
Power Panel?	No
Alternative Use	Yes
Lighting	
Instance on Room 509	Inspected
Lighting Fixture - Fluorescent	

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X067

Question	Response
SCIENCE PREP ROOM	
Lighting	
Lighting Fixture - Fluorescent	
Instance on Room 509	Inspected
Pendant Mounted	
Instance on Room 509	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 509	Does not exist
Recessed Mounted	
Instance on Room 509	Does not exist
Lighting Fixture - HID	
Instance on Room 509	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 509	Does not exist
Lighting Fixture - LED	
Instance on Room 509	Does not exist
Emergency Gas Shut-Off Valve	
Instance on Room 509	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	
Instance on Room 509	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Power Supply	
Instance on Room 509	Does not exist
SWIMMING POOL	Does not exist
TOILET ROOM - STAFF	Inspected
Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	
Does not exist	
Surface Mounted	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Does not exist	
Lighting Fixture - HID	
Does not exist	
Lighting Fixture - Incandescent	
Does not exist	
Lighting Fixture - LED	
Does not exist	
TOILET ROOM - STUDENT	Inspected
Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Does not exist	
Lighting Fixture - HID	
Does not exist	
Lighting Fixture - Incandescent	
Does not exist	
Lighting Fixture - LED	
Does not exist	
AUXILIARY SIGNAL/BELL SYSTEM	Inspected

NYC Department of Education
Building Condition Assessment Survey 2023-2024

Electrical Inspection

X067

Question	Response
AUXILIARY SIGNAL/BELL SYSTEM	
Condition	3- Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not exist
EMERGENCY GENERATOR SET	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Condition	3- Fair
Deficiency	LESS THAN 20% SPARE CIRCUIT BREAKERS
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL NEW PANEL BOARD
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Non Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Non Battery Pack	Does not exist
EXIT/EMERGENCY LIGHT	Does not exist
FIRE ALARM SYSTEM	Inspected
Bell/Horn	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Strobe	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Manual Pull Station	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Duct Smoke Detector	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Area Smoke Detector	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
CO Detector	Does not exist
Heat Detector	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Elevator Recall	Does not exist
Magnetic Door Holder/Contactor	Does not exist
Fused Cutout Panel	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X067

Question	Response
FIRE ALARM SYSTEM	
Fused Cutout Panel	
Condition	3- Fair
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	Does not exist
Main Panel	Inspected
Bell At Panel	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Main Entrance Lobby
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Notifier
Model	AFP - 400
EquipmentId	Main Fire Alarm Panel
Installation Year	2022
Source of Installation Year	Documented
Deficiency	SYSTEM DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR SYSTEM
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Fire Alarm Control Panel (Standard)	Does not exist
Sub-Panel	Does not exist
Remote Annunciator	Inspected
Display Monitor	Does not exist
Panel	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Printer	Does not exist
Punch Register	Does not exist
Sprinkler Flow/Air Pressure Switch	Does not exist
Tamper Flow Switch/Chain	Does not exist
GROUNDING SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	Does not exist
LAN	Inspected
Local Distribution Frame (L/DF)	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Does not exist
MOTOR CONTROLLER	Inspected
MOTOR CONTROL CENTER	Does not exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X067

Question	Response
MOTOR CONTROLLER	
Variable Frequency Drive	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Does not exist
Molded Case Circuit Breaker Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Throughout the Building
Deficiency Quantity	14
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
PUBLIC ADDRESS SYSTEM	Inspected
Instance	Main Office - Room 211
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Telecor II
Installation Year	1998
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
SECURITY	Inspected
IPDVS/CCTV System	Inspected
Condition	2- Between Good and Fair
Installation Year	2012
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	Custodian's Office
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 50P
Installation Year	1998
Source of Installation Year	Documented
Deficiency	PANEL NOT CONNECTED TO DOE CENTRAL STATION
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REWIRE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Violations	No violations recorded
Infrared Sensor	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X067

Question	Response
SECURITY	
Intrusion Alarm System	
Panic Switch	
Condition	3- Fair
Deficiency	No deficiencies recorded
Remote Annunciator	
Condition	3- Fair
Deficiency	No deficiencies recorded
Siren/Strobe	
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting - Security	
	Inaccessible
SERVICE SWITCH	
	Inspected
Instance	Electrical Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Lexington
EquipmentId	N/A
Capacity/Size Quantity	1600
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1964
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
SWITCHBOARD	
	Inspected
Number of Spares	4
Fused Disconnect Switch Type	
	Inspected
Instance	Electrical Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Mac Power
EquipmentId	N/A
Capacity/Size Quantity	1600
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	3
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	1998
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fused Knife Switch Type	
	Does not exist
Molded Case Circuit Breaker Type	
	Does not exist
TELEPHONE SYSTEM	
	Inspected
PBX/Intercom	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded

NYC Department of Education
Building Condition Assessment Survey 2023-2024

Electrical Inspection

X067

Question	Response
TELEPHONE SYSTEM	
Standard	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
TRANSFORMER	Does not exist