

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X086

Asset: P.S. 86 - BRONX, 2756 RESERVOIR AVENUE, BRONX, NY, 10468

Inspection Id	Inspection Type	Time In	Last Edited
1144	ELECTRICAL	2023-11-21 08:49AM	2024-05-02 02:21PM

Asset Data

Question	Answer
Have any Systems/Major Building Components been upgraded?	Systems: Public Address System (Amplifier) Years: 2023 Systems: LAN, Library (LED Lighting) Years: 2022 Systems: Partial Exit Lights (Battery Pack) Years: 2016 Systems: LED Lighting (Auditorium, 3rd Floor Gymnasium) Years: 2015 Systems: Security Lights Years: 2014 Systems: Intercom System (Elevator) Years: 2012 Systems: Telephone System, Auditorium (Dimming System, Theater Lighting) Years: 2011 Systems: Service Switch, Switchboard, Panel Boards, Grounding System, Emergency Light/Exit Light Panel, Exit/Emergency Light, Library, HID Lighting Years: 2006 Systems: Interior Lighting, Fire Alarm System, Local Sound System (Auditorium) Years: 2000 Systems: Intrusion Alarm System Years: 1995
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration In Electrical Room?	No

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	No

Priority Condition

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image	
		No condition recorded						

Inspection

Question	Response
Electrical	
ATHLETIC FIELD	Does not exist
AUDITORIUM	Inspected
Instance on 1st Floor	Inspected
House Lighting	
Instance on 1st Floor	Inspected
Does a Chandelier Exist?	Yes
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X086

Question	Response
AUDITORIUM	
House Lighting	
Lighting Fixture - Fluorescent	
Surface Mounted	
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor	Does not exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on 1st Floor	Does not exist
Recessed Mounted	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor	Does not exist
Local Sound System	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Installation Year	2000
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Auditorium-1st Floor
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Projection System	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Is the projector on a cart or installed on the ceiling?	Cart
Deficiency	No deficiencies recorded
Theater Lighting System	
Instance on 1st Floor	Inspected
Dimming System	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X086

Question	Response
AUDITORIUM	
Theater Lighting System	
Theater Lighting	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
CAFETERIA	
Instance on 1st Floor	Inspected
Lighting	
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor	Does not exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not exist
Local Sound System	
Instance on 1st Floor	Inspected
Instance Condition	5- Poor
Installation Year	1968
Source of Installation Year	Documented
Deficiency	AMPLIFIER NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE SYSTEM
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Projection System	
Instance on 1st Floor	Does not exist
Theater Lighting System	
Instance on 1st Floor	Does not exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	
Does a Chandelier Exist?	Yes
Lighting Fixture - Fluorescent	
Pendant Mounted	
Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Condition	3- Fair
Deficiency	No deficiencies recorded

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X086

Question	Response
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	
Lighting Fixture - Fluorescent	
Recessed Mounted	Does not exist
Lighting Fixture - HID	
	Does not exist
Lighting Fixture - Incandescent	
	Inspected
Pendant Mounted	
Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	
	Does not exist
Recessed Mounted	
	Does not exist
Lighting Fixture - LED	
	Does not exist
COMPUTER LAB	
	Inspected
Instance on Room 209	Inspected
Power Panel?	No
Instance on Room 407	Inspected
Power Panel?	Yes
Lighting	
Instance on Room 209	Inspected
Instance on Room 407	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 209	Inspected
Instance on Room 407	Inspected
Pendant Mounted	
Instance on Room 209	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 407	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 209	Does not exist
Instance on Room 407	Does not exist
Recessed Mounted	
Instance on Room 209	Does not exist
Instance on Room 407	Does not exist
Lighting Fixture - HID	
Instance on Room 209	Does not exist
Instance on Room 407	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 209	Does not exist
Instance on Room 407	Does not exist
Lighting Fixture - LED	
Instance on Room 209	Does not exist
Instance on Room 407	Does not exist
Raceway With Receptacles	
Instance on Room 209	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 407	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
GYMNASIUM	
	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X086

Question	Response
GYMNASIUM	
Instance on 3rd Floor	Inspected
Instance on 5th Floor	Inspected
Lighting	
Instance on 3rd Floor	Inspected
Instance on 5th Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 3rd Floor	Does not exist
Instance on 5th Floor	Inspected
Pendant Mounted	
Instance on 5th Floor	Does not exist
Surface Mounted	
Instance on 5th Floor	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	
Instance on 5th Floor	Does not exist
Lighting Fixture - HID	
Instance on 3rd Floor	Does not exist
Instance on 5th Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 3rd Floor	Does not exist
Instance on 5th Floor	Does not exist
Lighting Fixture - LED	
Instance on 3rd Floor	Inspected
Instance on 5th Floor	Does not exist
Pendant Mounted	
Instance on 3rd Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on 3rd Floor	Does not exist
Recessed Mounted	
Instance on 3rd Floor	Does not exist
Local Sound System	
Instance on 3rd Floor	Inspected
Instance Condition	5- Poor
Installation Year	1968
Source of Installation Year	Documented
Deficiency	AMPLIFIER NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE SYSTEM
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance on 5th Floor	Inspected
Instance Condition	5- Poor
Installation Year	1968

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X086

Question	Response
GYMNASIUM	
Local Sound System	
Source of Installation Year	Documented
Deficiency	AMPLIFIER NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE SYSTEM
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Projection System	
Instance on 3rd Floor	Does not exist
Instance on 5th Floor	Does not exist
Scoreboard	
Instance on 3rd Floor	Does not exist
Instance on 5th Floor	Does not exist
Theater Lighting System	
Instance on 3rd Floor	Does not exist
Instance on 5th Floor	Does not exist
KITCHEN	
Instance on 1st Floor	Inspected
Lighting	
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor	Does not exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not exist
LIBRARY	
Instance on Room 207	Inspected
Lighting	
Instance on Room 207	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 207	Does not exist
Lighting Fixture - HID	
Instance on Room 207	Inspected
Pendant Mounted	
Instance on Room 207	Does not exist
Surface Mounted	
Instance on Room 207	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X086

Question	Response
LIBRARY	
Lighting	
Lighting Fixture - HID	
Recessed Mounted	
Instance on Room 207	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting Fixture - Incandescent	
Instance on Room 207	Does not exist
Lighting Fixture - LED	
Instance on Room 207	Inspected
Pendant Mounted	
Instance on Room 207	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 207	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Room 207	Does not exist
Raceway With Receptacles	
Instance on Room 207	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Projection System	
Instance on Room 207	Does not exist
LOCKER ROOM	Does not exist
MULTIPURPOSE ROOM	Inspected
Instance on 1st Floor - North, 1st Floor - South	Inspected
Lighting	
Instance on 1st Floor - North, 1st Floor - South	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor - North, 1st Floor - South	Inspected
Pendant Mounted	
Instance on 1st Floor - North, 1st Floor - South	Does not exist
Surface Mounted	
Instance on 1st Floor - North, 1st Floor - South	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor - North, 1st Floor - South	Does not exist
Lighting Fixture - HID	
Instance on 1st Floor - North, 1st Floor - South	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor - North, 1st Floor - South	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor - North, 1st Floor - South	Does not exist
Local Sound System	
Instance on 1st Floor - North, 1st Floor - South	Inspected
Instance Condition	5- Poor
Installation Year	1968
Source of Installation Year	Documented
Deficiency	AMPLIFIER NOT OPERATIONAL

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X086

Question	Response
MULTIPURPOSE ROOM	
Local Sound System	
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE SYSTEM
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Projection System	
Instance on 1st Floor - North, 1st Floor - South	Does not exist
Theater Lighting System	
Instance on 1st Floor - North, 1st Floor - South	Does not exist
SCIENCE DEMO ROOM	Does not exist
SCIENCE LAB	Does not exist
SCIENCE PREP ROOM	Does not exist
SWIMMING POOL	Does not exist
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not exist
EMERGENCY GENERATOR SET	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	3- Fair

NYC Department of Education
Building Condition Assessment Survey 2023-2024

Electrical Inspection

X086

Question	Response
EMERGENCY LIGHTING	
Battery Pack	
Deficiency	BATTERY NOT OPERATIONAL
Deficiency Location/Instance	Auditorium, Gymnasiums, Cafeteria, Corridor near Staircases C/3, D/5, Room 515
Deficiency Quantity	10
Quantity Uom	EACH
Potential Action	REPLACE BATTERY
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
Non Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EXIT LIGHT	
	Inspected
Battery Pack	
Condition	3- Fair
Deficiency	FIXTURE NOT OPERATIONAL
Deficiency Location/Instance	Corridor near Stairs C/5, C/4
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
Non Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EXIT/EMERGENCY LIGHT	
Condition	3- Fair
Deficiency	No deficiencies recorded
FIRE ALARM SYSTEM	
	Inspected
Bell/Horn	
Condition	3- Fair
Deficiency	No deficiencies recorded
Strobe	
Condition	3- Fair
Deficiency	No deficiencies recorded
Manual Pull Station	
Condition	3- Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	
Condition	3- Fair
Deficiency	No deficiencies recorded
Duct Smoke Detector	
Condition	3- Fair
Deficiency	No deficiencies recorded
Area Smoke Detector	
Condition	3- Fair
Deficiency	No deficiencies recorded
CO Detector	
	Does not exist
Heat Detector	
Condition	3- Fair
Deficiency	No deficiencies recorded
Elevator Recall	
	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X086

Question	Response
FIRE ALARM SYSTEM	
Elevator Recall	
Condition	3- Fair
Deficiency	No deficiencies recorded
Magnetic Door Holder/Contactor	Does not exist
Fused Cutout Panel	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	Does not exist
Main Panel	Inspected
Bell At Panel	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Main Entrance Lobby
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Mircom
Model	FX - 2000
EquipmentId	Fire Alarm Control
Installation Year	2000
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	Does not exist
Sub-Panel	Does not exist
Remote Annunciator	Inspected
Display Monitor	Does not exist
Panel	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Printer	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Punch Register	Does not exist
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Tamper Flow Switch/Chain	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	
Condition	3- Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	
Elevator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Holding Area	Does not exist
LAN	
Local Distribution Frame (I/LDF)	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X086

Question	Response
LAN	
Main Equipment Rack (MDF)	
Condition	1- Good
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Does not exist
MOTOR CONTROLLER	Inspected
MOTOR CONTROL CENTER	Does not exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Does not exist
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Does not exist
Molded Case Circuit Breaker Type	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
PUBLIC ADDRESS SYSTEM	Inspected
Instance	General Office - Room 258
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Plena Mixer Amplifier
Installation Year	1968
Source of Installation Year	Documented
Deficiency	CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Classrooms and Corridors
Deficiency Quantity	15
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	SPEAKER NOT OPERATIONAL
Deficiency Location/Instance	3rd Floor Gymnasium
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	General Office - Room 258
Deficiency Quantity	111,000
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
SECURITY	Inspected
IPDVS/CCTV System	Does not exist
Intrusion Alarm System	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X086

Question	Response
SECURITY	
Intrusion Alarm System	
Central Control Panel	Inspected
Instance	Basement - Staff Locker Room Near Boiler Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 50P
Installation Year	1995
Source of Installation Year	Documented
Deficiency	PANEL NOT CONNECTED TO DOE CENTRAL STATION
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REWIRE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Violations	No violations recorded
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Basement - Staff Locker Room Near Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 3
Violations	No violations recorded
Infrared Sensor	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting - Security	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
SERVICE SWITCH	Inspected
Instance	Basement - Electrical Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Galaxy Switchgear
EquipmentId	N/A
Capacity/Size Quantity	2000
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2006
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Basement - Electrical Room
Instance Condition	2- Between Good and Fair

NYC Department of Education
Building Condition Assessment Survey 2023-2024

Electrical Inspection

X086

Question	Response
SERVICE SWITCH	
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Galaxy Switchgear
EquipmentId	N/A
Capacity/Size Quantity	600
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2006
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
SWITCHBOARD	Inspected
Number of Spares	13
Fused Disconnect Switch Type	Inspected
Instance	Basement - Electrical Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Galaxy Switchgear
EquipmentId	N/A
Capacity/Size Quantity	2000
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	4
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Service Switch Size
Installation Year	2006
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Basement - Outside Electrical Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Galaxy Switchgear
EquipmentId	DP-3
Capacity/Size Quantity	1200
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	2006
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not exist
Molded Case Circuit Breaker Type	Does not exist
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
TRANSFORMER	Does not exist