Building Condition Assessment Survey 2023-2024

Mechanical Inspection	X088

Asset: P.S. 88 - BRONX, 1340 SHERIDAN AVEN	UE, BRONX, NY	4, 10456			
Inspection Id Inspection Type			Time 1	[n	Last Edited
4931 MECHANICAL			2024-0	04-24 08:54AN	M 2024-04-24 08:57PN
sset Data					
Question		Answer			
Have any Systems/Major Building Components been upgraded?		Systems:		rip Traps, Term	inal Unit Thermostatic er Heater
		Years:	2024		
		Systems:	DX Split Syste LL5, LL6	ems for Rooms	LL1, LL2, LL3, LL4,
		Years:	2021		
		Systems:	MDF Room - System)	Dedicated A/C	Equipment (DX Split
		Years:	2015		
Are there fuel tanks?		No			
Total # of water main service entries to the asset		1			
MERs/Fan Rooms Locations			oom Mechanical . feteria - Fan Roo		.5 - MER; Kitchen -
Are there any spaces with Missing or Defective CO Detectors?		No			
Are there any Painted/Obstructed Sprinkler Heads?		No			
Are there any Emergency Stop Switches with Missing Hammers?		No compo	onents		
iority Condition					
Exist Priority Condition	Component	Location	Person(s)	Person(s)	Photo
ast Year? Category Description	Affected	Description	Notified	Title	Image
No condition recorded					
nspection					
Question		Response	2		
Mechanical		•			
AIR CONDITIONING		Inspected			
Chilled Water System		Does not			
Condenser Water Distribution: Piping, Pumps and Auxilian	ries	Does not	exist		
Cooling Coil in Ductwork		Does not	exist		
Cooling Tower		Does not	exist		
DX Split System		Inspected	<u> </u>		
Indoor Unit		Inspected			
Condition		1- Good			
Deficiency		No defici	encies recorded		
Outdoor Unit		Inspected	1		
Condition		1- Good			
Deficiency		No defici	encies recorded		
Dry Cooler		Does not			
Packaged / Rooftop Unit		Does not			
Packaged Terminal A/C		Does not			
Refrigerant Leak Detection System		Does not			
Refrigerant Piping		Inspected 1- Good			
Condition Deficiency			encies recorded		
Return Fan		Does not			
CENTRAL ACID WASTE NEUTRALIZING TANK		Does not			
			nstruction		
CLIMATE CONTROL SYSTEM					
COMPACTOR		Does not			
		-			
CONVEYING		Does not			
CONVEYING DOMESTIC WATER SYSTEM		Does not Inspected Inspected			

Building Condition Assessment Survey 2023-2024

Mechanical Inspection X088

nunicui Inspeciion	Αυσο
Question	Response
DOMESTIC WATER SYSTEM	
Domestic Cold Water System	
Pressure Booster System	Does not exist
Water Service	Inspected
Instance	Basement - Water/Gas Meter Room B14
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Deficiency	WATER MAIN:MISSING BACKFLOW PREVENTION
•	DEVICE
Deficiency Location/Instance	Basement - Water/Gas Meter Room B14
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Domestic Hot Water System	Inspected
Domestic Hot Water Remote Storage Tank	Does not exist
Domestic Water Heat Exchanger	Does not exist
Electric Domestic Water Heater	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Gas Fired Domestic Water Heater	Does not exist
Oil Fired Domestic Water Heater	Does not exist
Heat Pump Domestic Water Heater	Under construction
Domestic Water Distribution Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
DRAIN/WASTE/VENT AND STORM SYSTEM	Inspected
Interior Storm Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Sewage/Waste/Vent Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
	Does not exist
Sewage Ejector Pump	Under construction
Sump Pump	Does not exist
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	
FIXTURES	Inspected
Staff And Other	Inspected
Janitor Sink	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lavatory/Sink	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Toilet	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Urinal	Does not exist
Student	Inspected
Drinking Fountain	Inspected
Condition	3- Fair

Building Condition Assessment Survey 2023-2024

Mechanical Inspection	X088

ment inspection	Au
estion	Response
IXTURES	
Student	
Drinking Fountain	
Deficiency	No deficiencies recorded
Lavatory/Sink	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Locker Room Shower	Does not exist
Sink And Fountain Combo Unit	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Toilet	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Urinal	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
SAS FIRED FURNACE	Does not exist
SAS SERVICE	Under construction
<u>IEATING</u>	Inspected
Heating Coil In Ductwork	Does not exist
Hydronic Heating	Does not exist
Radiator/Convector/Fin Tube Condition	Inspected 3- Fair
	No deficiencies recorded
Deficiency	Inspected
Steam Heating E&T/Steam Drin Tran	Inspected
F&T/Steam Drip Trap Condition	1- Good
	No deficiencies recorded
Deficiency	Inspected
MER Steam and Condensate Piping Condition	3- Fair
Deficiency	DEFECTIVE VALVE
Deficiency Location/Instance Deficiency Quantity	Room LL5 - MER @ House Heating And Ventilating Unit
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Steam Condensate Return Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Steam Condensate Return Pumping System	Does not exist
Steam Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Terminal Unit Thermostatic Trap	Inspected
Condition Condition	1- Good
Deficiency	No deficiencies recorded
	Does not exist
Steam supplied by External Sources	
	Under construction
Unit Heater/Cabinet Heater IEATING PLANT	Under construction Inspected

Building Condition Assessment Survey 2023-2024

	Response	
IDF Room	·	
'		
	nispected	
	Not required	
	. Total and a	
Instance on Basement	Does not exist	
Trap		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
•		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Exhaust Ductwork		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Basement	Inspected	
Instance Condition	5- Poor	
Deficiency	DEFECTIVE/DETERIORATED	
	Kitchen (wall mounted)	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Fire Suppression System		
Instance on Basement	Does not exist	
ater Temperature Booster		
Instance on Basement	Does not exist	
n Sink		
Instance on Basement	Inspected	
Instance Condition		
	MISSING INDIRECT WASTE	
	Kitchen	
	1	
Urgency of Action Purpose of Action	PRIORITY 3 LEVEL 2	
	LEVEL 2	
	No violations recorded	
Violations	No violations recorded	
Violations om	Inspected	
Violations om Instance on Room 301B		
Violations om Instance on Room 301B ted A/C Equipment	Inspected Inspected	
Violations om Instance on Room 301B ted A/C Equipment Instance on Room 301B	Inspected Inspected Inspected	
Violations om Instance on Room 301B ted A/C Equipment Instance on Room 301B Instance Condition	Inspected Inspected Inspected 4- Between Fair and Poor	
Violations om Instance on Room 301B ted A/C Equipment Instance on Room 301B Instance Condition Deficiency	Inspected Inspected Inspected 4- Between Fair and Poor DEFECTIVE	
Violations om Instance on Room 301B ted A/C Equipment Instance on Room 301B Instance Condition Deficiency Deficiency Location/Instance	Inspected Inspected Inspected 4- Between Fair and Poor DEFECTIVE Room 301B	
Violations om Instance on Room 301B ted A/C Equipment Instance on Room 301B Instance Condition Deficiency	Inspected Inspected Inspected 4- Between Fair and Poor DEFECTIVE	
	Instance on Basement Instance Condition Deficiency Instance on Basement Instance Condition Deficiency Exhaust Ductwork Instance on Basement Instance Condition Deficiency Exhaust Fan Instance on Basement Instance Condition Deficiency Deficiency Deficiency Deficiency Location/Instance Deficiency Quantity Quantity Uom Potential Action Urgency of Action Purpose of Action Purpose of Action Violations Fire Suppression System Instance on Basement	Response Dees not exist

Building Condition Assessment Survey 2023-2024

Mechanical Inspection X088

•		
uestion	Response	
MDF Room		
Dedicated A/C Equipment		
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
SCIENCE DEMO ROOM	Does not exist	
SCIENCE LAB	Does not exist	
SCIENCE PREP ROOM	Does not exist	
SPRINKLERS, STANDPIPE, FIRE SYSTEM	Inspected	
Dry Sprinkler Alarm Valve Assembly	Does not exist	
Wet Sprinkler Alarm Valve Assembly	Does not exist Does not exist	
Fire Booster Pump Assembly	Does not exist Does not exist	
Roof Tank Siamese Connection	Does not exist Does not exist	
	Inspected	
Sprinkler Head	3- Fair	
Condition	No deficiencies recorded	
Deficiency		
Sprinkler Piping	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Standpipe System	Does not exist	
Water Gong	Does not exist	
SWIMMING POOL	Does not exist	
VENTILATION	Inspected	
Is the building Mechanically ventilated?	Partial	
Exhaust Fan	Inspected	
Condition	3- Fair	
Approximate Total # of Fans	1-25	
Deficiency	DEFECTIVE	
Deficiency Location/Instance	Staff Toilet Room BM-5 (wall mounted)	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Heating And Ventilating Unit	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Metal Ductwork	Inspected	
Condition	3- Fair	
Are there any uninsulated ductwork by design in Mechanical rooms?	Yes	
Are there chain operated dampers?	Yes	
Deficiency	DAMAGED FLEXIBLE CONNECTION	
Deficiency Location/Instance	Cafeteria - Fan Room B-12 @ Cafeteria Exhaust Fan	
Deficiency Quantity	2	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Deficiency	DAMAGED/MISSING INSULATION	
Deficiency Location/Instance	Kitchen - MER	
Deficiency Quantity	10	
Quantity Uom	L.F.	

Building Condition Assessment Survey 2023-2024

anical Inspection		X088
Question	Response	
VENTILATION		
Metal Ductwork		
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Supply Fan	Does not exist	

Does not exist

Unit Ventilator