

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Mechanical Inspection

X089



Asset: P.S. 89 - BRONX, 980 MACE AVENUE, BRONX, NY, 10469

Inspection Id	Inspection Type	Time In	Last Edited
1315	MECHANICAL	2023-11-29 08:20AM	2023-12-28 10:44AM

Asset Data

Question	Answer
Have any Systems/Major Building Components been upgraded?	Systems: Fixtures - Toilets; Kitchen - Grease Trap Years: 2022 Systems: MDF Room - Dedicated A/C Equipment (DX Split System) Years: 2018 Systems: DX Split Systems for Gymnasium (4 of 16), Climate Control System - Electric System; Enclosed IDF Rooms - Dedicated A/C Equipment (window A/C's); Climate Control System - Pneumatic System; Refrigerated Air Dryer, Terminal Unit Controllers Years: 2017 Systems: DX Split Systems for Auditorium and Large Cafeteria (12 of 16); F&T/Steam Drip Traps; Terminal Unit Thermostatic Traps (~75%) Years: 2016 Systems: Gas Fired Domestic Water Heater; Domestic Hot Water Remote Storage Tank Years: 2014 Systems: Electric Domestic Water Heater (1 of 2) Years: 2013
Are there fuel tanks?	Yes
Total # of above ground tanks	1
Total capacity of all above ground tanks in gal.	10,000
Total # of below ground tanks	0
Total capacity of all below ground tanks in gal.	0
Total # of water main service entries to the asset	2
MERs/Fan Rooms Locations	Basement Mechanical Area, Basement Fan Room
Are there any spaces with Missing or Defective CO Detectors?	Yes
Location(s)	Science Lab
Are there any Painted/Obstructed Sprinkler Heads?	Yes
Location(s)	Basement Storage Room (painted, 2)
Are there any Emergency Stop Switches with Missing Hammers?	No components

Priority Condition

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
No	Defective Emergency Stop Switch	Broken Glass	Boiler Emergency Stop Switch	Boiler Room Entrance (1 of 2)	John Plunkett	Fireman	
No	Defective Boiler Safety Auxiliary	(1)	Boiler Safety Valve	Boiler Room @ Boiler #1	John Plunkett	Fireman	

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Mechanical Inspection

X089

No	Defective CO/Gas Leak Detection	Fault Signal At Panel	CO/Gas Leak Detection	Custodian's Office, Basement by Gas Meter Room	John Plunkett	Fireman
----	---------------------------------	-----------------------	-----------------------	--	---------------	---------



Inspection

Question	Response
Mechanical	
AIR CONDITIONING	Inspected
Chilled Water System	Does not exist
Condenser Water Distribution: Piping, Pumps and Auxiliaries	Does not exist
Cooling Coil in Ductwork	Does not exist
Cooling Tower	Does not exist
DX Split System	Inspected
Indoor Unit	Inspected
Condition	1- Good
Deficiency	UP TO 5 TONS:DEFECTIVE
Deficiency Location/Instance	Large Cafeteria (1 of 16)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Outdoor Unit	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Dry Cooler	Does not exist
Packaged / Rooftop Unit	Does not exist
Packaged Terminal A/C	Does not exist
Refrigerant Leak Detection System	Does not exist
Refrigerant Piping	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Return Fan	Does not exist
CENTRAL ACID WASTE NEUTRALIZING TANK	Does not exist
CLIMATE CONTROL SYSTEM	Inspected
BMS	Does not exist
Pneumatic System	Inspected
Instance	Throughout
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Building Area Covered by Operational System	81-100%
Deficiency	DEFECTIVE TEMPERATURE CONTROL ZONE VALVE
Deficiency Location/Instance	Basement Mechanical Area @ Playroom Blower, Boys and Girls Gymnasium Blowers, Auditorium Blower
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Hybrid System	Does not exist
Electric System	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Mechanical Inspection

X089

Question	Response
CLIMATE CONTROL SYSTEM	
Electric System	
Instance	Throughout (Heat Timer System)
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Building Area Covered by Operational System	81-100%
Deficiency	No deficiencies recorded
COMPACTOR	Does not exist
CONVEYING	Does not exist
DOMESTIC WATER SYSTEM	Inspected
Domestic Cold Water System	Inspected
Gravity System	Does not exist
Pressure Booster System	Does not exist
Water Service	Inspected
Instance	Basement Mechanical Area
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Deficiency	WATER MAIN:MISSING BACKFLOW PREVENTION DEVICE
Deficiency Location/Instance	Basement Mechanical Area
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Boiler Room
Instance Condition	5- Poor
Instance Quantity	1
Instance Quantity Uom	EACH
Deficiency	WATER MAIN:DETERIORATED
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	WATER MAIN:MISSING BACKFLOW PREVENTION DEVICE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Domestic Hot Water System	Inspected
Domestic Hot Water Remote Storage Tank	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Domestic Water Heat Exchanger	Does not exist
Electric Domestic Water Heater	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Mechanical Inspection

X089

Question	Response
DOMESTIC WATER SYSTEM	
Domestic Hot Water System	
Electric Domestic Water Heater	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Gas Fired Domestic Water Heater	
Inspected	Inspected
Instance	Boiler Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Lochinvar
EquipmentId	N/A
Capacity/Size Quantity	650
Capacity/Size UOM	MBH Input
Capacity/Size 2 Quantity	0
Capacity/Size 2 UOM	Gallons
Source of Capacity/Size	Documented
Installation Year	2014
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
Oil Fired Domestic Water Heater	
Does not exist	
Heat Pump Domestic Water Heater	
Does not exist	
Domestic Water Distribution Piping	
Inspected	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE VALVE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	DEFECTIVE/LEAKS
Deficiency Location/Instance	Boy's Toilet Room 459
Deficiency Quantity	10
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
DRAIN/WASTE/VENT AND STORM SYSTEM	
Inspected	
Interior Storm Piping	
Inspected	
Condition	3- Fair
Deficiency	No deficiencies recorded
Sewage/Waste/Vent Piping	
Inspected	
Condition	3- Fair
Deficiency	SEWAGE/WASTE PIPING:CLOGGED
Deficiency Location/Instance	Basement (backs-up during heavy rain)
Deficiency Quantity	100
Quantity Uom	L.F.
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	SEWAGE/WASTE PIPING:DEFECTIVE/LEAKS
Deficiency Location/Instance	Boiler Room, Toilet Room 158

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Mechanical Inspection

X089

Question	Response
DRAIN/WASTE/VENT AND STORM SYSTEM	
Sewage/Waste/Vent Piping	
Deficiency Quantity	20
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	HOUSE TRAP:DETERIORATED/LEAKS
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Sewage Ejector Pump	Does not exist
Sump Pump	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	
	Does not exist
FIXTURES	
	Inspected
Staff And Other	
	Inspected
Janitor Sink	
Condition	3- Fair
Deficiency	No deficiencies recorded
Lavatory/Sink	
Condition	3- Fair
Deficiency	No deficiencies recorded
Toilet	
Condition	1- Good
Deficiency	No deficiencies recorded
Urinal	
Condition	3- Fair
Deficiency	CLOGGED/LEAKING
Deficiency Location/Instance	4th Floor Toilet Room by Stair "G"
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Student	
	Inspected
Drinking Fountain	
Condition	3- Fair
Deficiency	No deficiencies recorded
Lavatory/Sink	
Condition	3- Fair
Deficiency	DEFECTIVE AUXILIARY (FAUCET, SHUT OFF VALVE,ETC.)
Deficiency Location/Instance	Boy's Toilet Room 356, Girl's Toilet Room 358
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Mechanical Inspection

X089

Question	Response
FIXTURES	
Student	
Lavatory/Sink	
Purpose of Action	LEVEL 2
Violations	No violations recorded
Locker Room Shower	
	Does not exist
Sink And Fountain Combo Unit	
	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Toilet	
	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Urinal	
	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
GAS FIRED FURNACE	
	Does not exist
GAS SERVICE	
	Inspected
Gas Distribution Piping	
	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Gas Meter Room Exhaust Fan	
	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Gas Meter Room Vent	
	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Gas Pressure Booster	
	Does not exist
CO/Gas Leak Detection	
	Inspected
Instance	Boiler Room, Gas Meter Room
Instance Condition	4- Between Fair and Poor
Instance Quantity	1
Instance Quantity Uom	EACH
Installation Year	1999
Source of Installation Year	Inspector Estimate
Deficiency	DEFECTIVE CONTROL PANEL
Deficiency Location/Instance	Basement by Gas Meter Room, Custodian's Office
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
HEATING	
	Inspected
Heating Coil In Ductwork	
	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Hydronic Heating	
	Does not exist
Radiator/Convactor/Fin Tube	
	Inspected
Condition	3- Fair
Deficiency	AUXILIARY (VALVE, VENT):DEFECTIVE
Deficiency Location/Instance	1st Floor by Exit 9, Corridor by Room 401, Girl's Toilet Room 457 and other locations
Deficiency Quantity	20
Quantity Uom	EACH
Potential Action	MAINTENANCE

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Mechanical Inspection

X089

Question	Response
HEATING	
Radiator/Convactor/Fin Tube	
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	RADIATOR/CONVECTOR:DEFECTIVE
Deficiency Location/Instance	Room 407
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	RADIATOR/CONVECTOR:MISSING GUARD/SHIELD
Deficiency Location/Instance	Boy's Toilet Room 356
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Steam Heating	Inspected
F&T/Steam Drip Trap	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
MER Steam and Condensate Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Steam Condensate Return Piping	Inspected
Condition	3- Fair
Deficiency	DAMAGED/MISSING INSULATION
Deficiency Location/Instance	Basement Mechanical Area, Crawlspace
Deficiency Quantity	200
Quantity Uom	L.F.
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	DEFECTIVE/LEAKS
Deficiency Location/Instance	Crawlspace, Basement Mechanical Area Exit
Deficiency Quantity	20
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Steam Condensate Return Pumping System	Inspected
Condition	5- Poor
Deficiency	DEFECTIVE/DETERIORATED
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Mechanical Inspection

X089

Question	Response
HEATING	
Steam Heating	
Steam Piping	Inspected
Condition	3- Fair
Deficiency	DAMAGED/MISSING INSULATION
Deficiency Location/Instance	Basement Mechanical Area, Crawlspace
Deficiency Quantity	200
Quantity Uom	L.F.
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	DEFECTIVE/LEAKS
Deficiency Location/Instance	Room 413
Deficiency Quantity	10
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Terminal Unit Thermostatic Trap	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Steam supplied by External Sources	Does not exist
Unit Heater/Cabinet Heater	Does not exist
HEATING PLANT	
Instance on Basement	Inspected
Is there a water meter on the boiler make-up water piping?	Yes
Observed Operational?	Yes
Burner Manufacturer	Gordon-Piatt
Burner Model	F14.9-GO-30
Burner Type	Dual Fuel (Gas/Oil)
Heating Plant Oil Number	2
Boiler Auxiliaries	
Instance on Basement	Inspected
Boiler Auxiliary Piping	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	DEFECTIVE BOILER MAKE-UP WATER PIPING
Deficiency Location/Instance	Boiler Room @ Boiler Feedwater System
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Boiler Emergency Stop Switch	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	DEFECTIVE
Deficiency Location/Instance	Boiler Room Exit (1 of 2)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Mechanical Inspection

X089

Question	Response
HEATING PLANT	
Boiler Auxiliaries	
Boiler Emergency Stop Switch	
Violations	No violations recorded
Boiler Feedwater System	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Boiler Feedwater Treatment(Automatic)	
Instance on Basement	Inspected
Instance Condition	4- Between Fair and Poor
Deficiency	DEFECTIVE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Boiler Flue Exhaust	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Boiler Make-up Water Backflow Preventer	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Boiler Room Steam And Condensate Piping	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Boiler Safety Valve	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	DEFECTIVE
Deficiency Location/Instance	Boiler Room @ Boiler #1 (1 of 4)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Boiler System	
Instance on Basement	Inspected
Coal-fired Boiler	
Instance on Basement	Does not exist
Hot Water Boiler	
Instance on Basement	Does not exist
Modular Boiler	
Instance on Basement	Does not exist
Steam Boiler	
Instance on Basement	Inspected
Instance on Basement	Inspected
Instance	Boiler Room

NYC Department of Education
Building Condition Assessment Survey 2023-2024

Mechanical Inspection

X089

Question	Response
HEATING PLANT	
Boiler System	
Steam Boiler	
Instance Condition	3- Fair
Instance Quantity	5,198
Instance Quantity Uom	MBH NET
Cast Iron Boiler?	No
Manufacturer	A. L. Eastmond & Sons Inc.
EquipmentId	6213-1
Capacity/Size Quantity	5198
Capacity/Size UOM	MBH Net
Source of Capacity/Size	Documented
Installation Year	1999
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Boiler Room
Instance Condition	3- Fair
Instance Quantity	5,198
Instance Quantity Uom	MBH NET
Cast Iron Boiler?	No
Manufacturer	A. L. Eastmond & Sons Inc.
EquipmentId	6213-2
Capacity/Size Quantity	5198
Capacity/Size UOM	MBH Net
Source of Capacity/Size	Documented
Installation Year	1999
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fuel System	
Instance on Basement	Inspected
Boiler Fresh Air Louver/Damper	
Instance on Basement	Inspected
Instance Condition	3- Fair
Type	Automatic
Deficiency	No deficiencies recorded
Burner/Burner Control Panel	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Fuel Oil Storage/Supply System	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Gas Trains And Vent At The Boiler	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Enclosed IDF Room	
Instance on Rooms 256, 263	Inspected
Dedicated A/C Equipment	
Instance on Rooms 256, 263	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
KITCHEN	
Instance on 1st Floor	Inspected

NYC Department of Education
Building Condition Assessment Survey 2023-2024

Mechanical Inspection

X089

Question	Response
KITCHEN	
CO Detector	
Instance on 1st Floor	Not required
Gas System	
Instance on 1st Floor	Does not exist
Grease Trap	
Instance on 1st Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Hood	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Hood Exhaust Ductwork	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Hood Exhaust Fan	
Instance on 1st Floor	Inspected
Instance Condition	4- Between Fair and Poor
Deficiency	DEFECTIVE
Deficiency Location/Instance	Building Exterior by Mace Ave Side
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Hood Fire Suppression System	
Instance on 1st Floor	Does not exist
Hot Water Temperature Booster	
Instance on 1st Floor	Does not exist
Kitchen Sink	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	Missing Air Gap
Deficiency Location/Instance	Kitchen
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
MDF Room	
Instance on Room 100A	Inspected
Dedicated A/C Equipment	
Instance on Room 100A	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
SCIENCE DEMO ROOM	
	Does not exist
SCIENCE LAB	
	Inspected
Instance on Room 424	Inspected
Alternative Use	No
Acid Waste Neutralizing Tank	
Instance on Room 424	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Mechanical Inspection

X089

Question	Response
SCIENCE LAB	
Acid Waste Neutralizing Tank	
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
CO Detector	
Instance on Room 424	Inspected
Instance Condition	4- Between Fair and Poor
Deficiency	DEFECTIVE/MISSING
Deficiency Location/Instance	Room 424
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Emergency Shower	
Instance on Room 424	Does not exist
Eye Wash	
Instance on Room 424	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Hood Exhaust Ductwork	
Instance on Room 424	Does not exist
Hood Exhaust Fan	
Instance on Room 424	Does not exist
Fixed Laboratory Hood	
Instance on Room 424	Does not exist
Laboratory Sink	
Instance on Room 424	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Make-up Air Unit	
Instance on Room 424	Does not exist
SCIENCE PREP ROOM	
Does not exist	
SPRINKLERS, STANDPIPE, FIRE SYSTEM	
Inspected	
Dry Sprinkler Alarm Valve Assembly	
Does not exist	
Wet Sprinkler Alarm Valve Assembly	
Does not exist	
Fire Booster Pump Assembly	
Does not exist	
Roof Tank	
Does not exist	
Siamese Connection	
Does not exist	
Sprinkler Head	
Inspected	
Condition	3- Fair
Deficiency	DEFECTIVE/DETERIORATED
Deficiency Location/Instance	Basement Storage Room (painted, 2)
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Sprinkler Piping	
Inspected	
Condition	3- Fair
Deficiency	No deficiencies recorded
Standpipe System	
Does not exist	
Water Gong	
Does not exist	

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Mechanical Inspection

X089

Question	Response
SWIMMING POOL	Does not exist
VENTILATION	Inspected
Is the building Mechanically ventilated?	Yes
Exhaust Fan	Inspected
Condition	3- Fair
Approximate Total # of Fans	1-25
Deficiency	DEFECTIVE MOTOR
Deficiency Location/Instance	Boiler Room / Paint Room Exhaust Fan
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Heating And Ventilating Unit	Does not exist
Metal Ductwork	Inspected
Condition	3- Fair
Are there any uninsulated ductwork by design in Mechanical rooms?	Yes
Are there chain operated dampers?	Yes
Deficiency	DAMAGED FLEXIBLE CONNECTION
Deficiency Location/Instance	Basement Mechanical Area @ Girls Gymnasium Blower, Auditorium Blower, Auditorium EF
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	DEFECTIVE REGISTER/DIFFUSER
Deficiency Location/Instance	Corridor by Room 400B
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Supply Fan	Inspected
Condition	3- Fair
Approximate Total # of Fans	1-5
Deficiency	No deficiencies recorded
Unit Ventilator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded