# **Building Condition Assessment Survey 2023-2024**

#### Mechanical Inspection

Asset: P.S. 110 - BRONX, 580 CROTONA PARK SOUTH, BRONX, NY, 10456				
Inspection Id	Inspection Type		Time In	Last Edited
3438	MECHANICAL		2024-02-23 08:29AM	2024-04-07 01:49PM
sset Data				
Question		Answer		
Have any Systems/Major Building Components been upgraded?		Systems:	Heating Plant; Gas Service; Dom System; Steam Condensate Return of 2); Sump Pumps; Unit Heater/ Heating Coils In Ductwork; Clin	rn Pumping System (1 /Cabinet Heaters;
		Years:	2023	late Control System
		Systems: Years:	Terminal Unit Thermostatic Trap Trap; Steam Condensate Return 2); MER Steam and Condensate 2022	Pumping System (1 of
		Systems:	Kitchen - Grease Traps	
		Years:	2015	

	Years: 2015
Are there fuel tanks?	No
Total # of water main service entries to the asset	2
MERs/Fan Rooms Locations	MER G12; 2nd Floor MER
Are there any spaces with Missing or Defective CO Detectors?	No
Are there any Painted/Obstructed Sprinkler Heads?	Yes
Location(s)	Rooms G34, Custodial Locker Room, 229 (painted, 6)
Are there any Emergency Stop Switches with Missing Hammers?	No components

#### **Priority Condition**

Exist	Priority	Condition	Component	Location	Person(s)	Person(s)	Photo
Last Year?	Category	Description	Affected	Description	Notified	Title	Image
No condi	tion recorded						

Inspection

iestion	Response	
echanical		
AIR CONDITIONING	Inspected	
Chilled Water System	Does not exist	
Condenser Water Distribution: Piping, Pumps and Auxiliaries	Does not exist	
Cooling Coil in Ductwork	Does not exist	
Cooling Tower	Does not exist	
DX Split System	Inspected	
Indoor Unit	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Outdoor Unit	Inspected	
Condition	4- Between Fair and Poor	
Deficiency	UP TO 5 TONS:DEFECTIVE	
Deficiency Location/Instance	Areaway by the playground	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPAIR	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Dry Cooler	Does not exist	
Packaged / Rooftop Unit	Does not exist	
Packaged Terminal A/C	Does not exist	
Refrigerant Leak Detection System	Does not exist	
Refrigerant Piping	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	

# **Building Condition Assessment Survey 2023-2024**

### Mechanical Inspection

unicui Inspeciion	A1
uestion	Response
AIR CONDITIONING	
Return Fan	Does not exist
CENTRAL ACID WASTE NEUTRALIZING TANK	Does not exist
CLIMATE CONTROL SYSTEM	Inspected
BMS	Does not exist
Pneumatic System	Does not exist
Hybrid System	Does not exist
Electric System	Inspected
Instance	Throughout
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Building Area Covered by Operational System	81-100%
Deficiency	No deficiencies recorded
COMPACTOR	Does not exist
CONVEYING	Does not exist
DOMESTIC WATER SYSTEM	Inspected
Domestic Cold Water System	Inspected
Gravity System	Does not exist
Pressure Booster System	Does not exist
Water Service	Inspected
Instance	Boiler Room, Gas/Water Meter Room G33
Instance Condition	3- Fair
Instance Quantity	2
Instance Quantity Uom	EACH
	WATER MAIN:MISSING BACKFLOW PREVENTION
Deficiency	DEVICE
Deficiency Location/Instance	Boiler Room, Gas/Water Meter Room G33
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	INSTALL
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Domestic Hot Water System	Inspected
Domestic Hot Water Remote Storage Tank	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Domestic Water Heat Exchanger	Does not exist
Electric Domestic Water Heater	Inspected
Condition	1- Good
Deficiency	NOT IN USE
Deficiency Location/Instance	Kitchen
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	NO ACTION
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 1
Violations	No violations recorded
Gas Fired Domestic Water Heater	Inspected
Instance	Boiler Room
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH

# **Building Condition Assessment Survey 2023-2024**

### **Mechanical Inspection**

unicui Inspection		2011
uestion	Response	
DOMESTIC WATER SYSTEM		
Domestic Hot Water System		
Gas Fired Domestic Water Heater		
Manufacturer	Laars	
EquipmentId	N/A	
Capacity/Size Quantity	299	
Capacity/Size UOM	MBH Input	
Capacity/Size 2 Quantity	0	
Capacity/Size 2 UOM	Gallons	
Source of Capacity/Size	Documented 2023	
Source of Installation Year	Custodial Staff	
Deficiency	No deficiencies recorded	
Oil Fired Domestic Water Heater	Does not exist	
Heat Pump Domestic Water Heater	Does not exist	
Domestic Water Distribution Piping	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
	Inspected	
DRAIN/WASTE/VENT AND STORM SYSTEM	Inspected	
Interior Storm Piping Condition	3- Fair	
Deficiency	No deficiencies recorded	
	Inspected	
Sewage/Waste/Vent Piping Condition	3- Fair	
Deficiency	No deficiencies recorded	
	Does not exist	
Sewage Ejector Pump	Inspected	
Sump Pump Condition	1- Good	
Deficiency	No deficiencies recorded	
-	Does not exist	
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)		
FIXTURES	Inspected	
Staff And Other	Inspected	
Janitor Sink	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lavatory/Sink	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Toilet	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Urinal	Inspected	
Condition	5- Poor	
Deficiency	CRACKED/PHYSICAL DAMAGE	
Deficiency Location/Instance	1st Floor Staff Toilet Room	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Student	Inspected	
Drinking Fountain	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	

### **Building Condition Assessment Survey 2023-2024**

### **Mechanical Inspection**

mean Inspection		111
estion	Response	
IXTURES		
Student		
Lavatory/Sink	Inspected	
Condition	3- Fair	
Deficiency	CRACKED/PHYSICAL DAMAGE	
Deficiency Location/Instance	Boy's Toilet Room 220	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Locker Room Shower	Does not exist	
Sink And Fountain Combo Unit	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Toilet	Inspected	
Condition	3- Fair	
Deficiency	CRACKED/PHYSICAL DAMAGE	
Deficiency Location/Instance	Boy's Toilet Room G20	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Urinal	Inspected	
Condition	3- Fair	
Deficiency	CRACKED/PHYSICAL DAMAGE	
Deficiency Location/Instance Deficiency Quantity	Boy's Toilet Room G20 1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
AS FIRED FURNACE	Does not exist	
AS SERVICE	Inspected	
Gas Distribution Piping	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Gas Meter Room Exhaust Fan	Does not exist	
Gas Meter Room Vent	Does not exist	
Gas Pressure Booster	Does not exist	
CO/Gas Leak Detection	Inspected	
Instance	Boiler Room	
Instance Condition	1- Good	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Installation Year	2023	
Source of Installation Year	Custodial Staff	
Deficiency	No deficiencies recorded	
	No deficiencies recorded           Inspected           Inspected	

# **Building Condition Assessment Survey 2023-2024**

### **Mechanical Inspection**

estion	Response
IEATING	
Heating Coil In Ductwork	
Deficiency	No deficiencies recorded
Hydronic Heating	Does not exist
Radiator/Convector/Fin Tube	Inspected
Condition	3- Fair
Deficiency	RADIATOR/CONVECTOR:DEFECTIVE
Deficiency Location/Instance	Custodians Office, Kitchen Staff Room, Boy's Toilet Room 120,
	3rd Floor - Men's Toilet Room
Deficiency Quantity	4
Quantity Uom Potential Action	EACH
Urgency of Action	MAINTENANCE PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Steam Heating	Inspected Inspected
F&T/Steam Drip Trap	
Condition	1- Good
Deficiency	No deficiencies recorded
MER Steam and Condensate Piping	Inspected
Condition	1- Good
Deficiency	DEFECTIVE/LEAKS
Deficiency Location/Instance	2nd Floor MER
Deficiency Quantity	10
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Steam Condensate Return Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Steam Condensate Return Pumping System	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Steam Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Terminal Unit Thermostatic Trap	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Steam supplied by External Sources	Does not exist
Unit Heater/Cabinet Heater	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
EATING PLANT	Inspected
Instance on Ground Floor	Inspected
Is there a water meter on the boiler make-up water piping?	Yes
Observed Operational?	No
Burner Manufacturer	Weishaupt
Burner Model	WM-GO/3-A, ZM
Burner Type	Gas
Heating Plant Oil Number	N/A

# **Building Condition Assessment Survey 2023-2024**

### **Mechanical Inspection**

		Λ
tion	Response	
CATING PLANT		
oiler Auxiliaries		
Boiler Auxiliary Piping		
Instance on Ground Floor	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Boiler Emergency Stop Switch		
Instance on Ground Floor	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Boiler Feedwater System		
Instance on Ground Floor	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Boiler Feedwater Treatment(Automatic)		
Instance on Ground Floor	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Boiler Flue Exhaust		
Instance on Ground Floor	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Boiler Make-up Water Backflow Preventer		
Instance on Ground Floor	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Boiler Room Steam And Condensate Piping		
Instance on Ground Floor	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Boiler Safety Valve	No deficicies recorded	
Instance on Ground Floor	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
	No deficicies recolded	
coller System Instance on Ground Floor	Inspected	
Coal-fired Boiler	inspected	
Instance on Ground Floor	Does not exist	
	Does not exist	
Hot Water Boiler Instance on Ground Floor	Does not exist	
Modular Boiler	Does not exist	
Instance on Ground Floor	Does not exist	
	Does not exist	
Steam Boiler	Y , 1	
Instance on Ground Floor	Inspected	
Instance on Ground Floor	Inspected	
Instance	Boiler Room	
Instance Condition	1-Good	
Instance Quantity	3,694	
Instance Quantity Uom	MBH NET	
Cast Iron Boiler?	No	
Manufacturer	Burnham	
EquipmentId Capacity/Size Quantity	50912-N01 4758	

# **Building Condition Assessment Survey 2023-2024**

### **Mechanical Inspection**

	A
uestion	Response
HEATING PLANT	
Boiler System	
Steam Boiler	
Source of Capacity/Size	Documented
Installation Year	2023
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
Instance	Boiler Room
Instance Condition	1- Good
Instance Quantity	3,694
Instance Quantity Uom	MBH NET
Cast Iron Boiler?	No
Manufacturer	Burnham
EquipmentId	50912-N02
Capacity/Size Quantity	4758
Capacity/Size UOM	MBH Gross
Source of Capacity/Size	Documented
Installation Year	2023
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
Fuel System	
Instance on Ground Floor	Inspected
Boiler Fresh Air Louver/Damper	
Instance on Ground Floor	Inspected
Instance Condition	1- Good
Туре	Automatic
Deficiency	No deficiencies recorded
Burner/Burner Control Panel	
Instance on Ground Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Fuel Oil Storage/Supply System	
Instance on Ground Floor	Does not exist
Gas Trains And Vent At The Boiler	
Instance on Ground Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Enclosed IDF Room	Inspected
Instance on Room 100A	Inspected
Dedicated A/C Equipment	To success of
Instance on Room 100A	Inspected
Instance Condition	4- Between Fair and Poor
Deficiency	DOES NOT EXIST
Deficiency Location/Instance Deficiency Quantity	Room 100A
	1
Quantity Uom Potential Action	EACH INSTALL
Urgency of Action	INSTALL PRIORITY 3
Purpose of Action	LEVEL 2
Violations	LEVEL 2 No violations recorded
KITCHEN	Inspected
Instance on Ground Floor	Inspected
CO Detector	
Instance on Ground Floor	Inspected
Instance Condition	2- Between Good and Fair

### **Building Condition Assessment Survey 2023-2024**

#### **Mechanical Inspection**

inical Inspection		
lestion	Response	
KITCHEN		
CO Detector		
Deficiency	No deficiencies recorded	
Gas System		
Instance on Ground Floor	Does not exist	
Grease T <u>rap</u>		
Instance on Ground Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Hood		
Instance on Ground Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Hood Exhaust Ductwork		
Instance on Ground Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Hood Exhaust Fan		
Instance on Ground Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Hood Fire Suppression System		
Instance on Ground Floor	Does not exist	
Hot Water Temperature Booster		
Instance on Ground Floor	Does not exist	
Kitchen Sink		
Instance on Ground Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
1DF Room	Inspected	
Instance on Room 125A	Inspected	
Dedicated A/C Equipment		
Instance on Room 125A	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
CIENCE DEMO ROOM	Does not exist	
CIENCE LAB	Inspected	
Instance on Room 331	Inspected	
Alternative Use	No	
Acid Waste Neutralizing Tank		
Instance on Room 331	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
CO Detector		
Instance on Room 331	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Emergency Shower		
Instance on Room 331	Does not exist	
Eye Wash		
Instance on Room 331	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	

### **Building Condition Assessment Survey 2023-2024**

#### **Mechanical Inspection**

uestion	Response
SCIENCE LAB	
Hood Exhaust Ductwork	
Instance on Room 331	Does not exist
Hood Exhaust Fan	
Instance on Room 331	Does not exist
Fixed Laboratory Hood	
Instance on Room 331	Does not exist
Laboratory Sink	
Instance on Room 331	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Make-up Air Unit Instance on Room 331	Does not exist
	Does not exist
SCIENCE PREP ROOM	
SPRINKLERS, STANDPIPE, FIRE SYSTEM	Inspected
Dry Sprinkler Alarm Valve Assembly	Does not exist
Wet Sprinkler Alarm Valve Assembly	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fire Booster Pump Assembly	Does not exist
Roof Tank	Does not exist
Siamese Connection	Does not exist
Sprinkler Head	Inspected 3- Fair
Condition	
Deficiency	DEFECTIVE/DETERIORATED
Deficiency Location/Instance Deficiency Quantity	Rooms G34, Custodial Locker Room, 229 (painted, 6)
	6
Quantity Uom Potential Action	EACH REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Sprinkler Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Standpipe System	Does not exist
Water Gong	Does not exist
Water Going SWIMMING POOL	Does not exist
VENTILATION	Inspected Partial
Is the building Mechanically ventilated?	Inspected
Exhaust Fan Condition	3- Fair
Approximate Total # of Fans	1-25
Deficiency	DEFECTIVE
Deficiency Location/Instance	Roof / Exhaust Fan #9
Deficiency Quantity	
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Heating And Ventilating Unit	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Metal Ductwork	Inspected

# **Building Condition Assessment Survey 2023-2024**

### **Mechanical Inspection**

iestion	Response	
VENTILATION		
Metal Ductwork		
Condition	3- Fair	
Are there any uninsulated ductwork by design in Mechanical rooms?	Yes	
Are there chain operated dampers?	Yes	
Deficiency	DEFECTIVE REGISTER/DIFFUSER	
Deficiency Location/Instance	Gymnasium	
Deficiency Quantity	2	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Supply Fan	Inspected	
Condition	3- Fair	
Approximate Total # of Fans	1-5	
Deficiency	No deficiencies recorded	
Unit Ventilator	Inspected	
Condition	3- Fair	
Deficiency	DEFECTIVE	
Deficiency Location/Instance	Rooms 128, 130 (2 of 4)	
Deficiency Quantity	2	
Quantity Uom	EACH	
Potential Action	REPAIR	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	