Building Condition Assessment Survey 2023-2024

Mechanical Inspection X111

Asset:	P.S. 111 - BRONX, 3740 BAYCHESTER AVENUE, BRONX, NY, 10466					
Inspection Id	Inspection Type		Time In	Last Edited		
1469	MECHANICAL		2023-12-05 07:36AM	2024-01-09 04:30PM		
set Data						
Question		Answer				
Have any Systems/Major Building Components been upgraded?		Systems:	Sump Pumps; Steam Condensate System	Return Pumping		
		Years:	2023			
		Systems:	Electric Domestic Water Heater ((temporary)		
		Years:	2021			
		Systems:	Kitchen - Grease Trap			
		Years:	2018			
		Systems:	F&T/Steam Drip Traps; Termina Traps; Fixtures - Toilets	l Unit Thermostatic		
		Years:	2015			
		Systems:	MDF Room - Dedicated A/C Equ System)	uipment (DX Split		
		Years:	2013			
Are there fuel t	anks?	No				
Total # of water	r main service entries to the asset	2				
MERs/Fan Roo	oms Locations	MERs B4	8, B51			
Are there any s	paces with Missing or Defective CO Detectors?	No				
Are there any P	ainted/Obstructed Sprinkler Heads?	No				

Priority Condition

Are there any Emergency Stop Switches with Missing Hammers?

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
Yes	Defective Kitchen Gas System	By-pass Valve of Master Gas Control Valve is in open position	Gas System	Kitchen	Ismael Carrero	Fireman	
No	Other	Vent is covered with spray foam material	Gas Meter Room Vent	Basement - Gas/Sprinkler/ Water Meter Room B30	Ismael Carrero	Fireman	

No components

Inspection

Question	Response	
Mechanical Technology (1997)		
AIR CONDITIONING	Does not exist	
CENTRAL ACID WASTE NEUTRALIZING TANK	Does not exist	
CLIMATE CONTROL SYSTEM	Under construction	
COMPACTOR	Does not exist	
CONVEYING	Inspected	
Dumbwaiter	Does not exist	
Elevator	Inspected	
Condition	5- Poor	
Are all the existing elevators operable?	No	
Deficiency	No deficiencies recorded	
Escalator	Does not exist	
Non-auditorium Handicap Lift - Vertical	Does not exist	
Non-auditorium Handicap Lift - Stair	Does not exist	

Mechanical Inspection	XIII

Question Resp	sponse
CONVEYING	r. · · · ·
	es not exist
	es not exist
	pected
	pected
	es not exist
	es not exist
	pected
	sement - Sprinkler/Water Meter Room B30
Instance Condition 3- Fe	-
Instance Quantity 2	
Instance Quantity Uom EAC	СН
Deficiency WAT	TER MAIN:MISSING BACKFLOW PREVENTION VICE
Deficiency Location/Instance Base	sement - Sprinkler/Water Meter Room B30
Deficiency Quantity 2	
Quantity Uom EAC	СН
	STALL
ε ,	IORITY 3
1	VEL 2
	violations recorded
	pected
	der construction
	es not exist
	pected
	Good
Deficiency No c	deficiencies recorded
Guy I med 2 Gmessee () the C I I content	der construction
on Theu Domestic Water Treater	es not exist
Treat I unip Domestic Water Treater	es not exist
	pected
Condition 3- Fa	
Deficiency No c	deficiencies recorded
DRAIN/WASTE/VENT AND STORM SYSTEM Insp	pected
1 0	pected
Condition 3- Fa	Fair
Deficiency No c	deficiencies recorded
	pected
Condition 3- Fa	Fair
	WAGE/WASTE PIPING:DEFECTIVE/LEAKS
	om 110
Deficiency Quantity 10	
Quantity Uom L.F.	
	PLACE
e ,	IORITY 3
1	VEL 2
	violations recorded
serrage Ejector Lamp	es not exist
	pected
	Good
D-C-:	Good
-	deficiencies recorded
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER) Does	deficiencies recorded es not exist
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER) Does FIXTURES Insp	deficiencies recorded es not exist pected
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER) Does FIXTURES Insp Staff And Other Insp	deficiencies recorded es not exist

Mechanical Inspection	XIII

estion	Response	
IXTURES		
Staff And Other		
Janitor Sink		
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lavatory/Sink	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Toilet	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Urinal	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Student	Inspected	
Drinking Fountain	Inspected	
Condition	3- Fair	
Deficiency	CLOGGED/LEAKING	
Deficiency Location/Instance	Corridor near Room 135	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Lavatory/Sink	Inspected	
Condition	3- Fair	
	No deficiencies recorded	
Deficiency	Does not exist	
Locker Room Shower		
Sink And Fountain Combo Unit	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Toilet	Inspected	
Condition	2- Between Good and Fair	
Deficiency	DEFECTIVE FLUSHOMETER VALVE	
Deficiency Location/Instance	Girl's Toilet Room B22	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Deficiency	CRACKED/PHYSICAL DAMAGE	
Deficiency Location/Instance	Boy's Toilet Room B12	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Urinal	Inspected	
Condition	3- Fair	
Deficiency	CLOGGED/LEAKING	
Deficiency Deficiency Location/Instance	Boy's Toilet Room B12	
Deficiency Quantity	Doj o Tollot Room D12	

Mechanical Inspection	XIII

*	
uestion	Response
FIXTURES	
Student	
Urinal	
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
GAS FIRED FURNACE	Does not exist
GAS SERVICE	Inspected
Gas Distribution Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Gas Meter Room Exhaust Fan	Does not exist
Gas Meter Room Vent	Inspected
Condition	4- Between Fair and Poor
Deficiency	DEFECTIVE
Deficiency Location/Instance	Basement - Sprinkler/Water Meter Room B30
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Gas Pressure Booster	Under construction
CO/Gas Leak Detection	Under construction
HEATING	Inspected
Heating Coil In Ductwork	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Hydronic Heating	Does not exist
Radiator/Convector/Fin Tube	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Steam Heating	Inspected
F&T/Steam Drip Trap	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
MER Steam and Condensate Piping	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE/LEAKS
Deficiency Location/Instance	MERs B48, B51
Deficiency Quantity	30
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	DAMAGED/MISSING INSULATION
Deficiency Location/Instance	MERs B48, B51
Deficiency Quantity	80
Quantity Uom	L.F.
	₽•1 ·
	MAINTENANCE
Potential Action Urgency of Action	MAINTENANCE PRIORITY 3

Mechanical Inspection	X111
-----------------------	------

*	n	
uestion	Response	
HEATING		
Steam Heating		
MER Steam and Condensate Piping		
Violations	No violations recorded	
Steam Condensate Return Piping	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Steam Condensate Return Pumping System	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Steam Piping	Inspected	
Condition	3- Fair	
Deficiency	DEFECTIVE/LEAKS	
Deficiency Location/Instance	MER B51, Rooms B40, 330	
Deficiency Quantity	30	
Quantity Uom	L.F.	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Terminal Unit Thermostatic Trap	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Steam supplied by External Sources	Does not exist	
Unit Heater/Cabinet Heater	Does not exist	
HEATING PLANT	Inspected	
Instance on Basement	Under construction	
Enclosed IDF Room	Inspected	
Instance on Room 218	Inspected	
Dedicated A/C Equipment		
Instance on Room 218	Inspected	
Instance Condition	4- Between Fair and Poor	
Deficiency	DOES NOT EXIST	
Deficiency Location/Instance	Room 218	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	INSTALL	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
KITCHEN	Inspected	
Instance on 1st Floor	Inspected	
CO Detector	•	
Instance on 1st Floor	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Gas System		
Instance on 1st Floor	Inspected	
Instance Condition	4- Between Fair and Poor	
Deficiency	DEFECTIVE MASTER GAS CONTROL VALVE	
Deficiency Deficiency Location/Instance	Kitchen	
Deficiency Quantity	Kitchen 1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 5	

Question	Response	
KITCHEN		
Gas System		
Purpose of Action	LEVEL 6	
Violations	No violations recorded	
Grease Trap		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Hood		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Hood Exhaust Ductwork		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Hood Exhaust Fan	2 451151515151454	
Instance on 1st Floor	Inspected	
Instance Condition	4- Between Fair and Poor	
Deficiency	DEFECTIVE	
Deficiency Location/Instance	Closet inside the Kitchen	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Hood Fire Suppression System		
Instance on 1st Floor	Does not exist	
Hot Water Temperature Booster		
Instance on 1st Floor	Does not exist	
Kitchen Sink		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	Missing Air Gap	
Deficiency Location/Instance	Kitchen	
Deficiency Quantity	2	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
MDF Room	Inspected	
Instance on Room 129	Inspected	
Dedicated A/C Equipment	•	
Instance on Room 129	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
SCIENCE DEMO ROOM	Does not exist	
SCIENCE LAB	Does not exist	
SCIENCE PREP ROOM	Does not exist	
SPRINKLERS, STANDPIPE, FIRE SYSTEM	Inspected	
Dry Sprinkler Alarm Valve Assembly	Does not exist	
Wet Sprinkler Alarm Valve Assembly	Inspected	

Building Condition Assessment Survey 2023-2024

Mechanical Inspection X111

unicui Inspection		AIII
uestion	Response	
SPRINKLERS, STANDPIPE, FIRE SYSTEM		
Wet Sprinkler Alarm Valve Assembly		
Deficiency	No deficiencies recorded	
Fire Booster Pump Assembly	Does not exist	
Roof Tank	Does not exist	
Siamese Connection	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Sprinkler Head	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Sprinkler Piping	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Standpipe System	Does not exist	
Water Gong	Does not exist	
SWIMMING POOL	Does not exist	
VENTILATION	Inspected	
Is the building Mechanically ventilated?	Partial	
Exhaust Fan	Inspected	
Condition	3- Fair	
Approximate Total # of Fans	1-25	
Deficiency	DEFECTIVE	
Deficiency Location/Instance	Main Roof, Lower Roof (9 of 24)	
Deficiency Quantity	9	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Heating And Ventilating Unit	Does not exist	
Metal Ductwork	Inspected	
Condition	3- Fair	
Are there any uninsulated ductwork by design in Mechanical rooms?	Yes	
Are there chain operated dampers?	No	
Deficiency	DEFECTIVE REGISTER/DIFFUSER	
Deficiency Location/Instance	Enclosed IDF Room 218	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Supply Fan	Inspected	
Condition	3- Fair	
Approximate Total # of Fans	1-5	
Deficiency	No deficiencies recorded	
Unit Ventilator	Does not exist	