Building Condition Assessment Survey 2023-2024

Mechanical Inspection X117

| Asset: | I.S. 117 - BRONX, 1865 MORRIS AVENUE, BRONX, NY, 10453 | | |
|---------------|--|--------------------|--------------------|
| Inspection Id | Inspection Type | Time In | Last Edited |
| 1553 | MECHANICAL | 2023-12-08 07:47AM | 2024-01-09 04:53PM |
| . D . | | | |

Kitchen 2014

Years:

No

Asset Data Question Answer Systems: Fixtures - Drinking Fountains Have any Systems/Major Building Components been upgraded? Years: Science Labs; Science Prep Room; Electric Domestic Systems: Water Heater for Science Labs; Kitchen - Gas System Years: F&T/Steam Drip Traps; Terminal Unit Thermostatic Systems: Traps; Toilet Rooms Fixtures (~90%) Years: Systems: Sump Pump; DX Split Systems for Cafeteria and

Total # of water main service entries to the asset

MERs/Fan Rooms Locations

Boiler Room Mechanical Area, Basement Mechanical Area,
Cafeteria MER

Are there any spaces with Missing or Defective CO Detectors?

Location(s)

Are there any Painted/Obstructed Sprinkler Heads?

Yes

Yes

Location(s)

Auditorium Stage; Rooms 128, 130, 132, 331, 334A, 427

(painted, 50)
Are there any Emergency Stop Switches with Missing Hammers? No components

Priority Condition

Are there fuel tanks?

| Exist Last Year? | Priority Category | Condition Description | Component Affected | Location Description | Person(s) Notified | Person(s) Title | Photo Image |
|---------------------|--|---------------------------------------|-----------------------|-------------------------------------|-----------------------|--------------------|----------------|
| Yes | Defective Sprinkler/Standpipe System | Defective/Leaking | Sprinkler Piping | Boiler Room Exit by Stair "C" | Alcindo Fernandes | Fireman | |
| Yes | Defective Kitchen Gas System | Defective Master Gas Control Valve | Gas System | Kitchen | Alcindo Fernandes | Fireman | - CAS |

Inspection

| Question | Response | |
|---|--------------------------|--|
| Mechanical | | |
| AIR CONDITIONING | Inspected | |
| Chilled Water System | Does not exist | |
| Condenser Water Distribution: Piping, Pumps and Auxiliaries | Does not exist | |
| Cooling Coil in Ductwork | Does not exist | |
| Cooling Tower | Does not exist | |
| DX Split System | Inspected | |
| Indoor Unit | Inspected | |
| Condition | 2- Between Good and Fair | |
| Deficiency | No deficiencies recorded | |
| Outdoor Unit | Inspected | |
| Condition | 2- Between Good and Fair | |

Building Condition Assessment Survey 2023-2024

| anicai inspection | X |
|---|--|
| uestion | Response |
| AIR CONDITIONING | |
| DX Split System | |
| Outdoor Unit | |
| Deficiency | No deficiencies recorded |
| Dry Cooler | Does not exist |
| Packaged / Rooftop Unit | Does not exist |
| Packaged Terminal A/C | Does not exist |
| Refrigerant Leak Detection System | Does not exist |
| Refrigerant Piping | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Return Fan | Does not exist |
| CENTRAL ACID WASTE NEUTRALIZING TANK | Does not exist |
| CLIMATE CONTROL SYSTEM | Inspected |
| BMS | Does not exist |
| Pneumatic System | Inspected |
| Instance | Throughout |
| Instance Condition | 3- Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Building Area Covered by Operational System | 41-60% |
| Deficiency | DEFECTIVE TEMPERATURE CONTROL THERMOSTAT |
| Deficiency Location/Instance | Various Locations |
| Deficiency Quantity | 30 |
| Quantity Uom | EACH |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Hybrid System | Does not exist |
| Electric System | Does not exist |
| COMPACTOR | Does not exist |
| | Does not exist |
| CONVEYING | |
| DOMESTIC WATER SYSTEM | Inspected |
| Domestic Cold Water System | Inspected |
| Gravity System | Does not exist |
| Pressure Booster System | Does not exist |
| Water Service | Inspected |
| Instance | Basement Mechanical Area, Boiler Room |
| Instance Condition | 3- Fair |
| Instance Quantity | 2 |
| Instance Quantity Uom | EACH |
| Deficiency | No deficiencies recorded |
| Domestic Hot Water System | Inspected |
| Domestic Hot Water Remote Storage Tank | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Domestic Water Heat Exchanger | Does not exist |
| Electric Domestic Water Heater | Inspected |
| Condition | 2- Between Good and Fair |
| | No deficiencies recorded |
| Deficiency | |
| Gas Fired Domestic Water Heater | Inspected |
| Instance | Boiler Room |

Building Condition Assessment Survey 2023-2024

| Mechanical Inspection | X117 |
|-----------------------|------|
| | |

| Question | Response |
|---|---------------------------------------|
| DOMESTIC WATER SYSTEM | |
| Domestic Hot Water System | |
| Gas Fired Domestic Water Heater | |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Manufacturer | Rheem / Ruud |
| EquipmentId | N/A |
| Capacity/Size Quantity | 399 |
| Capacity/Size UOM | MBH Input 0 |
| Capacity/Size 2 Quantity Capacity/Size 2 UOM | 0 Gallons |
| Source of Capacity/Size | Documented |
| Installation Year | 2011 |
| Source of Installation Year | Documented |
| Deficiency | No deficiencies recorded |
| Oil Fired Domestic Water Heater | Does not exist |
| Heat Pump Domestic Water Heater | Does not exist |
| Domestic Water Distribution Piping | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| DRAIN/WASTE/VENT AND STORM SYSTEM | Inspected |
| Interior Storm Piping | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Sewage/Waste/Vent Piping | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Sewage Ejector Pump | Does not exist |
| Sump Pump | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER) | Does not exist |
| FIXTURES | Inspected |
| Staff And Other | Inspected |
| Janitor Sink | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Lavatory/Sink | Inspected |
| Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| Toilet | Inspected |
| Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| Urinal | Inspected |
| Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| Student | Inspected |
| Drinking Fountain | Inspected |
| Condition | 1- Good |
| Deficiency | DEFECTIVE AUXILIARY (FAUCET, SHUT OFF |
| | VALVE,ETC.) |
| Deficiency Location/Instance | Room 306A |
| Deficiency Quantity | 1 FACH |
| Quantity Uom Potential Action | EACH MAINTENANCE |
| | MAINTENANCE Print Data 9/9/2024 |

Building Condition Assessment Survey 2023-2024

| писан і пярестоп | XII |
|-------------------------------|--|
| estion | Response |
| IXTURES | |
| Student | |
| Drinking Fountain | |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Lavatory/Sink | Inspected |
| Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| Locker Room Shower | Inspected |
| Instance on 3rd Floor - Girls | Inaccessible |
| Instance on 4th Floor - Boys | Inaccessible |
| Sink And Fountain Combo Unit | Does not exist |
| Toilet | Inspected |
| Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| Urinal | Inspected |
| Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| • | Does not exist |
| GAS FIRED FURNACE | |
| SAS SERVICE | Inspected |
| Gas Distribution Piping | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Gas Meter Room Exhaust Fan | Does not exist |
| Gas Meter Room Vent | Does not exist |
| Gas Pressure Booster | Does not exist |
| CO/Gas Leak Detection | Does not exist |
| IEATING | Inspected |
| Heating Coil In Ductwork | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Hydronic Heating | Does not exist |
| Radiator/Convector/Fin Tube | Inspected |
| Condition | 3- Fair |
| Deficiency | AUXILIARY (VALVE, VENT): DEFECTIVE |
| Deficiency Location/Instance | Corridor near Room 233 |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Deficiency | RADIATOR/CONVECTOR: DAMAGED GUARD/SHIELD |
| Deficiency Location/Instance | Library, 3rd Floor Gymnasium Office |
| Deficiency Quantity | 2 |
| Quantity Uom | EACH |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Steam Heating | Inspected |
| F&T/Steam Drip Trap | Inspected |
| Condition | 2- Between Good and Fair |

Building Condition Assessment Survey 2023-2024

| Response |
|---|
| |
| |
| |
| No deficiencies recorded |
| Inspected |
| 3- Fair |
| DAMAGED/MISSING INSULATION |
| Boiler Room Mechanical Area, Basement Mechanical Area, Cafeteria MER |
| 100 |
| L.F. |
| MAINTENANCE |
| PRIORITY 3 |
| LEVEL 2 |
| No violations recorded |
| DEFECTIVE/LEAKS |
| Basement Mechanical Area |
| 10 |
| L.F. |
| REPLACE |
| PRIORITY 3 |
| LEVEL 2 |
| No violations recorded |
| Inspected |
| 3- Fair |
| DEFECTIVE/LEAKS |
| Boiler Room Mechanical Area; Toilet Room inside Basement Mechanical Area |
| 20 |
| L.F. |
| REPLACE |
| PRIORITY 3 |
| LEVEL 2 |
| No violations recorded |
| Under construction |
| Inspected |
| 3- Fair |
| DEFECTIVE/LEAKS |
| Boiler Room Mechanical Area, Corridor near Room 133 |
| 20 |
| L.F. |
| REPLACE |
| PRIORITY 3 |
| LEVEL 2 |
| No violations recorded |
| Inspected |
| 2- Between Good and Fair |
| No deficiencies recorded |
| Does not exist |
| Does not exist |
| Inspected |
| Under construction |
| Inspected |
| Inspected |
| |

Building Condition Assessment Survey 2023-2024

| meui Inspection | All |
|---|------------------------------------|
| estion | Response |
| nclosed IDF Room | |
| Dedicated A/C Equipment | |
| Instance on Room 320A | Inspected |
| Instance Condition | 5- Poor |
| Deficiency | DEFECTIVE/DETERIORATED |
| Deficiency Location/Instance | Room 320A (Window A/C) |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| TTCHEN | Inspected |
| Instance on Basement | Inspected |
| CO Detector | nispected |
| Instance on Basement | Inspected |
| Instance Condition | 1- Good |
| | No deficiencies recorded |
| Deficiency | No deficiencies recorded |
| Gas System | |
| Instance on Basement | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | DEFECTIVE MASTER GAS CONTROL VALVE |
| Deficiency Location/Instance | Kitchen |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 5 |
| Purpose of Action | LEVEL 6 |
| Violations | No violations recorded |
| Grease Trap | |
| Instance on Basement | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Hood | |
| Instance on Basement | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Hood Exhaust Ductwork | 110 031101101101101101 |
| Instance on Basement | Inspected |
| | 3- Fair |
| Instance Condition | |
| Deficiency | No deficiencies recorded |
| Hood Exhaust Fan | |
| Instance on Basement | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Hood Fire Suppression System | |
| Instance on Basement | Inspected |
| Instance Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| | |
| Hot Water Temperature Booster | |
| Hot Water Temperature Booster Instance on Basement | Does not exist |
| Instance on Basement | Does not exist |
| Instance on Basement Kitchen Sink | |
| Instance on Basement | Inspected 3- Fair |

Building Condition Assessment Survey 2023-2024

| uestion | Response | |
|---------------------------------|--------------------------|--|
| MDF Room | Inspected | |
| Instance on Room 108 | Inspected | |
| Dedicated A/C Equipment | mspeeced | |
| Instance on Room 108 | Inspected | |
| Instance Condition | 4- Between Fair and Poor | |
| Deficiency | DEFECTIVE | |
| Deficiency Location/Instance | Room 108 | |
| Deficiency Quantity | 1 | |
| Quantity Uom | EACH | |
| Potential Action | MAINTENANCE | |
| Urgency of Action | PRIORITY 3 | |
| Purpose of Action | LEVEL 2 | |
| Violations | No violations recorded | |
| SCIENCE DEMO ROOM | Does not exist | |
| | | |
| SCIENCE LAB | Inspected | |
| Instance on Rooms 221, 319, 419 | Inspected | |
| Alternative Use | No | |
| Acid Waste Neutralizing Tank | | |
| Instance on Rooms 221, 319, 419 | Inspected | |
| Instance Condition | 1- Good | |
| Deficiency | No deficiencies recorded | |
| CO Detector | | |
| Instance on Rooms 221, 319, 419 | Inspected | |
| Instance Condition | 4- Between Fair and Poor | |
| Deficiency | DEFECTIVE/MISSING | |
| Deficiency Location/Instance | Rooms 221, 319, 419 | |
| Deficiency Quantity | 3 | |
| Quantity Uom | EACH | |
| Potential Action | MAINTENANCE | |
| Urgency of Action | PRIORITY 5 | |
| Purpose of Action | LEVEL 6 | |
| Violations | No violations recorded | |
| Emergency Shower | | |
| Instance on Rooms 221, 319, 419 | Does not exist | |
| Eye Wash | | |
| Instance on Rooms 221, 319, 419 | Inspected | |
| Instance Condition | 1- Good | |
| Deficiency | No deficiencies recorded | |
| Hood Exhaust Ductwork | | |
| Instance on Rooms 221, 319, 419 | Does not exist | |
| Hood Exhaust Fan | | |
| Instance on Rooms 221, 319, 419 | Does not exist | |
| Fixed Laboratory Hood | | |
| Instance on Rooms 221, 319, 419 | Does not exist | |
| Laboratory Sink | | |
| Instance on Rooms 221, 319, 419 | Inspected | |
| Instance Condition | 1- Good | |
| Deficiency | No deficiencies recorded | |
| | 140 deficiences recorded | |
| Make-up Air Unit | Does not exist | |
| Instance on Rooms 221, 319, 419 | | |
| SCIENCE PREP ROOM | Inspected | |
| Instance on Room 321 | Inspected | |
| Alternative Use | No | |
| Acid Waste Neutralizing Tank | | |

Building Condition Assessment Survey 2023-2024

| estion | Response |
|------------------------------------|---|
| SCIENCE PREP ROOM | |
| Acid Waste Neutralizing Tank | |
| Instance Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| CO Detector | |
| Instance on Room 321 | Inspected |
| Instance Condition | 4- Between Fair and Poor |
| Deficiency | DEFECTIVE/MISSING |
| Deficiency Location/Instance | Room 321 |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 5 |
| Purpose of Action | LEVEL 6 |
| Violations | No violations recorded |
| Emergency Shower | |
| Instance on Room 321 | Does not exist |
| Eye Wash | |
| Instance on Room 321 | Does not exist |
| Hood Exhaust Ductwork | |
| Instance on Room 321 | Does not exist |
| Hood Exhaust Fan | |
| Instance on Room 321 | Does not exist |
| Fixed Laboratory Hood | |
| Instance on Room 321 | Does not exist |
| Laboratory Sink | |
| Instance on Room 321 | Inspected |
| Instance Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| Make-up Air Unit | |
| Instance on Room 321 | Does not exist |
| PRINKLERS, STANDPIPE, FIRE SYSTEM | Inspected |
| Dry Sprinkler Alarm Valve Assembly | Does not exist |
| Wet Sprinkler Alarm Valve Assembly | Does not exist |
| Fire Booster Pump Assembly | Does not exist |
| Roof Tank | Does not exist |
| Siamese Connection | Does not exist |
| Sprinkler Head | Inspected |
| Condition | 3- Fair |
| Deficiency | DEFECTIVE/DETERIORATED |
| Deficiency Location/Instance | Auditorium Stage; Rooms 128, 130, 132, 331, 334A, 427 |
| | (painted, 50) |
| Deficiency Quantity | 50 |
| Quantity Uom | EACH |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 5 |
| Purpose of Action | LEVEL 6 |
| Violations | No violations recorded |
| Sprinkler Piping | Inspected |
| Condition | 3- Fair |
| Deficiency | DEFECTIVE/LEAKS |
| Deficiency Location/Instance | Boiler Room Exit by Stair "C" |
| Deficiency Quantity | 10 |
| Quantity Uom | L.F. |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 5 |

Building Condition Assessment Survey 2023-2024

| unicui Inspection | |
|---|--|
| uestion | Response |
| SPRINKLERS, STANDPIPE, FIRE SYSTEM | |
| Sprinkler Piping | |
| Purpose of Action | LEVEL 6 |
| Violations | No violations recorded |
| Standpipe System | Does not exist |
| Water Gong | Does not exist |
| WIMMING POOL | Does not exist |
| | |
| VENTILATION | Inspected |
| Is the building Mechanically ventilated? | Yes |
| Exhaust Fan | Inspected 3- Fair |
| Condition | |
| Approximate Total # of Fans | 1-25 |
| Deficiency | No deficiencies recorded |
| Heating And Ventilating Unit | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Metal Ductwork | Inspected |
| Condition | 3- Fair |
| Are there any uninsulated ductwork by design in Mechanical rooms? | Yes |
| Are there chain operated dampers? | No |
| Deficiency | DAMAGED FLEXIBLE CONNECTION |
| Deficiency Location/Instance | Basement Mechanical Area @ EF #5 |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Deficiency | DEFECTIVE REGISTER/DIFFUSER |
| Deficiency Location/Instance | 3rd Floor Gymnasium |
| Deficiency Quantity | 6 |
| Quantity Uom | EACH |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Supply Fan | Inspected |
| Condition | 3- Fair |
| Approximate Total # of Fans | 1-5 |
| Deficiency | DEFECTIVE |
| Deficiency Location/Instance | |
| Deficiency Quantity | Basement Mechanical Area / Auditorium Blower (bearing) |
| | 1 EACH |
| Quantity Uom Potential Action | EACH MAINTENIANCE |
| | MAINTENANCE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Unit Ventilator | Inspected |
| Condition | 3- Fair |