

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X118

Asset: I.S. 118 - BRONX, 577 EAST 179 STREET, BRONX, NY, 10457

Inspection Id	Inspection Type	Time In	Last Edited
1741	ELECTRICAL	2023-12-18 08:35AM	2024-01-12 02:47PM

Asset Data

Question	Answer
Have any Systems/Major Building Components been upgraded?	Systems: Security Lights Years: 2023, 2010 Systems: LAN, Service Switch, Switchboard, Grounding System, IPDVS/CCTV System, Cafeteria (Lighting) Years: 2023 Systems: Most Exit Lights, Battery Pack Emergency Lights, Gymnasium (LED Lighting), Auditorium (Projection System, Local Sound System, Theater Lighting System) Years: 2022 Systems: Most Molded Case Circuit Breaker Panel Board Years: 2021, 2005, 2003, 1995 Systems: Partial Non Battery Emergency Lights Years: 2014 Systems: Most Motor Starters Years: 2012, 2009, 2003 Systems: Library (Lighting) Years: 2010 Systems: Interior Lighting, Gymnasium - HID Lighting Years: 2008 Systems: Telephone System Years: 2007 Systems: Local Sound System - Gymnasium and Cafeteria Years: 2006 Systems: Emergency Light/Exit Lighting Panel, Partial Fused Disconnect Panelboards, Fire Alarm System - Sub Panel, Elevator Recall, Fused Cutout Panel, Lightning Protection, Elevator - Intercom Years: 2003 Systems: Fire Alarm System - Remote Annunciator Years: 1998 Systems: Intrusion Alarm System, Public Address System Years: 1990 Type of Service Below Ground Does Interactive Whiteboard (IWB) Exist? Yes Water Penetration In Electrical Room? Yes

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	Yes
Are dedicated intercoms available in all of these spaces for use during a fire?	Yes
Are all dedicated intercoms operational?	Yes

Priority Condition

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
Yes	Intercom - Not Connected to Remote Monitoring Station	N/A	Intercom System - Elevator	Elevator Device ID: 2P10411	Zaheer Kalamadeen	Custodian	No Photo Taken
No	Water Penetration in Electrical Room	N/A	Electrical Equipment	Electrical Room	Zaheer Kalamadeen	Custodian	No Photo Taken

Inspection

Question	Response
----------	----------

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X118

Question	Response
Electrical	
ATHLETIC FIELD	Does not exist
AUDITORIUM	Inspected
Instance on 1st Floor	Inspected
House Lighting	
Instance on 1st Floor	Inspected
Does a Chandelier Exist?	Yes
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on 1st Floor	Does not exist
Recessed Mounted	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not exist
Local Sound System	
Instance on 1st Floor	Inspected
Instance Condition	1- Good
Installation Year	2022
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Projection System	
Instance on 1st Floor	Inspected
Instance Condition	1- Good
Is the projector on a cart or installed on the ceiling?	Ceiling
Deficiency	No deficiencies recorded
Theater Lighting System	
Instance on 1st Floor	Inspected
Dimming System	
Instance on 1st Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Theater Lighting	
Instance on 1st Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
CAFETERIA	Inspected
Instance on Basement	Inspected
Lighting	
Instance on Basement	Inspected
Lighting Fixture - Fluorescent	
Instance on Basement	Does not exist
Lighting Fixture - HID	
Instance on Basement	Does not exist
Lighting Fixture - Incandescent	
Instance on Basement	Does not exist

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X118

Question	Response
CAFETERIA	
Lighting	
Lighting Fixture - LED	
Instance on Basement	Inspected
Pendant Mounted	
Instance on Basement	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Basement	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Basement	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Local Sound System	
Instance on Basement	Inspected
Instance Condition	3- Fair
Installation Year	2006
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Projection System	
Instance on Basement	Does not exist
Theater Lighting System	
Instance on Basement	Does not exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	
Pendant Mounted	
Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Lighting Fixture - HID	
Lighting Fixture - Incandescent	
Lighting Fixture - LED	
COMPUTER LAB	
GYMNASIUM	
Instance on 4th Floor	Inspected
Instance on 3rd Floor	Inspected
Lighting	
Instance on 4th Floor	Inspected
Instance on 3rd Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 4th Floor	Does not exist
Instance on 3rd Floor	Does not exist
Lighting Fixture - HID	
Instance on 4th Floor	Inspected
Instance on 3rd Floor	Inspected
Pendant Mounted	

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X118

Question	Response
GYMNASIUM	
Lighting	
Lighting Fixture - HID	
Pendant Mounted	
Instance on 4th Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on 3rd Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on 4th Floor	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance on 3rd Floor	Does not exist
Recessed Mounted	
Instance on 4th Floor	Does not exist
Instance on 3rd Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 4th Floor	Does not exist
Instance on 3rd Floor	Does not exist
Lighting Fixture - LED	
Instance on 4th Floor	Inspected
Instance on 3rd Floor	Inspected
Pendant Mounted	
Instance on 4th Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Instance on 3rd Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on 4th Floor	Does not exist
Instance on 3rd Floor	Does not exist
Recessed Mounted	
Instance on 4th Floor	Does not exist
Instance on 3rd Floor	Does not exist
Local Sound System	
Instance on 4th Floor	Inspected
Instance Condition	3- Fair
Installation Year	2006
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance on 3rd Floor	Inspected
Instance Condition	3- Fair
Installation Year	2006
Source of Installation Year	Documented
Deficiency	No deficiencies recorded

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X118

Question	Response
GYMNASIUM	
Projection System	
Instance on 4th Floor	Does not exist
Instance on 3rd Floor	Does not exist
Scoreboard	
Instance on 4th Floor	Does not exist
Instance on 3rd Floor	Does not exist
Theater Lighting System	
Instance on 4th Floor	Does not exist
Instance on 3rd Floor	Does not exist
KITCHEN	
Instance on Basement	Inspected
Lighting	
Instance on Basement	Inspected
Lighting Fixture - Fluorescent	
Instance on Basement	Inspected
Pendant Mounted	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Basement	Does not exist
Recessed Mounted	
Instance on Basement	Does not exist
Lighting Fixture - HID	
Instance on Basement	Does not exist
Lighting Fixture - Incandescent	
Instance on Basement	Does not exist
Lighting Fixture - LED	
Instance on Basement	Does not exist
LIBRARY	
Instance on Room 315	Inspected
Lighting	
Instance on Room 315	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 315	Inspected
Pendant Mounted	
Instance on Room 315	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 315	Does not exist
Recessed Mounted	
Instance on Room 315	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Room 315	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 315	Inspected
Pendant Mounted	
Instance on Room 315	Does not exist
Surface Mounted	
Instance on Room 315	Inspected

NYC Department of Education
Building Condition Assessment Survey 2023-2024

Electrical Inspection

X118

Question	Response
LIBRARY	
Lighting	
Lighting Fixture - Incandescent	
Surface Mounted	
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Room 315	Does not exist
Lighting Fixture - LED	
Instance on Room 315	Does not exist
Raceway With Receptacles	
Instance on Room 315	Does not exist
Projection System	
Instance on Room 315	Does not exist
LOCKER ROOM	
Instance on 4th Floor	Inspected
	Inaccessible
MULTIPURPOSE ROOM	
Instance on 1st Floor	Inspected
	Inspected
Lighting	
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor	Does not exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not exist
Local Sound System	
Instance on 1st Floor	Does not exist
Projection System	
Instance on 1st Floor	Does not exist
Theater Lighting System	
Instance on 1st Floor	Does not exist
SCIENCE DEMO ROOM	
Instance on Room 423	Inspected
Power Panel?	Inspected
Alternative Use	Yes
	Yes
Lighting	
Instance on Room 423	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 423	Inspected
Pendant Mounted	
Instance on Room 423	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X118

Question	Response
SCIENCE DEMO ROOM	
Lighting	
Lighting Fixture - Fluorescent	
Surface Mounted	
Instance on Room 423	Does not exist
Recessed Mounted	
Instance on Room 423	Does not exist
Lighting Fixture - HID	
Instance on Room 423	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 423	Does not exist
Lighting Fixture - LED	
Instance on Room 423	Does not exist
Emergency Gas Shut-Off Valve	
Instance on Room 423	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	
Instance on Room 423	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Power Supply	
Instance on Room 423	Does not exist
Projection System	
Instance on Room 423	Does not exist
SCIENCE LAB	
Instance on Room 419	Inspected
Power Panel?	Yes
Alternative Use	No
Lighting	
Instance on Room 419	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 419	Inspected
Pendant Mounted	
Instance on Room 419	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 419	Does not exist
Recessed Mounted	
Instance on Room 419	Does not exist
Lighting Fixture - HID	
Instance on Room 419	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 419	Does not exist
Lighting Fixture - LED	
Instance on Room 419	Does not exist
Emergency Gas Shut-Off Valve	
Instance on Room 419	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	
Instance on Room 419	Inspected
Instance Condition	3- Fair

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X118

Question	Response
SCIENCE LAB	
Emergency Shut-Off Power	
Deficiency	No deficiencies recorded
Power Supply	
Instance on Room 419	Does not exist
Projection System	
Instance on Room 419	Does not exist
SCIENCE PREP ROOM	Inspected
Instance on Room 414	Inaccessible
SWIMMING POOL	Does not exist
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Condition	5- Poor
Deficiency	BELL TRANSFORMER PANEL NOT OPERATIONAL
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE PANEL
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not exist
EMERGENCY GENERATOR SET	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Condition	3- Fair
Deficiency	LESS THAN 20% SPARE CIRCUIT BREAKERS
Deficiency Location/Instance	Outside Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL NEW PANEL BOARD
Urgency of Action	PRIORITY 5

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X118

Question	Response
EMERGENCY LIGHT/EXIT LIGHT PANEL	
Purpose of Action	LEVEL 2
Violations	No violations recorded
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Non Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Non Battery Pack	Does not exist
EXIT/EMERGENCY LIGHT	Does not exist
FIRE ALARM SYSTEM	Inspected
Bell/Horn	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Strobe	Does not exist
Manual Pull Station	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	Does not exist
Duct Smoke Detector	Does not exist
Area Smoke Detector	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
CO Detector	Does not exist
Heat Detector	Does not exist
Elevator Recall	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Magnetic Door Holder/Contactor	Does not exist
Fused Cutout Panel	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	Does not exist
Main Panel	Inspected
Bell At Panel	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Does not exist
Fire Alarm Control Panel (Standard)	Inspected
Instance	Boiler Room Adjacent to Electrical Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Faraday
EquipmentId	Fire Alarm
Installation Year	1938
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X118

Question	Response
FIRE ALARM SYSTEM	
Main Panel	
Fire Alarm Control Panel (Standard)	
Deficiency Location/Instance	Boiler Room Adjacent to Electrical Room
Deficiency Quantity	93,000
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Sub-Panel	Inspected
Bell At Panel	Does not exist
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Boiler Room Adjacent to Electrical Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Notifier
Model	AFP-400
EquipmentId	Interior Fire Alarm
Installation Year	2003
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	Does not exist
Remote Annunciator	Inspected
Display Monitor	Does not exist
Panel	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Printer	Does not exist
Punch Register	Does not exist
Sprinkler Flow/Air Pressure Switch	Does not exist
Tamper Flow Switch/Chain	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	
Condition	1- Good
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	
Elevator	Inspected
Condition	3- Fair
Deficiency	NOT CONNECTED TO REMOTE MONITORING STATION
Deficiency Location/Instance	Elevator Device ID: 2P10411
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL CONNECTION
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Holding Area	Does not exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X118

Question	Response
LAN	
Main Equipment Rack (MDF)	
Condition	1- Good
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	
Condition	Inspected
Deficiency	3- Fair
MOTOR CONTROLLER	
Condition	Inspected
MOTOR CONTROL CENTER	
Condition	Does not exist
MOTOR STARTER/CONTACTOR	
Condition	Inspected
Deficiency	3- Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	
Condition	Does not exist
PANEL BOARD	
Condition	Inspected
Fused Disconnect Switch Type	
Condition	Inspected
Deficiency	3- Fair
Deficiency	No deficiencies recorded
Fused Knife Switch Type	
Condition	Inspected
Deficiency	3- Fair
Deficiency Location/Instance	PANEL BOARD BEYOND USEFUL LIFE Boiler Room, Boiler Room Mechanical Area, Cafeteria Mechanical Room
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fused Toggle Switch Type	
Condition	Inspected
Deficiency	3- Fair
Deficiency Location/Instance	PANEL BOARD BEYOND USEFUL LIFE Throughout the Building
Deficiency Quantity	13
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Molded Case Circuit Breaker Type	
Condition	Inspected
Deficiency	3- Fair
Deficiency Location/Instance	PANEL BOARD BEYOND USEFUL LIFE Electrical Room
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
PUBLIC ADDRESS SYSTEM	
Instance	Inspected
Instance Condition	Principal's Office - Room 209
Instance Quantity	3- Fair
Instance Quantity Uom	1
Model	EACH
Installation Year	Dukane MACS 1990

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X118

Question	Response
PUBLIC ADDRESS SYSTEM	
Source of Installation Year	Documented
Deficiency	CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Throughout the Building
Deficiency Quantity	20
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Principal's Office - Room 209
Deficiency Quantity	93,000
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
SECURITY	Inspected
IPDVS/CCTV System	Inspected
Condition	1- Good
Installation Year	2023
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	Room 108
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	4140 XMPT
Installation Year	1990
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Room 108
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 3
Violations	No violations recorded
Infrared Sensor	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting - Security	Inspected
Condition	2- Between Good and Fair

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X118

Question	Response
SECURITY	
Lighting - Security	
Deficiency	No deficiencies recorded
SERVICE SWITCH	
	Inspected
Instance	Electrical Room
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	All City Switchboard
EquipmentId	Service Switch #1
Capacity/Size Quantity	2500
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2023
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
SWITCHBOARD	
	Inspected
Number of Spares	4
Fused Disconnect Switch Type	
	Inspected
Instance	Electrical Room
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	All City Switchboard
EquipmentId	Distribution Panel Sections #1, 2, 3
Capacity/Size Quantity	1500
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	3
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	2023
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fused Knife Switch Type	
	Does not exist
Molded Case Circuit Breaker Type	
	Does not exist
TELEPHONE SYSTEM	
	Inspected
PBX/Intercom	
	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Standard	
	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
TRANSFORMER	
	Does not exist