

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X129

Asset: I.S. 129 (PAIRED W P234) - BRONX, 2055 MAPES AVENUE, BRONX, NY, 10460

Inspection Id	Inspection Type	Time In	Last Edited
3950	ELECTRICAL	2024-03-12 09:30AM	2024-04-05 03:29PM

Asset Data

Question	Answer
Have any Systems/Major Building Components been upgraded?	Systems: Partial Molded Case Circuit Breaker Panel Board Years: 2023, 2011, 2000, 1990 Systems: Intrusion Alarm System (Panic Switch) Years: 2023 Systems: IPDVS/CCTV System, LAN Years: 2022 Systems: Security Lighting Years: 2018 Systems: Intrusion Alarm System Years: 2016 Systems: Interior Fluorescent Lighting (Except Science Lab Room 431, Science Prep Room 429, Auditorium), Emergency/Exit Lights Years: 2013 Systems: Science Lab Room 431, Science Prep Room 429 Years: 2012 Systems: Fire Alarm System, Local Sound System, Public Address System Years: 2009 Systems: Auditorium (House Lighting, Theater Lighting System) Years: 2008 Systems: Emergency Light/Exit Light Panel Years: 1990
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration In Electrical Room?	No

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	No

Priority Condition

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
No	Water Leaks onto Electrical Equipment	Pipe Leak	Lighting Fixture	Kitchen Office	Gabriel Orta	Fireman	No Photo Taken
Yes	Fire Alarm System - Components Not Operational	N/A	Fire Alarm System - Sprinkler Flow/Air Pressure Switch	Room C18	Marcos Ramos	Custodian	No Photo Taken

Inspection

Question	Response
Electrical	
ATHLETIC FIELD	Does not exist
AUDITORIUM	Inspected
Instance on 1st Floor	Inspected
House Lighting	
Instance on 1st Floor	Inspected
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X129

Question	Response
AUDITORIUM	
House Lighting	
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	10
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Surface Mounted	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not exist
Local Sound System	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Installation Year	2009
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Projection System	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Is the projector on a cart or installed on the ceiling?	Ceiling
Deficiency	No deficiencies recorded
Theater Lighting System	
Instance on 1st Floor	Inspected
Dimming System	
Instance on 1st Floor	Inspected
Instance Condition	4- Between Fair and Poor
Deficiency	DIMMING RACK/LIGHT CONSOLE NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Theater Lighting	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X129

Question	Response
CAFETERIA	Inspected
Instance on Rooms 127, 134	Inspected
Lighting	
Instance on Rooms 127, 134	Inspected
Lighting Fixture - Fluorescent	
Instance on Rooms 127, 134	Inspected
Pendant Mounted	
Instance on Rooms 127, 134	Does not exist
Surface Mounted	
Instance on Rooms 127, 134	Does not exist
Recessed Mounted	
Instance on Rooms 127, 134	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Rooms 127, 134	Does not exist
Lighting Fixture - Incandescent	
Instance on Rooms 127, 134	Does not exist
Lighting Fixture - LED	
Instance on Rooms 127, 134	Does not exist
Local Sound System	
Instance on Rooms 127, 134	Inspected
Instance Condition	3- Fair
Installation Year	2009
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Projection System	
Instance on Rooms 127, 134	Does not exist
Theater Lighting System	
Instance on Rooms 127, 134	Does not exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected
Lighting	Inspected
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
COMPUTER LAB	Inspected
Instance on Room 233	Inspected
Power Panel?	No
Instance on Room 333	Inspected
Power Panel?	Yes
Lighting	
Instance on Room 233	Inspected
Instance on Room 333	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X129

Question	Response
COMPUTER LAB	
Lighting	
Lighting Fixture - Fluorescent	
Instance on Room 233	Inspected
Instance on Room 333	Inspected
Pendant Mounted	
Instance on Room 233	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 333	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 233	Does not exist
Instance on Room 333	Does not exist
Recessed Mounted	
Instance on Room 233	Does not exist
Instance on Room 333	Does not exist
Lighting Fixture - HID	
Instance on Room 233	Does not exist
Instance on Room 333	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 233	Does not exist
Instance on Room 333	Does not exist
Lighting Fixture - LED	
Instance on Room 233	Does not exist
Instance on Room 333	Does not exist
Raceway With Receptacles	
Instance on Room 233	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 333	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
GYMNASIUM	
Instance on 1st Floor	Inspected
Lighting	
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Does not exist
Recessed Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X129

Question	Response
GYMNASIUM	
Lighting	
Lighting Fixture - LED	
Instance on 1st Floor	Does not exist
Local Sound System	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Installation Year	2009
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Projection System	
Instance on 1st Floor	Does not exist
Scoreboard	
Instance on 1st Floor	Does not exist
Theater Lighting System	
Instance on 1st Floor	Does not exist
KITCHEN	
Instance on 1st Floor	Inspected
Instance on 1st Floor	Inspected
Lighting	
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not exist
LIBRARY	
Instance on Room 344	Inspected
Instance on Room 344	Inspected
Lighting	
Instance on Room 344	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 344	Inspected
Pendant Mounted	
Instance on Room 344	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 344	Does not exist
Recessed Mounted	
Instance on Room 344	Does not exist
Lighting Fixture - HID	
Instance on Room 344	Does not exist

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X129

Question	Response
LIBRARY	
Lighting	
Lighting Fixture - Incandescent	
Instance on Room 344	Does not exist
Lighting Fixture - LED	
Instance on Room 344	Does not exist
Raceway With Receptacles	
Instance on Room 344	Does not exist
Projection System	
Instance on Room 344	Does not exist
LOCKER ROOM	
MULTIPURPOSE ROOM	
SCIENCE DEMO ROOM	
SCIENCE LAB	
Instance on Room 431	Inspected
Power Panel?	No
Alternative Use	No
Lighting	
Instance on Room 431	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 431	Inspected
Pendant Mounted	
Instance on Room 431	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 431	Does not exist
Recessed Mounted	
Instance on Room 431	Does not exist
Lighting Fixture - HID	
Instance on Room 431	Inspected
Pendant Mounted	
Instance on Room 431	Does not exist
Surface Mounted	
Instance on Room 431	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Room 431	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 431	Does not exist
Lighting Fixture - LED	
Instance on Room 431	Does not exist
Emergency Gas Shut-Off Valve	
Instance on Room 431	Does not exist
Emergency Shut-Off Power	
Instance on Room 431	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Power Supply	
Instance on Room 431	Inspected
Instructor Unit	
Instance on Room 431	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X129

Question	Response
SCIENCE LAB	
Power Supply	
Instructor Unit	
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Meter Demonstration Unit	
Instance on Room 431	Does not exist
Student Unit	
Instance on Room 431	Does not exist
Projection System	
Instance on Room 431	Does not exist
SCIENCE PREP ROOM	
Instance on Room 429	Inspected
Power Panel?	Inspected
Alternative Use	Yes
Lighting	
Instance on Room 429	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 429	Inspected
Pendant Mounted	
Instance on Room 429	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 429	Does not exist
Recessed Mounted	
Instance on Room 429	Does not exist
Lighting Fixture - HID	
Instance on Room 429	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 429	Does not exist
Lighting Fixture - LED	
Instance on Room 429	Does not exist
Emergency Gas Shut-Off Valve	
Instance on Room 429	Does not exist
Emergency Shut-Off Power	
Instance on Room 429	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Power Supply	
Instance on Room 429	Does not exist
SWIMMING POOL	
Instance on Room 429	Does not exist
TOILET ROOM - STAFF	
Instance on Room 429	Inspected
Lighting	
Instance on Room 429	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 429	Inspected
Pendant Mounted	
Instance on Room 429	Does not exist
Surface Mounted	
Instance on Room 429	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Room 429	Does not exist
Lighting Fixture - HID	
Instance on Room 429	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 429	Does not exist
Lighting Fixture - LED	
Instance on Room 429	Does not exist

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X129

Question	Response
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EMERGENCY GENERATOR SET	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD DOOR LOCK IS MISSING
Deficiency Location/Instance	Electrical Room C12
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	3- Fair
Deficiency	BATTERY NOT OPERATIONAL
Deficiency Location/Instance	By Exits 10, 2, By Stair A/2
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE BATTERY
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
Non Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EXIT/EMERGENCY LIGHT	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
FIRE ALARM SYSTEM	Inspected
Bell/Horn	Inspected

NYC Department of Education
Building Condition Assessment Survey 2023-2024

Electrical Inspection

X129

Question	Response
FIRE ALARM SYSTEM	
Bell/Horn	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Strobe	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Manual Pull Station	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Duct Smoke Detector	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Area Smoke Detector	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
CO Detector	Does not exist
Heat Detector	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Elevator Recall	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Magnetic Door Holder/Contactor	Does not exist
Fused Cutout Panel	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	Does not exist
Main Panel	Inspected
Bell At Panel	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Main Entrance Lobby - X129
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	General Electric
Model	EST 2
EquipmentId	Fire Alarm Control Panel
Installation Year	2009
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	Does not exist
Sub-Panel	Does not exist
Remote Annunciator	Inspected
Display Monitor	Does not exist
Panel	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Printer	Inspected
Condition	2- Between Good and Fair

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X129

Question	Response
FIRE ALARM SYSTEM	
Remote Annunciator	
Printer	
Deficiency	No deficiencies recorded
Punch Register	Does not exist
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	3- Fair
Deficiency	SWITCH NOT OPERATIONAL
Deficiency Location/Instance	Room C18
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Tamper Flow Switch/Chain	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	Inspected
Elevator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Holding Area	Does not exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Does not exist
MOTOR CONTROLLER	Inspected
MOTOR CONTROL CENTER	Does not exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Does not exist
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Under construction
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room C12
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Molded Case Circuit Breaker Type	Inspected
Condition	3- Fair

NYC Department of Education
Building Condition Assessment Survey 2023-2024

Electrical Inspection

X129

Question	Response
PANEL BOARD	
Molded Case Circuit Breaker Type	
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Throughout the Building
Deficiency Quantity	18
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	NO SPARE
Deficiency Location/Instance	Kitchen, Corridor near Room 334, 212
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PANEL BOARD DOOR LOCK IS MISSING
Deficiency Location/Instance	Corridor near Room C9
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
PUBLIC ADDRESS SYSTEM	Inspected
Instance	General Office - Room 143
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Telecor II
Installation Year	2009
Source of Installation Year	Documented
Deficiency	CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Classrooms and Corridors
Deficiency Quantity	10
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
SECURITY	Inspected
IPDVS/CCTV System	Inspected
Condition	1- Good
Installation Year	2022
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	Custodian's Office - Room 102
Instance Condition	2- Between Good and Fair
Instance Quantity	2
Instance Quantity Uom	EACH
Model	Vista 128BPT

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X129

Question	Response
SECURITY	
Intrusion Alarm System	
Central Control Panel	
Installation Year	2016
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Infrared Sensor	
	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Panic Switch	
	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Remote Annunciator	
	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Siren/Strobe	
	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting - Security	
	Inspected
Condition	2- Between Good and Fair
Deficiency	LIGHTING FIXTURE PHOTOCELL NOT OPERATIONAL
Deficiency Location/Instance	Building Perimeters
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 3
Violations	No violations recorded
SERVICE SWITCH	
	Inspected
Instance	Electrical Room C12
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Royal Switchboard Co.
EquipmentId	N/A
Capacity/Size Quantity	3000
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1971
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room C12
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
SWITCHBOARD	
	Inspected
Number of Spares	0
Fused Disconnect Switch Type	
	Inspected
Instance	Electrical Room C12
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X129

Question	Response
SWITCHBOARD	
Fused Disconnect Switch Type	
Manufacturer	Royal Switchboard Co.
EquipmentId	N/A
Capacity/Size Quantity	3000
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	3
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Service Switch Size
Installation Year	1971
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room C12
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fused Knife Switch Type	Does not exist
Molded Case Circuit Breaker Type	Does not exist
TELEPHONE SYSTEM	
PBX/Intercom	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
TRANSFORMER	Does not exist