

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X136

Asset: P.S. 186 (OLD J136) - BRONX, 750 JENNINGS STREET, BRONX, NY, 10459

Inspection Id	Inspection Type	Time In	Last Edited
487	ELECTRICAL	2023-10-26 08:18AM	2024-04-01 11:11AM

Asset Data

Question	Answer
Have any Systems/Major Building Components been upgraded?	Systems: Battery Pack Emergency Lights, LED Lighting in Rooms B38, 304 Years: 2022 Systems: Auditorium (Local Sound System, Projection System, Theater Lighting System) Years: 2021 Systems: Lightning Protection Years: 2020 Systems: Most Molded Case Circuit Breaker Panel Board Years: 2017, 2009, 1995, 1990 Systems: Telephone System, Intrusion Alarm System (Central Control Panel) Years: 2017 Systems: Exit/Emergency Lights, Exit Lights (Battery Packs), LAN Years: 2016 Systems: Interior Lighting (Except Library) Years: 2015 Systems: Fire Alarm System, Partial Motor Starters, Intercom System (Elevator, Fire Rescue Areas), Security Lights Years: 2014 Systems: Library Years: 2009 Systems: Switchboards Years: 1995, 1990 Systems: Partial Service Switches Years: 1995 Systems: Most Fused Disconnect Switch Type Panel Board, Public Address System, Emergency Light/Exit Light Panel Years: 1990 Type of Service Below Ground Does Interactive Whiteboard (IWB) Exist? Yes Water Penetration In Electrical Room? No

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	Yes
Are dedicated intercoms available in all of these spaces for use during a fire?	Yes
Are all dedicated intercoms operational?	No
Which rooms or areas have non-operational dedicated intercoms?	301

Priority Condition

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
No	Public Address System - Speakers Not Operational	Students and school personnel cannot hear any announcements in these locations.	Public Address System	Auditorium and 7 classrooms	Julio Peralta	Fireman	No Photo Taken

Inspection

Question	Response
Electrical ATHLETIC FIELD	Does not exist

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X136

Question	Response
AUDITORIUM	Inspected
Instance on 1st Floor	Inspected
House Lighting	
Instance on 1st Floor	Inspected
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor	Does not exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Does not exist
Recessed Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Local Sound System	
Instance on 1st Floor	Inspected
Instance Condition	4- Between Fair and Poor
Installation Year	2021
Source of Installation Year	Documented
Deficiency	AMPLIFIER NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Projection System	
Instance on 1st Floor	Inspected
Instance Condition	1- Good
Is the projector on a cart or installed on the ceiling?	Ceiling
Deficiency	No deficiencies recorded
Theater Lighting System	
Instance on 1st Floor	Inspected
Dimming System	

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X136

Question	Response
AUDITORIUM	
Theater Lighting System	
Dimming System	
Instance on 1st Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Theater Lighting	
Instance on 1st Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
CAFETERIA	
Instance on Basement - Students	Inspected
Instance on Basement - Staff	Inspected
Lighting	
Instance on Basement - Students	Inspected
Instance on Basement - Staff	Inspected
Lighting Fixture - Fluorescent	
Instance on Basement - Students	Inspected
Instance on Basement - Staff	Inspected
Pendant Mounted	
Instance on Basement - Students	Does not exist
Instance on Basement - Staff	Does not exist
Surface Mounted	
Instance on Basement - Students	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Basement - Staff	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Basement - Students	Does not exist
Instance on Basement - Staff	Does not exist
Lighting Fixture - HID	
Instance on Basement - Students	Does not exist
Instance on Basement - Staff	Does not exist
Lighting Fixture - Incandescent	
Instance on Basement - Students	Does not exist
Instance on Basement - Staff	Does not exist
Lighting Fixture - LED	
Instance on Basement - Students	Does not exist
Instance on Basement - Staff	Does not exist
Local Sound System	
Instance on Basement - Students	Inspected
Instance Condition	3- Fair
Installation Year	1990
Source of Installation Year	Inspector Estimate
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Cafeteria-Basement - Students
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X136

Question	Response
CAFETERIA	
Local Sound System	
Instance on Basement - Staff	Does not exist
Projection System	
Instance on Basement - Students	Does not exist
Instance on Basement - Staff	Does not exist
Theater Lighting System	
Instance on Basement - Students	Does not exist
Instance on Basement - Staff	Does not exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	Inspected
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Lighting Fixture - Incandescent	
Lighting Fixture - LED	
Pendant Mounted	
Surface Mounted	
Recessed Mounted	
Condition	1- Good
Deficiency	No deficiencies recorded
COMPUTER LAB	
GYMNASIUM	
Instance on 1st Floor	Inspected
Lighting	
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor	Does not exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X136

Question	Response
GYMNASIUM	
Lighting	
Lighting Fixture - LED	
Surface Mounted	
Instance on 1st Floor	Does not exist
Recessed Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Local Sound System	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Installation Year	1990
Source of Installation Year	Inspector Estimate
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Gymnasium-1st Floor
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Projection System	
Instance on 1st Floor	Does not exist
Scoreboard	
Instance on 1st Floor	Does not exist
Theater Lighting System	
Instance on 1st Floor	Does not exist
KITCHEN	
Instance on Basement	Inspected
Lighting	
Instance on Basement	Inspected
Lighting Fixture - Fluorescent	
Instance on Basement	Inspected
Pendant Mounted	
Instance on Basement	Does not exist
Surface Mounted	
Instance on Basement	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Basement	Does not exist
Lighting Fixture - HID	
Instance on Basement	Does not exist
Lighting Fixture - Incandescent	
Instance on Basement	Does not exist
Lighting Fixture - LED	
Instance on Basement	Does not exist
LIBRARY	
Instance on Room 217	Inspected
Lighting	
Instance on Room 217	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 217	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X136

Question	Response
LIBRARY	
Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	
Instance on Room 217	Inspected
Instance Condition	4- Between Fair and Poor
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	24
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Surface Mounted	
Instance on Room 217	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Room 217	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Lighting Fixture - HID	
Instance on Room 217	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 217	Inspected
Pendant Mounted	
Instance on Room 217	Does not exist
Surface Mounted	
Instance on Room 217	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Room 217	Does not exist
Lighting Fixture - LED	
Instance on Room 217	Does not exist
Raceway With Receptacles	
Instance on Room 217	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Projection System	
Instance on Room 217	Does not exist
LOCKER ROOM	
Instance on Room B29 - Boys, B30 - Girls	Inspected
Alternative Use	Yes
Lighting	
Instance on Room B29 - Boys, B30 - Girls	Inspected
Lighting Fixture - Fluorescent	
Instance on Room B29 - Boys, B30 - Girls	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X136

Question	Response
LOCKER ROOM	
Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	
Instance on Room B29 - Boys, B30 - Girls	Does not exist
Surface Mounted	
Instance on Room B29 - Boys, B30 - Girls	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Room B29 - Boys, B30 - Girls	Does not exist
Lighting Fixture - HID	
Instance on Room B29 - Boys, B30 - Girls	Does not exist
Lighting Fixture - Incandescent	
Instance on Room B29 - Boys, B30 - Girls	Does not exist
Lighting Fixture - LED	
Instance on Room B29 - Boys, B30 - Girls	Does not exist
MULTIPURPOSE ROOM	Does not exist
SCIENCE DEMO ROOM	Inspected
Instance on Rooms 233, 234, 237	Inspected
Power Panel?	No
Alternative Use	Yes
Lighting	
Instance on Rooms 233, 234, 237	Inspected
Lighting Fixture - Fluorescent	
Instance on Rooms 233, 234, 237	Inspected
Pendant Mounted	
Instance on Rooms 233, 234, 237	Does not exist
Surface Mounted	
Instance on Rooms 233, 234, 237	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Rooms 233, 234, 237	Does not exist
Lighting Fixture - HID	
Instance on Rooms 233, 234, 237	Does not exist
Lighting Fixture - Incandescent	
Instance on Rooms 233, 234, 237	Does not exist
Lighting Fixture - LED	
Instance on Rooms 233, 234, 237	Does not exist
Emergency Gas Shut-Off Valve	
Instance on Rooms 233, 234, 237	Does not exist
Emergency Shut-Off Power	
Instance on Rooms 233, 234, 237	Does not exist
Power Supply	
Instance on Rooms 233, 234, 237	Does not exist
Projection System	
Instance on Rooms 233, 234, 237	Does not exist
SCIENCE LAB	Does not exist
SCIENCE PREP ROOM	Inspected
Instance on Room 235	Inspected
Power Panel?	No
Alternative Use	Yes

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X136

Question	Response
SCIENCE PREP ROOM	
Lighting	
Instance on Room 235	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 235	Inspected
Pendant Mounted	
Instance on Room 235	Does not exist
Surface Mounted	
Instance on Room 235	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Room 235	Does not exist
Lighting Fixture - HID	
Instance on Room 235	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 235	Does not exist
Lighting Fixture - LED	
Instance on Room 235	Does not exist
Emergency Gas Shut-Off Valve	
Instance on Room 235	Does not exist
Emergency Shut-Off Power	
Instance on Room 235	Does not exist
Power Supply	
Instance on Room 235	Does not exist
SWIMMING POOL	Does not exist
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not exist
EMERGENCY GENERATOR SET	Does not exist

NYC Department of Education
Building Condition Assessment Survey 2023-2024

Electrical Inspection

X136

Question	Response
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Non Battery Pack	Does not exist
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EXIT/EMERGENCY LIGHT	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
FIRE ALARM SYSTEM	Inspected
Bell/Horn	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Strobe	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Manual Pull Station	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Duct Smoke Detector	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Area Smoke Detector	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
CO Detector	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Heat Detector	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Elevator Recall	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Magnetic Door Holder/Contactor	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fused Cutout Panel	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	Does not exist
Main Panel	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X136

Question	Response
FIRE ALARM SYSTEM	
Main Panel	
Bell At Panel	Does not exist
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Main Entrance Lobby
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Edwards System Technology
Model	EST3X
EquipmentId	Fire Alarm Control Panel
Installation Year	2014
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	Does not exist
Sub-Panel	Does not exist
Remote Annunciator	Inspected
Display Monitor	Does not exist
Panel	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Printer	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Punch Register	Does not exist
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Tamper Flow Switch/Chain	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	Inspected
Elevator	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Holding Area	Does not exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
MOTOR CONTROLLER	Inspected
MOTOR CONTROL CENTER	Does not exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X136

Question	Response
MOTOR CONTROLLER	
Variable Frequency Drive	Does not exist
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room, Mechanical Room B28
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Auditorium Stage
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Molded Case Circuit Breaker Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Throughout the Building
Deficiency Quantity	21
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
PUBLIC ADDRESS SYSTEM	Inspected
Instance	Main Office - Room 136
Instance Condition	4- Between Fair and Poor
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Bogen HTA125A
Installation Year	1990
Source of Installation Year	Inspector Estimate
Deficiency	SPEAKER NOT OPERATIONAL
Deficiency Location/Instance	Classrooms and Auditorium
Deficiency Quantity	12
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Deficiency	CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Throughout the Building
Deficiency Quantity	23
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3

NYC Department of Education
Building Condition Assessment Survey 2023-2024

Electrical Inspection

X136

Question	Response
PUBLIC ADDRESS SYSTEM	
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	MASTER CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Main Office
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Main Office - Room 136
Deficiency Quantity	165,000
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
SECURITY	Inspected
IPDVS/CCTV System	Does not exist
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	Vestibule by Auditorium
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista 128BPT
Installation Year	2017
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting - Security	Inspected
Condition	2- Between Good and Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Location/Instance	Main Roof, Main Entrance
Deficiency Quantity	7
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 3
Violations	No violations recorded
SERVICE SWITCH	Inspected
Instance	Basement - Electrical Room

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X136

Question	Response
SERVICE SWITCH	
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Metropolitan
EquipmentId	Ser SW A
Capacity/Size Quantity	1600
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1960
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Basement - Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Basement -Electric Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Metropolitan
EquipmentId	Ser SW B
Capacity/Size Quantity	1600
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1960
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Basement -Electric Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Basement - Room Next to Electrical Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Electrotech
EquipmentId	MDP-A
Capacity/Size Quantity	1600
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1995
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
Instance	Basement - Next to Electrical Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Electrotech
EquipmentId	MDP-B

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X136

Question	Response
SERVICE SWITCH	
Capacity/Size Quantity	1600
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1995
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
SWITCHBOARD	
Number of Spares	16
Fused Disconnect Switch Type	
Instance	Inspected
Instance Condition	Basement - Electrical Room
Instance Quantity	3- Fair
Instance Quantity Uom	1
Manufacturer	EACH
EquipmentId	Siemens
Capacity/Size Quantity	Service Switch A
Capacity/Size UOM	1600
Capacity/Size 2 Quantity	Amps Total
Capacity/Size 2 UOM	3
Source of Capacity/Size	Section(s)
Installation Year	Service Switch Size
Source of Installation Year	1990
Deficiency	Documented
Instance	No deficiencies recorded
Instance Condition	Basement - Electrical Room
Instance Quantity	3- Fair
Instance Quantity Uom	1
Manufacturer	EACH
EquipmentId	Siemens
Capacity/Size Quantity	Service Switch B
Capacity/Size UOM	1600
Capacity/Size 2 Quantity	Amps Total
Capacity/Size 2 UOM	3
Source of Capacity/Size	Section(s)
Installation Year	Service Switch Size
Source of Installation Year	1990
Deficiency	Documented
Instance	No deficiencies recorded
Instance Condition	Basement - Room Next to Electrical Room
Instance Quantity	3- Fair
Instance Quantity Uom	1
Manufacturer	EACH
EquipmentId	Electrotech
Capacity/Size Quantity	N/A
Capacity/Size UOM	1600
Capacity/Size 2 Quantity	Amps Total
Capacity/Size 2 UOM	2
Source of Capacity/Size	Section(s)
Installation Year	Service Switch Size
Source of Installation Year	1995
Deficiency	Custodial Staff
Instance	No deficiencies recorded
Instance Condition	Basement - Room Next to Electrical Room
Instance Quantity	3- Fair
Instance Quantity Uom	1
Manufacturer	EACH

NYC Department of Education
Building Condition Assessment Survey 2023-2024

Electrical Inspection

X136

Question	Response
SWITCHBOARD	
Fused Disconnect Switch Type	
Manufacturer	Electrotech
EquipmentId	N/A
Capacity/Size Quantity	1600
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	2
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Service Switch Size
Installation Year	1995
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not exist
Molded Case Circuit Breaker Type	Does not exist
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
TRANSFORMER	Does not exist